

PRIVILEGED and CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE

February 7, 2023

TC Energy 450-1 Street S.W. Calgary, AB, Canada, T2P 5H1 Attn: Brian Yeung **By Email**

Re: 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline

Dear Mr. Yeung:

Pursuant to your request, this report details the findings of the metallurgical investigation of the Keystone Pipeline rupture near MP-14 in Washington County, Kansas.

GENERAL NOMENCLATURE

The identification and location of specific features of the pipe are made in reference to top dead center (TDC). Clockwise position is established when viewed in the direction of flow. Positions of features are referenced interchangeably using both degrees and inches from TDC, using the conversion $1^\circ = 0.314$ ".

BACKGROUND INFORMATION

It was reported that on December 7, 2022, TC Energy experienced an in-service failure of the 36" Keystone Pipeline Phase 2 (KS10 segment) near the Mill Creek crossing at MP-14 in Washington County, Kansas. The pipeline was reportedly a 36" nominal diameter with a 0.465" nominal wall thickness, API 5L grade X70 PSL 2 material. The failure was reported at a girth weld joining a 0.515" wall thickness pup to a 30° elbow with a thickness of ~0.80". The material

ANDERSON & ASSOCIATES, INC.

test reports (MTR) for the pups and elbow are provided in Appendices A and B, respectively. The failed section of pipe was received at Anderson & Associates on December 19, 2022, and the metallurgical investigation began on January 9, 2023. The pipe section is shown after removal from its transport crate below in Figure 1.



Figure 1 – *Pipe section shown as-received after un-boxing. Girth weld identifications and flow direction (red arrow) were as noted.*

VISUAL EXAMINATION

General Condition

The visual examination was conducted in the as-received condition and after abrasive grit blasting removal of the external coating. The external coating appeared consistent with a green colored fusion bonded epoxy (FBE). The coating appeared to be in good condition, with two isolated instances of "fresh" damage identified. The coating on each end of the pipe sample had been removed, likely during the excavation in preparation to liberate the sample from the line. In order from upstream to downstream, the pipe sample consisted of the following sections:

- A short ligament of spiral welded line pipe joined via girth weld (GWD) 13510 to a longitudinally seam welded pup. An analysis of GWD 13510 was not included in the test protocol.
- The pup section was joined to the upstream side of a 30° elbow via GWD 13520.

 The downstream end of the elbow was joined to a longitudinally seam welded pup section via GWD 13530. The orientation of the seam weld of the pup with respect to TDC was 122° clockwise.

The overall length of the pipe sample was 13', 11.25". The outer diameter (OD) of the pipe was measured in one-foot increments along the length beginning at the upstream side using a pi-tape. The measurements are summarized in Table 1.

D ·

Table I – Pipe Diameter	
Position from	
US End (ft)	Diameter (in)
0	36.050
1	36.025
2	36.059
3	36.078
4	36.075
5	36.125
Wrinkle (5.5)	36.508
6	36.120
7	36.035
8	35.956
9	35.880
10	35.860
11	36.128 (FBE)
12	36.110
13	36.100
13.9375	36.083

Features of Interest

There were two major features of interest that were visually identified – the first being a circumferentially oriented crack located coincidentally with the toe of the girth weld on the pup side of GWD 13530 as shown in Figure 2. There was a protective pad that was duct taped to the pipe covering the crack when it was received. After the protective pad was removed, it was observed that black sharpie marking indicated the visual extent of the crack to span from 333°

ANDERSON & ASSOCIATES, INC.

to 54°, a total of approximately 81° (~25.43"). The crack appeared to be located entirely on the pipe-side of the girth weld. There were two sections of rubber hosing placed in the crack space, presumably installed in the field to prevent the mating fracture surfaces from contacting each other during transport. The FBE coating on the pipe-side of GWD 13530 exhibited parallel cracking at the terminal ends of the fracture as shown in Figure 3.

The second feature of interest was what initially described as a "bulge", but upon examination appeared more consistent with a wrinkle (pipe buckle), was located on the intrados (bottom side) of the upstream pup adjacent to GWD 13520 as shown in Figure 4. The wrinkle was approximately centered upon bottom dead center and spanned approximately 180°.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 5 of 86





Figure 2 – (a) Photograph showing the condition of GWD 13530 as it was received. The leak location was protected with a yellow pad and secured in place with duct tape. (b) Photograph showing rupture in the pipe at GWD 13530 after removing the protective covering. There were sections of rubber hosing installed in the rupture location, presumably to protect the fracture faces from mechanical contact.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 6 of 86



Figure 3 – View of parallel cracking in the FBE coating on the pipe-side of GWD 13530 at the counter-clockwise terminal end of the crack. Protective rubber hosing installed in the crack surfaces to prevent contact.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 7 of 86



Figure 4 – View of the bulge (wrinkle) on the intrados side of the US pup adjacent to GWD 13520.

Following the initial visual inspection, the pipe was transported to AAA Blastcoat in Houston, Texas for the purposes of removing the FBE coating via abrasive grit blasting. Approximately 9" either side of GWD 13530 and approximately 180° around the circumference were masked off to prevent contamination of the fracture with the abrasive media. Removal of the FBE coating was necessary for subsequent non-destructive analyses that were to be performed by Applus RTD. A photograph showing the freshly grit blasted pipe is shown in Figure 5.

With the FBE coating removed, stamped identification was located on the intrados side of the elbow fitting. The identification on the elbow fitting was as follows:



ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 8 of 86



Figure 5 – *View of the pipe after grit blasting to remove the FBE coating in preparation for* NDT.

NON-DESTRUCTIVE TESTING

Applus RTD was contracted to perform a series of non-destructive testing (NDT). Included in the scope of work was the following examinations on the girth welds: radiographic testing (RT), phased array ultrasonic testing (PAUT), ultrasonic wall thickness testing, magnetic particle inspection (MPI) on both OD and inner diameter (ID) of the girth welds, time of flight diffraction (TOFD), and inverse wave field extrapolation (IWEX). The entirety of the OD and ID surfaces were also mapped via laser scanning and wall thickness measurements were taken ultrasonically.

Of particular importance for the metallurgical failure investigation were the results of the radiographic testing, PAUT and MPI, which would help guide the sectioning plan to extract the crack and subsequent metallographic sections from the pipe. The radiographic report for GWD 13530 indicated the presence of a "rejectable crack" spanning a total of approximately 47.73" (152°) of the circumference. Radiographic examination of GWD 13520 showed several instances of porosity and slag inclusions, none of which were identified as rejectable per the Applus RTD radiography report. There were numerous MPI indications identified around the circumference, both OD and ID on both GWD 13520 and 13530, most if not all were associated with the toe of the girth welds. PAUT identified numerous toe lack-of-fusion and toe cracks on both GWD 13520 and 13530, most if not all were coincident with MPI indications. Radiography, PAUT, UT wall thickness, TOFD, and IWEX reports have been delivered to TC Energy by Applus RTD, the NDT report is provided in Appendix C.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 9 of 86

Crack Measurement

The physical dimensions of the crack were documented prior to extraction from the pipe. The dimensions were measured by first tracing the crack on to sheets of white tracing paper, then measuring the width of the transcribed crack using calipers in half-inch increments as shown in Figure 6. Using this technique, the overall length of the crack on the OD was determined to be 26.50", and the maximum displacement (width) was measured to be 0.638". From these measurements it was found that the crack was not symmetric about TDC.



Figure 6 – Traced image of the crack on the OD of GWD 13530 with width measurements acquired every 0.50".

ANDERSON & ASSOCIATES, INC.

Crack Length	Crack Width
(in)	(in)
0	0.097
0.50	0.158
1.00	0.222
1.50	0.233
2.00	0.251
2.50	0.340
3.00	0.356
3.50	0.225
4.00	0.310
4.50	0.397
5.00	0.383
5.50	0.471
6.00	0.411
6.50	0.410
7.00	0.600
7.50	0.606
8.00	0.623
TDC	
8.50	0.635
9.00	0.638
9.50	0.638
10.00	0.426
10.50	0.407
11.00	0.372
11.50	0.414
12.00	0.426
12.50	0.408
13.00	0.400
13.50	0.335
14.00	0.339
14.50	0.372
15.00	0.507
15.50	0.531
16.00	0.596
16.50	0.481
17.00	0.473
17.50	0.508
18.00	0.489
18.50	0.455
19.00	0.551
19.50	0.651
20.00	0.643
20.50	0.527
21.00	0.464
21.50	0.428
22.00	0.482
22.50	0.266
23.00	0.326
23.50	0.359
24.00	0.300
24.50	0.368
25.00	0.352
25.50	0.340
26.00	0.373
26.50	0.100

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 11 of 86

Following the completion of NDT inspections, the fracture on both the OD and ID was masked and a panel encompassing the fracture in GWD 13530 was removed using a plasma cutter. The extracted panel is shown in Figure 7. To facilitate trimming, the weld on the ID was examined using wet fluorescent magnetic particle inspection to assess the extent of ID crack extension. As shown in Figures 8 and 9, there were linear indications on the pipe-side weld toe spanning nearly the entire length of the panel. Consequently, initial trim cuts were conservative e.g., removing minimal material from the edges so to as inspect for any evidence of depth of the indications. Following several initial trim cuts with no evidence of visible extension of the indications through the thickness of the material, the decision was made to trim at the visible extent of the opened crack region. The panel was then submerged in liquid nitrogen to facilitate freeze breaking the remaining ligaments. The reassembled panel after breaking is shown in Figure 10.



Figure 7 – *View of the panel containing the ruptured section of GWD 13530 after removal from the pipe.*

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 12 of 86



Figure 8 – (L) photograph showing the ID of \overline{GWD} 13530 clockwise to the rupture (\overline{R}) same portion of the weld using ultra-violet light after WFMP showing a crack-like indication at the toe (yellow arrow).

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 13 of 86



Figure 9 – (L) photograph showing the ID of the GWD 13530 counter-clockwise to the rupture (R) same portion of the weld using ultra-violet light after WFMP showing a crack-like indication at the toe (yellow arrow).

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 14 of 86



Figure 10 – *View of the re-assembled freeze fractured panel from GWD 13530. Yellow scales are in inches.*

FRACTOGRAPHIC EXAMINATION

Visual and Stereoscopic Examination

After freeze breaking the fractured region to expose the surfaces for detailed examination it was observed that there were three prominent elliptical or bow shaped crack features present on the fractured surface as shown on the DS side (pipe side) panel in Figure 11. All the elliptical crack shaped features appeared flat, coincident with the weld toe, and appeared to originate at or near the ID surface. The largest, shown in Figure 12 was symmetrical in profile and spanned approximately 8.70" and was centered approximately 4.5" (14.3°) clockwise from TDC. The second largest elliptical crack feature shown in Figure 13 measured approximately 4" in length and was asymmetrical in the depth profile (tear drop shaped) and the deepest portion was located approximately 4.25" (13.5°) counterclockwise from TDC. The elliptical crack feature with the

ANDERSON & ASSOCIATES, INC.

smallest profile shown in Figure 14 also had an asymmetric depth profile and the deepest portion was located approximately 13" (41.4°) clockwise from TDC.

Separating Cracks 2 and 3 from Crack 1 were two regions exhibiting a shear morphology (fracture surfaces oriented at $\sim 45^{\circ}$). Examination of the Upstream fracture side (weld side) showed that these two shear regions appeared coincident with discontinuities in the continuous root pass that appeared consistent with weld repairs. Further evidence observed indicating these two regions were coincident with weld repairs were grind marks observed as shown in Figures 15 and 16. It was further observed that the weld bead in these two shear regions was thicker in comparison to the original root pass.



Figure 11 – *View of the GWD 13530 downstream (pipe side) of the exposed fracture. The yellow arrows identify the three elliptical crack features, TDC is marked with the dashed yellow line.*

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 16 of 86





Figure 12 – (a) Magnified view of Crack 1 (b) Crack 1 depth profile measured with calipers.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 17 of 86





Figure 13 – (a) Magnified view of Crack 2 (b) Crack 2 depth profile measured with calipers.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 18 of 86





Figure 14 – (a) Magnified view of Crack 3 (b) Crack 3 depth profile measured with calipers.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 19 of 86



Figure 15 – Photograph showing the ID region of the rupture coincident with the shear lip separating GWD 13530 Cracks 1 and 2. The arrow identifies grind marks identified on the bevel of the elbow.



Figure 16 – Photograph showing the ID region of the crack coincident with the shear lip separating GWD 13530 Cracks 1 and 3. The arrows identify grind marks on the remnant pipe ligament (top) and elbow bevel (bottom).

ANDERSON & ASSOCIATES, INC.

The elliptical crack regions were sectioned out using dry saw cuts and cleaned using a combination of a dilute Citrinox solution (2%) and an ultrasonic bath. One elliptical crack section (Sample 1-1) was not initially cleaned so that the chemical composition of the surface scale could be examined in the SEM. The remaining sections were initially examined using a low magnification digital microscope (Keyence VHX-6000). The general features common to the three elliptical cracks were as follows:

- Each appeared to initiate at or near the ID surface and had multiple, radially oriented crack initiation features (ratchet marks).
- Each showed evidence of progressive cracking in the form of multiple crack arrest features; 10 15 clearly distinguishable arrest lines were identified on Cracks 1 and 2. There was evidence observed that the crack arrest features were coincident with individual weld passes as shown in Figure 18.



Figure 17 – Low magnification view of the center region of GWD13530 Crack 1 showing multiple crack arrest lines throughout the elliptical crack feature. Several of the most clearly defined arrest lines are identified with yellow arrows.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 21 of 86



Figure 18 – Oblique view of the weld-side metallographic section prepared through GWD 13530 *Crack 2 showing coincidence between crack arrest lines (yellow arrows) and individual weld passes (highlighted with yellow dashed lines).*



Figure 19 – Low magnification view of GWD 13530 Crack 3. This crack was unique amongst the fatigue cracks as it exhibited multiple advancing crack fronts, the peaks of the two advancing fronts are identified with yellow arrows.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 22 of 86

SEM/EDS Examination

The sectioned portions of each elliptical crack features on the DS (pipe side) were examined in the scanning electron microscope (SEM) using both backscatter electron contrast (BES) and secondary electron imaging (SEI), the latter being more sensitive to surface topography. The DS fracture surfaces were selected for examination to mitigate the need to trim potentially salient weld features on the US (elbow side). All samples except for Sample 1-1 were cleaned using a combination of a 2% Citrinox solution and an ultrasonic bath. Sample 1-1 was examined "as-is" so that the chemistry of the scale product on the surface could be examined using energy dispersive x-ray spectroscopy (EDS). EDS is a qualitative chemical analysis technique that can accurately identify elements present on a surface but cannot identify compounds and only provides a semi-quantitative chemical composition. The results of the EDS analysis, shown in Figure 21 showed primarily carbon, sulfur, silicon, aluminum, calcium, and oxygen; elements typically found in both crude oil and soil.



Figure 20 – Low magnification digital photograph showing GWD 13530 Sample 1-1 before cleaning. EDS examination shown in Figure 21 was taken from the region encompassed by the yellow box.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 23 of 86



Figure 21 – (a) Low magnification view of GWD 13530 Sample 1-1 before cleaning with the area examined with EDS encompassed within the yellow box (b) Corresponding EDS spectrum showing high concentrations of non-native elements (sulfur, calcium, and oxygen). The non-native elements identified via EDS appeared consistent with exposure to crude oil and soil.

ANDERSON & ASSOCIATES, INC.

GWD 13530 Crack 1 - Sample 1-2

The central region of Crack 1 identified as "Sample 1-2" is shown after cleaning in low magnification in Figure 22. The full thickness of the fracture was examined, fractographs included in this report were selected as representative of the features of interest. Examination of the ID region of the crack at low magnifications showed a flat, featureless morphology except for several radially oriented ratchet marks, one of which is shown in Figure 23. Also present in this fractograph was a prominent change in fracture orientation at the ID surface, the geometry of which appeared to mirror the geometry of the weld toe. Figure 24 shows the fracture morphology near the ID to have been consumed by oxidation and no distinct identifying features were present. The region of the fracture encompassing the mid-wall to OD surface offered more detail at low magnification, with several distinct crack arrest lines identified as shown in Figure 25. The crack arrest lines were more closely spaced nearer the OD surface, yet individually distinct. As shown in Figure 26, there were thin bands of micro-void coalescence (MVC) or dimpled rupture between some of the crack arrest lines. Much of the space between the crack arrest lines appeared brittle, and no evidence of striations (incremental cyclical crack growth) was observed, shown representatively in Figure 29. The shear overload region shown in Figure 30 was observed to consisted of characteristic micro-void coalescence (MVC), consistent with a ductile overload.



Figure 22 – Low magnification view of Crack 1 on GWD 13530, the yellow boxes indicate locations examined in the SEM.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 25 of 86



Figure 23 – Low magnification SEM fractograph showing the ID region of GWD 13530 Crack 1. Dashed lines identify a change in fracture orientation at the ID. The change in fracture orientation appeared consistent with the geometry of the weld toe. The yellow arrow identifies a ratchet mark.



Figure 24 – Higher magnification SEM fractograph showing the fracture morphology of GWD 13530 Crack 1 near the ID surface. The fracture surface near the ID had been consumed by oxidation and fine-scale features were not discernable.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 26 of 86



Figure 25 – Low magnification SEM fractograph of GWD 13530 Crack 1 showing multiple crack arrest lines on the elliptical crack region near the transition to final overload.



Figure 26 – *Higher magnification SEM fractograph of GWD 13530 Crack 1 showing a band of dimpled rupture associated with a crack arrest line nearer the shear overload region.*

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 27 of 86



Figure 27 – *High magnification SEM fractograph of GWD 13530 Crack 1 showing the transition from ductile tearing (dimpled morphology) and flat, brittle appearing fracture.*



Figure 28 – High magnification SEM fractograph of GWD 13530 Crack 1 showing the flat fracture morphology observed between crack arrest lines. Also seen was secondary cracking normal to the fracture plane (yellow arrow), a feature consistent with fatigue crack propagation.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 28 of 86



Figure 29 – *High magnification SEM fractograph showing a dimpled morphology in the shear overload region of GWD 13530 Crack 1.*

GWD 13530 Crack 2 - Sample 2-2

A low magnification stereophotograph of Sample 2-2 is shown in Figure 30. This sample was unique among those examined in this investigation as it exhibited a narrow band of transgranular cleavage fracture near the ID surface as shown in Figures 31 - 33. Transgranular cleavage is a brittle fracture morphology indicating sudden, unstable crack growth (colloquially referred to as a brittle pop).

Crack arrest lines nearer the transition from progressive cracking to sudden overload were well defined, and like Sample 1-2, there was a narrow band of dimple rupture coincident with the arrest lines.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 29 of 86



Figure 30 – Low magnification view of the deepest portion of GWD 13530 Crack 2. There was a narrow band of brittle fracture morphology near the ID, the yellow box identifies the region examined in the SEM.



Figure 31 – Low magnification SEM fractograph of GWD 13530 Crack 2 showing the thin band of transgranular cleavage fracture near the ID.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 30 of 86



Figure 32 – *Higher magnification SEM fractograph of GWD 13530 Crack 2 showing detail of the brittle morphology. The features appeared consistent with transgranular cleavage.*



Figure 33 – *High magnification SEM fractograph of GWD 13530 Crack 2 showing typical transgranular cleavage morphology including river patterns and faceted surfaces.*

ANDERSON & ASSOCIATES, INC.

GWD 13530 Crack 3 – Sample 3 - 2

A low magnification stereophotograph of Sample 3-2 is shown in Figure 34. This crack consisted of two separate advancing cracks that had coalesced as evidenced by the two distinct elliptical "humps".

Like the other cracks examined, there were multiple distinct crack arrest lines. The number of crack arrest lines appeared consistent (between 10 - 15). At higher magnification the fracture morphology of Crack 3 appeared identical to that of Cracks 1 and 2.



Figure 34 – Low magnification view of GWD 13530 Crack 3.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 32 of 86



Figure 35 – Low magnification SEM fractograph showing multiple crack arrest lines on GWD 13530 Crack 3.



Figure 36 – *SEM fractograph showing crack arrest lines identified with yellow arrows in the central region of GWD 13530 Crack 3. The morphology otherwise appeared flat and featureless.*

ANDERSON & ASSOCIATES, INC.

METALLOGRAPHIC EXAMINATION

Sections for metallographic examination were removed from both GWD 13530 and GWD 13520. All sections were cut and prepared in accordance with ASTM E3 and were photodocumented in both the "as polished" and etched conditions. A 3% Nital solution was used to etch the microstructure. Specific locations of sections removed from GWD 13530 are as follows:

- Mated fracture metallographic specimens were removed from Samples 1-2, 2-2, and 3-2, Shear 1-2, and Shear 1-3.
- Weld side fracture of Sample 2-2.
- Cross-weld sections from 55°, 76°, 82°, 139°, and 270°.

The general microstructure of the pipe, heat affected zones, weld metal, and elbow was documented on all examined specimens. The general impressions of each zone were as follows:

• Figure 37 shows the pipe base metal to consist of finely banded, extremely fine-grained ferrite and pearlite (ASTM E112 grain size 10 or finer). The banding in the microstructure is attributed to micro-segregation of carbide forming elements during the initial processing of the material and is aligned axially due to the rolling process. The pipe was reportedly manufactured using thermomechanically controlled processing (TMCP) which encompasses the simultaneous hot working and heat treatment to produce higher strength steel.

ANDERSON & ASSOCIATES, INC.

3% Nital.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 34 of 86



(b) **Figure 37** – (a) 12.5x optical micrograph showing the general microstructure of the pipe to exhibit a finely-banded structure (b) 200x optical micrograph showing detail of the banded ferrite and pearlite microstructure, typical of a TMCP product. Both micrographs etched with

• The microstructure of the elbow consisted of a mixture of ferrite, acicular and proeutectoid ferrite, tempered martensite, and bainite; all of which are transformation

ANDERSON & ASSOCIATES, INC.

products that form in low-alloy steels upon rapid cooling (quenching) of a steel from austenitizing temperatures (generally > 1,600°F). As shown in Figure 38a, there was slight decarburization at both the OD and ID surfaces of the elbow, most likely an artifact of heat treatment and appeared inconsequential in terms of the overall performance. The concentration of proeutectoid ferrite and bainite was higher nearer the surfaces (Figure 38b) of the elbow, likely reflecting the slightly lower carbon concentration. As shown in Figure 39, the microstructure at mid-wall appeared homogenous, consisting of tempered martensite and bainite.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 36 of 86



Figure 38 – (a) 12.5x optical micrograph showing the ID region of the elbow with a thin band of light etching microstructure at the ID surface characteristic of decarburization (b) 500x optical micrograph showing the microstructure of the elbow at the ID to consist of ferrite and pearlite with some bainite. Both micrographs shown etched with 3% Nital.
ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 37 of 86



Figure 39 – (a) 12.5x optical micrograph showing the elbow microstructure at mid-wall to appear homogenous. (b) 500x optical micrograph showing the microstructure at mid-wall to consist of tempered martensite and bainite. Both micrographs shown etched with 3% Nital.

ANDERSON & ASSOCIATES, INC.

• The microstructures of the weld and heat affected zones (HAZ) on both the pipe (Figure 40) and elbow side (Figure 41) were also examined. Based on the physical characteristics it was evident that the girth welds were not post weld heat treated (PWHT). Specific evidence observed supporting this conclusion was the weld microstructure appearing "aswelded" or "as-cast" consisting of large columnar grains comprised of acicular ferrite and carbide. The weld root and lower hot passes appeared heavily tempered from the heat of subsequent weld passes. The cap passes did not exhibit any evidence of tempering. The HAZ on both elbow and pipe sides exhibited coarse and fine-grained microstructures (CGHAZ and FGHAZ, respectively), which are typically developed during welding and are attributed to the temperature profile (coarse-grained microstructure sees higher temperature).

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 39 of 86



(b)

Figure 40 – Pipe side weld and heat affected zone structures at the OD. (a) 12.5x (b) 100x, 3% Nital etch. Coarse-grained HAZ (CGHAZ)

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 40 of 86



Figure 41 – Elbow-side weld and HAZ structures (a) 12.5x (b) 100x. 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 41 of 86

GWD 13530 Sample 1-2

The mated cross-section from Sample 1-2 is shown below in Figure 42. The fracture propagated linearly through nearly the entire thickness of the pipe side, intersecting both HAZ and weld microstructures. There was no evidence observed that the fatigue crack propagated through the full thickness of the pipe and/or weld. The angular feature at the ID toe of the girth weld on the pipe side identified visually and in the SEM was also evident in cross-section. Metallographically the angular feature at the toe of the girth weld appeared to parallel the fusion line and was approximately 200 μ m in length. It was evident that the fatigue crack originated from this feature as there was no additional or secondary cracking observed.



Figure 42 – Overall view of the metallographic section prepared through GWD 13530 Crack 1.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 42 of 86



Figure 43 – *Photomontage of optical micrographs showing GWD 13530 Crack 1 propagation through multiple microstructural features. Originally photographed at 12.5x, 3% Nital etch.*

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 43 of 86



Figure 44 – Optical micrograph showing the root pass of the GWD 13530 adjacent to the fracture. A prominent lip was observed at the ID intersection of the crack, the profile of the lip appeared to parallel the fusion line. 12.5x, 3% Nital etch.



Figure 45 – Higher magnification optical micrograph showing the ID toe lip feature on GWD 13530, Crack 1. The lip appeared coincident with the fusion line of the weld and was approximately 200 μ m in length. 50x, 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 44 of 86

GWD 13530 Sample 439-2-2

The mated cross-section from Sample 2-2 is shown below in Figure 46. As with Crack 1, Crack 2 propagated linearly through pipe-side of the weld and originated at the ID toe. Higher magnification examination showed some transgranular branching of the brittle crack in the CGHAZ region as shown in Figures 48 - 49. There was no evidence observed that the fatigue crack propagated through the full thickness of the pipe and/or weld. The angular feature at the ID toe of the girth weld on the pipe side identified visually and in the SEM was also evident in cross-section. It was evident that the fatigue crack originated from this feature as there was no additional cracking observed.



Figure 46 – Overall view of the metallographic section prepared through GWD 13530 Crack 2.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 45 of 86



Figure 47 – *Photomontage of optical micrograph showing the full cross-section of GWD 13530 Crack 2. Originally photographed at 12.5x, 3% Nital etch.*



Figure 48 – Optical micrograph showing the pipe-side weld and HAZ associated with the brittle pop in GWD 13530 Crack 2. 12.5x, 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 46 of 86



Figure 49 – *Higher magnification optical micrograph showing the coarse-grained HAZ on the pipe side of GWD 13530 Crack 2 associated with the brittle pop. 100x, 3% Nital etch.*



Figure 50 – Optical micrograph showing the pipe-side of the fracture on GWD 13530 Crack 2. There was an anomaly noted with the toe of the weld that appeared consistent with lack-of-fusion. 12.5x, 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 47 of 86



Figure 51 – *Higher magnification optical micrograph showing the ID weld anomaly profile on the pipe side of GWD 13530 Crack 2. 100x, 3% Nital etch.*

GWD 13530 Sample 439-3-2

The metallographic section prepared through the deepest portion of Crack 3 is shown in Figure 52. Similar to the other two fatigue cracks, Crack 3 initiated at the ID toe of the weld, propagated approximately 0.191" into the pipe side HAZ and then experienced a shear overload event.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 48 of 86



Figure 52 – Overall view of the metallographic section prepared through GWD 13530 Crack 3.



Figure 53 – *Photomontage of optical micrographs showing the complete wall thickness profile of the pipe through GWD 13530 Crack 3. Originally photographed at 12.5x, 3% Nital etch.*

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 49 of 86



Figure 54 – *Higher magnification optical micrograph showing the ID initiation region of GWD* 13530 Crack 3. 12.5x, 3% Nital etch.



Figure 55 – Higher magnification optical micrograph showing detail of the root anomaly identified on the pipe-side of the GWD 13530 Crack 3. The anomaly appeared to fit the profile of the toe of the root pass. 200x, 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

GWD 13530 Sample 439-139°

A metallographic section was removed across GWD 13530 at 139° from TDC, a location that was coincident with a PAUT indicated feature. As shown in Figures 57 - 58, there was an indication consistent with a lack-of-fusion (LOF) defect identified at the toe of the girth weld on the pipe side.



Figure 56 – Overall view of the sample from GWD 13530 removed 139° from TDC. The feature was consistent with the location of Applus PAUT Indication 2 reported for GWD 13530.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 51 of 86



Figure 57 – Optical micrographs showing a scale-filled, approximately $200\mu m \log LOF$ at the pipe-side weld toe of GWD 13530. The upward curvature of the defect at the terminal end may be due to the onset of fatigue cracking. Both micrographs taken at 100x, (a) as-polished (b) 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 52 of 86



Figure 58 – High magnification optical micrograph showing dense, tightly adhered oxide scale consistent in appearance with magnetite lining the defect surfaces on the LOF on GWD 13530. 500x, 3% Nital etch.

Sample 439-270°

The macro-section prepared across GWD 13530 from the 270° position is shown overall in Figure 59. A small linear indication approximately 200µm in length coincident with the toe of the weld on the ID of the pipe side was identified. Upon closer examination it was observed that the indication was filled with a dense, tightly adhered oxide scale and appeared to parallel the fusion line. SEM/EDS examination show in Figure 62 of the scale adhered to the indication consisted primarily of iron, oxygen, manganese and silicon. These features indicated that this feature was most likely a LOF defect originating at the time of welding.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 53 of 86



Figure 59 – Overall view of the sample from GWD 13530 removed 270° from TDC.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 54 of 86



Figure 60 – Optical micrographs showing a scale-filled, approximately $200\mu m \log LOF$ defect at the pipe-side weld toe of GWD 13530. Both micrographs taken at 100x, (a) as-polished (b) 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 55 of 86



Figure 61 – *High magnification optical micrograph showing tightly adhered oxide scale to the defect surfaces indicating the feature to be a LOF defect on GWD 13530. 500x, 3% Nital etch.*

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 56 of 86



Figure 62–(a) Backscatter electron micrograph showing the LOF defect at the ID toe of Sample 439-270° from GWD 13530 (b) EDS spectrum collected from the scale adhered to the surfaces of the LOF defect.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 57 of 86

GWD 13530 Shear Regions 1-2 and 1-3

The mated cross sections through Shear 1-2 and Shear 1-3 are shown in Figures 63 and 64, respectively. Both samples exhibited substantial necking (localized reduction of thickness) on the pipe side of the weld, evidencing that the pipe underwent plastic deformation prior to rupturing. The metallurgical macrostructure of these two specimens differed largely from the other mated cross sections in that there was evidence that the root on the ID had been re-welded from the ID, evidenced by the fact that the HAZ from the root overlapped the hot passes. This finding is consistent with the visual observations made in these areas that the appearance of the weld bead on the ID (width and ripple coarseness) in comparison to the bulk of the ID root.



Figure 63 – Overall view of the metallographic section prepared through GWD 13530 Shear 1 – 2 region showing characteristic ductile shear fracture morphology on the pipe side. No evidence of progressive cracking was observed in this specimen.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 58 of 86



Figure 64 – Overall view of the metallographic section prepared through GWD 13530 Shear 1 – 3 region showing characteristic ductile shear fracture morphology on the pipe side. No evidence of progressive cracking was observed in this specimen.

GWD 13520

Cross-girth weld sections from GWD 13520 were removed from 4°, 80°, and 312° relative to TDC and were metallographically prepared and documented in the same manner as the intact sections removed from GWD 13530. The samples from 4° and 80° were coincident with rejectable indications reported by Applus RTD in the PAUT report (Feature Numbers 1 and 2, respectively). As shown in Figures 65 - 71 samples removed from the 4° and 80° locations both exhibited a lack-of-fusion feature at the ID toe of the girth weld, but unlike GWD 13530, the lack-of-fusion was located on the elbow-side toe. The sample at 4° also exhibited an ~500 μ m diameter porosity on the pipe-side fusion line as well as root pass lack-of-fusion defect coincident with the gas porosity. The most salient feature observed on the 4° sample was crack approximately 750 μ m in length originating from the lack-of-fusion. The sample removed from GWD 13520 at 312° exhibited evidence of having been weld repaired at the ID as shown in Figure 72.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 59 of 86



Figure 65 – Overall view of the metallographic specimen prepared from GWD 13520 at 4° from TDC. Two notable features were identified, the first was a small gas porosity/LOF defect on the pipe-side fusion line and the second was a small linear crack originating from lack-of-fusion at the ID toe of the weld on the elbow side.



Figure 66 – Optical micrograph showing the combination gas porosity and LOF defect identified on the GWD 13520 specimen at 4° from TDC. The defect was located between the root pass and first hot pass. 50x, 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 60 of 86



Figure 67 – Optical micrographs showing a linear crack originating from a LOF defect at the ID toe of GWD 13520 on the elbow side (a) as-polished (b) 3% Nital etch. Both micrographs photographed at 12.5x.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 61 of 86



Figure 68 – *Higher magnification optical micrograph showing the linear crack originating from LOF at the ID toe of GWD 13520 on the elbow side. 50x, 3% Nital etch.*



Figure 69 – *High magnification optical micrograph showing tightly adhered oxide scale to the surfaces, positively identifying the feature as LOF. 500x, 3% Nital etch.*

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 62 of 86



Figure 70 – High magnification optical micrograph showing the tip of the crack originating from LOF on GWD 13520. There was no evidence of plastic deformation associated with the crack tip, and the crack propagated transgranularly, consistent with a fatigue crack. 500x, 3% Nital etch.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 63 of 86



Figure 71 – (a) Overall view of the as-polished metallographic section taken from GWD 13520 at 80° clockwise from TDC (b) lack-of-fusion defect identified at the ID toe of the girth weld on the elbow side, 12.5x, as-polished.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 64 of 86



Figure 72 – Overall view of the metallographic specimen prepared from GWD 13520, 312° from TDC. This metallographic section indicated the ID root had been repaired, evidenced by the overlay of the ID HAZ on the intermediate hot passes.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 65 of 86

MECHANICAL TESTING

Tensile Testing

Tensile testing of the pipe body and elbow materials was conducted in accordance with API 5L and MSS SP-75-2004. Cross girth weld tensile testing was conducted in accordance with API 1104. Tensile testing consisted of both full wall thickness and sub-size round test specimens. The results of the tests are summarized in the following tables. The tensile datasheets for the full-wall thickness pipe and elbow body specimens are included as Appendix D and the tensile datasheets for all sub-size tensile specimens are included as Appendix E.



¹ ASME IX (2010) QW-153.1 "In order to pass the tension test, the specimen shall have a tensile strength that is not less than (a) the minimum specified tensile strength of the base metal (b) the minimum specified tensile strength of the weaker of the two, if base metals of different minimum tensile strengths are used..."

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 66 of 86





² API 5L minimum elongation calculated by $e = 625,000 \frac{Acx^{0.2}}{UTS^{0.9}}$

³ "X-SW" = cross seam-weld

⁴ MSS SP-75-2004 Section 8.4 states yield strength can be determined using either 0.2% offset or 0.5% EUL method.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 67 of 86

Redacted by TC Energy

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 68 of 86



⁵ API 5L minimum elongation calculated by $e = 625,000 \frac{Acx^{0.2}}{UTS^{0.9}}$

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 69 of 86



CVN Impact Testing

Sets of full-size, transverse oriented Charpy V-Notch (CVN) impact specimens was removed from each of the following locations of the upstream and downstream pup sections – base metal 90° from the seam weld, seam weld HAZ (FL + 1mm)⁸, and seam weld centerline in accordance with API 5L. The specimens were prepared and tested in accordance with ASTM A370 at -5°C. The results demonstrate the pipe met the minimum absorbed energy requirement of 40 ft-lbs for API 5L grade X70 PSL 2 pipe.



⁶ CANDAOIL Forge LTD Material Test Report 6235

⁷ MSS SP-75-2004 Section 8.4 states yield strength can be determined using either 0.2% offset or 0.5% EUL method.

⁸ HAZ notch location (FL+1mm) measured at mid-wall.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 70 of 86



ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 71 of 86



Girth Weld CVN Impact Testing

Sets of longitudinally oriented, full-size CVN specimens were removed from both GWD 13530 and 13520. Three sets of three CVN specimens were notched in the girth weld HAZ (FL+1mm)⁹, and three sets of three CVN specimens were notched in the weld centerline. Specimens were

⁹ HAZ notch location (FL+1mm) measured at mid-wall.

ANDERSON & ASSOCIATES, INC.

tested at -5°C. All tested specimens met the minimum requirements for impact toughness in API 1104 (21st Edition). It should be noted however that the edition of API 1104 that these welds would have been fabricated to (API 1104 20th Edition) did not require CVN impact testing. Photographs of the scribed notch locations are included as Appendix G.


ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 73 of 86

Redacted by TC Energy	

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 74 of 86

Redacted by TC Energy	

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 75 of 86



CTOD Testing

Six Bx2B SE(B) CTOD specimens were removed from each girth weld following the guidelines of API 1104 understanding that the entire girth weld was not available for testing. The first number corresponds to the girth weld, 20 for girth weld 13520, and 30 for girth weld 13530.

The SE(B) CTOD specimens were compression stress relieved per ISO 15653:2018 Annex C.2. All specimens pre-cracked at room temperature and tested per ISO 15653:2018 at 20°C. All but one tested specimen (439-20-16) met the minimum required CTOD value (0.005in) set forth in API 1104 (20th Edition). The datasheets are included as Appendix H, notch locations and posttest fracture pictures are provided as Appendix I. The results are summarized as follows:

ANDERSON & ASSOCIATES, INC.

Girth Weld 13520					
Specimen	Zone	[inches]	Validity		
439-20-6	Pipe HAZ	$\delta_m = 0.020$	Valid		
439-20-16	Pipe HAZ	$\delta_u = 0.0047$	Valid		
439-20-30	Pipe HAZ	$\delta_m = 0.013$	Valid		
439-20-63	Weld	$\delta_m = 0.0069$	Valid		
439-20-82	Weld	$\delta_m = 0.0084$	Valid		
439-20-310	Weld	$\delta_m = 0.017$	Valid		

Girth Weld 13530					
Specimen	Zone	CTOD [inches]	Validity		
439-30-207	Pipe HAZ	$\delta_m = 0.023$	Valid		
439-30-235	Pipe HAZ	$\delta_{\rm m} = 0.028$	Valid		
439-30-256	Pipe HAZ	$\delta_{\rm m} = 0.024$	Valid		
439-30-131	Weld	$\delta_m = 0.0068$	Valid		
439-30-132	Weld	$\delta_m = 0.0089$	Valid		
439-30-206	Weld	$\delta_m = 0.0087$	Valid		

Microhardness Testing

A Vickers microhardness survey (HV10) was conducted metallographically prepared crosssections from GWDs 13530 and 13520 in accordance with the protocol submitted by TC Energy. Results were converted to appropriate Rockwell B [HRB] and Rockwell C [HRC] scales per ASTM E140 for ease of interpretation. The results of the hardness tests on GWD 13530 showed the hardness to be uniform across the base metal, pipe-side HAZ, weld, elbow-side HAZ, and elbow. There were local hard-spots identified, however they appeared to be remote from the failure location on the elbow-HAZ associated with the cap pass. The hardness results from GWD 13520 were similar to those from GWD 13530, the notable difference being the hardness of sample GWD 13520-312° (ID weld repair), being consistently higher than the hardness at the OD and mid-wall. The results of the microhardness tests for both welds are summarized in Figures 73 – 76 below.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 77 of 86

Customer	TC Energy	Our Job #	220439	
Description	GWD 13530	Date	1-26-2023	
	Crack 2-2			
Test Load	10KG	Technician	Thomas Tripodi	
Test Magnification	100x			

	Terrane Pr. 30	HRB	HRC			HRB	HRC
Location	Vickers	Converted	Converted	Location	Vickers	Converted	Converted
Тор				Middle			
1	222	96.9		17	212	95.3	
2	212	95.3		18	216	96.0	
3	210	95.1		19	210	94.9	
4	221	96.9		20	190	91.1	
5	227	97.8		21	197	92.4	
6	223	97.2		22	260		24.1
7	214	95.7					
8	272		26.1	Bottom			
9	258		23.7	23	216	96.1	
10	219	96.5		24	238	99.7	
11	251		22.4	25	240		20.4
				26	242		20.8
Middle				27	206	94.3	
12	195	92.0		28	227	97.8	
13	196	92.3		29	209	94.7	
14	200	93.0		30	223	97.2	
15	224	97.3		31	202	93.4	
16	223	97.1		32	201	93.2	
				33	257		23.5



Figure 73 – Vickers microhardness survey on metallographic specimen GWD 13530 Crack 2.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 78 of 86

Customer	TC Energy	Our Job #	220439
Description	GWD 13530-76°	Date	1/26/2023
Test Load	10KG	Technician	Thomas Tripodi
Test Magnification	100x		

		HRB	HRC			HRB	HRC
Location	Vickers	Converted	Converted	Location	Vickers	Converted	Converted
Тор				Middle			
1	221	96.7	1	17	193	91.6	
2	232	98.7		18	210	95.0	
3	249		22.1	19	236	99.3	
4	246		21.6	20	222	97.0	
5	225	97.4		21	198	92.6	
6	225	97.5		22	248		21.9
7	226	97.6					
8	333		33.6	Bottom			
9	339		34.3	23	211	95.1	
10	336		34.0	24	211	95.1	
11	278		36.9	25	216	96.1	
				26	217	96.2	
Middle				27	214	95.6	
12	214	95.6		28	213	95.5	
13	197	92.3	· ·	29	208	94.6	
14	193	91.5		30	226	97.7	
15	196	92.1		31	223	97.2	
16	194	91.9		32	222	97.0	
				33	268		25.3



Figure 74 – Vickers microhardness survey on metallographic specimen GWD 13530-76°.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 79 of 86

Customer TC Energy		Our Job #	220439
Description	GWD 13520-80°	Date	02/03/2023
Test Load	10KG	Technician	Andrés R.
Test Magnification	100x		

		HRB	HRC			HRB	HRC
Location	Vickers	Converted	Converted	Location	Vickers	Converted	Converted
Тор				Middle			
1	219.1	96.5	1	17	205.0	94.0	
2	204.0	93.8		18	193.9	91.8	
3	218.9	96.5		19	191.7	91.3	
4	229.0	98.2		20	188.0	90.6	
5	199.6	92.9		21	181.4	89.3	
6	192.2	91.4		22	227.2	97.9	
7	226.9	97.8					
8	313.4		31.4	Bottom			
9	287.1		28.1	23	222.8	97.1	
10	242.2		20.8	24	186.0	90.2	
11	25.15		22.6	25	192.7	91.5	
				26	204.2	93.8	
Middle				27	197.7	92.5	
12	205.3	94.1		28	198.2	92.6	
13	185.1	90.0		29	193.9	91.8	
14	178.3	88.6		30	210.4	95.1	
15	194.9	92.0		31	240.0		20.4
16	189.8	91.0		32	258.8		23.8
				33	274.5		26.4



Figure 75 – Vickers microhardness survey on metallographic specimen GWD 13520-80°.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 80 of 86

Customer	TC Energy	Our Job #	220439
Description	GWD 13520-312°	Date	02/03/2023
Test Load	10KG	Technician	Andrés R.
Test Magnification	100x		

		HRB	HRC			HRB	HRC
Location	Vickers	Converted	Converted	Location	Vickers	Converted	Converted
Тор				Middle			
1	217.8	96.3		17	195.9	92.2	
2	195.4	92.1		18	193.5	91.7	
3	205.2	94.0		19	214.6	95.8	
4	213.0	95.5		20	198.8	92.8	
5	205.5	94.1		21	211.3	95.2	
6	196.8	92.4		22	231.6	98.6	
7	206.3	94.2					
8	254.5		23.1	Bottom			
9	251.3		22.5	23	222.7	97.1	
10	222.8	97.1		24	214.0	95.7	
11	266.9		25.2	25	221.9	97.0	
				26	222.6	97.1	
Middle				27	238.2	99.7	
12	197.2	92.4		28	255.4		23.2
13	191.4	91.3		29	256.3		23.6
14	178.3	88.6		30	288.2		28.3
15	200.1	93.0		31	212.0	95.3	
16	198.8	92.8		32	193.1	91.6	
				33	247.4		21.7



Figure 76 – Vickers microhardness survey on metallographic specimen GWD 13520-312°.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 81 of 86

Chemical Analysis

Coupons from the DS and UP pups, DS and US ends of the elbow fitting, and the center of each girth weld were removed and submitted for a detailed chemical composition determination via optical emission spectroscopy (OES) per ASTM A751. The chemical compositions were compared to the specifications for API 5L grade X70 PSL 2, MSS-SP-75, and the reported welding electrodes. Additional coupons consisting of repaired and "original" welds from the ID roots of both GWD 13530 and 13520 were remove. The results of the chemical analyses are summarized below.

Element	DS Pup [weight %]	US Pup [weight %]	API 5L grade X70 PSL 2 [weight %]
Carbon	0.060	0.059	0.22 max
Manganese	1.57	1.55	1.65 max
Phosphorus	0.016	0.016	0.025
Sulfur	0.003	0.003	0.015
Silicon	0.25	0.25	-
Nickel	0.03	0.03	h
Molybdenum	< 0.01	< 0.01	h
Chromium	0.19	0.19	h
Copper	0.02	0.02	h
Aluminum	0.029	0.029	-
Vanadium	0.003	0.039	g
Titanium	0.021	0.021	0.06 max
Niobium	0.046	0.044	-
Cobalt	< 0.005	< 0.005	l
Boron	< 0.0005	< 0.0005	-
Zirconium	< 0.01	< 0.01	-
Tungsten	< 0.01	< 0.01	-
Tin	< 0.005	< 0.005	-
Arsenic	< 0.002	< 0.002	-
Antimony	0.004	0.003	-
Calcium	0.0023	< 0.0005	-
CE _{Pcm}	0.159	0.158	0.25 max
Iron	Balance	Balance	Balance

g) Unless otherwise agreed: $Nb + V + Ti \le 0.15\%$

h) Unless otherwise agreed: $Cu \le 0.50\%$, $Ni \le 0.50\%$, $Cr \le 0.50\%$, and $Mo \le 0.50\%$

l) No intentional additions of B, $B \le 0.001\%$

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 82 of 86

Element	DS Elbow [weight %]	US Elbow [weight %]	MSS-SP-75 Composition [weight %]
Carbon	0.13	0.14	0.30 max
Manganese	1.35	1.14	1.60 max
Phosphorus	0.012	0.010	0.035 max
Sulfur	0.002	0.012	0.035 max
Silicon	0.32	0.23	0.50 max
Nickel	0.03	0.05	0.50 max*
Molybdenum	0.01	0.01	0.13 max*
Chromium	0.23	0.18	0.25 max*
Copper	0.04	0.09	0.50 max
Aluminum	0.035	0.026	-
Vanadium	0.050	0.039	0.13 max
Titanium	0.003	< 0.002	0.05 max
Niobium	< 0.002	< 0.002	0.10 max
Cobalt	0.005	0.005	-
Boron	< 0.0005	< 0.0005	-
Zirconium	< 0.01	< 0.01	-
Tungsten	< 0.01	< 0.01	-
Tin	< 0.005	0.007	-
Arsenic	< 0.002	0.002	-
Antimony	< 0.002	< 0.002	-
Calcium	< 0.0005	< 0.0005	-
Iron	Balance	Balance	Balance

* $\sum (Cu, Ni, Mo) \le 1\%$

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 83 of 86

	GWD 13520	GWD 13530	E81T1-Ni1
Element	Center [weight %]	[weight %]	[weight %] ¹⁰
Carbon	0.058	0.070	0.03
Manganese	1.25	1.26	1.15
Phosphorus	0.009	0.009	0.008
Sulfur	0.007	0.007	0.008
Silicon	0.42	0.44	0.41
Nickel	0.91	0.81	0.91
Molybdenum	0.01	0.01	-
Chromium	0.05	0.07	-
Copper	0.03	0.03	-
Aluminum	< 0.005	0.006	-
Vanadium	0.023	0.026	-
Titanium	0.030	0.034	-
Niobium	0.012	0.013	-
Cobalt	< 0.005	< 0.005	-
Boron	< 0.0005	< 0.0005	-
Zirconium	< 0.01	< 0.01	-
Tungsten	< 0.01	< 0.01	-
Tin	0.007	0.006	-
Arsenic	< 0.002	< 0.002	-
Antimony	0.004	< 0.002	-
Calcium	< 0.0005	< 0.0005	-
Iron	Balance	Balance	Balance

¹⁰ Composition from Pinnacle Alloys E81T1-Ni1 Data Sheet 0514REV0. Typical deposit composition using 100% CO₂.

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Page 84 of 86

Element	GWD 13520 Original Root	GWD 13520 Repair Root	GWD 13530 Original Root	GWD 13530 Repair Root	E80S-Ni1 Composition
	[weight %]	[weight %]	[weight %]	[weight %]	[weight %] ¹¹
Carbon	0.089	0.070	0.13	0.062	0.10
Manganese	0.70	1.11	1.04	0.95	1.10
Phosphorus	0.009	0.010	0.011	0.010	0.01
Sulfur	0.010	0.011	0.015	0.011	0.01
Silicon	0.27	0.52	0.26	0.39	0.60
Nickel	0.77	0.82	0.23	0.71	1.00
Molybdenum	0.22	0.19	0.08	0.20	0.10
Chromium	0.09	0.14	0.15	0.12	-
Copper	0.19	0.23	0.12	0.22	0.12
Aluminum	0.015	0.024	0.029	0.005	-
Vanadium	0.003	0.004	0.027	0.005	-
Titanium	< 0.002	0.006	0.002	0.003	-
Niobium	0.002	0.005	< 0.002	0.005	-
Cobalt	0.007	0.007	0.005	0.006	-
Boron	0.0005	0.0006	0.0005	0.0005	-
Zirconium	< 0.01	< 0.01	< 0.01	< 0.01	-
Tungsten	< 0.01	< 0.01	< 0.01	< 0.01	-
Tin	0.007	0.006	0.007	0.007	-
Arsenic	0.003	0.002	0.002	0.002	-
Antimony	0.004	0.004	0.003	0.004	-
Calcium	0.0023	0.0051	0.0013	0.0011	-
Iron	Balance	Balance	Balance	Balance	Balance

DISCUSSION and CONCLUSIONS

The cause of the rupture in GWD 13530 was attributed to fatigue (progressive) cracking. There were three, circumferentially oriented individual fatigue cracks identified; the largest being centered approximately 4.5" clockwise from TDC. The circumferential orientation of the cracks suggests a bending stress to be the driving mechanism. The fatigue cracks originated from a lack-of-fusion region at the ID toe of the girth weld on the pipe-side. The individual fatigue cracks propagated linearly through the pipe side of the weld, intersecting multiple microstructural features in the process. There was no evidence observed that any of the fatigue cracks penetrated the full wall thickness, indicating the final overload and subsequent petroleum

¹¹ Composition from Pinnacle Alloys E80S-Ni1 Data Sheet 0514REV0. Typical deposit composition.

ANDERSON & ASSOCIATES, INC.

release was an instantaneous event that occurred when the remaining ligament could no longer support the applied load.

The primary evidence observed that identified the initiating feature/s as lack-of-fusion was the tightly adhered oxide scale lining the surfaces of the features. Tightly adhered oxide scale (magnetite or Fe₃O₄) forms preferentially at higher temperatures, typically higher than 600°C. This temperature would likely have been achieved and or exceeded during welding operations. The presence of this magnetite scale indicates that the surfaces were exposed to an oxygen atmosphere while still at high temperature.

The fatigue cracks in GWD 13530 appeared to progress via an unstable (brittle) crack extension mechanism consisting of a series of advance/arrest events. There was evidence of dimpled rupture observed coincident with several of the arrest features, indicating there may have been ductile tearing preceding unstable crack extension.

There was no evidence found to support a finding that the pipe material was deficient. The microstructure of the pups consisted of finely banded, fine-grained ferrite and pearlite, typical of a low carbon, microalloyed steel used to fabricate high strength line pipe. The bulk weld microstructure appeared sound, though there was intermittent interpass lack-of-fusion, gas porosity, and slag entrapment separate from the lack-of-fusion identified at the ID weld toes. The interpass defects were determined to be acceptable discontinuities per the inspection report prepared by Applus RTD. The mechanical properties and chemical composition of the pipe met the minimum specifications for API 5L grade X70 PSL 2, though there is evidence that some of the HAZ hardness exceeded the maximum set forth for grade X70. Similarly, cross-girth weld mechanical testing showed there were no deficiencies with the mechanical properties of GWD 13530 and 13520 with respect to the minimums set forth in API 1104. The exception to this was one HAZ notched CTOD specimen from GWD 13520 (439-20-16) that failed to meet the minimum CTOD value of 0.005in.

The initiating features appeared consistent with lack-of-fusion at the ID toe approximately 200µm in length. Lack-of-fusion and cracking extending from the LOF was observed on both

ANDERSON & ASSOCIATES, INC.

GWD 13530 and 13520. The toe cracking on GWD 13520 was associated with the elbow-side toe. Of importance, all indications identified by PAUT were verified metallographically.

In summary, the cause of this rupture was attributed to fatigue cracking. The fatigue cracks propagated circumferentially from a series of ID intermittent weld-toe lack-of-fusion on the pipeside. Fatigue cracking propagated until the final overload event that resulted in the rupture and subsequent spillage of the contents of the pipe. There was no evidence that there was a leak prior to the rupture event e.g., fatigue cracking did not penetrate the full wall thickness.

If you have any questions, or need any additional information, please let us know. The samples from this investigation will be held until instructions for material disposition are provided by TC Energy.

Respectfully submitted February 7, 2023.

ANDERSON & ASSOCIATES, INC. Engineering Firm Registration # F-816

Andrés Rodela, Ph.D., P.E. Vice President of Engineering TX Lic. #127892

APPENDICES

- Appendix A ILVA SPA Material Test Report 2010/00007605/01 (Pups)
- Appendix B CANDAOIL Forge LTD. Material Test Report 6235 (Elbow)
- Appendix C Applus RTD Non-Destructive Test Report
- Appendix D Full wall thickness tensile datasheets
- Appendix E Sub-size pipe body tensile datasheets
- Appendix F Sub-size cross girth weld and all-weld tensile datasheets
- Appendix G CVN notch location photographs
- Appendix H CTOD datasheets
- Appendix I CTOD notch location and fracture photographs

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix A ILVA SPA Material Test Report 2010/00007605/01 (Pups)

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

A01 Manufact ILVA SPA - VIALE SOCIETA' SOGG COORDINAMEN	ure's works CERTOSA, 249 ETTA ALL'ATTIVI TO DI RIVA FIRE	- 20151 MILANO TA' DI DIREZIONE I S.P.A.		A02 Type of docume INSPECTION C ISO 10474 -	ERTIFICA	TE			tomer's Order nr ted by TC Energy tomer's Order nr ted by TC Energy	02.1 Date of issue 22/04/2010 em Date 20/0	A04 T 1/TA 2/2009
	AB. DI TARAN	ITO VIA APPIA S	57 Km648	A05 Originator of the	e document ROL ILVA				A Order Item A0 a Dy TC Energy A0 ssel Name D DI VANCOITVE	9 Customer referen	Date
A06.1 Custor TRANSCAN 450 - 15	ner ADA KEYS I STREET	TONE PIPE S.W.	LINE LP				A06.2 Consignee TRANSCANADA C/O THE BAY	A KEYSTONE PIPELI	VE LP	101154170	1/2020
A06.3 Consig	mee of the docu	ment	ITED	CANADA	A10 36"	Supplementary PIPELIN	commercial informat B PROJECT -	ion PROJECT: KEYSTON	3 XL : Redact	ted by TC I	Energy
450 - 15 00000 CA	T STREET LGARY AL	S.W. BERTA - T	2P 5H1	CANADA	ORD ITE INT	ER FOR P M A, EXH ERNAL AN	IPE NO.:001 IBIT 2: HEAD EXTERNAL	AVY WALL HCA ; DES BARE IN ACCORDANC	SIGN FACTOR: (TE WITH: API 5),72. 5L 44TH ED	ITION;
B01 Product B02 Steel quai	lity	SAWL	STEEL PI L 44TH H	IPES COLD EX IDITION - 20	PANDED 07	-PIPE-SA	w-US Rev.0.	B06 Marking	NOM. DIMENSION Units	NS: IN.	ts)
B03 Suppleme	ntary requirem	L485M	/X70M PS	SL2			•		B09 Thickness B10 Diameter O	0,515	0
Dor Dearchy		: THERM	O-MECHAP	ICAL CONTRO	L PROCES	5			B12 Theor.Mass B16 Heat nr.	7811 LBS 991579	0
B07	DELIVER	ED MATERL B13	AL	Starting	C04 Ref	erence t	est sample			D09 Test	Time
Pipe no 0030380	Heat 991579	Mass 8091	Leng. 39,53	Material 443501201	PdC 030431	030435	PP1	PP2 PD 030283	PS PW 030384	Pr. /PSI 1890	Sec. 10
0030382	991579	8201	39,94	443508101	030431	030435		030301	030313	1890	10
0030421	991579	7782	38,09	443505201	030431	030435		030283	03031	7 1890	10
0030435	991579	7727	37,81	443494201	030431	030435		030301	030098	1890 1890	10
0030464	991579	8058	39,21	443495101	030431	030435		030469	030177	1890	10
0030473 0030474	991579 991579	8201 6911	39,91 33,84	443495201 443502201	030431 030431	030435 030435		030474 030474	030052	2 1890 7 1890	10 10
0030475	991579	7474	36,55	443509101	030431	030435		030301	030573	1890	10
0030489 0030494	991579 991579	7793	38,07	443486101 444420101	030431	030435		030469	030099	1890	10
0030507	991579	7683	37,71	443506201	030431	030435		030282	030051	1890	10
0030519	991579	8003	39,03	443503201	030431	030435		030469	030050	1890	10
0030521	991579	8003	39,14	443487101	030431	030435		030474	030052	2 1890	10
0030647	991579	8135	39,83	443512101	030431	030435		030623	030051	1890	10
0030705	991579 991579	6967 7110	34,27	443511101 443505101	030431	030435		030640	030310) 1890 1890	10 10
0030720	991579	8201	39,99	443493201	030431	030435		030640	030278	1890	10
0030732 0030769	991579 991579	8091 8036	39,45 39,16	443492201 443506101	030431 030431	030435		030623 030633	030317	7 1890) 1890	10 10
0030780	991579	8146	39,60	443511201	030431	030435		030623	030317	1890	10
0030794	991579	8135	39,47	443510201	030431	030435		030625	030573	1890	10
0030828	991579 991579	8179 7981	39,96	443499101	030431	030435		030633	030384	1890 7 1890	10
0030873	991579	8124	39,55	443494101	030431	030435		030469	030050	1890	10
0030897 0030921	991579 991579	8179 8223	39,98 39.94	443497201 444421101	030431	030435		030880 030962	032130) 1890 1890	10 10
0030943	991579	8025	39,32	443498201	030431	030435		030987	031362	1890	10
0031071 0031149	991579 991579	7892	38,53 37,25	444418101 443508201	030431	030435		031197 030962	030907	1890	10
0031177	991579	7485	36,48	443496101	030431	030435		031068	030999	1890	10
0031210	991579	8080	39,53	443499201	030431	030435		031093	031406	1890	10
0031234	991579 991579	7430 8058	36,53	443510101 443493101	030431	030435		031093	031194	1890 1890	10 10
0031383	991579	8179	39,93	443489101	030431	030435		031312	031189	1890	10
0031384 0031389	991579 991579	8113 8190	39,58 39,94	443490201 443490101	030431	030435		031452 031365	031253	1890	10
0031443	991579	8036	39,24	443488101	030431	030435		031365	030908	1890	10
0031709	991579	7760	37,91	444418201	030431	031771		031664	030904	1890	10
0031752	991579	7716	37,48	443512201	030431	031771		031664	030999	1890	10
0031934	991579	7738	37,65	443507101	030431	031771		031759	031219	1890	10
C04 Frequency	code	C10 Shape of the	e test						Z03 Inspection B	ody Stamp	
PdC = Heat PLC = Lot of he	at	P = Prisma	tic								
PP1 = Prod. lot	1	C = Round	d bar								
PD = Per Day	~ F	* = Mill 1	No.		1						
PS = Per shift PW = Per Weel		F = Rejec R = Retes	t s	Skt 728724	4				Z02.2 QC Validat	ion	×
205 Ms Certifica	bons	150 9001:200	the the state	DOB DEL							RICTOOD
IQNet		160/TS 1594	7 300	1.Å	1					9	÷]
	a luga	CHISAS 1800		U CO	1				M. BUCCI	M	

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

A01 Manufactur ILVA SPA - VIALE C SOCIETA SOGGE	e's works ERTOSA, 249 TTA ALL'ATTIVIT	20151 MILANC		A02 INSE ISO	Type of docum ECTION (10474 -	ent CERTIF 3.1.B	ICATE					A03	Docume dacted	ent Nr. by TC E	nergy 2 nr 11	02.1 Date of 22/04/2 em	Tissue 2010 Date	^{A04} ≭ I/TA
	B. DI TARAN	TO VIA APPLA	<u>[1]] 11</u> SS7 Km648	A05 QUAI	Originator of the	ie documer FROL I	t LVA					Re	dacted of	by TC Er	hergy ^{A0}	9 Customer A13Code	Al4 I	/2009 : Date
A06.1 Custom	:r								A06.2 Consign	nee			ELO D	I VAN	COUVE	101232	21/04	/2010
450 - 1ST 00000 CAL	DA KEYS STREET GARY ALI	S.W. BERTA -	T2P 5H		CANADA		A10 Sup	lementary o	CO THE	BAYOU W IBI	J COMP ERIA, 1	ANIES L	LC NA		USA			
TRANSCANA 450 - 1ST	DA PIPEI STREET	LINES LI S.W.	MITED				36" P. ORDER	FOR PI	PROJEC	T - 1 001	PROJEC	r: Keyst	ONE X	ь;і	Redac	ted by	TC E	nergy
00000 CAL	GARY ALI	BERTA -	T2P 5H		CANADA		ITEM J INTERJ TES-PJ	A, EXHI NAL ANI IPE-SAM	BIT 2: EXTERN U-US Rev	HEAV	ARE IN	HCA ; ACCORD (See	DESIG ANCE Annex	N FAC WITH: for	API 5 accept),72. 5L 44TH :ance]	H EDI:	FION;
B01 Product B02 Steel qualit	у	: SAWI : API	STREL 5L 44TH	PIPES	COLD E	KPANDE 007	D			B	6 Marking			NOM. D Uni	IMENSION	NS:		
B03 Supplement B04 Delivery co	tary requireme ndition	L485 nts: : THER	MO-MECH	PSL2	L CONTRO	OL PRO	CESS							BIO Dia BIO Dia BII Ler BII The	meter O ngth eor.Mass	0, 36, 480, <u>7811</u>	5150 0000 0000 LBS	
807 1	DELIVERI	ED MATER	IAL	St	arting	C04	Refer	ence te	st samo					Die ne	a, 12.	991575	est l'	Time
Pipe no 0031958	Heat 991579	Mass 8168	Leng.	Ma 0 44	terial 3496201	Pd 0304	C 31	PLC 031771	PP1	Ĩ	PP2	PD 031759	PS		PW 030999	Pr. /	PSI	Sec.
0031990 0031991	991579 991579	8190 8146	39,6 39,9	8 44 3 44	3486201 3502101	0304 0304	31 31	031771 031771				032013 032041		*	764487	185	90 90	10 10
0032001 0032002	991579 991579	8168 8146	39,1	8 44 6 44	3504201 3509201	0304 0304	31 31	031771 031771				032013 031760		*	764487	189 189	90 90	10 10
0032121	991579	8025	39,0	4 44	4419201	0304	31	031771				032109			031189	189	90	10
B08 Tota	l pieces	S	:	54		314 To	tal 1	nass I	BS:	426	790	Т	otal	Lengt	h	FT :	2083	,62
C70 Stee	HEMICAL	COMPOSI	TION AN	D STE	ELMAKING	G PROC	Oxyg	en)	C94	Casti	ing me	thod	: 0	ontin	uous (asting		
Identif.	Locat	tion	Code C	1	Si %	Mn %	C74 P %	C75	C76	8 C	Nb %	V 8	C79 M	0 %	Ni 1	C81	8 (Cu %
030431	Prodi	uct	PdC (,063	0,230	1,640	0,0	15 0,00	47 0,0	30 (29 (0,041	0,002	0,	008	0,033	0,1	71 (0,023
031771	Prod	ict	PLC 0	,064	0,235	1,632	0,0	16 0,00	45 0,0	31 (0,041	0,002	0,	007	0,032	0,1	69	0,022
C00 Samol	elC01 T	est	C04 C	3	C84 0	785	C86	1087	C88		39	C90	1091		C92	C93	CEO	*
Identif,	Locat	tion	Code 1	'i €	N ppm 70	В ррп 1	Ca p 31	om Sn	\$ Hp	pm (V1 0,0660	V2 0,043	V 0 1.	3 8210	V4	ITC) []: 165]	IIW
030431 030435	Prod	uct	PdC 0	,021 ,021	62 62	2	30 28			(0,0630 0,0640	0,042	0 1, 0 1,	8120 8180	0,391	0 0,1	L66	
031771	Produ	uct	PLC (,021	60	2	28			(0,0630	0,042	0 1,	8080	0,390	0,1	66	
	Restric	ctions					He Min	eat	lax	l Mir	Product	t Max						
V1 = Nb + V2 = Nb +	Ti + V V							0	,150			0,150						
V3 = Mn + V4 = C +	Cr + Mc Mn / 5	0							,950			1,950	1					
ITO		macim]	,200			0,200						
COO Sampl	e C01	CO4 CO2	CO3	B05	Heat C	10 C	24 /Ømm	223 : I	0 C09	it	C11 Y	S C12	C13	1C1	4 C1	.5 C16	IXA	
030431 030431	T180 TW	PdC T PdC T	+ 20	1160		P 3 P 3	8,10 8,10	50,80	mm MP	a	517	636 648	37,	80 0 00	,81			
C00 Sampl	IMPACT ?	C45	10	4 00	2 C40	B05	Heat	C41	C09	C03	C42 E	nergy V	al C4	3 C4	4 Shea	r a C4	3 C4	5
Identif. 030431	T90	surfac	e _1	de Di dC 1	r T. Ty KV 2 1	m Tre	atmen	Width 10	J	Te°C - 5	<u>K1</u> 210	K2 K 200 1	3 A 98 2	ve D 02 10	1 D2 0 100	D3 Av 100 10	re Bn. 00 55	5 S.A
C04 5		010 01	The total											702 7	enertia - P	viu Stame		
PdC = Heat	uue	piece	ule test											2005 11	specilon Bo	му эшир		
PPI = Prod. lot 1	τ.	P = Pris C = Rc	matic ound bar															
PD = Per Day PS = Per shift	· ;	* = Mill F = Reid	No.															
PW = Per Week Z05 Ms Certificati	ons	R = Rete	est	Skt	728724									202.2	QC Validat	ion		ŝ
Charles and the	R	150 9001 190/TE 1	2008	NAGENENT.	ANE+												_	RICT
IQNet	IGO	Q 160 140			<u>A</u>									м.	BUCCI	Å	H	
			3	SINCERT S	24 W						-					/	<u></u>	RR

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

A01 Manufacture's works	ment CERTIFICATE	2	5472-GE2-GQT-GAQ-00001 r00 A03. Document Nr. Restated by 1C Energy 222/04/2010 1/TT/
ISO 10474 - COORDINAMENTO DI RIVA FIRE S.P.A.	· 3.1.B		A07 Customer's Order nr Redacted by TC Energy 20/02/200
A05 Originator of QUALITY CON STAB. DI TARANTO VIA APPIA SS7 Km648	the document TROL ILVA		A09 Customer reference A09 Customer reference A12 Vessel Name CIELO DI VANCOUVE 10123221/04/201
A06.1 Customer TRANSCANADA KEYSTONE PIPELINE LP 150 - 15T STREET S.W. 00000 CALCARY ALMETTA - TOP 541 CANADA	A06.2 TRAN C/O	Consignee SCANADA KEYSTONE P THE BAYOU COMPANIE C NEW TEPETA LOUT	IPELINE LP S LLC STAND USD
AG63 CONSIGNED ALL ACCUMENT AND AND A AG63 CONSIGNED OF A DOCUMENT AND A PIPELINES LIMITED	A10 Supplementary commen 36" PIPELINE PR	cial information	ISTONE XL; Redacted by TC Energ
450 - 1ST STREET S.W. D0000 CALGARY ALBERTA - T2P 5H1 CANADA	ORDER FÖR PIPE ITEM A, EXHIBIT INTERNAL AND EX INTERNAL AND EX INTERNAL AND EX	NO.:001 2: HEAVY WALL HCA FERNAL BARE IN ACC Rev.01 (S	; DESIGN FACTOR: 0,72. DRDANCE WITH: API 5L 44TH EDITION DE Annex for acceptance limits)
B01 Product : SAWL STEEL PIPES COLD E B02 Steel quality : API 5L 44TH EDITION - 2	EXPANDED	B06 Marking	NOM. DIMENSIONS : Units IN.
LASSM/X70M PSL2 B03 Supplementary requirements B04 Delivery condition THERMO-MECHANICAL CONTR	OL PROCESS		B09 Thickness 0,5150 B10 Diameter 0 36,0000 B11 Length 480,0000 B12 B12 Theor.Mass 7811 LBS B16 Heat nr. 991579 991579
IMPACT TEST			
Job Sample C01 C45 C04 C02 C04 Identif. Code Dir T. Ty Code Dir T. Ty Code Dir T. Ty 030431 WM surface PdC T KV 2 030431 HAZ 2 mm PdC T KV 2	B05 Heat C41 C0 pe Treatment Width D mm 10 J mm 10 J	9 C03 C42 Emerg nit Te°C K1 K2 - 5 86 92 - 5 138 146	Val C43 C44 Shear a C43 C44 Shear Shear C43 C44 Shear C43 C44 Shear C43 C44 Shear C43 C44 C44 Shear C43 C44 Shear C43 C44 Shear C43 C44 Shear C43 C44 Shear Shear C43 C44 Shear C43
HARDNESS TEST 200 Sample C01 C04 C30 C33 Sample Loc. Code Method Load 030431 TW PdC VICKERS 1	C31 WM (Kg) min max mea: 222 228 224	HAZ 1 min max mean 208 219 211	BM 1 <u>min max mean</u> 193 199 196
BEND TEST	C51 C52	1050	
Identif. Loc. Code Dir Kind of Test 030435 TW PLC T Face-Root API 5 031771 TW PLC T Face-Root API 5	Angle Ma L 180° 15 L 180° 15	Result 7,5 OK 7,5 OK	
DWTT TEST - PRESSED NOTCH COO Sample CO1 CO4 CO2 C41 CO3	C44 Shear area	C43	
Identif. Loc. Code Dir Thickness Te 030431 T90 PdC T Full -	mp°C S1 S2 5 100 100	S3 Ave 100	
MACROGRAPHIC INVESTIGATION	Inside	weld Out of	of line Cross pen.
Sample Code width Height 030431 PdC 23,1 13,7	10,8 24,3 8	9 6,3 (0,8 3,1
001 Visual, marking and dimensional inspecti	on : OK	tch NG _ hole 1	6
201 We hereby certify that the material com	plies with the terms	of the order.	
204 Frequency code C10 Shape of the test			Z03 Inspection Body Stamp
ILC = Lot of heat P = Prismatic P1 = Prod. lot 1 C = Round bar			
P2 = Prod. lot 2 D = Per Day * = Mill No. S ~ Per shift F = Reject			
W = Per Week R = Retest Skt 728724	-		Z02.2 QC Validation
			M. BUCCI
ALTER BIRLE			

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix B CANDAOIL Forge LTD. Material Test Report 6235 (Elbow)

G	CANAI D5 Boul, Alj écancour, Q el : (819) 2	DOIL honse De uébec (0 4-6600	FOR shales S9H 2Y8 Fax : (CANA 819) 29	LTD	T To	MA' EST 3.1.8, 1	TER ' REI En 10 2	IAL POR 204 (199	Г 1)	ISO Custor	900:	1:20 CFC I	08 C	Certifica	ate Nun	nber: (5235	Dat	:e: 20	9 10/11 P. O.:	/1.5 Redacted by TC Energy	Page	(1 of 2	(2)
Sales Order:	10367	Packin	ig List:	1875	2 - 0	1 F	Product Specifica	ation 1	MSS SP- Trans-Ci	75 (O Anada	8) WPH US T	1Y-70 1 ES-FIT	Welder G-LD-L	i JS				Tests			Notes		a a an		
Theme Theme I		<u></u> .		<u>-</u>			0	uantity	Canado	Heat	Code	Heat Tr	eatmen	t Type		Tem	D (F°)	1. All bu	tt weld	s were	radiograp	hed and	acceptabl	e to	
	Jescription	EIS W/D		v			Q.	variary 2	NPY-	C	Code	Quench	& Tem	perina		Tem	pering	2 Harde		of Doct	mad 7	Penor	Dof # 4	275204	
Piece Number	174458	174459	120	100.0	1	••••••••		?						·			1110	a. maiul	NDC		adi 🔨	Dentit	Dof #	NULU 1	
2 ELL 3	6" 3D 30"	515 WP	HY70-V	1			1260	5	NQF-	C		Quench	& Tem	pering		Tem	pering	3. Other	NDEF	-enom	ed:	report	rtei. #:	N/A	
Piece Number	(174462	174463	17445	52 - 174	453 (1)	74461)	INE	. 12.6	A 14	0						:	1110	4. Indica	ated spin	ecificati	on limits on h	of tensile	tests (if a	iny)	
2.1 ELL 3	6" 3D 30° (515 WP	HY70-V	v	>		1	1	NOP	C	• •	Quench	& Tem	pering		Tem	pering	5 Indica	ated shu	ecificati	on limite r	ase mall fimdad	tests (if	anv) '	
Piece Number	174469	98															1110	are fo	r base	materia	al only.	a napaci			
2.1 ELL 3	6" 3D 30° (,515 WP	HY70-V	٧				1	NRM-	С		Quench	& Tem	pering		Tem	pering	Legend							
Plece Number	- 174477																1110	L -	Heat (la	adle) al	nalysis	N/A -	Not appli	cable	
2.1 ELL 3	6" 3D 30"	,515 WP	PHY70-V	۷			-	3	NRN	С]	Quench	& Tem	pering	•••••	Tem	ipering	P -	Produc	t analy	sis				
Piece Number	- 174470	174474	- 17449	91					107	0		0	D T	maring		Tom	UTT	Long	Base n	naterial	longitudi	nal		1	
4 ELL 3	6" 3D 34º (,465 WP	'HY70-V	V				1	NQG	C	·	Quench	o lem	pering		iem	4110	Trans	Base n	naterial	, transvere	al		2	
Spec. Mir	-		i-	+	Re	suits	of Che	mical	Analys	is (%	b)					Te Min 4	nsile To 82.00	vveid L - est Resu 70.00	i lts	Min A	Impac ve 5	t Test	Results		
Limits Ma	× 0.3	1.6	0.5	0.04	0.04	0.25	0.5	0.25		0.5	0.1	0,13		0.05		Max	Tencilo	Viold	% Elono	min C	Ener	20	Shear		
Heat Cl	EC	Mn	Si	P	S	Cr	Ni	Mo	Al	Cu	Cb	V	B	Tì	N	Loc.	[Ksl]	[Kşl]	(2")	Loc.	(ib-fi	1	[%]	remp	
2 L	D.16	1.15	0.23	0.006 ;	0.002	0.17	0.04	0.01	0.017 ;	0.09	0.001	0.044	0.0005	0.002		Long. Weld	90.79	72.81	41	Base	29.5-39.1 86.3-78.5	- 40.6	52 - 52 - 50	-51	
NPY-C P0.43	0.181	1.19	0.247	0.0063	0.005	0.175	0.055	0.016	0.014	0.096	0.0022	0.041	0.0011	0.0015	0.019	N/A_				N/A		· · · · · · ·			(*)
2 L	D. 16	1.15	0.23	0.01	0.003	0.17	0.06	0.02	0.018	0.12	0.001	0.04	0.0007	0.002		Long.	08.33	70.92	44	Base	125.4-193	2-133.5	57 - 62 - 63	-51	
NOF-C PO.41	95 0.168	1.17	0.236	0.011	0.006	0.172	0.07	0.018	0.015	0.124	0.0018	0.038	0.0008	0.0013	0.019	N/A	00.02			N/A					
2.1	0.19	1.34	0.33	0.011	0.003	0.23	0.03	0.01	0.033	0.04	0.001	0.051		0.004		Long.	97.61	75.56		Base	112.1-115.	8-129.8	36 - 38 - 50	-51	
NOP-C PD.44	33 0.159	1.33	0.321	0.012	0.005	0.232	0.034	0.0087	0.027	0.04	0.0025	0.048	0.0008	0.0033	0.0049	N/A	+- 93.26	/3.24	33	N/A	04.2-02.0	- 00.0		-51	
21	D 10	1.17	0.24	0.012	0.003	0.18	0.13	0.03	0.015	0.14	0.002	0.044	0 0005	0.002		Long.	108.78	98.19	35	Base	115.8- 92.2	2-106.9	50 - 50 - 52	-51	
	36 0.179	1,18	0.243	0.011	0.005	0.174	0.138	0.031	0.012	0.147	0.0024	0.04	0.0009	0.0014	0.019	Weld N/A	97.32	78.18		Weld .	69.3-85.0	67.9		-51	
NRM-C PO 44		4.44	0.00	0.0100	0.001	0.47		0.04	0.094	0.19	0.001	0.043	0.0000	0.002		Long.	101.67	84.56	38	Base	113.6-100.1	3-103.3 ·	55 - 52 - 52	-51	
NRM-C P0.44	0.16	1.18	0.242	0.015	0.004	0.175	0.116	0.046	0.021	0,192	0.002	0.041	0.001	0.0015	0.019	Weld	98.05	78.47	39	Weld	44.3- 56.4	- 70.1		-51	
NRM-C P 0.44	10 0.17					0.10		0.07	0.054	0.05	0.033	0.040		0.004		Long.	93.69	80.21	44	Base	115.1-130.	5-130.5	50 - 52 - 50	-51	
NRM-C P 0.44		1.11	0.34	0.013	0.004	0.19	0.05	0.07	0.031	0.03	0.032	0.049	0 0007	0.0039	0.0064	Weld	86.88	73.97	36	Weld	73.8- 78.2	- 78.2		-51	
NRM-C P 0.44 2.1 L NRN-C P 0.44 4 L	0.16	4.4		0.010	0.001	0.10	0,000	0.001	0.047	0.010						LN/A								┉┸┯╼╦┙	
NRM-C P 0.44 2.1 L NRN-C P 0.44 L NRO-C P 0.39 NQG-C P 0.39	0.18 062 0.149	1.1		anter nie					the second s	the second se															

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Page 2 of 2 ISO 9001:2008 Certificate Number: 6235 Date: 2010/11/15 MATERIAL CANADOIL FORGE LTD. TEST REPORT 805 Boul, Alphonse Deshales P. O .: Customer: CFC INC. Bécancour, Québec G9H 2Y8 CANADA To 3.1.B, EN 10 204 (1991) Tel : (819) 294-6600 Fax : (819) 294-6189 Note: The Traceability table is attached to the report for the tagging references. Transverse Guided Weld Bend Tests are acceptable for each Heat lot. Cracking Test CF-18# : Material A 572 Gr. 50 modified, Heat Code HRV-C / CFT-2904 rev.1. The starting plate thickness for Heat code: NQG-C -0.866"; NQF-C - 0.79"; NOP-C - 0.79"; NOP-C - 0.866"; NRN-C - 0.71"; NRM-C - 0.71" . Quench & modned, Heat Code HKV-C / CF1-2904 rev.1. The starting plate thickness for heat code: NQG-C -0.050°; NUF-C -0.79°; NOF-C -0.050°; NKM-C -0.71; NKM-C Protected From Release ntidential under F Commei OIA, G cial Information 5 USC 552(b)(4) 552(b)(4), and FERC CEII enieman 2010/11/15 01 DATE WE HEREBY CERTIFY THAT THE MATERIALS LISTED ABOVE HAVE EVEN MADE IN STRICT ACCORDANCE WITH STATED SPECIFICATIONS AND THAT THE RESULT OF THE CHEMICAL ANALYSIS (HEAT) IS A TRUE AND CORRECT COPY OF THE MILL CERTIFICATE ISSUED BY THE MANUFACTURER OF THE PLATE. APPROVED BY: Quality Assurance Manage

ANDERSON & ASSOCIATES, INC

CONFIDENTIAL – SUBJECT to AT 220439 TC Energy - Metallurgical Ar Pipeline Incident Report Appendices

ATTORNEY-CLIENT PRIVILEGE Analysis of NPS-36 KS10 MP-14

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix C Applus RTD Non-Destructive Test Report

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

	Conf Protected From Relea	idential Commercial In se under FOIA, 5 USC	ormation 552(b)(4), and FERC CEII	
A rplus [®]	EXAMIN	ATION OVI	RVIEW	
	PROJECT INFO CLIENT: JOB LOCATION: PROJECT: APPLUS JOB NO.: PO / WO NO.:	TC ENERGY ANDERSON & ASSOC KEYSTONE NPS36 OU 2008000 N/A	ATES, PEARLAND, TX T-OF-SERVICE PIPE FRACTURE INVESTIGATION	
	INSPECTION DATE(S) REPORT DATE:): 01/11/2023 - 01/13/2 1/18/2023	023	
	INDIVIDUALS NAME Dennis Teeter, Jr. Cameron Seward Bobby Shrout Grayson Davies Nick Balzer Josh Rangel	INVOLVED ROLE Operations Manager Advanced Lead Lead Lead Assistant Assistant	METHOD(S) N/A MT, UT, PAUT, ToFD, IWEX, HandyScan RT, RTR IWEX RT, RTR IWEX	
			Applus RTD USA, Inc.	
Applus Energy & Industy			11801 S. Sam Houston Pkwy W., Houston, TX, 77031 (832) 295-5000 <u>www.applus.com</u>	

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

	olus [⊕]		11801 S. Sam Housto	App n Pkwy W., Ho	ouston, TX, 77031 (832) 295-5000 www.applus.con
	TC Energy	DEDORT NUMBER.			
	Anderson & Associates, Rearland, TV		1/18/2022	DACE NO :	1 of 1
PROJECT:	Keystone NPS36 Pine Fracture Investiga	tion PROCEDURE NO :	N/A	PAGE NO.	N/A
APPLUS 10B NO 1	2008000		N/A	REV NO	 N/A
NDE REQUEST NO.:	N/A	CODE/STANDARD:	N/A - Information Only		
PO / WO NO.:	N/A	SPECIFICATION:	N/A		
TABLE OF CO	NTENTS				
Evaluation Sum Photograph Rep OD MPI Report ID MPI Report Ultrasonic Thick	nary ort ness Report				
Hi-Lo Measuren	nent Report				14
PAUT & ToFD R	eport				18
PAUT & ToFD So	reenshots				20
OD HandyScan S	Summary Report				40
ID HandyScan S	ummary Report				41
Conventional R	Report				
K I K REPOR					

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Ap	olus⊕			11801 S. Sam He	Арр ouston Pkwy W., He	www.applus.com
EVALUA	TION SUMMAR	Y				
			REPORT NUMBER	ĭ		
	Anderson & Associates, Pearland	X	-	1/18/2023	PAGE NO -	1 of 1
PROJECT:	Keystone NPS36 Pipe Fracture Inv	/estigation	PROCEDURE NO.:	N/A	REV. NO.:	N/A
APPLUS JOB NO.:	2008000		- TECHNIQUE NO.:	N/A	REV. NO.:	N/A
NDE REQUEST NO .:	N/A		CODE/STANDARD:	N/A - Information O	nly	
PO / WO NO .:	N/A		SPECIFICATION:	N/A		
INSPECTION	SUMMARY		_			
Inspection was carrie All bare pipe areas w location. The pipe segment co Additionally, one (1) Assessment Scope: Visual inpsection was Magnetic Particle Ins Additionally, MPI was extent due to not wa Zero degree ultrason Phased array ultrason Applus IWEX full-mat the pipe segment, IW RT/RTR was perform Creaform HandyScan	d out in accordance with Applus written ere abrasive blast bleaned to near white ntained one (1) 3D bend pipe fitting of G field girth weld and two (2) factory weld performed on the abrasive blasted pip pection (MPI) was performed on the ful s performed on the full circumference on thing to intruduce any contaminants in ic inspection, with supplemental ToFD rix capture ultrasonic inspection was per EX was determined to not provide any ed on all three exposed girthwelds. GW mapping of both the ID and OD surface were taken utilizing a Hi-Lo guage taken	i practice and procedures i finish (NACE 2/SSPC 10) D.850" NWT, two (2) adjac is were present. e for the extent of the bar l circumference of the bla f the ID root pass and HA2 the fracture region. e actual wall thickness and inspection, was performe erformed on all three expc additional beneficial infor 13520 was not able to be e was collected for further n from the centerline of th	in conformance with TC for inspection. Coating w ent pups of 0.550" NWT, re pipe area. Isted area on the OD surf Z of GW13510, 13520. G1 d scan for laminations ne ed on all three exposed gi osed girth welds. Howeve mation over PAUT/ToFD scanned with RTR. RT/R1 r modeling and analysis.	Energy guidelines. vas not removed or blaster , and one (1) segment of li iace including all exposed : W13530 was assessed for ar the weld. rth welds. er, after analysis of the col inspection. R results are provided in s ream and downstream ex	d in the area in proxim near transmission pip seams and girth welds approximantely 75% o lected data, due to the	ity to the fracture ing of 0.500" NWT. f the circumferential e complex geometry c s.
HI-LO Measurements	0 0 0		ne weld for both the upst		tents of the three exp	osed girthwelds.
	NAME	SIGN	ATURE	CERTIFIC	ATION	osed girthwelds.
Technician:	NAME Cameron Seward	SIGN	ATURE	CERTIFIC IWEX, Hand SNT-TC-1A LVL	ATION dyScan II MT, ToFD III Standard	DATE 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

App	olus⊕		11801 S. Sam Houston	Pkwy W., Hous	ton, TX, 77031 832) 295-5000 www.applus.com
РНОТО І	REPORT				
PROJECT / CI	LIENT INFORMATION				
CLIENT:	TC Energy	REPORT NUMBER:	1		-
JOB LOCATION:	Anderson & Associates, Pearland, TX	REPORT DATE:	1/18/2023	PAGE NO.:	1 of 7
PROJECT:	Reystone NPS36 Pipe Fracture Investigation	PROCEDURE NO.:	N/A	REV. NO.:	N/A
NDE REQUEST NO :			N/A - Information Only	REV. NO	N/A
PO / WO NO	N/A	SPECIFICATION:	N/A		
Photograph P	aport				
12 O'clock Specie					
6 O'clock Specima	n Overview				
6 O'clock Specime	<image/> <section-header></section-header>				
6 O'clock Specime	<image/> <section-header><section-header></section-header></section-header>				
6 O'clock Specime	<image/> <section-header></section-header>				DATE
6 O'clock Specime			CERTIFICATIO WEX, HandyScan SNT-TC-1A LVL II MT, T	DN I	DATE 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Ap	olus [⊕]		11801 S. Sam Houston P	kwy W., Houston, TX, 77031 (832) 295-5000 www.applus.com
РНОТО	REPORT			
PROJECT / C				
CLIENT:	TC Energy	REPORT NUMBER:	1/12/2022	ACE NO . 2 of 7
JOB LOCATION:	Anderson & Associates, Pearland, TX		1/13/2023 P	AGE NO.: 2 OF 7
APPLUS 10B NO -	2008000	TECHNIQUE NO :	N/A R	EV. NO: N/A
NDE REQUEST NO.:	N/A	CODE/STANDARD:	N/A - Information Only	
PO / WO NO.:	N/A	SPECIFICATION:	N/A	2
Photograph	Report			
Upstream Intern	al Specimen Overview			
			1.	
Downstream Int	ernal Specimen Overview			
Downstream Int	ernal Specimen Overview			
Downstream Int				
Downstream Int	ernal Specimen Overview	SIGNATURE	CERTIFICATION WEX, HandyScan SNT-TC-1A LVL II MT, TO SNT-TC-1A LVL II MT, TO	N DATE FD 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

	alua		11801 S. Sam Houston Pkwy	W., Houston, TX, 77031
	JIUS			(832) 295-5000
				www.applus.com
рното	REPORT			
PROJECT / C	LIENT INFORMATION			
CLIENT:	TC Energy	REPORT NUMBER:	1	1000 at 1000ar
JOB LOCATION:	Anderson & Associates, Pearland, TX	DATE:	1/13/2023 PAGE I	NO.: <u>3 of 7</u>
ADDILLE TOP NO :	Reystone NPS36 Pipe Fracture Investigation	PROCEDURE NO.:	N/A REV. N	NO.: <u>N/A</u>
NDE REQUEST NO -	N/A		N/A - Information Only	NO.: N/A
PO / WO NO.:	N/A	SPECIFICATION:	N/A	2
Photograph	Report			
OD MPI Indicati	on #1 Overview			
	4 55	Xis	7447 5.5 "	
	56 57 58	L)		
OD MPI Indicait	on #2 Overview			
OD MPI Indicait	on #2 Overview			
OD MPI Indicait	or #2 Overview			DATE
OD MPI Indicait	on #2 Overview			DATE
OD MPI Indicait	or #2 Overview Or #2 Overview Overview	SIGNATURE Grown	CERTIFICATION IVEX, HandyScan SNT-TC-1A LVL II MT, ToFD PCN LVL II UT, PAUT	DATE 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Act	olus [⊕]		11801 S. Sam Housto	Applus RTD USA, Inc. on Pkwy W., Houston, TX, 77031 (832) 295-5000 <u>www.applus.com</u>
РНОТО І	REPORT			
PROJECT / CI	LIENT INFORMATION			
CLIENT:	TC Energy	REPORT NUMBER:	1	
JOB LOCATION:	Anderson & Associates, Pearland, TX	DATE:	1/13/2023	PAGE NO.: 4 of 7
PROJECT:	Keystone NPS36 Pipe Fracture Investigation	PROCEDURE NO.:	N/A	REV. NO.: N/A
APPLUS JOB NO .:	2008000	TECHNIQUE NO.:	N/A	REV. NO.: N/A
NDE REQUEST NO .:	N/A	CODE/STANDARD:	N/A - Information Only	
PO / WO NO.:	N/A	SPECIFICATION:	N/A	
Photograph R	teport			
			and the second se	
ID MPI Indicaitor	#1 Overview & Close-up	51		
ID MPI Indicaitor	1 21 Overview & Close-up			ID G
ID MPI Indicaitor	*#1 Overview & Close-up •#10verview & Close-up ••••••••••••••••••••••••••••••••••••	SIGNATURE		1 Д С С С П С П С П С П С П С П С П С П С
ID MPI Indicaitor	s #1 Overview & Close-up s #1 Overview & Close-up	SIGNATURE Gray Mark	CERTIFICATI TWEX, HandySca SNT-TC-1A LVL II M PCM I/M IFT 20	1D 0 1D 0 1D 0 1T 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

App	olus⊕		11801 S. Sam Houston Pk	Applus RTD USA, Inc. wy W., Houston, TX, 77031 (832) 295-5000 <u>www.applus.com</u>
PHOTO	REPORT			
CLIENT: JOB LOCATION: PROJECT: APPLUS JOB NO.: NDE REQUEST NO.:	TC Energy Anderson & Associates, Pearland, TX Keystone NPS36 Pipe Fracture Invest 2008000 N/A	REPORT NUMBER: DATE: DATE: DATE: PROCEDURE NO.: TECHNIQUE NO.: CODE/STANDARD:	1 1/13/2023 P/ N/A RI N/A RI N/A Information Only	AGE NO.: <u>5 of 7</u> EV. NO.: <u>N/A</u> EV. NO.: <u>N/A</u>
PO / WO NO.:	N/A	SPECIFICATION:	N/A	
Photograph F	Report			
ID MPI Indication	n #3 Overview			
ID MPI Indication	n #3 Overview			
ID MPI Indication	n #3 Overview			
ID MPI Indication	AME Cameron Seward	SIGNATURE Gray Market	CERTIFICATION IVEX, HandyScan SNT-C1A LVL II MT, Tof PCN LVL II MT, Tof	DATE 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Ap	olus⊕		11801 S. Sam Houston	аррі n Pkwy W., Ho	uston, TX, 77031 (832) 295-5000 www.applus.com
PHOTO PROJECT / C	REPORT				
CLIENT:	TC Energy	REPORT NUMBER:	1		
JOB LOCATION:	Anderson & Associates, Pearland, T	TX DATE:	1/13/2023	PAGE NO.:	6 of 7
PROJECT:	Keystone NPS36 Pipe Fracture Inve	estigation PROCEDURE NO.:	N/A	REV. NO.:	N/A
APPLUS JOB NO .:	2008000	TECHNIQUE NO.:	N/A	REV. NO.:	N/A
NDE REQUEST NO .:	N/A	CODE/STANDARD:	N/A - Information Only		
PO / WO NO.:	N/A	SPECIFICATION:	N/A		
Photograph	Report				
		- 8:30			
		- 8:30 - 8:30			
ID MPI Indicatio	n #5 Overview	830 830			
ID MPI Indicatio	n #5 Overview				
ID MPI Indicatio	n #5 Overview				DATE
ID MPI Indicatio	n #5 Overview NAME Cameron Seward	REAL BIGNATURE	CERTIFICATION INVEX, HandyScan SNT-TC-1A LVL II MT, PCN LVL II UT, PAIL	ON I	DATE 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Acc	olus [⊕]		مبر 11801 S. Sam Houston Pkwy W.,	Houston, TX, 77031 (832) 295-5000 <u>www.applus.com</u>
РНОТО Р	REPORT			
PROJECT / CL	IENT INFORMATION			
CLIENT:	TC Energy	REPORT NUMBER:	1	
JOB LOCATION:	Anderson & Associates, Pearland, TX	DATE:	1/13/2023 PAGE NO.:	7 of 7
PROJECT:	Keystone NPS36 Pipe Fracture Investigation	PROCEDURE NO.:	N/A REV. NO.:	N/A
NDE REQUEST NO.:	N/A	CODE/STANDARD:	N/A - Information Only	N/A
PO / WO NO.:	N/A	SPECIFICATION:	N/A	70
Photograph R	eport			
ID MPI Indicaiton	#6 Overview			
	and the second se			
Technician:	NAME Cameron Seward	SIGNATURE	CERTIFICATION IWEX, HandyScan SNT-TC-1A LVL II MT. ToFD	DATE 1/18/2023
Technician:	NAME Cameron Seward	SIGNATURE	CERTIFICATION IWEX, HandyScan SNT-TC-1A LVL II MT, ToFD PCN LVL II UT, PAUT	DATE 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Arr	ا		Ð				11801	s. s	aml	Houston	Ap Pkwy W., H	oplus RTD USA, Inc louston, TX, 7703
	JU	5										(832) 295-500
												www.applus.cor
MAGNET	IC PA	RTIC	CLE I	EXAMINA	TION R	EPO	RT					
PROJECT / CL	IENT INF	ORMAT	ION									
CLIENT:	TC Energy				REPORT NUMB	ER:	1					
JOB LOCATION:	Anderson &	Associates,	, Pearland,	ТХ	DATE:	_	1/13/202	3			PAGE NO .:	1 of 1
PROJECT:	Keyston NPS	536 Pipe Fra	acture Inve	estigation		o.: _	MT 01 N	DE US	SA		REV. NO.:	8
APPLUS JOB NO .:	2008000				TECHNIQUE NO	D.: _	MT 01				REV. NO.:	8
NDE REQUEST NO .:	N/A				CODE/STANDAI	RD: -	N/A - Inf	orma	tion	Only		
PO / WO NO.:	N/A				SPECIFICATION	4: <u> </u>	N/A		_			
ITEM(S) EXAM	IINED AN	D SURI	FACE C	ONDITIONS								
PART(S) EXAMINED:	OD sur	face of out	-of-service	piping segment	PART NO.	/ ID: _	N/A					
MATERIAL: MI	ild Carbon Stee		CKNESS:	0.550" - 0.85	0" SURFACE CONE		NAC	E 2	00.1	SURFACE	TEMP:	Ambient
LIGHTING CONDITION	s: 🗌	UV Intens	sity ≥ 100	ιυ μνν/cm° @ test s	urtace 🗹 V	white Light	t Intensity	/ ≥ 1	UU fe	@ test :	surface	
EQUIPMENT	-				MATERI	ALS					-	
Equipment/Cal. Block	(s) Asset	: / Serial N	0.	Calibration Date	Material I	Batch Num	ber		Pro	duct ID		Manufacturer
AC Yoke	_	22322		12/13/2022	2	2G11C			V	/CP-2	_	Magnaflux
AC Yoke		5/346		6/10/2022		210/8			8	szua		CircleSafe
MAGNETIC PA	RTICLET	NSPEC	TION T	ECHNIOUE								
THACHE THE TA				Loundor	MACHETIC FIEL		ATION	Γ		ccont	Reject	
CURRENT: AC	- Continuous						A 10.11.			ALCEDI		
CURRENT: AC	C - Continuous Wet co	olor contrast	t (water-ba	ased)	YOKE LIFT TES	T VERIFICA	TION:	Ĺ		Accept	Reject	N/A
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A	C - Continuous Wet co APPLICATION:	olor contrast	t (water-ba Spray	ased) Powder Applicat	YOKE LIFT TES	T VERIFICA	TION: OVAL:	[Accept Accept	Reject	 N/A ✓ N/A
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION:	C - Continuous Wet co APPLICATION:	olor contrast	t (water-ba Spray [Accept	ased) Powder Applicat V Not Required	YOKE LIFT TES OF MAGNETIC PAR POST CLEANING	T VERIFICA	TION: TION: OVAL:]] letec		Accept Accept	Reject	IV/A N/A V N/A equired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I	C - Continuous Wet co APPLICATION: Com DETAILS -	olor contrast	t (water-ba Spray [Accept L TS	ased) Powder Applicat Not Required	YOKE LIFT TES	T VERIFICA	TION: TION: OVAL:]] letec		Accept Accept	Reject	 N/A N/A √ N/A equired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I	Vet co Wet co APPLICATION: Com DETAILS -	olor contrast	t (water-ba Spray [Accept L TS	ased) Powder Applicat Not Required	YOKE LIFT TES	T VERIFICA	TION: OVAL: Comp	[] letec		Accept	Reject	 N/A N/A ✓ N/A equired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I	APPLICATION:	Plot contrast Ploted / A RESUI	t (water-ba Spray [Accept L TS	ased) Powder Applicat Not Required	YOKE LIFT TES		TION: OVAL:	letec		Accept	☐ Reject	equired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER	C - Continuous Wet co APPLICATION: Com DETAILS -	pleted / A	t (water-ba Spray [Accept L TS	Ased) Powder Applicat Not Required INDICAT	YOKE LIFT TES YOKE LIFT TES OT MAGNETIC PAR POST CLEANING THE THE THE TES TO TO TO TO TO TO TO TO TO TO	T VERIFICA	TION: OVAL:	letec		Accept	☐ Reject ☐ Reject ☐ Reject ✓ Not R COM	equired MENTS
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER	Vet co Wet co APPLICATION: Com DETAILS -	olor contrast pleted / A • RESUI	t (water-ba Spray [Accept LTS	Ased) Powder Applicat Not Required INDICATION (IN.)	YOKE LIFT TES YOKE LIFT TES OT MAGNETIC PAR POST CLEANIN (IN)	T VERIFICA	TION: OVAL:	letec		Accept	Com	equired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER	Vet co Vet co APPLICATION: Com DETAILS -	olor contrast pleted / / • RESUI ORELINITATION	t (water-ba Spray [Accept LTS	Powder Applicat Powder Applicat Not Required INDICATION		T VERIFICA	TTON: TTON: OVAL: Comp			Accept	☐ Reject ☐ Reject ☐ Reject ✓ Not R COM	MENTS
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER 13510		plor contrast ploted / A • RESUI	t (water-ba Spray [Accept LTS	Ased) Powder Applicat Not Required START OF -55.500	YOKE LIFT TES OT MAGNETIC PAR POST CLEANING OF OF OF OF OF OF OF OF OF OF		8.000	[[letec		Accept Accept Mill Scab in	n the BM	MENTS
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER 13510 13520	Continuous Wet co Wet co APPLICATION: Com DETAILS	Plor contrast plor contrast ploted / A RESUI OR EIN A Axial Circ	t (water-bz Spray [Accept LTS # 1 2	Powder Applicat Powder Applicat Not Required START OP -55.500 -53.625	YOKE LIFT TES OF MAGNETIC PAR POST CLEANING OF -63.500 -66.625		8.000 13.000	[[]		Accept Accept Mill Scab in Linear Ind	n the BM	e US weld cap toe
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER 13510 13520 13520 NOTES	C - Continuous Wet co APPLICATION: Com DETAILS - Com TO TIONE TIONE TIONE TIONE TIONE TIONE TIONE TIONE	Plor contrast P	t (water-bz Spray [Accept LTS # 1 2 3	Ased) Powder Applicat Not Required INDICATION -55.500 -53.625 -55.500	YOKE LIFT TES YOKE LIFT TES OF MAGNETIC PAR POST CLEANIN UDICATION -63.500 -66.550		8.000 13.000		Image: state	Mill Scab in Linear Ind	n the BM	e US weld cap toe
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER 13510 13520 13520 NOTES	Continuous Wet co Wet co APPLICATION: Com OFTAILS I.62 -0.03 -0.03 as perfomed on	Apleted / / RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL RESUL	t (water-ba Spray [Accept LTS FFACTOR # 1 2 3 d and sand	Ased) Powder Applicat Not Required	YOKE LIFT TES YOKE LIFT TES OT MAGNETIC PAR POST CLEANIN OT -63.500 -66.625 -66.500 g was not removed o	on GW 1353	8.000 8.000 13.000 0 in the re	ACCEPT		Mill Scab in Linear Ind	n the BM	ID /A I
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER 13520 13520 NOTES Ill circumference MPI was sessed.	Continuous Wet co Wet co APPLICATION: Com OFTAILS Com OFTAILS 1.62 -0.03 -0.03 as performed on	Avial Circ Circ Circ Circ Circ Circ Circ	t (water-ba Spray [Accept LTS T T T T T T T T T T T T T T T T T T	Ased) Powder Applicat Not Required	YOKE LIFT TES YOKE LIFT TES OT MAGNETIC PAR POST CLEANIN -63.500 -66.625 -66.500 g was not removed o	on GW 1353	8.000 13.000 0 in the re			Mill Scab in Linear Ind Linear Ind	In the BM In the BM In the BM In the BM In the BM In the BM	E US weld cap toe e US weld cap toe e US weld cap toe d thus was not
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD 13520 13520 13520 NOTES Ill circumference MPI was sessed.	C - Continuous Wet co Vet co APPLICATION: Com DETAILS 1.66 -0.03 -0.03 as performed on	AME	t (water-ba Spray [Accept LTS # 1 2 3 d and sand	Ased) Powder Applicat Not Required	YOKE LIFT TES YOKE LIFT TES OT MAGNETIC PAR POST CLEANIN -63.500 -66.525 -66.500 g was not removed of SNATURE	on GW 1353	8.000 13.000 10.000 0 in the re	gion s		Mill Scab in Linear Ind Linear Ind Inding the	In the BM COM	E US weld cap toe e US weld cap toe e US weld cap toe e US weld cap toe e US weld cap toe

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Acc	blu	S	Ð			118	01 S.	Sam	Houston	Pkwy	Appl W., Ho	us RTD USA, Inc uston, TX, 7703: (832) 295-5000 www.applus.cor
				XAMINA	TION R	EPORT	_			_		
CI JENT:	TC Energy		1011			D: 1		-				
-	Anderson & J	Accociates	Pearland	ту		K. <u>1</u> 1/15/	0022			PAGE	NO ·	1 of 1
PROIECT:	Keyston NPS	36 Pine Fra	acture Inve	stigation	PROCEDURE NO	. MT 01	NDF I	ISA		- REV	NO ·	8
APPLUS JOB NO.:	2008000				TECHNIQUE NO	.: MT 01				REV.	NO.:	8
NDE REQUEST NO .:	N/A				CODE/STANDAR	D: N/A -	Inform	ation	Only			
PO / WO NO.:	N/A				SPECIFICATION	N/A						
ITEM(S) EXAM	INED AN	D SURF	ACE CO	ONDITIONS	_	<u> </u>						
PART(S) EXAMINED	ID Root	8 HAZ of	GW13510	13520, 13530	PART NO	TD: N/A					_	
MATERIAL: Mil	d Carbon Steel		KNESS:	0.550" - 0.850	SURFACE CONDI	TION: N/A	ACF 2		SURFACE	TEMP	4	Ambient
		UV Intens	ity ≥ 1000) µW/cm ² @ test su	rface V	hite Light Inten	sity ≥	100 f	c @ test	surfac	ce	
FOUTPMENT			,	,, e tott bu	MATERI				2 .051			
Equipment/Cal. Block/	(c) Accet	/ Corial N		Calibration Data	Motorial D	atch Number	T	Dee	duct TD	Ι		Anufacturor
	S) ASSEL	7 301101 140	J.	12/12/2022		CI1C		FIU		-	1	Magnaflux
AC Yoke		37346		12/13/2022		1078	+		8204	-		CircleSafe
10 lb Block		17989		6/10/2022		10/0	+		0204			Circlebare
MAGNETIC PA	RTICLE IN	SPECT		ECHNIQUE			-	_		-		
										-		
CURRENT: AC	- Continuous				MAGNETIC FIEL				Accept	F	Reject	V N/A
CURRENT: AC	- Continuous	or contrast	(water-ba	sed)		D VERIFICATION:			Accept Accept		Reject Reject	✓ N/A
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A	- Continuous Wet col	or contrast	: (water-bas Sprav	sed) Powder Applicato	MAGNETIC FIEL	D VERIFICATION: VERIFICATION:			Accept Accept Accept	ק ק ק	Reject Reject Reject	 ✓ N/A □ N/A ✓ N/A
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION:	- Continuous Wet col PPLICATION:	or contrast	: (water-bas Spray	sed)] Powder Applicato ☑ Not Required	MAGNETIC FIEL YOKE LIFT TEST MAGNETIC PART POST CLEANING	D VERIFICATION: VERIFICATION: TICLE REMOVAL:	nplete	. [] [] [] [] []	Accept Accept Accept	a a a n	Reject Reject Reject Not Reg	✓ N/A N/A ✓ N/A uired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION F	- Continuous Wet col PPLICATION: Com	or contrast	: (water-bas Spray Accept	sed) Powder Applicato V Not Required	MAGNETIC FIEL YOKE LIFT TEST MAGNETIC PART POST CLEANING	D VERIFICATION: VERIFICATION: TICLE REMOVAL: : Cor	nplete	□, , , , 2d	Accept Accept Accept	ק ק ק M	Reject Reject Reject Not Req	✓ N/A N/A ✓ N/A uired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION D	- Continuous Wet col PPLICATION: Com DETAILS -	or contrast v pleted / A RESUL	: (water-ba: Spray Accept _ TS	sed)] Powder Applicato] Not Required	MAGNETIC FIEL	D VERIFICATION: VERIFICATION: TICLE REMOVAL: : Col	nplete	□ , □ , 2d	Accept Accept Accept	ק ק ק ע ₪	Reject Reject Reject Not Req	✓ N/A N/A ✓ N/A uired
CURRENT: <u>AC</u> INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION E GIRTHWELD NUMBER		or contrast pleted / A RESUL ORELINITATION	. (water-bas Spray Accept .TS	sed) Powder Applicato Not Required START OF (IN)	MAGNETIC FIELI YOKE LIFT TEST MAGNETIC PART POST CLEANING INDICATION		nplete ACCEPT		Accept Accept Accept	I	Reject Reject Reject Not Req	V N/A N/A V N/A uired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION D GIRTHWELD NUMBER 13520		or contrast pleted / A RESUL ORELINITATION Circ	: (water-bas Spray Accept .TS	sed) Powder Applicato Not Required START OF -2.750	MAGNETIC FIELI YOKE LIFT TEST MAGNETIC PART POST CLEANING INDICATOR INDICATOR 3.875		ACCEPT		Accept Accept Accept	F F F F V N	Reject Reject Reject Not Req COMMI	V N/A N/A V N/A uired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION D GIRTHWELD NUMBER 13520 13520		or contrast pleted / A RESUL ORELINITATION Circ Circ Circ	: (water-bas Spray Accept .TS FEATURE #	sed) Powder Applicato Not Required START OF -2.750 8.000	MAGNETIC FIEL YOKE LIFT TEST MAGNETIC PART POST CLEANING UNITED OF 3.875 12.800		ACCEPT		Accept Accept Accept Edge of E Edge of I	Pooth sice	Reject Reject Not Req COMMI	V N/A N/A V N/A uired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION D GIRTHWELD NUMBER 13520 13520	- Continuous Wet col PPLICATION: Com DETAILS - Com (F) 0.03 0.03 0.03	or contrast pleted / A RESUL OREINITATION Circ Circ Circ Circ	: (water-bas Spray .ccept .TS .TS .TS .TS .TS .TS .TS .TS .TS .TS	sed) Powder Applicato Not Required START OF -2.750 8.000 68.000	MAGNETIC FIEL YOKE LIFT TEST MAGNETIC PART POST CLEANING UNITED OF NUTLING SUBJECT OF NUTLING NUTLING SUBJECT OF NUTLING SUBJECT OF SUBJECT OF SUBJE		ACCEPT 5 0		Accept Accept Accept <u>Edge of E</u> Edge of E	F F F F F F F F F F F F F F F F F F F	Reject Reject Not Req COMMI de of root pass	✓ N/A M/A ✓ N/A wired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION E GIRTHWELD NUMBER 13520 13520 13520	- Continuous Wet col PPLICATION: Com DETAILS - Com (F) 0.03 0.03 0.03 0.03 0.03	or contrast pleted / A RESUL OREINITATION Circ Circ Circ Circ Circ	: (water-bas Spray	sed) Powder Applicato Not Required START OF -2.750 8.000 68.000 77.400	MAGNETIC FIEL YOKE LIFT TEST MAGNETIC PART POST CLEANING UNCLEANING STOLEANIN	D VERIFICATION: VERIFICATION: TICLE REMOVAL: CON CON CON CON CON CON CON CON	ACCEPT 55 0		Accept Accept Accept Edge of E Edge of E Edge of I Edge of I	F F F F F F F F F F F F F F F F F F F	Reject Reject Not Req COMMI de of root pass pass	✓ N/A ○ N/A ✓ N/A uired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION E GIRTHWELD NUMBER 13520 13520 13520 13520	- Continuous Wet col PPLICATION: Com Com Com Com Com Com Com Com	Circ Circ Circ Circ Circ	(water-bas Spray cccept .TS * 1 2 3 4 5	sed) Powder Applicato ✓ Not Required INDICATION -2.750 8.000 68.000 77.400 19.500	MAGNETIC FIELI YOKE LIFT TEST MAGNETIC PART POST CLEANING UNCLEANING OF 3.875 12.800 73.900 83.800 25.750	D VERIFICATION: VERIFICATION: TICLE REMOVAL: Contemporation Contemporation 6.62 4.80 5.90 6.30 6.25	ACCEPT ACCEPT 5 5 0 0		Accept Accept Accept Edge of E Edge of E Edge of I Edge of I	F F F V V V V V V V V V V V V V V V V V	Reject Reject Not Req COMMI is pass is pass is pass	V N/A N/A V N/A uired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION E GIRTHWELD NUMBER 13520 13520 13520 13520 13530	- Continuous Wet col PPLICATION: Com Com Com Com Com Com Com Com	Circ Circ Circ Circ Circ Circ Circ Circ	C (water-bas Spray C Ccept -TS FFF * * 1 2 3 4 5 6 6	sed) Powder Applicato ✓ Not Required INDICATION -2.750 8.000 68.000 77.400 19.500 90.300	MAGNETIC FIELI YOKE LIFT TEST MAGNETIC PART POST CLEANING UNCLEANING OF 3.875 12.800 73.900 83.800 25.750 96.300	D VERIFICATION: VERIFICATION: TICLE REMOVAL: Contemportation:	nplete		Accept Accept Accept Edge of E Edge of I Edge of I Edge of I Edge of I	F F <t< td=""><td>Reject Reject Not Req COMMI pass pass pass pass pass</td><td>V N/A N/A V N/A uired</td></t<>	Reject Reject Not Req COMMI pass pass pass pass pass	V N/A N/A V N/A uired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION I GIRTHWELD NUMBER 13520 13520 13520 13530 NOTES	- Continuous Wet col PPLICATION: Com Com Com Com Com Com Com Com	Circ Circ Circ Circ Circ Circ Circ Circ	(water-baa Spray kccept .TS * * 1 2 3 4 5 6	sed) Powder Applicato ✓ Not Required	MAGNETIC FIELI YOKE LIFT TEST MAGNETIC PART POST CLEANING UNCLEANING STOLEANI	D VERIFICATION: VERIFICATION: TICLE REMOVAL: CON CON CON CON CON CON CON CON	ACCEPT 5 5 5 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Accept Accept Accept Edge of L Edge of C Edge of L Edge of C Edge of C	F F F F F F F F F F F F F F F F F F F	Reject Reject Reject Not Req COMMI de of root pass pass pass pass pass pass	✓ N/A N/A ✓ N/A uired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION E GIRTHWELD NUMBER 13520 13520 13520 13520 13530 NOTES PI was performed on the st wanting intruduce any ientation of the pipe seg	- Continuous Wet col PPLICATION: Com	Circ Circ Circ Circ Circ Circ Circ	(water-bas Spray Ccept -TS -TS -TS -TS -TS -TS -TS -TS -TS -TS	sed) Powder Applicato Not Required	MAGNETIC FIELI YOKE LIFT TEST MAGNETIC PART POST CLEANING 3.875 12.800 73.900 83.800 25.750 96.300	D VERIFICATION: VERIFICATION: TICLE REMOVAL: Contemportation Contempor	ACCEPT ACCEPT 5 5 5 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Accept Accept Accept Accept Edge of L Edge of L Edge of C Edge of C Edge of C Edge of C	Forthermannen Forther	Reject Reject Reject Not Req COMMI de of rool pass pass pass pass pass pass pass circumfe be obtain	N/A N/A N/A N/A vired
CURRENT: AC INSPECTION MEDIUM: MAGNETIC PARTICLE A DEMAGNETIZATION: INSPECTION E GIRTHWELD NUMBER 13520 13520 13520 13520 13530 NOTES PI was performed on the bt wanting intruduce any ientation of the pipe seg	- Continuous Wet col PPLICATION: Com DETAILS - Com DETAILS - Com Com DETAILS - Com Com Com Com Com Com Com Com	Circ Circ Circ Circ Circ Circ Circ Circ	(water-back Spray	sed) Powder Applicato Not Required STATE OF Not Required State State SIG	MAGNETIC FIELI YOKE LIFT TEST T MAGNETIC PART POST CLEANING 3.875 12.800 73.900 83.800 25.750 96.300 0, 13520. GW13530 ns are approximate	D VERIFICATION: VERIFICATION: TICLE REMOVAL: CONT	appro		Edge of E Edge of E Edge of E Edge of C Edge of C	→ F → F → F → F → F → F → F → F	Reject Reject Reject Not Req COMMI is pass pass pass pass circumfe be obtain	V/A N/A N/A N/A uired

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices


CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

PRO	JEC	T / CLII		ORMATIC	ON							
CLIEN	т:		TC Energ	ЭY				REPORT N	UMBER:	1		
JOB LC		DN:	Anderso	n & Associates,	Pearland, TX			DATE:		1/13/	2023 PAGE	NO.: 1 of 1
PROJE	CT:		Keyston	NPS36 Pipe Fra	cture Investig	gation		PROCEDUR	RE NO.:	N/A	REV. N	NO.: <u>N/A</u>
APPLU	S JOB	NO.:	2008000					TECHNIQU	E NO.:	<u>N/A</u>	REV. N	NO.: <u>N/A</u>
		T NO.:	N/A						NDARD:	N/A -	Information Only	
INS	DEC		FTATI S	- DESIII T	C				11011.	<u></u>		
HI-LO	D REA	DINGS TA	BLE (IN.)	RESULT	3							
_												
		13	510	Hielo	13	520	Hi-Lo	13	530	Hielo		
	12	- 1/8	- 1/8	0	- 1/16	- 5/32	3/32	- 1/32	- 3/32	1/16		
C	1	0	- 1/16	1/16	0	- 5/32	5/32	- 1/8	- 1/32	3/32		
I	2	- 1/32	- 1/16	1/32	- 1/32	- 5/32	1/8	- 1/32	- 1/16	1/32	Coating &	Tape
o c	3	- 1/16	- 1/16	0	1/16	- 5/32	3/32	- 1/8	1/32	3/32	Interfera	nce
k	4	- 1/8	- 1/16	1/16	- 1/16	W	-	- 1/8	1/32	3/32		
Р	5	- 1/16	- 1/32	1/32	0	W	-	- 1/32	- 5/32	1/8	W	
s	6	- 1/16	- 1/32	1/32	- 1/16	W	-	- 1/16	- 1/16	0	Measurement	Not Able
í t	7	- 1/16	0	1/16	0	W	-	- 1/32	- 1/32	0	to be Taken Presnece of	Due to Wrinkle
i	8	- 3/32	- 1/16	1/32	1/16	W		- 1/32	0	1/32		
n	10	- 1/16	- 1/32	0	- 1/32	- 1/16	0	- 1/16	- 1/32	3/32		
	11	- 1/32	- 1/16	1/32	- 3/32	- 1/16	1/32	- 1/32	- 3/32	1/16		

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



		2						000000000000000000000000000000000000000	00-(1) / 1/ - 10	i I	-					Applus	RTD USA, Inc.
)	t										1180:	. S. Sam Hous	ton PH	cwy W., Houst	ton, TX, 77031
		ņ	U													(8	332) 295-5000
		C														WW	vw.applus.com
PHASED ARRAY	/ ULTRA	SONIC	(PA	UT) / TI	MEOFI	FLIGHT	DIFFRA	CTION (TOFD) V	E	U	AMI	NATION R	EPORT			
PROJECT / CLIEF	VT INFOR	MATIO	ž														
CLIENT: TC I	Energy						REPOR	T NUMBER:	GW 13510	0, GW	13520,	GW 135	30				
JOB LOCATION: And	lerson & Associ	ates, Pearla	and, TX				DATE:		1/12/202	ω				PAGE NO .:		1 of 1	
PROJECT: Key	stone NPS36 Pi	ipe Fracture	e Investi	gation			PROCE	DURE NO .:	UT 46 ND	E USA				REV. NO .:		2	
APPLUS JOB NO .: 200	8000						TECHN	IQUE NO.:	PIA 200.1					REV. NO .:		2	
NDE REQUEST NO .: N/A							CODE	/ STANDARD:	N/A - Infc	ormatio	n Only						
PO / WO NO .: N/A							SPECIF	ICATION:	N/A								
TESTING EQUIPN	MENT ANI	D SET-U	JP PA	IRAMETE	RS												
ACQUISITION	V UNIT	PR	OBE A	ND WEDGE	SKEW 90	SKEW 27	TOFD) GRO	NGS 1	N	ω	4	INFORM	ATION	2	EF STD	ITEM
MODEL:	Olymp	us X3 PRO	BE		10L32	10L32	1/8" Sin	gle SCAN:	99	8	27	0 270	MATERIAL TYPE		G	bon Steel	Mild Carbon Stee
MODULE TYPE:	32:12	BPR PRC	DBE MOI	DEL:	A10	A10	C563	ANGLE:	40-:	70 40-	70 40-	70 40-7	0 VELOCITY:		0.1	276 in/µs	0.1276 in/µs
MAIN FRAME SERIAL NO .:	QC-007	73503 SEF	RIAL NO		U1307	V1692	127338	39 START:	0.0	0.0	0.0	0.0	SURFACE COND			olished	NACE 2
CAL DUE DATE:	8/17/	2023 FRE	QUENC	1:	10 MHz	10 MHz	10 MH	z RANGE:	2.4	F" 4.9)" 2. <i>4</i>	4.9	COUPLANT:			Water	Water
MODULE SERIAL NO .:	QC-007	73503 CAE	BLE LEN	STH:	6 ft.	6 ft.	6 ft.	REF dB:	44.	9 43	8 43	1 46.8	TEMPERATURE:			Imbient	Ambient
INSPECTION VERSION:	MXU 5	.11.1 WE	DGE MO	DEL:	SA10-N555	SA10-N55	S ST1-70	L TRAN dB:	0	0	0	0		S	PECIN	MEN	
ENCODER RESOLUTION:	414.52 :	stps/in. MA	TERIAL:		Rexolite	Rexolite	Steel	SCAN + 6 c	IB: 50.	9 49	8 49	1 52.8	PIPE DIAMETER	(NPS)	VPS36		
SCAN RESOLUTION:	0.03	39" RAI	Snic		Hat	Flat	Flat	CAL IN / C/	L OUT: 11:0	00 AM /	4:30 F	ž	THICKNESS (in.)	-	0.550"	- 0.850"	
PRF:	Aut	to EQL	JIP. REF	BLOCK:		IIW Block S/P	V 12-2363, C	arbon Steel PAG	CS Block S/N 2	2020-5	131		WELDING PROC	ESS	(1) GM	AW, (2) SMAW	
EXAMINATION D	ETAILS A	ND RE	SULT	S													
NUMBER GIRTHWELD (IN.) WALL WALL	LOCETTON (FT.) WALL	JAIXA	SKEM	anutaa Mumber Maber	LENGTH (IN.) SCAN	START OF INDICATION (IN.)	(IN') ENDICETION END OF	ГЕИСТН (IV.)	нетент (ім.)		('NI)	TAAT2 HT930	(IN.) DEPTH END	ACUTAL THICKNESS (IN.)	ACCEPT	NOOSIG	TINUITY TYPE
							จ	W 13510									
13510	0.550	0.00	8	4	117.008	0.102	2.833	2.731	0.1	38		0.26	8 0.406	0.542	×	Intermittent	t Interpass LOF
13510	0.550	0.00	90	2	117.008	5.399	24.840	19.441	0.0	93		0.35	6 0.449	0.537	\times	Intermittent	t Interpass LOF
13510	0.550	0.00	90	ω	117.008	58.104	98.592	40.489	0.0	86		0.39	6 0.485	0.540	×	Intermittent	t Interpass LOF
13510	0.550	0.00	90	4	117.008	113.293	113.568	0.275	0.0	8		0.48	4 0.523	0.542	×	Slag Inclusio	on
							9	W 13520									
13520 0.550 -	0.850	0.00	90	1	117.008	7.370	15.311	7.941	0.1	49		0.71	8 0.867	0.863		× Intermittent	t Root Toe Crack
13520 0.550 -	0.850	0.00	90	2	117.008	16.842	32.294	15.452	0.1	49		0.70	1 0.850	0.850		X Root Toe Cr	rack
13520 0.550 -	0.850	0.00	90	ω	117.008	35.017	61.911	26,894	0.1	6		0.74	.9 0.855	0.855		× Root Toe Cr	rack
13520 0.550 -	0.850	0.00	90	4	117.008	69.102	96.551	27.449	0.1	ل ا ا		0.74	.8 0.861	0.861		× Intermittent	t Root Fusion

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

0.138 0.415 0.537 X Root Toe Crack 0.138 0.415 0.553 X Root Toe Crack 0.089 0.458 0.547 X Root Crack 0.116 0.426 0.542 X Intermittent Root Crack mate based on a theoretical approximation of how the ultrasonic signals propogated through the area of	in the season around the t	ON10500 :	- Annoning the	NT 4404 mitarios	Alla mar Al	- Janmad and	- CONTOCIO MA		instantions Ann
0.000 0.000 <th< th=""><th>in the area around the t</th><th>nt of GW13530 i</th><th>n. Assessment</th><th>PI 1104 criterior</th><th>d and significan</th><th>as deemed acc</th><th>of GW13510 was</th><th>omplex geo</th><th>inspection. Ass</th></th<>	in the area around the t	nt of GW13530 i	n. Assessment	PI 1104 criterior	d and significan	as deemed acc	of GW13510 was	omplex geo	inspection. Ass
0.138 0.415 0.553 0.553 X Root Toe Crack 0.138 0.415 0.553 0.553 X Root Toe Crack 0.116 0.426 0.547 0.542 X Intermittent Root Crack	in the area around the t plementary ToFD. Addition	nt of GW13530 i n PAUT and support of the support o	n. Assessmen sence in both	PI 1104 criterion sal" due the pres	ceptable per Ai ice of being "re	as deemed acc phest confiden	of GW13510 was nich have the high	those whic	inspection. Ass indications are
0.077 0.177 0.126 0.020 of intermiseant sour Lawor 0.138 0.415 0.53 0.553 X Root Toe Crack 0.069 0.458 0.547 0.547 X Root Crack 0.116 0.426 0.542 X Intermittent Root Crack	plementary ToFD. Additi	n PAUT and sup	n. Assessmen sence in both	al" due the pres	ice of being "re	is deemed acc jhest confiden	ich have the high	those which	indications are
0.000 0.000 <th< th=""><th>in the area around the ti</th><th>nt of GW13530 i</th><th>n. Assessment</th><th>PI 1104 criterior</th><th>d and significan</th><th>as deemed acc</th><th>of GW13510 was</th><th>essment of</th><th>Due to the conspection. Ass</th></th<>	in the area around the ti	nt of GW13530 i	n. Assessment	PI 1104 criterior	d and significan	as deemed acc	of GW13510 was	essment of	Due to the conspection. Ass
0.070 0.771 0.720 <th< th=""><th>positioning is an estimat</th><th>oth and height</th><th>variation. det</th><th>t wall thickness</th><th>1 and significan</th><th>part examined</th><th>eometry of the p</th><th>omplex dec</th><th>Due to the c</th></th<>	positioning is an estimat	oth and height	variation. det	t wall thickness	1 and significan	part examined	eometry of the p	omplex dec	Due to the c
0.077 0.777 0.727 0.720 of intermised in source contracts in the contract is source in the contract in the contract in the contract is source in the contract in the contract in the contract is source in the contract in the contract in the contract is source in the contract in the contract in the contract in the contract is source in the contract in the cont									NOTES
0.077 0.177 0.120 0.120 0.1100 Interframework record reader 0.138 0.415 0.553 0.553 X Root Toe Crack 0.099 0.458 0.547 0.547 X Root Crack	21 16.255	0.166 86.42	18 70.	5 117.00	90	0.00	0 - 0.850	30 0.550 -	1353
0.138 0.415 0.553 0.553 X Root Toe Crack	4.439	.369 66.80	18 62.	4 117.00	98	0.00	0 - 0.850	30 0.550 -	1353
	70.00	0.024 27.02	, 10 , 10		; 20	, o.oo	- 0.000	00 0.000	1 June
	11 8 397	2 494 57.09	12 48	2 117.00	8	0 N	י - ט אבט	20 0 550 -	1353
	7.407	3.797 46.20	18 38.	2 117.00	90	0.00	0 - 0.850	30 0.550 -	1353
0.071 0.461 0.532 0.532 ^ Incomplete Root Fusion	2.519	119 33.63	38 31.	1 117.00	98	0.00	0 - 0.850	30 0.550 -	1353
0 071 0 461 0 532 0 532 X Incomplete Boot Flision	79 7 519	119 23 63	18	1 117 00	ŝ	000	1 - N 85N	20 0 550 -	1353
	GW 13530								
0.126 0.731 0.857 0.857 X Intermittent Root Crack	04 6.551	2.447 5.90	18 112.	6 117.00	90	0.00	0 - 0.850	20 0.550 -	1352
0.006 0.751 0.837 0.837 1 Intermittent Root Fusion		1.99/ T03.99	TOT SC	01./TT	ų	0.00	0-0.000	20 0.000-	727
I AAA I AAAA I AAAAAAAAAAAAAAAAAAAAAAA	oc	997 109.68	101 101	117.00	۹ N	n n	1 - 0 850	on n 550 -	135

ANDERSON & ASSOCIATES, INC.

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Technician:			Manadary Print, Print,			SCREENSHOTS	PO / WO NO.: N/A	NDE REQUEST NO .: N/A	APPLUS JOB NO .: 2008000	PROJECT: Keyston	JOB LOCATION: Anderso	CLIENT: TC Ener	PROJECT / CLIENT	PHASED ARRAY U		Arn
Cameron Seward	NAME				GW13510 SKEW 90 Scan Overview					e NPS36 Pipe Fracture Investigation	n & Associates, Pearland, TX	9Y	INFORMATION	ILTRASONIC (PAUT) / TIME O		ת €
Come f	SIGNATURE						SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO.:	PROCEDURE NO .:	DATE:	REPORT NUMBER:		F FLIGHT DIFFRACTION (TO		
ТИЕХ, HandyScan SNT-TC-1A LVL II МТ, ToFD PCN LVL II UT, PAUT	CERTIFICATION				GW13510 SKEW 270 Ove		N/A	N/A - Information Only	PIA 200.1 R	UT 46 NDE USA R	1/12/2023 P	GW 13510, GW 13520, GW 13530		OFD) WELD EXAMINATION SC		11801 S. S.
1/18/2023 Page 20 of 41	DATE				rerview				REV. NO.: 2	REV. NO.: 2	PAGE NO.: 1 of 20			CREENSHOTS	www.applus.com	Sam Houston Pkwy W., Houston, TX, 77031 (832) 295-5000











Applus Energy & Industry	Technician:			SCREENSHOTS	PO / WO NO.: N/A	NDE REQUEST NO .: N/A	APPLUS JOB NO.: 200800	PROJECT: Keyston	JOB LOCATION: Andersc	CLIENT: TC Ener	PROJECT / CLIENT	PHASED ARRAY L	Appl
	Cameron Seward	NAME	GW13520 SKEW 270 Overview					e NPS36 Pipe Fracture Investigation	n & Associates, Pearland, TX	9y	INFORMATION	ILTRASONIC (PAUT) / TIME O	US ⁽⁺⁾
	Connegour-P	SIGNATURE			SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO .:	PROCEDURE NO.:	DATE:	REPORT NUMBER:		F FLIGHT DIFFRACTION (TO	
	IVEX, HandyScan SNT-TC-1A LVL II MT, TOFD PCN LVL II UT, PAUT	CERTIFICATION	GW13520 ToFD Overviev		N/A	N/A - Information Only	PIA 200.1 REV	UT 46 NDE USA REV	1/12/2023 PAG	GW 13510, GW 13520, GW 13530		FD) WELD EXAMINATION SCR	11801 S. San
Page 26 of 41	1/18/2023	DATE	We				EV. NO.: 2	EV. NO.: 2	AGE NO.: 7 of 20			REENSHOTS	m Houston Pkwy W., Houston, TX, 77031 (832) 295-5000 <u>www.applus.com</u>

I echnician:			SCREENSHOTS	PO / WO NO .: N/A	NDE REQUEST NO .: N/A	APPLUS JOB NO.: 2008	PROJECT: Keys	JOB LOCATION: Ande	CLIENT: TC E	PROJECT / CLIEN	PHASED ARRAY	App
Cameron Seward	NAME	GW13520 F01 PAUT Overview				000	tone NPS36 Pipe Fracture Investigation	rson & Associates, Pearland, TX	nergy	T INFORMATION	ULTRASONIC (PAUT) / TIME	US [®]
Demande	SIGNATURE			SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO.:	PROCEDURE NO .:	DATE:	REPORT NUMBER:		OF FLIGHT DIFFRACTION (TO	
SNT-TC-1A LVL II MT, TOPD PCN LVL II UT, PAUT	CERTIFICATION IVEX, HandyScan	GW13520 F01 ToFD Ove		N/A	N/A - Information Only	PIA 200.1	UT 46 NDE USA	1/12/2023 F	GW 13510, GW 13520, GW 13530		OFD) WELD EXAMINATION SC	11801 S. S
1/18/2023 Page 27 of 41	DATE	rerview				REV. NO.: 2	REV. NO.: 2	PAGE NO.: 8 of 20			CREENSHOTS	Sam Houston Pkwy W., Houston, TX, 77031 (832) 295-5000 <u>www.applus.com</u>

Technician: Cameron Seward Applus Energy & Industry	NAME	GW13520 F02 PAUT Overview	SCREENSHOTS	PO / WO NO.: N/A	NDE REQUEST NO.: N/A	APPLUS JOB NO.: 2008000	PROJECT: Keystone NPS36 Pipe Fracture Investigation	JOB LOCATION: Anderson & Associates, Pearland, TX	CLIENT: TC Energy	PROJECT / CLIENT INFORMATION	PHASED ARRAY ULTRASONIC (PAUT) / TIME OF F	Acplus	Đ
Connect	SIGNATURE			SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO .:	PROCEDURE NO .:	DATE:	REPORT NUMBER:		LIGHT DIFFRACTION (T		
IVEX, HandySean SNT-TC-1A LVL II MT, ToFD PCN LVL II UT, РАИТ	CERTIFICATION	GW13520 F02 ToFD Overvi		N/A	N/A - Information Only	PIA 200.1 REV	UT 46 NDE USA REV	1/12/2023 PAG	GW 13510, GW 13520, GW 13530		OFD) WELD EXAMINATION SCR		11801 S. Sam
1/18/2023 Page 28 of 41	DATE	iew				V. NO.: 2	V. NO.: 2	GE NO.: 9 of 20			REENSHOTS	(832) 295-5000 www.applus.com	n Houston Plany W., Houston, TX, 77031



Applus Energy & Industry	Technician:			SCREENSHOTS	PO / WO NO .: N/A	NDE REQUEST NO.: N/A	APPLUS JOB NO .: 2008000	PROJECT: Keystone	JOB LOCATION: Anderson	CLIENT: TC Energy	PROJECT / CLIENT II	PHASED ARRAY UL	Applu
	Cameron Seward	NAME	GW13520 F04 PAUT Overview					NPS36 Pipe Fracture Investigation	& Associates, Pearland, TX		NFORMATION	.TRASONIC (PAUT) / TIME (LS +
	Connection-P	SIGNATURE			SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO.:	PROCEDURE NO .:	DATE:	REPORT NUMBER:		DF FLIGHT DIFFRACTION (TO	
	IVEX, HandyScan SNT-TC-1A LVL II МТ, TOFD PCN LVL II UT, РАИТ	CERTIFICATION	GW13520 F04 ToFD Overvie		N/A	N/A - Information Only	PIA 200.1 REV.	UT 46 NDE USA REV.	1/12/2023 PAGE	GW 13510, GW 13520, GW 13530		OFD) WELD EXAMINATION SCRI	11801 S. Sam
Page 30 of 41	1/18/2023	DATE	ew				NO:: 2	NO:: 2	E NO.: 11 of 20			EENSHOTS	Houston Pkwy W., Houston, TX, 77031 (832) 295-5000 <u>wwww.applus.com</u>



ipplus Energy & Industry	Technician:			SCREENSHOTS	PO / WO NO.: N/A	NDE REQUEST NO.: N/A	APPLUS JOB NO.: 20080	PROJECT: Keysto	JOB LOCATION: Anders	CLIENT: TC End	PROJECT / CLIENT	PHASED ARRAY	Appl	
	Cameron Seward	NAME	GW13520 F06 PAUT Overview				8	ne NPS36 Pipe Fracture Investigation	son & Associates, Pearland, TX	ergy	INFORMATION	ULTRASONIC (PAUT) / TIME	US [®]	Э
	Consection	SIGNATURE			SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO.:	PROCEDURE NO.:	DATE:	REPORT NUMBER:		OF FLIGHT DIFFRACTION (TO		
	IWEX, HandyScan SNT-TC-1A LVL II MT, TOFD PCN LVL II UT, PAUT	CERTIFICATION	GW13520 F06 ToFD Overv		N/A	N/A - Information Only	PIA 200.1 REV	UT 46 NDE USA REV	1/12/2023 PAC	GW 13510, GW 13520, GW 13530		OFD) WELD EXAMINATION SCR	11801 S. San	
Page 32 of 41	1/18/2023	DATE	iew				v. NO.: 2	v. NO.: 2	3E NO.: 13 of 20			REENSHOTS	n Houston Pkwy W., Houston, TX, 77031 (832) 295-5000 <u>www.applus.com</u>	

Technician:			SCREENSHOTS	PO / WO NO.: N/A	NDE REQUEST NO.: N/A	APPLUS JOB NO.: 200800	PROJECT: Keystor	JOB LOCATION: Anderse	CLIENT: TC Ene	PROJECT / CLIENT	PHASED ARRAY U	Appi	
Cameron Seward	NAME	GW13530 SKEW 90 Overview				ō	ne NPS36 Pipe Fracture Investigation	on & Associates, Pearland, TX	rgy	INFORMATION	JLTRASONIC (PAUT) / TIME OI		Ð
(Onenergy)	SIGNATURE			SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO.:	PROCEDURE NO.:	DATE:	REPORT NUMBER:		F FLIGHT DIFFRACTION (TO		
SNT-TC-1A LVL II MT, TOFD PCN LVL II ИТ, РАИТ	CERTIFICATION IVIEX, HandyScan	GW13530 SKEW 270 Overv		N/A	N/A - Information Only	PIA 200.1 REV	UT 46 NDE USA REV	1/12/2023 PAC	GW 13510, GW 13520, GW 13530		FD) WELD EXAMINATION SCR		11801 S. San
1/18/2023 Page 33 of 41	DATE	rview				EV. NO.: 2	EV. NO.: 2	AGE NO.: 14 of 20			REENSHOTS	(832) 295-5000 <u>www.applus.com</u>	m Houston Pkwy W., Houston, TX, 77031

Applus Energy & Industry	Technician:			weweitersest [] [] atjan p		SCREENSHOTS	PO / WO NO .:	NDE REQUEST NO .: N	APPLUS JOB NO.: 2	PROJECT: K	JOB LOCATION:	CLIENT: T	PROJECT / CLI	PHASED ARR/		Arr
	Cameron Seward	NAME			GW13530 ToFD Overview		4/A	V/A	1008000	ceystone NPS36 Pipe Fracture Investigation	Inderson & Associates, Pearland, TX	TC Energy	ENT INFORMATION	AY ULTRASONIC (PAUT) / TIME (
	Connection of	SIGNATURE					SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO .:	PROCEDURE NO .:	DATE:	REPORT NUMBER:)F FLIGHT DIFFRACTION (TO		
	IWEX, HandyScan SNT-TC-1A LVL II MT, ToFD PCN LVL II UT, PAUT	CERTIFICATION			GW13530 F01 PAUT Overvie		N/A	N/A - Information Only	PIA 200.1 REV.	UT 46 NDE USA REV.	1/12/2023 PAGE	GW 13510, GW 13520, GW 13530		FD) WELD EXAMINATION SCRE		11801 S. Sam F
Page 34 of 41	1/18/2023	DATE			W				NO.: 2	NO.: 2	NO.: 15 of 20			ENSHOTS	www.applus.com	-Jouston Pkwy W., Houston, TX, 77031 (832) 295-5000









Applus Energy & Industry	Technician:				n difees and the second se		Source Contrast Accuracy Sources Contrast Vision Contrasts Theorem Contrasts Theorem Contrasts Theorem Contrasts		SCREENSHOTS	PO / WO NO .: N	NDE REQUEST NO .: N	APPLUS JOB NO.: 21	PROJECT: K	JOB LOCATION: A	CLIENT: T	PROJECT / CLII	PHASED ARRA		Arr
	Cameron Seward	NAME					Anthroad Ant	GW13530 F05 ToFD Overview		JA	I/A	008000	eystone NPS36 Pipe Fracture Investigation	nderson & Associates, Pearland, TX	C Energy	ENT INFORMATION	NY ULTRASONIC (PAUT) / TIME		
	Conserved	SIGNATURE				ي 11 م 1 1 •				SPECIFICATION:	CODE / STANDARD:	TECHNIQUE NO.:	PROCEDURE NO.:	DATE:	REPORT NUMBER:		OF FLIGHT DIFFRACTION (TOF		
	IWEX, HandyScan SNT-TC-1A LVL II MT, TOFD PCN LVL II UT, PAUT	CERTIFICATION								N/A	N/A - Information Only	PIA 200.1 REV. NO.:	UT 46 NDE USA REV. NO.:	1/12/2023 PAGE NO.:	GW 13510, GW 13520, GW 13530		D) WELD EXAMINATION SCREEN		11801 S. Sam Hous
Page 39 of 41	1/18/2023	DATE										2	2	.: 20 of 20			NSHOTS	<u>www.applus.com</u>	ston Pkwy W., Houston, TX, 77031 (832) 295-5000

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

		YREPORT		11801 S. :	Sam Houston Pkwy '	Applus RTD USA, In W., Houston, TX, 770 (832) 295-50 <u>www.applus.c</u>
PROJECT / CL CLIENT: JOB LOCATION: PROJECT: APPLUS JOB NO.: NDE REQUEST NO.: PRO / WO NO :	IENT INFORMATION TC Energy Anderson & Associates, Pearland, Keystone NPS36 Pipe Fracture Inv 2008000 N/A N/A	TX estigation	REPORT NUMBER: DATE: PROCEDURE NO.: TECHNIQUE NO.: CODE/STANDARD: SPECTECATION:	1 1/13/2023 PIA 011.15 US PIA 011.15 N/A - Informa	P 3A R R bion Only	VAGE NO.: 1 of 1 KEV. NO.: 1 KEV. NO.: 1
ITEM(S) EXAMINED: PART(S) EXAMINED: MATERIAL: DESCRIPTION: FOULTPMENT	DD surface of out-of-servic OD surface of out-of-servic Mild Carbon Steel THICK Out of service pipe segment consistin	ONDITIONS re pipe segment NESS:	PART NO. / II SURFACE CONDITION Ind three pup joints of vary	D: N/A N: NACE ; ing nominal thickn	2SURFACE TI ess's	EMP: <u>Ambient</u>
- Contributed	Equipment		Asset / Serial No.		Calibr	ration Date
С	reaform HandyScan Black Elite		9270229		9/	/8/2022
HANDYSCAN	Creaform Reference Arrow	IF	850347			N/A
SCAN SURFACE	OUTER	INTERACTION RULE	N/A	DI	T-GUAGE TYPE	N/A
INSPECTION	SUMMARY	THE RECEIPTION ROLL.			. GUAGE TIFE.	
SCAN OVERVIEW	6:00					
SCAN OVERVIEW	6:00					
SCAN OVERVIEW	6:00		INATURE			

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

App	olus⊕			11801 S. Sam Hou	арри Iston Pkwy W., Hou	skin (53, 10 ston, TX, 7703 (832) 295-500 <u>www.applus.co</u>
HANDYS	CAN SUMMARY	REPORT				
PROJECT / CL	LIENT INFORMATION					
CLIENT:	TC Energy		REPORT NUMBER:	1		
JOB LOCATION:	Anderson & Associates, Pearland, T	x	DATE:	1/15/2023	PAGE NO.	1 of 1
PROJECT:	Keystone NPS36 Pipe Fracture Inves	stigation	PROCEDURE NO .:	PIA 011.15 USA	REV. NO.:	1
APPLUS JOB NO .:	2008000		TECHNIQUE NO .:	PIA 011.15	REV. NO.:	1
NDE REQUEST NO .:	N/A		CODE/STANDARD:	N/A - Information Only		
PO / WO NO .:	N/A		SPECIFICATION:	N/A		
ITEM(S) EXAN	MINED AND SURFACE CO	NDITIONS				
PART(S) EXAMINED	ID surface of out-of-service	nine segment	PART NO / T	D: N/A		
MATERIAL ·	Mild Carbon Steel THICKN	FSS: 0.550" - 0.850"		N: As Found	SUPEACE TEMP	Ambient
	Out of service pipe segment consisting	of one 3D bend fitting ar	d three pup joints of yard	ing nominal thickness's	SURFACE TEMP.	Amplent
DESCRIPTION:	Out of service pipe segment consisting	for one 3D bend hung ar	nd three pup joints of vary	ing nominal trickness s		
EQUIPMENT						
	Equipment		Asset / Serial No.		Calibration Da	te
C	Creaform HandyScan Black Elite		9270229		9/8/2022	
	Creaform Reference Arrow		850347		N/A	
HANDYSCAN	INSPECTION TECHNIQU	E				
SCAN SURFACE:	INNER	INTERACTION RULE:	N/A	PIT-GUAGE	TYPE: N/	A
INSPECTION	SUMMARY					
SCAN OVERVIEW	6:00					
SCAN OVERVIEW	6:00					
SCAN OVERVIEW	6:00 6:00 Cameron Sevard					DATE 1/18/2023

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix D Full-Wall Thickness Tensile Datasheets

ANDERSON & ASSOCIATES, INC.

Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy
CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix E Sub-size pipe body tensile datasheets

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix F Sub-Size Cross Girth Weld and All-Weld Tensile Datasheets

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pineline Incident Report Appendices

Redacted by TC Energy

Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pineline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14

Redacted by TC Energy

Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14

Redacted by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Redacted by TC Energy

CONFIDENTIAL - SUBJECT to ATTORNEY-CLIENT PRIVILEGE



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix G CVN Notch Location Photographs

Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy



Redactions made by TC Energy



Redactions made by TC Energy



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices


Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix H CTOD Datasheets

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

Appendix I CTOD Notch Location and Fracture Photographs

Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices



Redactions made by TC Energy

CONFIDENTIAL – SUBJECT to ATTORNEY-CLIENT PRIVILEGE 220439 TC Energy - Metallurgical Analysis of NPS-36 KS10 MP-14 Pipeline Incident Report Appendices

