NOTICE: This report is required by 49 CFR Part 191. Failure to report can result in a civil penalty as provided in 49 USC 60122.

U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration

No.

OMB NO: 2137-0635
EXPIRATION DATE: 6/30/2026

Original Report Date:

05/10/2019

20190049-32113
(DOT Use Only)

INCIDENT REPORT - GAS DISTRIBUTION SYSTEM

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0635. Public reporting for this collection of information is estimated to be approximately 12 hours per response, including the time for reviewing instructions, gathering the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding the burden or any other aspect of this collection of information, including suggestions for reducing the burden to: Information Collection Clearance Officer, PHMSA, Office of Pipeline Safety (PHP-30) 1200 New Jersey Avenue, SE, Washington, D.C. 20590.

INSTRUCTIONS

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the PHMSA Pipeline Safety Community Web Page at https://www.phmsa.dot.gov/pipeline/library/forms

PART A - KEY REPORT INFORMATION

Report Type: (select all that apply)	Original:	Supplemental:	Final:
	Yes		
Last Revision Date			
Operator's OPS-issued Operator Identification Number (OPID):	15938		
2. Name of Operator	ENBRIDGE GAS NORTH CA	ROLINA	
3. Address of Operator:			
3a. Street Address	800 GASTON ROAD		
3b. City	Gastonia		
3c. State	North Carolina		
3d. Zip Code	28056		
4. Local time (24-hr clock) and date of incident:	04/10/2019 10:06		
4a. Time Zone for local time (select only one)			
4b. Daylight Saving in effect?			
5. Location of Incident:			
5a. Street Address or location description	115 N Duke Street		
5b. City	Durham		
5c. County or Parish	Durham		
5d. State:	North Carolina		
5e. Zip Code:	27701		
5f. Latitude / Longitude	35.59599, -78.54286		
6. Gas released:	Natural Gas		
- Other Gas Released Name:			
7. Estimated volume of gas released unintentionally: - thousand standard cubic feet (mcf)	46.00		
Estimated volume of intentional and controlled release/blowdown:thousand standard cubic feet (mcf)	0		
9. Were there fatalities?	Yes		
- If Yes, specify the number in each category:			
9a. Operator employees	1		
9b. Contractor employees working for the Operator	0		
9c. Non-Operator emergency responders	0		
9d. Workers working on the right-of-way, but NOT associated with this Operator	0		
9e. General public	1		
9f. Total fatalities (sum of above)	2		
10. Were there injuries requiring inpatient hospitalization?	Yes		
- If Yes, specify the number in each category:			
10a. Operator employees	0		

4.0h. Cambra stan amanla va an visuldin in fan tha On anatan		
10b. Contractor employees working for the Operator	0	
10c. Non-Operator emergency responders	1	
10d. Workers working on the right-of-way, but NOT associated with this Operator	2	
10e. General public	2	
10f. Total injuries (sum of above)	5	
11. What was the Operator's initial indication of the Failure? (select only one)	Other	
- If Other, Specify:	notification from excavator via their NC-811 notification	
11a. If "Controller", "Local Operating Personnel, including contractors", "Air Patrol", or "Ground Patrol by Operator or its contractor" is selected in Question 11, specify.	nothing and in order vice vice and in the contribution.	
12. Local time operator identified failure	04/10/2019 09:35	
If 11 = Notification from Emergency Responder, skip questions 13 through 15.		
13. Did the operator communicate with Local, State, or Federal Emergency Responders about the incident?		
- If No, skip A14 and A15		
14. Which party initiated communication about the incident?		
15. Local time of initial Operator and Local/State/Federal Emergency Responder communication		
16. Local time operator resources arrived on site:	04/10/2019 10:03	
17. Local time of confirmed discovery:		
18. Local time (24-hr clock) and date of initial operator report to the National Response Center:	04/10/2019 11:17	
19. Initial Operator National Response Center Report Number:	1242352	
19a. Additional NRC Report numbers submitted by the operator:		
20. Method of Flow Control (select all that apply)		
"Key/Critical" Valve – inspected in accordance with Part 192.747		
Main Valve other than "Key/Critical"		
·		
Service (curb) Valve		
Meter/Regulator shut-off Valve		
Excess flow valve		
Squeeze-Off		
Stopple fitting		
Other		
- If Other, Specify:		
21. Did the gas ignite?	No	
If A21 = Yes, answer A21a through A21d.		
21a. Local time of ignition		
21b. How was the fire extinguished?		
- If Other, Specify:		
21c. Estimated volume of gas consumed by fire (MCF): (must be less than		
or equal to A7.)		
21d. Did the gas explode?	Yes	
22. Number of general public evacuated:	10	
PART B - ADDITIONAL LOCATION INFORMATION		
Was the Incident on Federal land?	No	
2. Location of Incident	Public property	
3. Area of Incident:	Underground	
Specify:	Under pavement	
If Other, Describe:		
3a. Depth of Cover:	30	
3b. Were other underground facilities found within 12 inches of the failure location?		
4. Did Incident occur in a crossing?	No	
- If Yes, specify type below:		
- If Bridge crossing –		
Cased/ Uncased:		
- If Railroad crossing –		
n ramous crooning	<u> </u>	

Cased	
Uncased	
Bored/drilled	
- If Road crossing –	
Cased	
Uncased	
Bored/drilled	
- If Water crossing –	
Cased	
Uncased	
Bored/drilled	
Name of body of water (If commonly known):	
Approx. water depth at time and location of Incident (ft):	
(select only one):	
(select only one).	
PART C - ADDITIONAL FACILITY INFORMATION	
Indicate the type of pipeline system:	Investor Owned
- If Other, specify:	
2. Part of system involved in Incident:	Service
- If Other, specify:	
2a. Year item involved in the incident was installed:	2008
2b. Year item involved in the incident was manufactured:	
When 2.is any value other than "Main", "Main Valve", "District Regulator/Metering	g Station", or "Other":
2c. Indicate the customer type: (select only one)	
2d. Was an EFV installed on the service line before the time of the incident?	
If 2d = Yes, then 2e. Did the EFV activate?	
2f. Was a curb valve installed on the service line before the time of the incident?	
3. When 2. is "Main" or "Service" answer 3a through c and 4:	
3a. Nominal Pipe Size:	0.75
•	ASTM D2513
3b. Pipe specification (e.g., API 5L, ASTM D2513):	
3c. Pipe manufacturer:	Performance
4. Material involved in Incident:	Plastic
- If Other, specify:	
4a. If Steel, Specify seam type:	
- If Other, specify:	
4b. If Steel, Specify wall thickness (inches):	
4c. If Plastic, Specify type:	Polyethylene (PE)
- If Other, describe:	
4d. If Plastic, Specify Standard Dimension Ratio (SDR):	11
Or wall thickness:	
Unknown	
4e. If Polyethylene (PE) is selected as the type of plastic in Part C, Question	n 4.c:
- Specify PE Pipe Material Designation Code (i.e. 2406, 3408, etc.)	2406
Unknown?	
5. Type of release involved :	Mechanical Puncture
- If Mechanical Puncture - Specify Approx. size:	
Approx. size: in. (axial):	2.00
in. (circumferential):	.80
- If Leak - Select Type:	
- If Other, Describe:	
- If Rupture - Select Orientation:	
- If Other, Describe:	
Approx. size: (widest opening):	
(length circumferentially or axially):	
- If Other - Describe:	

Class Location of Incident:	Class 3 Location
2. Estimated Property Damage:	Cidos o Escation
2a. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator	\$20,000,000
2b. Estimated cost of Operator's property damage & repairs	\$7,638
2c. Estimated cost of emergency response	\$15,467
2d. Estimated other costs	\$0
- Describe:	Unknown. Investigation is ongoing.
2e. Property damage subtotal (sum of above)	\$20,023,105
Cost of Gas Released	
Cost of Gas in \$ per thousand standard cubic feet (mcf):	\$
2f. Estimated cost of gas released unintentionally	\$196
2g. Estimated cost of gas released intentionally during controlled release/blowdown	\$
2h. Total estimated cost of gas released (sum of 2f and g)	\$196
2i. Estimated Total Cost (sum of 2e and 2h)	\$20,023,301
3. Estimated number of customers out of service:	
3a. Commercial entities	20
3b. Industrial entities	0
3c. Residences	0
Injured Persons not included in A10 The number of persons injured, admitted to a are reported in A10. If a person is included in A10, do not include them in D4.	a hospital, and remaining in the hospital for at least one overnight
Estimated number of persons with injuries requiring treatment in a medical facility but not requiring overnight in-patient hospitalization:	
If a person is included in 4, do not include them in 5.	
5. Estimated number of persons with injuries requiring treatment by EMTs at the site of incident:	
Buildings Affected	
6. Number of residential buildings affected (evacuated or required repair or had gas service interrupted):	
7. Number of business buildings affected (evacuated or required repair or had gas service interrupted):	
PART E - ADDITIONAL OPERATING INFORMATION	
Estimated pressure at the point and time of the Incident (psig):	58.00
2. Normal operating pressure at the point and time of the Incident (psig):	58.00
3. Maximum Allowable Operating Pressure (MAOP) at the point and time of the Incident (psig):	60.00
3a. MAOP established by 49 CFR section:	
3b. Date MAOP established:	
Describe the pressure on the system relating to the Incident:	Pressure did not exceed MAOP
5. Type of odorization system for gas at the point of failure:	
- If Other, Specify:	
6. Odorant level near the point of failure measured after the failure:	
7. Was a Supervisory Control and Data Acquisition (SCADA) based system in place on the pipeline or facility involved in the Incident?	Yes
- If Yes:	
7a. Was it operating at the time of the Incident?	Yes
7b. Was it fully functional at the time of the Incident?	Yes
7c. Did SCADA-based information (such as alarm(s), alert(s), event (s), and/or volume or pack calculations) assist with the initial indication of the Incident?	No

7d. Did SCADA-based information (such as alarm(s), alert(s), event (s), and/or volume calculations) assist with the confirmed discovery of the Incident?	No
8. Was an investigation initiated into whether or not the controller(s) or control room issues were the cause of or a contributing factor to the Incident? (select all that apply):	No, the Operator did not find that an investigation of the controller(s) actions or control room issues was necessary due to: (provide an explanation for why the Operator did not investigate)
- If "No, the operator did not find that an investigation of the controller(s) actions or control room issues was necessary due to:" (provide an explanation for why the operator did not investigate)	While there are two SCADA monitoring points on the distribution system, both are located on larger diameter feeder mains approximately 2 miles upstream; the volume of gas lost was inconsequential vs. the line-pack and delivery capacities in these feeder mains such that there was not a significant or correlating resultant pressure drop at these points.
- If Yes, Specify investigation result(s) (select all that apply):	
 Investigation reviewed work schedule rotations, continuous hours of service (while working for the Operator), and other factors associated with fatigue 	
 Investigation did NOT review work schedule rotations, continuous hours of service (while working for the Operator), and other factors associated with fatigue 	
- Provide an explanation for why not:	
- Investigation identified no control room issues	
- Investigation identified no controller issues	
Investigation identified incorrect controller action or controller error	
 Investigation identified that fatigue may have affected the controller(s) involved or impacted the involved controller(s) response 	
- Investigation identified incorrect procedures	
- Investigation identified incorrect control room equipment operation	
 Investigation identified maintenance activities that affected control room operations, procedures, and/or controller response 	
- Investigation identified areas other than those above	
Describe:	
PART F - DRUG & ALCOHOL TESTING INFORMATION	
As a result of this Incident, were any Operator employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations?	No
- If Yes:	
1a. How many were tested:	
1b. How many failed:	
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations?	No
- If Yes:	
2a. How many were tested:	
2b. How many failed:	
PART G - CAUSE INFORMATION	
Select only one box from PART G in shaded column on left representing the App the right. Enter secondary, contributing, or root causes of the Incident in Part J	Contributing Factors.
Apparent Cause:	G3 - Excavation Damage
G1 - Corrosion Failure – only one sub-cause can be picked from shaded let	ft-hand column
Corrosion Failure Sub-Cause:	
- If External Corrosion:	
1. Results of visual examination:	
- If Other, Specify:	
2. Type of corrosion:	

- Galvanic	
- Atmospheric	
- Stray Current	
- Microbiological	
- Selective Seam	
- Other	
- If Other, Describe:	
2a. If 2. is Stray Current, specify	
2b. Describe the stray current source:	
3. The type(s) of corrosion selected in Question 2 is based on the following:	
- Field examination	
- Determined by metallurgical analysis	
- Other	
- If Other, Describe:	
4. Was the failed item buried or submerged?	
- If Yes:	
4a. Was failed item considered to be under cathodic protection at the time of the incident?	
- If Yes, Year protection started:	
4b. Was shielding, tenting, or disbonding of coating evident at the point of the incident?	
4c. Has one or more Cathodic Protection Survey been conducted at the point of the incident? (select all that apply)	
If "Yes, CP Annual Survey" – Most recent year conducted:	
If "Yes, Close Interval Survey" – Most recent year conducted:	
If "Yes, Other CP Survey" – Most recent year conducted:	
Describe Other CP Survey:	
- If No:	
4d. Was the failed item externally coated or painted?	
5. Was there observable damage to the coating or paint in the vicinity of the corrosion?	
6. Pipeline coating type, if steel pipe is involved:	
- If Other, Describe:	
6a. Field Applied?	
- If Internal Corrosion:	
7. Results of visual examination:	
- If Other, Describe:	
8. Cause of corrosion (select all that apply):	
- Corrosive Commodity	
- Water drop-out/Acid	
- Microbiological	
- Erosion	
- Other	
- If Other, Specify:	
9. The cause(s) of corrosion selected in Question 8 is based on the following: (se	lect all that apply):
- Field examination	
- Determined by metallurgical analysis	
- Other	
- If Other, Describe:	
10. Location of corrosion (select all that apply):	
- Low point in pipe	
- Elbow	
- Drop-out	
- Other	
- If Other, Describe:	
11. Was the gas/fluid treated with corrosion inhibitor or biocides?	

12. Were any liquids found in the distribution system where the Incident occurred?	
Complete the following if any Corrosion Failure sub-cause is selected AND C, Question 2) is Main, Service, or Service Riser.	the "Part of system involved in incident" (from PART
13. Date of the most recent Leak Survey conducted	
14. Has one or more pressure test been conducted since original construction at the point of the Incident?	
- If Yes:	
Most recent year tested:	
Test pressure:	
G2 - Natural Force Damage - only one sub-cause can be picked from sha	ided left-handed column
Natural Force Damage – Sub-Cause:	
- If Earth Movement, NOT due to Heavy Rains/Floods:	
1. Specify:	
- If Other, Specify:	
- If Heavy Rains/Floods:	
2. Specify:	
- If Other, Specify:	
- If Lightning:	
3. Specify:	
- If Temperature:	
4. Specify:	
- If Other, Specify:	
- If Other Natural Force Damage:	
5. Describe:	
Complete the following if any Natural Force Damage sub-cause is selected	
6. Were the natural forces causing the Incident generated in conjunction with an extreme weather event?	
6a. If Yes, specify (select all that apply):	
- Hurricane	
- Tropical Storm	
- Tornado	
- Other	
- If Other, Specify:	
G3 – Excavation Damage – only one sub-cause can be picked from shade	
Excavation Damage – Sub-Cause:	Excavation Damage by Third Party
- If Previous Damage due to Excavation Activity: Complete the following Ol Question 2) is Main, Service, or Service Riser.	NLY IF the "Part of system involved in Incident" (from Part C,
Date of the most recent Leak Survey conducted	
2. Has one or more pressure test been conducted since original construction at the point of the Incident?	
- If Yes:	
Most recent year tested:	
Test pressure:	
Complete the following if any Excavation Damage sub-cause is selected.	
3. Did the operator get prior notification of the excavation activity?	Yes
3a. If Yes, Notification received from: (select all that apply):	I
- One-Call System	Yes
- Excavator	
- Contractor	
- Landowner	
3b. Per the primary Incident Investigator report, did State law exempt the excavator from notifying the one-call center?	
If yes, answer 3c through 3e.	

3c. (select only one)	
- If Other, Specify:	
3d. Exempting Authority:	
3e. Exempting Criteria:	
Do you want PHMSA to upload the following information to CGA-DIRT (<u>www.cga-dirt.com</u>)?	No
5. Right-of-Way where event occurred (select all that apply):	
- Public	Yes
- If Public, Specify:	City Street
- Private	
- If Private, Specify:	
- Pipeline Property/Easement	
- Power/Transmission Line	
- Railroad	
- Dedicated Public Utility Easement	
- Federal Land	
- Unknown/Other	
6. Was the facility part of a Joint Trench:	
7. Did this event involve a Cross Bore:	
8. Measured Depth from Grade:	
Measured depth From Grade in inches 9. Type of excavator:	Contractor
10. Type of excavation equipment:	Directional Drilling
11. Type of work performed:	Telecommunications
12. Was the One-Call Center notified?	Yes
If No, skip to question 13	103
12a. If Yes, specify ticket number:	190931483
12b. If this is a State where more than a single One-Call Center exists, list the name of the One-Call Center notified:	100001100
12c. Was work area white lined:	
13. Type of Locator:	Contract Locator
14. Were facility locate marks visible in the area of excavation?	Yes
15. Did the damage cause an interruption in service?	Yes
15a. If Yes, specify duration of the interruption:	
16. Description of the CGA-DIRT Root Cause (select the predominant CGA-DIR)	T Root Cause):
- Root Cause Category:	Miscellaneous Root Causes
- Root Cause Type:	Root Cause not listed (comment required)
(Comment required)	Investigation is ongoing.
G4 - Other Outside Force Damage - only one sub-cause can be selected	from the shaded left-hand column
Other Outside Force Damage – Sub-Cause:	
- If Damage by Car, Truck, or Other Motorized Vehicle/Equipment NOT Enga	aged in Excavation:
Vehicle/Equipment operated by:	
If this sub-cause is picked, complete questions 7-13 below.	
	w Vessele Set Advitt ov Which Hove Otherwise Loot Their
- If Damage by Boats, Barges, Drilling Rigs, or Other Maritime Equipment o Mooring:	
2. Select one or more of the following IF an extreme weather event was a factor:	
- Hurricane	
- Tropical Storm	
- Tornado	
- Heavy Rains/Flood	
- Other	
- If Other, Specify:	
- If Previous Mechanical Damage NOT Related to Excavation: Complete the Part C, Question 2) is Main, Service, or Service Riser.	following ONLY IF the "Part of system involved in Incident" (from

3. Date of the most recent Leak Survey conducted:	
4. Has one or more pressure test been conducted since original construction at	
the point of the Incident?	
- If Yes:	
Most recent year tested:	
Test pressure (psig):	
- If Intentional Damage:	
5. Specify:	
- If Other, Specify:	
- If Other Outside Force Damage:	
6. Describe:	
Complete the following if Damage by Car, Truck, or Other Motorized Vehicle/Equ	lipment NOT Engaged in Excavation sub-cause is selected.
7. Was the driver of the vehicle or equipment issued one or more citations	
related to the incident?	
If 7. is Yes, what was the nature of the citations (select all that apply)	
7a. Excessive Speed	
7b. Reckless Driving	
7c. Driving Under the Influence	
7d. Other:	
- If Other, Specify:	
8. Was the driver under control of the vehicle at the time of the collision?	
9. Estimated speed of the vehicle at the time of impact (miles per hour)?	0
Unknown	
10. Type of vehicle?	
11. Where did the vehicle travel from to hit the pipeline facility?	
12. Shortest distance from answer in 11. to the damaged pipeline facility (in feet):	
13. At the time of the incident, were protections installed to protect the damaged pipeline facility from vehicular damage?	
If 13. is Yes, specify type of protection (select all that apply):	
13a. Bollards/Guard Posts	
13b. Barricades, including "jersey" barriers and fences	
13c. Guard Rails	
13d. Meter Box	
13e. Ingress or Regress at a Residence	
13f. Other	
- If Other, Specify:	
G5 - Pipe, Weld, or Joint Failure - only one sub-cause can be selected from	m the shaded left-hand column
Pipe, Weld or Joint Failure – Sub-Cause:	
- If Body of Pipe:	
1. Specify:	
- If Other, Describe:	
- If Butt Weld:	
2. Specify:	
- If Other, Describe:	
- If Fillet Weld:	
3. Specify:	
- If Other, Describe:	
- If Pipe Seam:	I
4. Specify:	
- If Other, Describe:	
- If Mechanical Joint Failure	
5a. Specify the Mechanical Fitting Involved (select only one)	
Other Compression Type Fitting (specify):	
5b. Specify the Type of Mechanical Fitting (select only one)	

Other (specify):	
5c. Fitting Manufacturer:	
Unknown	
5d. Part or Model Number:	
Unknown	
5e. Fitting Material (select only one)	
Other (specify):	
5f. How did the joint failure occur? (select only one)	
Other (specify):	
- If Fusion Joint:	
6. Specify:	
- If Other, Specify:	
7. Year installed:	
8. Other attributes:	
Specify the two materials being joined:	
9a. First material being joined:	
9a. First material being joined If Other, Specify:	
9b. Second material being joined:	
- If Other, Specify:	
- If Other Pipe, Weld, or Joint Failure:	
10. Describe:	
Complete the following if any Pipe, Weld, or Joint Failure sub-cause is sele	cted.
11. Additional Factors (select all that apply):	
- Dent	
- Gouge	
- Pipe Bend	
- Arc Burn	
- Crack	
- Lack of Fusion	
- Lamination	
- Buckle	
- Wrinkle	
- Misalignment	
- Burnt Steel	
- Other	
- If Other, Specify:	
12. Was the Incident a result of:	
- Construction defect	
Specify:	
- Material defect	
Specify:	
- If Other, Specify:	
- Design defect	
- Previous damage	
13. Has one or more pressure test been conducted since original construction at the point of the Incident?	
- If Yes:	
Most recent year tested:	
Test pressure:	
G6 - Equipment Failure - only one sub-cause can be selected from the share	ded left-hand column
Equipment Failure – Sub-Cause:	
- If Malfunction of Control/Relief Equipment:	
Specify:	
- Control Valve	
- Instrumentation	
i i i i i i i i i i i i i i i i i i i	1

- SCADA	
- Communications	
- Block Valve	
- Check Valve	
- Relief Valve	
- Power Failure	
- Stopple/Control Fitting	
- Pressure Regulator	
- Other	
- If Other, Specify:	
- If Threaded Connection Failure:	
2. Specify:	
- If Other, Specify:	
- If Non-threaded Connection Failure:	
3. Specify:	
- If Other, Specify:	
- If Valve:	
4. Specify:	
- If Other, Specify:	
4a. Valve type:	
4a. Valve type. 4b. Manufactured by:	
4b. Manufactured by: 4c. Year manufactured:	
4d. Valve Material:	
- If Other, Specify:	
- If Other Equipment Failure:	T
5. Describe:	
G7 - Incorrect Operation - only one sub-cause can be selected from the sh	aded left-hand column
Incorrect Operation Sub-Cause:	
If Other Incomest Occupations	
- If Other Incorrect Operation: 1. Describe:	
Complete the following if any Incorrect Operation sub-cause is selected.	
2. Was this Incident related to: (select all that apply)	
- Inadequate procedure	
- No procedure established	
- Failure to follow procedure	
- Other	
- If Other, Describe: 3. What category type was the activity that caused the Incident:	
What category type was the activity that caused the incident. Was the task(s) that led to the Incident identified as a covered task in your	
Operator Qualification Program?	
4a. If Yes, were the individuals performing the task(s) qualified for the task(s)?	
G9 - Other Incident Cause, only one cub cause can be calcated from the	shadad laft hand calumn
G8 - Other Incident Cause - only one sub-cause can be selected from the	bilaucu iciciianu columni
Other Incident Cause – Sub-Cause:	
- If Miscellaneous:	
1. Describe:	
- If Unknown:	
2. Specify:	
Mandatory comment field:	
PART J - CONTRIBUTING FACTORS	
	neart Course and in this Book I to Court 1997 C. T.
The Apparent Cause of the accident is contained in Part G. Do not report the Apidentified, select all that apply below and explain each in the Narrative:	parent Cause again in this Part J. If Contributing Factors were

External Corrosion	
External Corrosion, Galvanic	
External Corrosion, Atmospheric	
External Corrosion, Stray Current Induced	
External Corrosion, Microbiologically Induced	
External Corrosion, Selective Seam	
Internal Corrosion	
Internal Corrosion, Corrosive Commodity	
Internal Corrosion, Water drop-out/Acid	
Internal Corrosion, Microbiological	
Internal Corrosion, Erosion	
Natural Forces	
Earth Movement, NOT due to Heavy Rains/Floods	
Heavy Rains/Floods	
Lightning	
Temperature	
High Winds	
Snow/Ice	
Tree/Vegetation Root	
Excavation Damage	
Excavation Damage by Operator (First Party)	
Excavation Damage by Operator's Contractor (Second Party)	
Excavation Damage by Third Party	
Previous Damage due to Excavation Activity	
Other Outside Force	
Nearby Industrial, Man-made, or Other Fire/Explosion	
Damage by Car, Truck, or Other Motorized Vehicle/Equipment NOT Engaged in Excavation	
Damage by Boats, Barges, Drilling Rigs, or Other Adrift Maritime Equipment	
Routine or Normal Fishing or Other Maritime Activity NOT Engaged in Excavation	
Electrical Arcing from Other Equipment or Facility	
Previous Mechanical Damage NOT Related to Excavation	
Intentional Damage	
Other underground facilities buried within 12 inches of the failure location	
Pipe/Weld Failure	
Design-related	
Construction-related	
Installation-related	
Fabrication-related	
Original Manufacturing-related	
Equipment Failure	
Malfunction of Control/Relief Equipment	
Threaded Connection/Coupling Failure	
Non-threaded Connection Failure	
Valve Failure	
Incorrect Operation	
Damage by Operator or Operator's Contractor NOT Excavation and NOT Vehicle/Equipment Damage	
Valve Left or Placed in Wrong Position, but NOT Resulting in Overpressure	
Pipeline or Equipment Overpressured	
Equipment Not Installed Properly	
Wrong Equipment Specified or Installed	
Inadequate Procedure	
No procedure established	
Failure to follow procedures	
	1

PART H - NARRATIVE DESCRIPTION OF THE INCIDENT

On the morning of April 10, 2019, a third-party telecommunications contractor, while in the process of boring in new facilities via horizontal directional drilling along N Duke Street in Durham NC, damaged below-ground piping in PSNC's natural gas system. The contractor notified NC-811, the state's one-call office, of the damage at approximately 9:31 am. NC 811 in turn automatically generated a damage ticket which was delivered to PSNC at approximately 9:35 am. An order was then automatically dispatched to PSNC's first responder at approximately 9:36 am. The first responder reviewed the ticket at approximately 9:43 am and began heading to the site. PSNC received a call from 911 at approximately 9:48 am noting that the fire department was already on the scene. PSNC's Dispatch contacted the first responder in route to advise him of a gas odor and a damaged line at 115 N Duke Street. The fire department issued a combination of evacuation and shelter in place orders at approximately 9:58 am. PSNC's first responder arrived at approx. 10:03 am. Between his arrival and approximately 10:06 am, the PSNC first responder as well as PSNC's Dispatch contacted additional resources to assist with securing and making the scene safe. At approximately 10:06 am, the structure at 115 N Duke Street exploded. Between 10:26am and 10:50 am, additional PSNC employees including a construction crew arrived at the site. Crews convened at the incident command center to evaluate options to shut off the gas flow. At 11:05 am the crews identified the proper valve, secured the necessary tools, and at approximately 11:10 am shut off gas flow to the impacted area by closing a valve located approximately three blocks from the scene. PSNC has since performed a leakage survey over the remaining piping in the vicinity with no leaks or issues found. The section of main approximately 1 block paralleling the bore on Duke Street remains out of service pending the investigation.

The explosion killed the owner/occupant in the structure that was evacuated. The explosion also severely injured a member of the contractor crew, the PSNC first responder, and a fire fighter. 17 to 25 individuals were reportedly taken to local area hospitals. Six are believed to have been admitted, including PSNC's first responder who died in the hospital, as a result of his injuries, on April 25th.

The explosion destroyed the structure at 115 N Duke Street and reportedly damaged two others to a point of being condemned until repairs could be completed. Approximately 15 buildings in total were reportedly damaged by the force of the explosion.

As to PSNC's investigation, it is still ongoing. To date, the investigation has revealed that the service line feeding the structure that exploded was punctured during the directional drilling operation. However, while PSNC has determined that its gas facilities were located by its contract service provider, the investigation has not yet confirmed that the lines either were or were not marked accurately.

PSNC has had no known issues with the distribution system in this area in the recent past. 15 of 20 impacted customers have been restored.

As of this report, and until the scene is fully investigated, there remains a number of additional unknowns:

- * PSNC has not yet been able to determine the precise time that its gas system was damaged.
- * PSNC has not been able to determine the ignition source inside of the structure that exploded.
- * PSNC has not been able to determine the precise number of injuries, again reported in the media to be between 17 and 25 persons.
- * PSNC still has not developed precise assessments of costs of property damage (operator and public), restoration/repairs that will be required to re-commission the gas system, emergency response costs, the amount of lost gas, etc. Therefore, all figures in this report should be read as estimates until finalized and provided by supplemental reports.

PART I - PREPARER AND AUTHORIZED PERSON

Preparer's Name	Michael B. Greene
Preparer's Title	General Manager-Engineering Services
Preparer's Telephone Number	704-217-9191
Preparer's E-mail Address	mgreene@scana.com
Preparer's Facsimile Number	
Local Contact Name:	
Local Contact Email:	
Local Contact Phone:	
Authorized Signer's Name	Scott Swindler
Authorized Signer's Title	General Manager-Operations and Maintenance
Authorized Signer's Email Address	mswindler@scana.com