DOTU.S. Department of TransportationPHMSAPipeline and Hazardous Materials Safety AdministrationOPSOffice of Pipeline Safety
Central Region

Principal Investigator	Gery Bauman/Public Utilities Commission of Ohio (PUCO)
Senior Accident Investigator	Brian Pierzina/Karen Butler
Region Director	David Barrett/Allan Beshore
Date of Report	7/30/2015
Subject	Failure Investigation Report—Tennessee Gas Pipeline Company—Material Failure—Girth Weld

Operator, Location, & Consequences

Date of Failure	3/1/2011
Commodity Released	Natural Gas
City/County & State	Cumberland/Guernsey, OH
OpID & Operator Name	19160 Tennessee Gas Pipeline Company
Unit # & Unit Name	9413 DIVISION E [IA]
SMART Activity #	133678
Milepost/Location	Line 200-1/209-1 + 2258
Type of Failure	Rupture, Material Failure, Girth Weld
Fatalities	0
Injuries	0
Description of area impacted	Class 1, Rural area, Non-HCA
Total Costs	\$ 389,949

Executive Summary

On March 1, 2011, at approximately 7:15 a.m. EST,¹ Tennessee Gas Pipeline Company (TGP) personnel detected a natural gas release on the 26-inch diameter 200-1 pipeline downstream of the 209 Compressor Station in Guernsey County, near Cumberland, Ohio. The employees heard a hissing sound downstream (northeast) of the compressor station when they reported to work in the morning. After investigating, they confirmed a release coming from the 200-1 pipeline approximately 2,250 feet downstream of the compressor station. Immediate measures were taken to shut down and isolate the pipeline, including closing main line block valves (MLBVs) upstream and downstream from the release location.

The failure occurred in a wooded area near a pasture (Class 1 location, Rural, Non-HCA) approximately 1,200 feet from the nearest residence, and was discovered to be the result of a ruptured girth weld. The failed weld was removed—along with the adjacent welds upstream and downstream from the failure location—and sent to an independent metallurgical laboratory for analysis. The metallurgical analysis determined the failure was the result of a crack around the top portion of the girth weld dating back to 1950, the year of the original construction. The crack was what is referred to as an underbead crack, cold crack, or hydrogen-assisted crack. It was approximately 31 inches long circumferentially, centered from the 10:00 o'clock to 2:40 o'clock position on the pipe. Stresses associated with pipe bend, possible ground movement, and/or operational changes may have contributed to the eventual failure of the weld. When the first cut was made to remove the failed pipe the pipe ends shifted, indicating the presence of residual stresses on the pipeline. Additional cracks were identified outside of the failed portion of the girth weld, and the adjacent girth weld upstream from the failure had a similar crack that was determined to date to original construction, but was not leaking.

Based upon information provided by the TGP, it appears the failure occurred at 3:42 a.m. at a pressure of 709 pounds per square inch gage (psig). There were no injuries or evacuations associated with this incident, and the escaping gas did not ignite. The total reported costs associated with emergency response, pipe replacement, and site clean-up were \$389,949.

System Details

The TGP is an interstate natural gas transmission pipeline operator with approximately 12,000 miles of pipeline, including 876 miles in Ohio. The TGP system in Ohio consists of four essentially parallel pipelines that travel across the Ohio River near Portsmouth, Ohio, in a northeasterly direction, ending near Boardman, Ohio. The four pipelines generally, but not always, share a common right-of-way. The failure occurred on the Line 200-1 pipeline, a 26-inch diameter, 0.281-inch wall thickness, API 5LX Grade X-52, electric flash-welded (EFW) pipe manufactured by A.O. Smith. The pipeline was coated with coal tar enamel and asbestos wrap, and cathodically protected with impressed current. This pipeline was constructed in 1950 with a maximum allowable operating pressure (MAOP) of 790 psig. The pipeline section containing the girth weld was hydrostatically pressure tested without failure on September 27, 1969, and was in a no-flow condition at the time the leak was discovered due to ongoing downstream pipeline repairs being performed on Line Section 214-1. When the pipeline was constructed in 1950, pipeline girth welds were not typically nondestructively tested. In 2004, the TGP ran a high-resolution Magnetic Flux Leakage (MFL) and Caliper In-line inspection (ILI). The ILI data was examined for

¹ All times are Eastern Standard Time (EST) unless otherwise noted.

Failure Date 3/1/2011

indications of dents and metal loss, but was not subjected to an analysis that considered girth weld defects.

Events Leading up to the Failure

On February 10, 2011, at approximately 10:30 p.m., the TGP experienced a pipeline rupture (girth weld failure) on the Line 214-4 pipeline near Hanoverton, Ohio. Station 209 was operating when this failure occurred, but was taken offline as a result of the rupture and subsequent fire approximately 15 minutes later. As the emergency response to the Hanoverton incident progressed, TGP Incident Command determined it would be necessary to bring Station 209 back online to maintain service to customers. The request to bring Station 209 back online (for Lines 1, 2, and 3) was made at at 10:56 p.m. It was unknown at that time that the auto-close valves for all four pipelines at Valve Station 215 had closed due to the rupture and fire. When Station 209 was brought back online, the gas discharge pressure rose rapidly from 740 psig to 765 psig between 12:18 a.m. and 12:23 a.m., then dropping to 743 psig by 12:28 a.m. From that point on discharge pressure rose gradually, reaching a maximum recorded pressure of 782 psig at 1:24 a.m., when Incident Command requested Station 209 be shut down. When it was determined that all four auto-close valves at Valve Station 215 had closed, and the TGP system isolated at that location, alternative means of providing service to distribution customers was established. This allowed Station 209 to remain offline until after the necessary repairs at 215-1 were completed; those repairs were still in process when the March 1, 2011, incident occurred. There were no reported maintenance activities on the section of pipe just downstream of Compressor Station 209 in the area of the leak prior to March 1, 2011.

Emergency Response

The leak was initially discovered by TGP employees when they reported for work at Compressor Station 209 after they investigated a sound of escaping gas that could be heard from the station. Only two of the four pipelines in the area of the failure share a common right-of-way, so the employees were quickly able to determine the release was coming from Line 1. The employees then began the process of isolating the pipeline, closing MLBV 209-1 (upstream from the failure) at Compressor Station 209 at 8:00 a.m. and MLBV 210-1 (downstream from the failure) at 8:20 a.m. This isolated approximately 12 miles of Line 1, including the failure location. The pressure on Line 1 was then monitored for a period of time, with a pressure drop from 658 psig to 464 psig observed from 8:23 a.m. to 9:20 a.m. After receiving this additional confirmation that Line 1 was leaking, the TGP employees prepared to blowdown the section of Line 1 between MLBV 209-1 and MLBV 210-1. The blowdown process began at 10:47 a.m. and was completed by 12:30 p.m. There was no fire or explosion associated with the incident. The TGP notified the National Response Center (NRC) at 10:12 a.m. (NRC Report #968824), reporting that "a 26-inch steel pipeline appears to have a leak due to unknown causes." Both the Public Utilities Commission of Ohio (PUCO) and the Pipeline and Hazardous Materials Safety Administration (PHMSA) Central Region Inspectors were dispatched to investigate. The PUCO inspector was in the area inspecting a different pipeline operator, and arrived on-site at 11:25 a.m. The inspectors were able to provide field observations, gather background information, and monitor investigation and repair activities. Excavation of the failure location did not begin until the morning of March 2, 2011.

Summary of Return-to-Service

PHMSA issued a Notice of Proposed Safety Order (NOPSO) to the TGP (CPF No. 3-2011-1001S) on March 11, 2011, addressing both the failure on February 10, 2011, at Line 214-4, and the failure on March 1, 2011, at 209-1. The NOPSO provisions required a written restart plan, 20% pressure reduction, airborne instrumented leak survey, accelerated patrol surveillance activities, 3rd-party mechanical and

Failure Date 3/1/2011

metallurgical testing and failure analysis, historical ILI data re-analysis, performance of additional ILI, evaluation of the results for girth weld anomalies, analysis of Supervisory Control and Data Acquisition (SCADA) activities, root cause analysis, development and implementation of an integrity verification and remedial work plan, and monthly status reports. Good faith settlement discussions between the TGP and PHMSA culminated in a Consent Agreement that described the work to be performed to remediate the integrity risks associated with the pipelines.

On March 22, 2011, the TGP replaced 86 feet of the Line 1 pipe with pre-tested pipe. Even though the pipeline remained out of service, it was purged and loaded with natural gas to facilitate the required leakage survey from 209-1 to 210-1. Following the leakage survey, this section of Line 1 remained out of service, isolated at a pressure of 475 psig. During May 2011, with PHMSA's approval, the TGP temporarily increased the pressure on Line 1 from 209-1 to 214-1 in order to facilitate the cleaning tool, gauge tool, and inspection tool runs required by the Consent Agreement. These activities were completed by May 12, 2011, after which the section between 209-1 and 210-1 was isolated once more and locked in at a pressure of 522 psig. Following investigation and remediation of anomalies reported by the prior and most recent ILI reviews, the TGP requested—and was granted—permission to return the 209 to 210 section of Line 1 to service at full operating pressure. This was completed on October 28, 2011.

Investigation Details

After the area of the rupture was made safe, the rupture site was examined by employees of the TGP, PHMSA, and the Gas Pipeline Safety Section of PUCO. Records were requested regarding the history and operation of the pipeline, and the TGP hired Det Norske Veritas (DNV) to complete a metallurgical investigation of the failure. During the pipe removal process, the upstream and downstream welds were radiographed and crack-like indications were observed in the upstream weld. As a result, the failed girth weld and both the upstream and downstream welds were sent to the DNV for metallurgical investigation.

Pipe sections involving the three girth welds were removed and shipped to the DNV's Columbus location for a metallurgical investigation to determine the cause of the failure. The TGP expanded their root cause analysis (RCA) associated with the February 10, 2011, incident to include this girth weld failure. The RCA team was comprised of subject matter experts from the TGP and outside contractors. Additionally, soil scientists from Battelle Memorial Institute conducted a geologic and soil investigation into the failure.

The results of the metallurgical analysis² offered the following conclusions and discussion:

The results of the metallurgical analysis indicate that the leak initiated at a pre-existing crack in a field girth weld. The crack was 2.6 feet long, circumferentially, and was located on the inside of the pipe between the 10:00 and 2:40 o'clock orientations. The maximum depth of the crack was 0.317 inches (79% through wall based on a pipe wall/girth weld thickness of 0.399 inches). The pre-existing crack initiated at the toe of the root pass in the heat-affected zone of the weld. The crack propagated primarily in the weld metal. The crack did alternate between the upstream and downstream root pass as it propagated. This type of crack is referred to as an under-bead crack, cold crack, or hydrogen assisted crack. A discussion of the factors related to hydrogen-assisted cracking is given in Appendix B of the metallurgical report.

² DNV Final Report—Metallurgical Analysis of Girth Weld Leak on Tennessee Gas Pipeline's 200-1 Line at Milepost 209-1 + 0.44—May 20, 2011.

Failure Date 3/1/2011

The primary cause of the leak was the presence of the pre-existing weld crack. A contributing factor in the failure was tensile axial stresses acting on the girth weld. The presence of the weld crack near the top of the pipe suggests that bending stresses acted on the pipe to place the crack in tension. This is consistent with shifting of the pipe after the initial field cut, in which the upstream end shifted upwards approximately 2.5 inches. Approximately 91 feet of the pipeline was excavated (approximately 45.5 feet on both sides of the failed girth weld) at the time of the initial cut.

Below is a summary of observations from the metallurgical analysis.

- The leak occurred at a field girth weld.
- A pre-existing weld crack was associated with the leak.
- The pre-existing crack was approximately 2.6 feet long, circumferentially, and located
- between the 10:00 and 2:40 o'clock orientations.
- The maximum depth of the crack was approximately 0.317 inches, corresponding to 79% through wall based on a pipe wall/girth weld thickness of 0.399 inches. The final brittle fracture was approximately 0.08 inches deep corresponding to 21% of the pipe wall / girth weld thickness.
- The crack originated at the toe of the weld root pass and extended through the weld metal of the girth weld.
- Intergranular fractographic features were present in Regions 1 and 2 of the crack.

Findings and Contributing Factors

- There was a change in the operational history of the Cumberland Compressor Station immediately upstream of the failed girth weld. The pipeline was shut-in due to the repair of the downstream girth weld failure, and the ambient temperature at the time of failure was 24 degrees Fahrenheit. The cooler operating temperature of the pipeline could have increased tensile stresses due to thermal contraction of the pipe.
- 2. Typically, pipelines are bent during construction to conform to local topography. The section of pipe in the immediate vicinity of the girth weld contained a 7.9-degree sag bend; upon replacement of the pipeline section, however, a sag bend of 5.5 degrees was installed to fit the topography. The difference of 2.4 degrees between the original and replacement construction indicates the possibility of bending stresses acting across the weld.
- 3. A geological analysis of the soil and the topography of the pipeline right-of-way in the vicinity of the failed weld indicated soil creep perpendicular to the pipeline. This extremely slow ground movement could increase the tensile stresses across the girth weld over time, leading to its failure.
- 4. The results of the DNV metallurgical investigation showed the failed girth weld contained a preexisting crack that extended through part of the girth weld. The preexisting crack initiated at the toe of the root bead and penetrated through part of the weld. The crack was 2.6 feet long circumferentially, and had a maximum depth of 0.317 inches (79% of the way through the wall based on a total weld thickness of 0.399 inches). The laboratory classified the crack as a hydrogen crack, also known as an under-bead crack, cold crack, or hydrogen-assisted crack. The conculsion that it was a hydrogen crack that led to this failure is supported by the metallurgy of the pipe and the welding electrodes used to complete the weld, as well as experience gained

Failure Date 3/1/2011

regarding welding since the pipeline was built in 1950. No signs of fatigue were observed; the crack formed during construction of the pipeline and remained dormant from the date of construction until the time of failure.

5. The restart of Station 209 during the Line 214-4 incident on February 10-11, 2011, was initiated shortly after the incident. Fires were still burning at this time, and the status of Lines 1, 2, and 3 was unconfirmed. As a result of all four pipelines being isolated at Valve Station 215, the discharge pressure at 209-1 reached at least 782 psig prior to the station being shut down again. The pressure records provided by the TGP for the period following this event show that the pressure at 209 was maintained between 630 psig and 670 psig until the end of February. The pressure began to increase steadily on February 28th, rising from 670 psig to 709 psig, at which point the failure occurred. It's possible this pressure cycle, just 18 days before the failure, may have been sufficient to destabilize the previously dormant defect.

Appendices

- A Map and Photographs
- B NRC Report
- C Operator's Report
- D Metallurgical Analysis
- E Root Cause Analysis (RCA)

Pipeline and Hazardous Materials Safety Administration	OPID 19160 Tennessee Gas Pipeline Co Cumberland, OH Incident PHMSA CENTRAL REGION	0 1.5 3	6 9 Miles ^w ψ ^N _s ε

660

Photo 1 view of leak site looking south down the right-of-way. The compressor station can be seen in the distance. The disturbed soil was blown from the ground as a result of the failed girth weld.



Photo 2 shows the excavation around the failed girth weld.



Photo 3 shows the failed girth weld.





Photo 4 shows a close-up of the top of the failed girth weld.

NATIONAL RESPONSE CENTER 1-800-424-8802 *** For Public Use *** Information released to a third party shall comply with any applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 968824

INCIDENT DESCRIPTION

*Report taken at 10:12 on 01-MAR-11 Incident Type: PIPELINE Incident Cause: UNKNOWN Affected Area: The incident was discovered on 01-MAR-11 at 09:15 local time. Affected Medium: AIR INTO THE AIR

SUSPECTED RESPONSIBLE PARTY

Organization: TENNESSEE GAS PIPELINE HOUSTON, TX 77046

Type of Organization: PRIVATE ENTERPRISE

SEE LAT/LONG County: GUERNSEY

COUNTY RD 15 CLAYSVILLE RD City: CLAYSVILLE State: OH Zip: 77046 Latitude: 39 57' 12" N

Longitude: 081 40' 33" W

RELEASED MATERIAL(S)

CHRIS Code: ONG Official Material Name: NATURAL GAS Also Known As: Qty Released: 0 UNKNOWN AMOUNT

DESCRIPTION OF INCIDENT

The caller is reporting that a 26 inch steel pipeline appears to have a leak due to unknown causes. An unknown amount of natural gas was released to the atmosphere.

INCIDENT DETAILS

Pipeline Type: TRANSMISSION DOT Regulated: YES Pipeline Above/Below Ground: BELOW Exposed or Under Water: NO Pipeline Covered: UNKNOWN

Fire Involved:	NO:	Fire	Extinguished: UNKNOW	DAMAGES N					
INJURIES:		NO	Hospitalized:		Empl/Crew:		Passenger:		
FATALITIES:		NO	Empl/Crew:		Passenger:		Occupant		
EVACUATIONS:		NO	Who Evacuated:		Radius/Are	a:			
Damages:		NO							
					Length	of	Direction of		
Closure Type		Descr	iption of Closure		<u>Clo</u>	sure	Closure		
Air:	N								
Road:	N							Major Artery:	N
Waterway:	N								
Track:	N								
Passengers Tra Environmental Media Interest	insfe Impa :: NC	erred: N .ct: UNK ONE Com	O NOWN munity Impact due to	Material:		<u>.</u>			

REMEDIAL ACTIONS THEY HAVE ISOLATED THE PIPELINE AND WILL DEPRESSURE IT. Release Secured: NO

Release Rate: Estimated Release Duration: WEATHER Weather: PARTLY CLOUDY, 32°F Wind speed: 2 MPH Wind directi ADDITIONAL AGENCIES NOTIFIED Federal: NONE State/Local: OH PUC State/Local On Scene: NONE State Agency Number: NONE NOTIFICATIONS BY NRC ATLANTIC STRIKE TEAM (MAIN OFFICE) 01-MAR-11 10:19 USCG ICC (ICC ONI) 01-MAR-11 10:19 CGIS RAO ST. LOUIS (COMMAND CENTER) 01-MAR-11 10:19 DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE) 01-MAR-11 10:19 U.S. EPA V (MAIN OFFICE) 01-MAR-11 10:21 10:21 NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE) 01-MAR-11 10:19 NOAA RPTS FOR OH (MAIN OFFICE) 01-MAR-11 10:19 OHIO DEPARTMENT OF HEALTH (OHDOH) 01-MAR-11 10:19 SECTOR OHIO VALLEY (COMMAND CENTER) 01-MAR-11 10:19 OH EPA ATTN: DUTY OFFICER (MAIN OFFICE) 01-MAR-11 10:19 OH EPA ATTN: DUTY OFFICER (SOUTHEAST DISTRICT OFFICE) 01-MAR-11 10:19 ADDITIONAL INFORMATION NO ADDITIONAL INFORMATION.

*** END INCIDENT REPORT # 968824 ***

http://www.nrc.uscg.mil/reports/rwservlet?standard_web+inc_seq=968824

NOTICE: This report is required by 49 CFR Part 191. Failure to report can result in a exceed 100,000 for each viola ion for each day that such violation persists except that penalty shall not exceed \$1.000.000 as provided in 49 USC 60122.	a civil penalty not to at the maximum civil	OMB NO: 2137-0522 EXPIRATION DATE: 10/31/2016		
N	Original Report	03/28/2011		
US Department of Transportation	No.	20110036 - 16819		
Pipeline and Hazardous Materials Safety Administration				
INCIDENT REPORT - GAS TRANSMISSION AND GATHERING PIPELINE SYSTEMS				
A federal agency may not conduct or sponsor, and a person is not required to respor with a collection of information subject to the requirements of the Paperwork Reducti OMB Control Number. The OMB Control Number for this information collection is 21 mandatory. Send comments regarding the burden estimate or any other aspect of h burden to: Information Collection Clearance Officer, PHMSA, Office of Pipeline Safet	nd to, nor shall a person b on Act unless that collect 37-0522. All responses his collection of informatio y (PHP-30) 1200 New Je	be subject to a penalty for failure to comply ion of information displays a current valid to this collection of information are in, including suggestions for reducing the rsey Avenue, SE, Washington, D.C. 20590.		
INSTRUCTIONS				
Important: Please read the separate instructions for completing this form before you examples. If you do not have a copy of the instructions, you can obtain one from the <u>http://www.phmsa.dot.gov/pipeline/library/forms</u> .	u begin. They clarify the PHMSA Pipeline Safety	information requested and provide specific Community Web Page at		
PART A - KEY REPORT INFORMATION				
Report Type: (select all that apply)	Original:	Supplemental: Final:		
Last Revision Date:	07/20/2015	Yes Yes		
1. Operator's OPS-issued Operator Identification Number (OPID):	19160			
2. Name of Operator	TENNESSEE GAS F	PIPELINE COMPANY		
3. Address of Operator:				
3a. Street Address	1001 LOUISIANA S	ST SUITE 1000		
3b. City	HOUSTON			
3c. State	Texas			
3d. Zip Code:	77002			
4. Local time (24-hr clock) and date of the Incident:	03/01/2011 07:15			
5. Location of Incident:	00.045400			
	39.945198			
Longitude:	-81.680369			
7. Local time (24-br clock) and date of initial telephonic report to the	900024			
National Response Center (if applicable):	03/01/2011 10:12			
8 Incident resulted from:	Unintentional release	se of das		
9. Gas released: (select only one, based on predominant volume				
released)	Natural Gas			
- Other Gas Released Name:				
10. Estimated volume of commodity released unintentionally - Thousand Cubic Feet (MCF):	29,745.00			
11. Estimated volume of intentional and controlled release/blowdown - Thousand Cubic Feet (MCF)	13,338.00			
12. Estimated volume of accompanying liquid release (Barrels):				
13. Were there fatalities?	No			
 If Yes, specify the number in each category: 	1			
13a. Operator employees				
13b. Contractor employees working for the Operator				
13c. Non-Operator emergency responders				
130. WORKERS WORKING ON THE FIGHT-OF-WAY, DUT NUT associated with this Operator				
13e General public				
13f. Total fatalities (sum of above)				
14. Were there injuries requiring inpatient hospitalization?	No			
- If Yes, specify the number in each category:				
14a. Operator employees				
14b. Contractor employees working for the Operator				
14c. Non-Operator emergency responders				
14d. Workers working on the right-of-way, but NOT				
associated with this Operator				
14e. General public				
141. I Otal Injuries (SUM Of above)	Vaa			
- If No Explain:	162			

- If Yes, complete Questions 15a and 15b: (use local time, 24-hr clock	k)
15a. Local time and date of shutdown	03/01/2011 08:20
15b. Local time pipeline/facility restarted	03/22/2011 16:09
- Still shut down? (* Supplemental Report Required)	
16. Did the gas ignite?	No
17. Did the gas explode?	No
18. Number of general public evacuated:	0
19. Time sequence (use local time, 24-hour clock):	
19a. Local time operator identified Incident– effective 10-2014, changed from "Incident" to "failure"	03/01/2011 07:15
19b Local time operator resources arrived on site	03/01/2011 08:00
PART B - ADDITIONAL LOCATION INFORMATION	
1. Was the origin of the Incident onshore?	Yes
- Yes (Complete Ques	tions 2-12)
- No (Complete Quest	ions 13-15)
If Onshore:	
2. State:	Ohio
3. Zip Code:	43732
4. City	Cumberland
5. County or Parish	Guernsey
6. Operator designated location	Milepost/Valve Station
Specify:	209-1@2258
7. Pipeline/Facility name:	Line 200-1
8. Segment name/ID:	Valve Section 209-1
 Was Incident on Federal land, other than the Outer Continental Shelf (OCS)2 	No
10 Location of Incident :	Pipeline Pight of way
11. Area of Incident (as found):	Inderground
Specify:	
Other Deserbe:	
Depth of Cover (in):	22
Deptin-or-Cover (III).	33
If Vos. specify type below:	NO
- If tes, specify type below.	
- If Bridge crossing –	
Cased/ Uncased:	
- If Railroad crossing –	
Cased/ Uncased/ Bored/drilled	
- If Road crossing –	
Cased/ Uncased/ Bored/drilled	
- If Water crossing –	
Cased/ Uncased	
Name of body of water (If commonly known):	
Approx. water depth (ft) at the point of the Incident:	
Select:	
If Offshore:	
13. Approx. water depth (ft) at the point of the Incident:	
14. Origin of Incident:	
- If "In State waters":	
- State:	
- Area:	
- Block/Tract #:	
- Nearest County/Parish:	
- If "On the Outer Continental Shelf (OCS)":	
- Area:	
- Block #:	
15. Area of Incident:	
PART C - ADDITIONAL FACILITY INFORMATION	
1 le the pipeline or facility: - Interstate Intractate	Interstate
2 Part of system involved in Incident:	Onshore Pineline, Including Value Sites
2. Fait of system involved in Incluent.	Wold including boat affected zone
	weiu, including neat-directed zone
- IT Pipe - Specify:	
3a. Nominal diameter of pipe (in):	20
3b. Wall thickness (in):	.281
3c. SMYS (Specified Minimum Yield Strength) of pipe (psi):	52,000

3d Pine specification:	Exceeds API 5
	Electronic Alinois
Se. Pipe Seam – Specily.	
- If Other, Describe:	
3t. Pipe manufacturer:	A.O. Smith
3g. Year of manufacture:	1950
 Pipeline coating type at point of Incident – Specify: 	Coal Tar
- If Other, Describe:	
 If Weld, including heat-affected zone – Specify: 	Pipe Girth Weld
- If Other, Describe:	
- If Valve – Specify:	
If Mainling Chasifu	
- II Mainline – Specity.	
- Ir Otner, Describe:	
31. Mainline valve manufacturer:	
3j. Year of manufacture:	
- If Other, Describe:	10-0
4. Year item involved in Incident was installed:	1950
5. Material involved in Incident:	Carbon Steel
 If Material other than Carbon Steel or Plastic – Specify: 	
6. Type of Incident involved:	Rupture
- If Mechanical Puncture – Specify Approx, size:	
in (axial) by	
in (circumferential)	
- If Leak - Select Type:	
If Other Describer	
- II Other – Describe.	
- If Rupture - Select Orientation:	Circumferential
- If Other – Descr be:	
Approx. size: in. (widest opening):	.4
by in. (length circumferentially or axially):	31.2
- If Other – Describe:	
PART D - ADDITIONAL CONSEQUENCE INFORMATION	
1. Class Location of Incident:	Class 1 Location
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? 	Class 1 Location No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes:	Class 1 Location No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA:	Class 1 Location No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this	Class 1 Location No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet:	Class 1 Location No 504
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident?	Class 1 Location No 504
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged	Class 1 Location No 504
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident?	Class 1 Location No 504 No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged	Class 1 Location No 504 No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident?	Class 1 Location No 504 No No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? 6. Were any of the fatalities or injuries reported for persons located	Class 1 Location No 504 No No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? 6. Were any of the fatalities or injuries reported for persons located outside the PIR?	Class 1 Location No 504 No No No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? 6. Were any of the fatalities or injuries reported for persons located outside the PIR? 7. Estimated Property Damage :	Class 1 Location No 504 No No No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? 6. Were any of the fatalities or injuries reported for persons located outside the PIR? 7. Estimated Property Damage : Za. Stimated cost of public and non-Operator private	Class 1 Location No 504 No No No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? 6. Were any of the fatalities or injuries reported for persons located outside the PIR? 7. Estimated Property Damage : 7a. Estimated cost of public and non-Operator private property domage naid/toimbursod by the Operator _ offective 6	Class 1 Location No 504 No No No No
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? 6. Were any of the fatalities or injuries reported for persons located outside the PIR? 7. Estimated Property Damage : 7a. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6- 2041 "maif (reimbursed by the Operator" menurod	Class 1 Location No 504 No No \$ 10,000
1. Class Location of Incident: 2. Did this Incident occur in a High Consequence Area (HCA)? - If Yes: 2a. Specify the Method used to identify the HCA: 3. What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: 4. Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? 5. Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? 6. Were any of the fatalities or injuries reported for persons located outside the PIR? 7. Estimated Property Damage : 7a. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6- 2011, "paid/reimbursed by the Operator" removed	Class 1 Location No 504 No No No \$ 10,000
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, 	Class 1 Location No 504 No No No \$ 10,000
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage :	Class 1 Location No 504 No No \$ 10,000
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, moved to item 7f Estimated cost of gas released during intentional and controlled 	Class 1 Location No 504 No No \$ 10,000
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, moved to item 7f Estimated cost of gas released during intentional and controlled blowdown – effective 6-2011, moved to item 7g 	Class 1 Location No 504 No No \$ 10,000
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, moved to item 7f Estimated cost of gas released during intentional and controlled blowdown – effective 6-2011, moved to item 7g Tb. Estimated cost of Operator's property damage & repairs 	Class 1 Location No 504 No No \$ 10,000 \$ 200,825
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, moved to item 7f Estimated cost of Operator's property damage & repairs 7c. Estimated cost of Operator's emergency response 	Class 1 Location No 504 No No \$ 10,000 \$ 200,825 \$ 6,800
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, moved to item 7f Estimated cost of Operator's property damage & repairs 7c. Estimated cost of Operator's emergency response 7d. Estimated other costs 	Class 1 Location No 504 No No \$ 10,000 \$ 10,000 \$ 200,825 \$ 6,800 \$ 0
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released during intentional and controlled blowdown – effective 6-2011, moved to item 7g Tb. Estimated cost of Operator's property damage & repairs 7c. Estimated cost of Operator's property damage & repairs 7c. Estimated cost of Operator's mergency response Td. Estimated other costs 	Class 1 Location No 504 No No No \$ 10,000 \$ 10,000 \$ 200,825 \$ 6,800 \$ 0
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes:	Class 1 Location No 504 No No No \$ 10,000 \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released during intentional and controlled blowdown – effective 6-2011, moved to item 7g Tb. Estimated cost of Operator's property damage & repairs Tc. Estimated cost of Operator's emergency response Td. Estimated cost of Operator's emergency response Td. Estimated other costs 	Class 1 Location No 504 No No No \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, moved to item 7f Estimated cost of Operator's property damage & repairs Tc. Estimated cost of Operator's property damage & repairs Tc. Estimated cost of Operator's emergency response Td. Estimated other costs Describe: Te. Property damage subtotal (sum of above) 	Class 1 Location No 504 No No \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released unintentionally – effective 6-2011, moved to item 7f Estimated cost of Operator's property damage & repairs Tc. Estimated cost of Operator's emergency response Td. Estimated other costs Describe: Te. Property damage subtotal (sum of above) 	Class 1 Location No 504 No No \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes:	Class 1 Location No 504 No No \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625 \$ 118,980
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released during intentional and controlled blowdown – effective 6-2011, moved to item 7g Tb. Estimated cost of Operator's property damage & repairs Tc. Estimated cost of Operator's emergency response Td. Estimated cost of Operator's emergency response Td. Estimated other costs Describe: Te. Property damage subtotal (sum of above) 	Class 1 Location No 504 No No \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625 \$ 118,980 \$ 118,980 \$ 52,244
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes: 2a. Specify the Method used to identify the HCA: What is the PIR (Potential Impact Radius) for the location of this Incident? Feet: Were any structures outside the PIR impacted or otherwise damaged due to heat/fire resulting from the Incident? Were any structures outside the PIR impacted or otherwise damaged NOT by heat/fire resulting from the Incident? Were any of the fatalities or injuries reported for persons located outside the PIR? Estimated Property Damage : Ta. Estimated cost of public and non-Operator private property damage paid/reimbursed by the Operator – effective 6-2011, "paid/reimbursed by the Operator" removed Estimated cost of gas released during intentional and controlled blowdown – effective 6-2011, moved to item 7g Tb. Estimated cost of Operator's property damage & repairs Tc. Estimated cost of Operator's mergency response Td. Estimated cost of operator gas released unintentional and controlled blowdown – effective 6-2011, moved to item 7g Tb. Estimated cost of Operator's property damage & repairs Tc. Estimated cost of Operator's mergency response Td. Estimated cost of gas released unintentional and controlled blowdown – effective costs Describe: Te. Property damage subtotal (sum of above) 	Class 1 Location No 504 No No No \$ 10,000 \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625 \$ 118,980 \$ 53,344
 Class Location of Incident: Did this Incident occur in a High Consequence Area (HCA)? If Yes:	Class 1 Location No 504 No No No \$ 10,000 \$ 10,000 \$ 200,825 \$ 6,800 \$ 0 \$ 217,625 \$ 118,980 \$ 53,344 \$ 172,324

PART E - ADDITIONAL OPERATING INFORMATION			
1. Estimated pressure at the point and time of the Incident (psig):	709.00		
2. Maximum Allowable Operating Pressure (MAOP) at the point and time of the Incident (psig):	790.00		
Added 10-2014 2a. MAOP established by 49 CFR section:	192.619(a)(3)		
- If Other, specify:			
3. Descr be the pressure on the system or facility relating to the Incident:	Pressure did not exceed MAOP		
4. Not including pressure reductions required by PHMSA regulations (such as for repairs and pipe movement), was the system or facility relating to the Incident operating under an established pressure restriction with pressure limits below those normally allowed by the MAOP?	Νο		
4a. Did the pressure exceed this established pressure			
4b. Was this pressure restriction mandated by PHMSA or the State?			
5. Was "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend" selected in PART C, Question 2?	Yes		
- If Yes - (Complete 5a. – 5e. below):			
5a. Type of upstream valve used to initially isolate release source:	Manual		
5b. Type of downstream valve used to initially isolate release source:	Manual		
5c. Length of segment isolated between valves (ft):	63,307		
5d. Is the pipeline configured to accommodate internal inspection tools?	Yes		
- If No – Which physical features limit tool accommodation? (select all the	nat apply)		
- Changes in line pipe diameter			
 Presence of unsuitable mainline valves 			
- Tight or mitered pipe bends			
 Other passage restrictions (i.e. unbarred tee's, projecting instrumentation, etc.) 			
 Extra thick pipe wall (applicable only for magnetic flux leakage internal inspection tools) 			
- Other			
- If Other, Describe:			
5e. For this pipeline, are there operational factors which significantly complicate the execution of an internal inspection tool run?	Νο		
- If Yes, which operational factors complicate execution? (select all that	apply)		
- Excessive debris or scale, wax, or other wall build-up			
 Low operating pressure(s) 			
- Low flow or absence of flow			
- Incompatible commodity			
- Other			
- If Other, Describe:			
5f. Function of pipeline system:	I ransmission System		
6. Was a Supervisory Control and Data Acquisition (SCADA)-based system in place on the pipeline or facility involved in the Incident?	Yes		
- II 105.	Voc		
6b. Was it fully functional at the time of the Incident?	Tes		
6c. Did SCADA-based information (such as alarm(s), alert(s), event(s), and/or volume or pack calculations) assist with the	No		
aetection of the Incident?			
6d. Did SCADA-based information (such as alarm(s), alert(s), event(s), and/or volume calculations) assist with the confirmation of the Incident?	No		
7. How was the Incident initially identified for the Operator?	Local Operating Personnel, including contractors		
- If Other – Describe:			
7a. If "Controller", "Local Operating Personnel, including contractors", "Air Patrol", or "Ground Patrol by Operator or its contractor" is selected in Question 7, specify:	Operator employee		
8. Was an investigation initiated into whether or not the controller(s) or control room issues were the cause of or a contributing factor to the Incident?	No, the Operator did not find that an investigation of the controller(s) actions or control room issues was necessary due to: (provide an explanation for why the Operator did not investigate)		

 If No, the operator did not find that an investigation of the 	
controller(s) actions or control room issues was necessary due to:	Pressures were never abnormal or in excess of MAOP.
(provide an explanation for why the operator did not investigate)	
 If Yes, Describe investigation result(s) (select all that apply): 	
 Investigation reviewed work schedule rotations, continuous 	
hours of service (while working for the operator), and other	
factors associated with fatigue	
 Investigation did NOT review work schedule rotations, 	
continuous hours of service (while working for the Operator)	
and other factors associated with fatigue	
- Provide an explanation for why not:	
Investigation identified no control room issues	
Investigation identified no controller issues	
 Investigation identified incorrect controller action or 	
controller error	
- Investigation identified that fatigue may have affected the	
controller(s) involved or impacted the involved controller(s)	
response	
Investigation identified incorrect procedures	
 Investigation identified incorrect control room equipment 	
operation	
 Investigation identified maintenance activities that affected 	
control room operations, procedures, and/or controller	
response	
 Investigation identified areas other than those above – 	
Describe:	
PART F - DRUG & ALCOHOL TESTING INFORMATION	
1. As a result of this Incident, were any Operator employees tested	
Under the post-accident drug and alconol testing requirements of DOT's	NO
brug & Alconol Testing regulations?	
- If Yes:	r
1a. How many were tested:	
1b. How many failed:	
2. As a result of this Incident, were any Operator contractor employees	
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of	No
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations?	No
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: Operator Contractor employees 	No
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many filted	No
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes:	No
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART C - APPARENT CALLSE	No
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes:	No
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe	No
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right Describe secondary, contributing, or root causes of	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H)
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represent questions on the right. Describe secondary, contributing, or root causes of	No Penting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H).
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause:	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause:	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shaded	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause:	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left repress questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure – Sub-cause:	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? - If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure – Sub-cause: If External Corrosion:	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: Results of visual examination: 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: Results of visual examination: If Other, Describe: 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: Results of visual examination: Type of corrosion: (select all that apply) 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: Results of visual examination: Type of corrosion: (select all that apply) Galvanic 	No Penting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: Results of visual examination: Type of corrosion: (select all that apply) Galvanic Atmospheric 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: Results of visual examination: Galvanic Atmospheric Stray Current 	No Penting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: Results of visual examination: Galvanic Atmospheric Stray Current Microbiological 	No Penting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld Ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure – Sub-cause: If External Corrosion: Results of visual examination: Galvanic Atmospheric Stray Current Microbiological Selective Seam 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left repress questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: 1. Results of visual examination: Stay Current Atmospheric Stray Current Microbiological Selective Seam Other 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left repress questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: 1. Results of visual examination: Stay Current Atmospheric Stray Current Microbiological Selective Seam Other If Other – Describe: 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left repress questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: 1. Results of visual examination: Galvanic Atmospheric Stray Current Microbiological Selective Seam Other If Other – Describe: 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column g: (select all that apply)
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure – Sub-cause: If External Corrosion: Results of visual examination: Galvanic Atmospheric Stray Current Microbiological Selective Seam Other If Other – Describe: 3. The type(s) of corrosion selected in Question 2 is based on the followin - Field examination	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column g: (select all that apply)
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left represe questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure – Sub-cause: If External Corrosion: Results of visual examination: Galvanic Atmospheric Stray Current Microbiological Selective Seam Other If Other – Describe: 3. The type(s) of corrosion selected in Question 2 is based on the followin - Field examination: Field examination 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column g: (select all that apply)
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left repress questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: 1. Results of visual examination: Galvanic Atmospheric Stray Current Microbiological Selective Seam Other If Other – Describe: 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column g: (select all that apply)
 2. As a result of this Incident, were any Operator contractor employees tested under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? If Yes: 2a. How many were tested: 2b. How many failed: PART G - APPARENT CAUSE Select only one box from PART G in the shaded column on the left repress questions on the right. Describe secondary, contributing, or root causes of Apparent Cause: G1 - Corrosion Failure - only one sub-cause can be picked from shade Corrosion Failure - Sub-cause: If External Corrosion: 1. Results of visual examination: Galvanic Atmospheric Stray Current Microbiological Selective Seam Other If Other – Describe: 	No enting the APPARENT Cause of the Incident, and answer the the Incident in the narrative (PART H). G5 - Material Failure of Pipe or Weld ded left-hand column g: (select all that apply)

- If Yes:	
4a. Was failed item considered to be under cathodic protection at	
the time of the incident?	
- If Yes, Year protection started:	
4b. Was shielding, tenting, or disbonding of coating evident at the	
point of the incident?	
4c. Has one or more Cathodic Protection Survey been conducted	
at the point of the incident?	
If "Yes, CP Annual Survey" – Most recent year conducted:	
If "Yes. Close Interval Survey" – Most recent year conducted:	
If "Yes. Other CP Survey" – Most recent year conducted	
- If No:	
Ad Was the failed item externally coated or painted?	
5. Was there observable damage to the coating or paint in the vicinity of	
the corrosion?	
- If Internal Corrosion:	
6 Results of visual examination:	
- If Other Describe:	
7 Cause of corrosion (select all that apply):	
Corrective Commedity	
- Water drop-out/Acid	
Microbiological	
- Other	
- Other Describe:	
- II Ottlei, Describe.	ing (soloct all that apply):
- Field examination	
- Tield examination	
Othor	
- Other Describe:	
- II Ottiel, Describe.	
9. Location of conosion (select all that apply).	
Elbow	
- EIDOW	
Other	
- Other Describe:	
- II Olliel, Describe.	
10. Was the gas/indu treated with corrosion inhibitors of biocides?	
11. Was the intention coaled of lined with protective coaling?	
12. Were cleaning/dewatering pigs (or other operations) routinely	
12 Were correction coupons routingly utilized?	
13. Were conosion coupons routinely utilized?	
Question 3) is Pipe or Weld.	AND the "Item Involved in Incident" (from PART C,
14. Has one or more internal inspection tool collected data at the point	
142. If Voc. for each tool used, select type of internal inspection tool	and indicate most recent year run:
Magnotic Flux Lookage Tool	
Most recent year run:	
- Ultrasonic	
- Ottasonic Most recent year run:	
Geometry	
Most recent year run:	
- Caliper	
Most recent year run:	
- Crack	
Most recent year run:	
- Hard Spot	
Most recent year run:	
- Combination Tool	
Most recent year run:	
- Transverse Field/Triavial	
Most recent year run:	
- Other	
Moet recent year run:	
If Other Describe:	
15 Has one or more hydrotest or other pressure test been conducted	
since original construction at the point of the Incident?	
- If Yes.	

Most recent year tested:	
Test pressure (psig):	
16. Has one or more Direct Assessment been conducted on this	
10. Has one of more Direct Assessment been conducted on this	
Segment?	i de uti
- If Yes, and an investigative dig was conducted at the point of the inc	ident:
Most recent year conducted:	
- If Yes, but the point of the Incident was not identified as a dig site:	
Most recent year conducted:	
17. Has one or more non-destructive examination been conducted at the point of the Incident since January 1, 2002?	
17a. If Yes, for each examination conducted since January 1, 2002, s	select type of non-destructive examination and indicate most
recent year the examination was conducted:	
- Radiography	
Most recent vear examined:	
- Guided Wave Ultrasonic	
Most recent year examined:	
Handhold I Iltraconic Tool	
- Handheid Olitasonic Tool Meet recent voor eveningdi	
Most recent year examined.	
- Wet Magnetic Particle Test	
Most recent year examined:	
- Dry Magnetic Particle Test	
Most recent year examined:	
- Other	
Most recent year examined:	
If Other, Describe:	
	<u>-</u>
G2 - Natural Force Damage - only one sub-cause can be picked from	n shaded left-handed column
Natural Force Damage – Sub-Cause:	
 If Earth Movement, NOT due to Heavy Rains/Floods: 	
1. Specify:	
- If Other, Describe:	
- If Heavy Rains/Floods:	
2 Specify	
- If Other Describe:	
If Linktring.	
3. Specify:	
- If Temperature:	
4. Specify:	
- If Other, Describe:	
- If Other Natural Force Damage	
5 Describe:	
Complete the following if any Natural Force Damage sub-cause is sele	cted.
6. Were the natural forces causing the Incident generated in conjunction	
with an extreme weather event?	
6a. If ves, specify: (select all that apply):	
- Hurricane	
- Tropical Storm	
- Torpado	
Othor	
If Other Describe:	
- II Other, Describe.	
G3 - Excavation Damage only one sub-cause can be picked from sh	aded left-hand column
Excavation Damage – Sub-Cause:	
- If Previous Damage Due to Excavation Activity: Complete Questions	s 1-5 ONLY IF the "Item Involved in Incident" (From Part C,
Question 3) is Pipe or Weid.	
1. Has one or more internal inspection tool collected data at the point of	
the incident?	
 1a. If Yes, for each tool used, select type of internal inspection tool ar 	nd indicate most recent year run:
- Magnetic Flux Leakage	
Year:	
- Ollasonic	
Year:	
- Geometry	
- Geometry	

Year	
- Crack	
Voor	
llord Spot	
Year:	
- Combination Tool	
Year:	
- Transverse Field/Triaxial	
Year:	
- Other:	
Year:	
Describe:	
2. Do you have reason to believe that the internal inspection was	
completed BEFORE the damage was sustained?	
3 Has one or more bydrotest or other pressure test been conducted	
since original construction at the point of the Incident?	
- II fes.	
Most recent year tested:	
l est pressure (psig):	
4. Has one or more Direct Assessment been conducted on the pipeline	
segment?	
- If Yes, and an investigative dig was conducted at the point of the Inc	ident:
Most recent year conducted:	
- If Yes, but the point of the Incident was not identified as a dig site:	
Most recent vear conducted:	
5 Has one or more non-destructive examination been conducted at the	
point of the Incident since January 1, 2002?	
5a. If Ves. for each examination conducted since January 1, 2002, se	lect type of non-destructive examination and indicate most
5a. If fes, for each examination conducted since January 1, 2002, se	lect type of non-destructive examination and indicate most
Pediamentu	
- Radiography	
Year:	
- Guided Wave Ultrasonic	
Year:	
- Handheld Ultrasonic Tool	
Year:	
- Wet Magnetic Particle Test	
Year:	
- Dry Magnetic Particle Test	
Voor:	
Othor	
- Ottlei	
rear:	
Describe:	
Complete the following if Excavation Damage by Third Party is select	ed as the sub-cause.
6 Did the operator get prior polification of the excavation activity?	
62. If Ves. Notification received from (select all that apply):	
One Cell System	
- Contractor	
- Landowner	
Complete the following mandatory CGA-DIRT Program questions if any	Excavation Damage sub-cause is selected.
7 Do you want PHMSA to upload the following information to CGA-	
DIRT (www.cga-dirt.com)?	
8 Right-of-Way where event occurred (select all that apply)	
o. Right-of-way where event occurred (select all that apply).	
- PUDIIC	
- If Public, Specify:	
- Private	
- If Private, Specify:	
- Pipeline Property/Easement	
- Power/Transmission Line	
- Railroad	
- Dedicated Public Utility Easement	
- Federal Land	
- Data not collected	
- Unknown/Other	
9. Type of excavator :	
10. Type of excavation equipment :	
11. Type of work performed :	
1.12. Was the One-Call Center notified? - Yes - No	

12a. If Yes, specify ticket number:			
12b. If this is a State where more than a single One-Call Center			
exists, list the name of the One-Call Center notified:			
13. Type of Locator:			
14. Were facility locate marks visible in the area of excavation?			
15. Were facilities marked correctly?			
16. Did the damage cause an interruption in service?			
16a. If Yes, specify duration of the interruption: (hours)			
17. Description of the CGA-DIRT Root Cause (select only the one predo	ninant first level CGA-DIRT Root Cause and then, where		
Predominant first level CGA-DIRT Root Cause:			
If One Call Natification Practices Not Sufficient Specify:			
If Locating Practices Not Sufficient, Specify.			
If Excavation Practices Not Sufficient, Specify:			
- II Excavation Fractices Not Sumclent, Specify.			
G4 - Other Outside Force Damage - only one sub-cause can be selected from the shaded left-hand column			
Other Outside Force Damage – Sub-Cause:			
- If Damage by Car, Truck, or Other Motorized Vehicle/Equipment NO	T Engaged in Excavation:		
1. Vehicle/Equipment operated by:			
- If Damage by Boats, Barges, Drilling Rigs, or Other Maritime Equipn Their Mooring:	nent or Vessels Set Adrift or Which Have Otherwise Lost		
2. Select one or more of the following IF an extreme weather event was a	factor:		
- Hurricane			
- Tropical Storm			
- Tornado			
- Heavy Rains/Flood			
- Other			
- If Other, Describe:			
- If Previous Mechanical Damage NOT Related to Excavation: Comple	ete Questions 3-7 ONLY IF the "Item Involved in Incident"		
(from PART C, Question 3) is Pipe or Weld.			
3. Has one or more internal inspection tool collected data at the point of			
the Incident?			
3a. If Yes, for each tool used, select type of internal inspection tool and the select type of internal inspection tool and the select type of internal inspection.	nd indicate most recent year run:		
- Magnetic Flux Leakage			
Most recent year run:			
- Ultrasonic			
Most recent year run:			
- Geometry			
Most recent year run:			
Coliner			
Most recent year run:			
- Crack			
Most recent year run:			
- Hard Spot			
Most recent year run:			
- Combination Tool			
Most recent your run:			
Trancyorco Field/Triaxial			
- Transverse Field/Triaxial			
- Transverse Field/Triaxial Most recent year run:			
- Transverse Field/Triaxial Most recent year run: - Other:			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run:			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe:			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained?			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 5. Has one or more hydrotest or other pressure test been conducted			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 5. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Incident?			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 5. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Incident? - If Yes:			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 5. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Incident? - If Yes: Most recent year tested:			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 5. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Incident? - If Yes: Most recent year tested: Test pressure (psig):			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 5. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Incident? - If Yes: Most recent year tested: Test pressure (psig): 6. Has one or more Direct Assessment been conducted on the pipeline			
- Transverse Field/Triaxial Most recent year run: - Other: Most recent year run: Describe: 4. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? 5. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Incident? - If Yes: Most recent year tested: Test pressure (psig): 6. Has one or more Direct Assessment been conducted on the pipeline segment?			

Most recent	year conducted:			
- If Yes, but the point of the Incident was not identified as a dig site:				
Most recent vear conducted:				
7. Has one or more non-destructive examination been conducted at the point of the Incident since January 1, 2002?				
7a. If Yes, for each examination conducted since	e January 1, 2002, se	elect type of non-destructive examination and indicate most		
recent year the examination was conducted:	-			
- Radiography				
Most recent year conducted:				
- Guided Wave Ultrasonic				
Most recent vear conducted:				
- Handheld Ultrasonic Tool				
Most recent vear conducted:				
- Wet Magnetic Particle Test				
Most recent year conducted				
- Dry Magnetic Particle Test	,			
Most recent	vear conducted:			
- Other	your conductod.			
Most recent y	vear conducted:			
	Describe:			
- If Intentional Damage:				
8 Specify	1			
- Opeeny.	If Other Describe:			
- If Other Outside Force Damage:				
9. Describe:				
G5 - Pipe, Weld, or Joint Failure	Use this section to Incident" (from PA	o report material failures ONLY IF the "Item Involved in RT C, Question 3) is "Pipe" or "Weld."		
	Only one sub-cause can be selected from the shaded left-hand column			
Pipe, Weld or Join Failure – Sub-Cause:		Construction-, Installation-, or Fabrication-related		
1. The sub-cause shown above is based on the follow	ving (select all that a	oply):		
- Field Examination		Yes		
Determined by Metallurgical Analysis		Yes		
- Other Analysis				
- If "Other Analysis", Describe - Sub-cause is Tentative or Suspected; Still Under Investigation				
(Supplemental Report required)				
- If Construction-, Installation- or Fabrication				
2. List contributing factors: (select all that apply)				
	Specifi <i>u</i> :			
	If Other Describe:			
- Mechanical Stress	n other, beschbe.	Yes		
- Other				
-	If Other, Describe:			
- If Environmental Cracking-related:	,			
3. Specify:				
	If Other, Descr be:			
Complete the following if any Material Failure of Pipe or Weld sub-cause is selected.				
4. Additional Factors (select all that apply):				
- Dent				
- Gouge				
- Pipe Bend		Yes		
- Arc Burn		Vac		
- UIBUK				
- Lack OF FUSION - Lamination				
- Buckle	- Lamination - Ruckle			
- Wrinkle				
- Misalignment				
- Burnt Steel				
- Other				
	If Other, Descr be:			
5. Has one or more internal inspection tool collected data at the point of Ye		Yes		

the Incident?	
5a. If Yes, for each tool used, select type of internal inspection tool a	nd indicate most recent year run:
- Magnetic Flux Leakage	Yes
Most recent vear run:	2004
- Ultrasonic	
Most recent year run:	
- Geometry	Yes
Most recent year run:	2004
- Caliper	
Most recent year run:	
- Crack	
Most recent year run:	
- Hard Spot	
- Tiald Spot	
Most recent year fun.	
Most recent year run:	
- Transverse Field/Triaxial	
Most recent year run:	
- Other	
Most recent year run:	
Describe:	
6. Has one or more hydrotest or other pressure test been conducted since	Yes
original construction at the point of the incident?	
- If Yes:	1000
Most recent year tested:	1969
Test pressure (psig):	1,054.00
7. Has one of more Direct Assessment been conducted on the pipeline	No
If Voc. and an invoctigative dig was conducted at the point of the Incid	ont:
- If res, and an investigative dig was conducted at the point of the inclu	
If Yes, but the point of the Insident was not identified as a dia site:	
- If res, but the point of the incident was not identified as a dig site.	
With the analog of more non-destructive exemination/a) have conducted at	
the point of the Incident since January 1 20022	No
8a If Ves for each examination conducted since January 1, 2002 se	lect type of pop-destructive examination and indicate most
recent year the examination was conducted.	side type of non destructive examination and indicate most
- Radiography	
Most recent year conducted:	
Cuided Weye Litropopie	
- Guided Wave Oilrasonic	
Most recent year conducted:	
- Handheld Ultrasonic Tool	
Most recent year conducted:	
- Wet Magnetic Particle Test	
Most recent year conducted:	
- Dry Magnetic Particle Test	
Most recent year conducted:	
Widst Tecenit year conducted.	
- Other	
Nost recent year conducted:	
Descr be:	
G6 - Equipment Failure - only one sub-cause can be selected from	the shaded left-hand column
Equipment Failure – Sub-Cause:	
- If Malfunction of Control/Relief Equipment:	
1. Specify:	
- Communications	
- Uneck valve	
- Keller Valve	
- Power Failure	

- Stopple/Control Fitting			
- Pressure Regulator			
ESD System Egiluro			
- ESD System Failule			
- Other Describe			
- If Other, Describe:			
- If Compressor or Compressor-related Equipment:			
2. Specify:			
- If Other, Describe:			
- If Threaded Connection/Coupling Failure:			
3 Specify			
- If Other Describe			
- If Non-throaded Connection Failure:			
A Crestly			
4. Specity:			
- If Other, Describe:			
- If Other Equipment Failure:			
5. Describe:			
Complete the following if any Equipment Failure sub-cause is selected			
6. Additional factors that contributed to the equipment failure (select all the	at apply)		
- Excessive vibration			
- Overpressunzation			
 No support or loss of support 			
- Manufacturing defect			
- Loss of electricity			
- Mismatched items (different manufacturer for tubing and tubing			
fittings)			
- Dissimilar metals			
- Breakdown of soft goods due to compatibility issues with			
transported gas/fluid			
- Valve vault or valve can contributed to the release			
- Alarm/status failure			
- Misalignment			
- Thermal stress			
Othor			
- Other Describer			
- II Otilei, Describe.			
G7 - Incorrect Operation - only one sub-cause can be selected from	the shaded left-hand column		
Incorrect Operation – Sub-Cause:			
- If Underground Gas Storage, Pressure Vessel, or Cavern Allowed o	r Caused to Overpressure:		
1. Specify			
- If Other Describe:			
If Other Incorrect Operation:			
- Il Other Incorrect Operation.			
Z. Describe:			
Complete the following if any Incorrect Operation sub-cause is selecte	d.		
3. Was this Incident related to: (select all that apply)			
- Inadequate procedure			
- No procedure established			
- Failure to follow procedure			
- Other:			
- Ouler:			
- II Otilei, Describe.			
4. What category type was the activity that caused the incident.			
5. was the task(s) that led to the incident identified as a covered task in			
your Operator Qualification Program?			
the task(s)?			
G8 - Other Incident Cause - only one sub-cause can be selected from the shaded left-hand column			
Other Incident Cause – Sub-Cause:			
K Minnellen ener			
1. Describe:			
- If Linknown:			

2. Specify:

PART - H NARRATIVE DESCRIPTION OF THE INCIDENT

On March 1, 2011, Tennessee Gas Pipeline (TGP) Company personnel arrived to begin their work day at Compressor Station 209 near Cumberland, Ohio, and noticed an audible sound like releasing gas just northeast of the station yard. Upon investigation, the point of the release was found in TGP's 26" 200-1 pipeline. Isolation valves were closed and the section of pipe was depressurized. There was no associated fire or explosion. A root cause analysis has determined the cause to be the failure of a girth weld in the form of a crack that originated at internal undercutting at the toe of the girth weld root pass and extending through the weld metal of the weld, also assisted by tensile axial stresses due to thermal stress at the low ambient temperature with no gas flow and bending stress at the sag bend.. The crack was likely produced during the initial welding process and ran from the 9 o'clock position to the 3 o'clock position around the pipe. The deficient weld was removed, new pipe installed, and the section has been placed back into service. Year of pipe manufacture is assumed to be commensurate with year of installation

2/10/2015 - Part C - Type of incident changed from "Leak" to "Rupture".

3/27/2015 - Part E - Updated MAOP determination method to 192.619(a)(3).

7/20/2015 - Part A - Local time of incident revised from time of determination at 8:00 to time that TGP personnel heard hissing at 7:15 am. Time of telephonic report to the NRC revised from 9:15 to 10:12. Both revisions based upon input from PHMSA.

PART I - PREPARER AND AUTHORIZED SIGNATURE

Preparer's Name	Merlin Moseman
Preparer's Title	Engineer - Pipeline
Preparer's Telephone Number	7134204614
Preparer's E-mail Address	merlin moseman@kindermorgan.com
Preparer's Facsimile Number	
Authorized Signature Title	Engineer - Pipeline
Authorized Signature Telephone Number	7134204614
Authorized Signature Email	merlin moseman@kindermorgan.com
Date	07/20/2015

Appendix D

Metallurgical Analysis

This document is on file at PHMSA

Appendix E

Root Cause Analysis

This document is on file at PHMSA