

Failure Investigation Report – Columbia Gas Transmission Rupture – Activity ID 122980

Principal Investigator Dave McMillan, PHMSA ER
Regional Director Byron Coy
Date of Report 2/18/2011
Subject Failure Investigation Report – Columbia Gas
Transmission Pipeline Rupture

Summary:

On November 5, 2008, at approximately 2:10 p.m., Columbia Line 1278 failed near Milford, PA, during an uprating procedure to increase the pressure in the line from a reduced 800 psig operating pressure back to the original 1000 psig MAOP of the pipeline. Columbia had recently been given authorization by PHMSA to increase the pressure in the pipeline back to the original MAOP after demonstrating that the integrity of the pipeline was adequate. The pipeline failure resulted in a rupture that involved three lengths of pipe in a wetland area. The failure occurred in the northern portion of the pipeline between Weber Road, Pike County, PA and Millrift, PA, 46 miles from the upstream compressor station at Easton, PA.

Pressure in the pipeline had been increased from 800 psig to 1000 psig in 50 psig increments. The operator then began to reduce the pressure, and at 986 psig the pipeline failed. There were no injuries. There was no ignition of gas. Valves were shut in both directions. No customers had service interrupted as a result of the pipeline failure. The failure occurred in a rural area.

After the failed section was isolated, Columbia began its investigation of the incident and its remediation to restore the line to service. Columbia installed 510 feet of new 14-inch, coated, steel pipeline in the wetland area to replace the pipe that failed. On December 6, 2008, service was restored in the pipeline.

The failed section of pipe separated into four pieces. These pieces along with several other segment of the pipeline were visually examined and analyzed by Kiefner and Associates, Inc. The lab tests results indicated that the failure was caused by near-neutral-pH stress corrosion cracking (SCC). This has been noted in the company reported apparent cause in Part G of Appendix 3.

Columbia pipeline 1278 runs from the Maryland/Pennsylvania state border to the Pennsylvania/NewYork state border. The pipeline was constructed in 1948. Over several years beginning in 2002, the pipeline went through a rehabilitation and replacement project due to a Corrective Action Order issued by the Department of Transportation due to a previous incident with the pipeline and the discovery of extensive external corrosion. The CAO required that the pressure in the pipeline be reduced from its original MAOP of 1000 psig to 600. The pressure was subsequently approved by PHMSA to be increased to 800 psig based on the findings of an inspection of the pipeline using an in-line inspection device.

Failure Investigation Report – Columbia Gas Transmission Rupture – Activity ID 122980

Operator, Location, & Consequences

Date & Time of Failure:	11/5/2008
Commodity Released:	Natural Gas
City/County & State:	Milford Township, PA
OpID & Operator Name	2616 Columbia Gas Transmission Corporation
Unit # & Unit Name	2901 Easton Field Office-PA
SMART Activity #:	122980
Milepost / Location	½ mile at the intersection North of I84 and Route 6 Lat: 41.33269870 Long: 74.84080223
Type of Failure:	Rupture
Fatalities:	0
Injuries	0
Description of area impacted	Rural
Property damage	Gas loss \$164,000 Property Damage \$1,685,692

Failure Investigation Report – Columbia Gas Transmission Rupture – Activity ID 122980

System Details

The Line 1278 System traverses the eastern counties of Pennsylvania beginning in Lancaster County and ending in Pike County. The Line 1278 system totals 146.5 miles, consisting of 14" and 20" pipe. Gas flow is predominantly south to north.

Events Leading up to the Failure

Over several years beginning in 2002, the pipeline went through a rehabilitation and replacement project due to a Corrective Action Order issued by the Department of Transportation due to a previous incident with the pipeline and the discovery of extensive external corrosion. The CAO required that the pressure in the pipeline be reduced from its original MAOP of 1000 psig to 600. The pressure was subsequently approved by PHMSA to be increased to 800 psig based on the findings of an inspection of the pipeline using an in-line inspection device. On November 5, 2008, at approximately 2:10 p.m., Columbia Line 1278 failed near Milford, PA, during an uprating procedure to increase the pressure in the line from a reduced 800 psig operating pressure back to the original 1000 psig MAOP of the pipeline.

Emergency Response

Time	Event
11:45 AM, 11/04/08	Began leak patrols of pipeline segment, with a total of four patrols at 800, 850, 900, and 950 psig.
4:10 PM, 11/04/08	Attained 950 psig increment with pressure held overnight.
10:30 AM, 11/05/08	Began leak patrol of pipeline segment
1:58 PM	Telemetry Record Rupture
2:14 PM	Gas Controller notices pressure drop on SCADA
2:15 PM	Smith dispatched to Weber Road facility
2:19 PM	Weitzel contacted by Gas Control
2:23 PM	Palmer returns call to Gas Control and reports personnel are responding
2:40 PM	Telemetry indicates closure of Milford mainline valve
3:37 PM	Compliance & Technical Training; incident reported to NRC (Report No. 889241).
3:48 PM	Telemetry indicates closure of Weber Road mainline valve (launcher)
4:06 PM	Palmer reports to Gas Control the site is secure and reports rupture location
5:45 PM	Personnel leave the rupture site for the night
6:00 PM	Gas Control conducts conference call to review events and status
5:45 AM, 11/06/08	Burnley arrives at site to preserve evidence and begin preliminary investigative process pending arrival of Federal and third party investigators.

Note: **Investigative process and repair activities continued 12 hours per day through to 11/24/08.**

Summary of initial start-up plan and return-to-service, including preliminary safety measures

Columbia installed 510 feet of new 14-inch, coated, steel pipeline in the wetland area to replace the pipe that failed. On December 6, 2008, service was restored in the pipeline.

Investigation Findings & Contributing Factors

The failed section of pipe separated into four pieces. These pieces along with several other segment of the pipeline were visually examined and analyzed by Kiefner and Associates, Inc. The lab tests results indicated that the failure was caused by near-neutral-pH stress corrosion cracking (SCC). This has been noted in the company reported apparent cause in Part G of Appendix 3.

Appendices

- | | |
|----------|-------------------------|
| 1 | Photo Documentation |
| 2 | NRC Report |
| 3 | CGT Incident Report |
| 4 | CGT Pressure Test Chart |
| 5 | CGT Rupture Map |
| 6 | Line 1278 and Line K |

Pipeline Failure Investigation Report



Figure 1: Severed 14.9 foot section of pipeline



Figure 2: Severed 37.1 foot section of pipeline

Pipeline Failure Investigation Report



Figure 3: Severed 9 foot section of pipeline



Figure 4: Severed 4.7 foot section of pipeline, piece 4

Pipeline Failure Investigation Report



Figure 5: End of severed 37.1 foot section of pipeline



Figure 6: End of 21.7 foot section of pipe in swamp

Pipeline Failure Investigation Report



Figure 7: Bent 21.7 foot section of pipe in swamp



Figure 8: Ruptured pipe in swamp

Pipeline Failure Investigation Report



Figure 9: Piece 4 exhibiting corrosion

NATIONAL RESPONSE CENTER 1-800-424-8802
 *** For Public Use ***
 Information released to a third party shall comply with any applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 889241

INCIDENT DESCRIPTION

*Report taken at 15:46 on 05-NOV-08
 Incident Type: PIPELINE
 Incident Cause: UNKNOWN
 Affected Area:
 The incident occurred on 05-NOV-08 at 14:10 local time.
 Affected Medium: AIR ATMOSPHERE

SUSPECTED RESPONSIBLE PARTY

Organization: COLUMBIA GAS TRANSMISSION
 CHARLESTON, WV 25314

 Type of Organization: PRIVATE ENTERPRISE

INCIDENT LOCATION

RT. 6 AND INTERSTATE I-84 County: PIKE
 State: PA

 Section: N/A Township: N/A Range: N/A

RELEASED MATERIAL(S)

CHRIS Code: ONG Official Material Name: NATURAL GAS
 Also Known As:
 Qty Released: 0 UNKNOWN AMOUNT

DESCRIPTION OF INCIDENT

THE CALLER STATED THAT A PIPELINE (#1278) WAS IN THE PROCESS RAISING THE PSI AND A LEAK WAS DETECTED CAUSING A FIRE TO SHOOT UP FROM THE PIPELINE. NO INJURIES OR FATALITIES HAVE BEEN REPORTED. THE FIRE HAS BEEN EXTINGUISHED AND THE VALVES WERE SHUT OFF SECURING THE RELEASE. NO CUSTOMER SERVICE WAS LOST IN THE INCIDENT. THE CAUSE OF THE LEAK IS STILL UNDER INVESTIGATION.

INCIDENT DETAILS

Pipeline Type: TRANSMISSION
 DOT Regulated: YES
 Pipeline Above/Below Ground: ABOVE
 Exposed or Under Water: NO
 Pipeline Covered: UNKNOWN

DAMAGES

Fire Involved: YES	Fire Extinguished: YES		
INJURIES: NO	Hospitalized:	Empl/Crew:	Passenger:
FATALITIES: NO	Empl/Crew:	Passenger:	Occupant:
EVACUATIONS: NO	Who Evacuated:	Radius/Area:	
Damages: NO			

<u>Closure Type</u>	<u>Description of Closure</u>	<u>Length of Closure</u>	<u>Direction of Closure</u>
Air:	N		
Road:	N		Major Artery: N
Waterway:	N		
Track:	N		

Passengers Transferred: NO
Environmental Impact: NO
Media Interest: NONE Community Impact due to Material:

REMEDIAL ACTIONS

RELEASE SECURED, FIRE EXTINGUISHED WHEN VALVE WAS CLOSED
Release Secured: YES
Release Rate:
Estimated Release Duration:

WEATHER

Weather: PARTLY CLOUDY, °F Wind speed: 5 MPH

ADDITIONAL AGENCIES NOTIFIED

Federal: NONE
State/Local: FIRE, POLICE
State/Local On Scene: FIRE, POLICE
State Agency Number: NONE

NOTIFICATIONS BY NRC

ATLANTIC STRIKE TEAM (MAIN OFFICE)
05-NOV-08 15:54
USCG ICC (ICC ONI)
05-NOV-08 15:54
DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE)
05-NOV-08 15:54
U.S. EPA III (MAIN OFFICE)
05-NOV-08 15:56
FLD INTEL SUPPORT TEAM PHILADELPHIA (MAIN OFFICE)
05-NOV-08 15:54
USCG COMMAND CENTER (MAIN OFFICE)
05-NOV-08 15:55
NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE)
05-NOV-08 15:54
NJ STATE POLICE (MARINE SERVICES BUREAU)
05-NOV-08 15:54
NOAA RPTS FOR PA (MAIN OFFICE)
05-NOV-08 15:54
NATIONAL RESPONSE CENTER HQ (MAIN OFFICE)
05-NOV-08 15:55
BUREAU TOXIC SUBSTANCE R. WILBURN (MAIN OFFICE)
05-NOV-08 15:54
NJ DEP POC: DUTY OFFICER (MAIN OFFICE)
05-NOV-08 15:54
PA EMERG MGMT AGCY (MAIN OFFICE)
05-NOV-08 15:54

ADDITIONAL INFORMATION

THE CALLER HAD NO ADDITIONAL INFORMATION.

*** END INCIDENT REPORT # 889241 ***

122980 Appendix 3 Incident Report

NOTICE: This report is required by 49 CFR Part 191. Failure to report can result in a civil penalty not to exceed \$25,000 for each violation for each day that such violation persists except that the maximum civil penalty shall not exceed \$500,000 as provided in 49 USC 1678. Form Approved OMB No. 2137-0522



INCIDENT REPORT - GAS TRANSMISSION AND GATHERING SYSTEMS

Report Date _____
 No. _____
 (DOT Use Only)

INSTRUCTIONS

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the Office Of Pipeline Safety Web Page at <http://ops.dot.gov>.

PART A – GENERAL REPORT INFORMATION

Check one or more boxes as appropriate:

Operator Name and Address	Original Report	Supplemental Report	Final Report
a. Operator's 5-digit Identification Number (when known) / _____ /			
b. If Operator does not own the pipeline, enter Owner's 5-digit Identification Number (when known) / _____ /			
c. Name of Operator _____			
d. Operator street address _____			
e. Operator address _____			
City, County or Parrish, State and Zip Code			

<p>2. Time and date of the incident</p> <p>_____ / _____ / _____ / _____ hr. month day year</p> <p>3. Location of incident</p> <p>a. _____ Nearest street or road</p> <p>b. _____ City and County or Parrish</p> <p>c. _____ State and Zip Code</p> <p>d. Mile Post/Valve Station _____</p> <p>e. Survey Station No. _____</p> <p>f. Latitude: _____ Longitude: _____ (if not available, see instructions for how to provide specific location)</p> <p>g. Class location description</p> <p>Onshore: Class 1 Class 2 Class 3 Class 4</p> <p>Offshore: Class 1 (complete rest of this item)</p> <p>Area _____ Block # _____</p> <p>State / _____ / or Outer Continental Shelf</p> <p>h. Incident on Federal Land other than Outer Continental Shelf Yes No</p> <p>i. Is pipeline Interstate Yes No</p> <p>4. Type of leak or rupture</p> <p>Leak: Pinhole Connection Failure (complete sec. F5) Puncture, diameter (inches) _____</p> <p>Rupture: Circumferential – Separation Longitudinal – Tear/Crack, length (inches) _____ Propagation Length, total, both sides (feet) _____</p> <p>N/A Other: _____</p>	<p>5. Consequences (check and complete all that apply)</p> <p>a. Fatality Total number of people: _____ / Employees: _____ / General Public: _____ / Non-employee Contractors: _____ /</p> <p>b. Injury requiring inpatient hospitalization Total number of people: _____ / Employees: _____ / General Public: _____ / Non-employee Contractors: _____ /</p> <p>c. Property damage/loss (estimated) Total \$ _____ Gas loss \$ _____ Operator damage \$ _____ Public/private property damage \$ _____</p> <p>d. Release Occurred in a 'High Consequence Area'</p> <p>e. Gas ignited – No explosion f. Explosion</p> <p>g. Evacuation (general public only) _____ / people Reason for Evacuation: Emergency worker or public official ordered, precautionary Threat to the public Company policy</p> <p>6. Elapsed time until area was made safe: _____ / hr. _____ / min.</p> <p>7. Telephone Report _____ / _____ / _____ / _____ / NRC Report Number month day year</p> <p>8. a. Estimated pressure at point and time of incident: _____ PSIG</p> <p>b. Max. allowable operating pressure (MAOP): _____ PSIG</p> <p>c. MAOP established by 49 CFR section: 192.619 (a)(1) 192.619 (a)(2) 192.619 (a)(3) 192.619 (a)(4) 192.619 (c)</p> <p>d. Did an overpressurization occur relating to the incident? Yes No</p>
---	--

PART B – PREPARER AND AUTHORIZED SIGNATURE

(type or print) Preparer's Name and Title	_____
	Area Code and Telephone Number
Preparer's E-mail Address	_____
	Area Code and Facsimile Number
Authorized Signature	_____
(type or print) Name and Title	_____
Date	_____
	Area Code and Telephone Number

F5 – MATERIAL AND WELDS

Material

- 14. Body of Pipe => Dent Gouge Wrinkle Bend Arc Burn Other: _____
- 15. Component => Valve Fitting Vessel Extruded Outlet Other: _____
- 16. Joint => Gasket O-Ring Threads Other: _____

Weld

- 17. Butt => Pipe Fabrication Other: _____
- 18. Fillet => Branch Hot Tap Fitting Repair Sleeve Other: _____
- 19. Pipe Seam => LF ERW DSAW Seamless Flash Weld Other: _____
 HF ERW SAW Spiral Other: _____

Complete a-g if you indicate **any** cause in part F5.



a. Type of failure:

- Construction Defect => Poor Workmanship Procedure not followed Poor Construction Procedures
- Material Defect

b. Was failure due to pipe damage sustained in transportation to the construction or fabrication site? Yes No

c. Was part which leaked pressure tested before incident occurred? Yes, complete d-g No

d. Date of test: / / mo. / / day / / yr.

e. Test medium: Water Natural Gas Inert Gas Other: _____

f. Time held at test pressure: / / hr.

g. Estimated test pressure at point of incident: _____ PSIG

F6 – EQUIPMENT AND OPERATIONS

- 20. Malfunction of Control/Relief Equipment => Valve Instrumentation Pressure Regulator Other: _____
- 21. Threads Stripped, Broken Pipe Coupling => Nipples Valve Threads Mechanical Couplings Other: _____
- 22. Ruptured or Leaking Seal/Pump Packing

23. Incorrect Operation

a. Type: Inadequate Procedures Inadequate Safety Practices Failure to Follow Procedures Other: _____

b. Number of employees involved who failed post-incident drug test: / / Alcohol test: / /


c. Were most senior employee(s) involved qualified? Yes No d. Hours on duty: / /

F7 – OTHER


- 24. Miscellaneous, describe: _____
- 25. Unknown
 Investigation Complete Still Under Investigation (submit a supplemental report when investigation is complete)

PART G – NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTING TO THE EVENT (Attach additional sheets as necessary)


122980 Appendix 4 Columbia Pipeline Pressure test Graph



122980 Appendix 5 - Columbia Gas Line 1278 Rupture map



Columbia Gas Transmission Line 1278 and Line K 02/09/2011



MP 7339+85 - 11/05/2008
Failure Location in Pike Co.
MP 7338+17 - 7343+27
replaced 510 ft with 14" pipe

Sparrowbush
CS

Section A

Section C

Section B

Hellertown CS

Easton CS

Milford CS

Line K

Line 1278

Quakertown

Bangor

Stroudsburg

Bushkill

Weber Road

Millrift
PA-NY State Line

Not Included in CAO

Replaced approximately 11 miles 14" pipe with 14" coated pipe

Replaced approximately 42 miles of 14" pipe with 20" coated pipe

"CGT Anticipates construction to replace this section starting in May 2011 and ending in September 2011. NGT&S commits to maintaining the operating pressure at a restricted level of 800 psig, as established by the CAO, from Weber Road in PA to the Sparrowbush Compressor Station in NY. This section contains the remaining 14" bare pipe along Lines 1278 and Line K. NGT&S commits to replace the remaining bare pipe in PA; approximately 12 miles." According to Columbia letter dated November 30, 2010.

CAO Section A Quakertown M&R Station to the Hellertown M&R Station

CAO Section B Easton Compressor Station to the Delaware River Crossing at the PA-NY State Line

CAO Section C All Uncoated Segments from Quakertown to Hellertown and from Easton to the PA-NY State Line

CPF# 1-2002-1004H