

**Failure Investigation Report – Columbia Seneca Compressor Gas Venting – Activity ID 128518**

**Principal Investigator** David Hippchen WV PSC  
**Regional Director** Byron Coy  
**Date of Report** 03/03/2011  
**Subject** Failure Investigation Report – Columbia Seneca  
Compressor Gas Venting

**Summary:**

Early on the morning of April 4, 2009, the grid power to the Seneca Compressor Station was momentarily interrupted. The loss of power caused two electrically driven air compressors that supplied instrument and safety system air to a new compressor building to drop off line and stay off line until manually reset. The station was unmanned at the time, and no personnel were available to reset the power. The air pressure continued to drop until the lack of balancing pressure triggered a building shutdown for Units 5 & 6. The building shutdown system vented gas at three locations, but the block valves did not isolate the building from working line pressure. Gas continued to vent until about 7:40 AM, when Columbia Gas personnel arrived at the station

**Operator, Location, & Consequences**

**Date & Time of Failure:** April 4, 2009, 5:00 AM  
**Commodity Released:** Natural Gas  
**City/County & State:** Seneca Rocks, Pendleton County, WV  
**OpID & Operator Name** 2616 Columbia Gas Transmission  
**Unit # & Unit Name** 67791 WB System Seneca Compressor  
**SMART Activity #:** 128518  
**Milepost / Location** Latitude 38.8813  
Longitude: -79.3762  
**Type of Failure:** Gas Venting  
**Fatalities:** 0  
**Injuries** 0  
**Description of area impacted** Rural  
**Property damage / gas loss** \$101,335

**System Details**

Seneca Compressor Station

**Events Leading up to the Failure**

At approximately 2:40 AM on the morning of April 4 the purchased electrical power at Seneca CS dropped off for an instant. One result of this brief power interruption was the loss of the service of the two electric driven air compressors used to supply instrument air pressure to the new compressor equipment. For approximately 2 hours and 20 minutes (from the time of the power interruption until 5:00 AM) the instrument air pressure slowly leaked down from 105 psi to approximately 10 psi at which point the springs in the valve actuators drove the vent valves open.

**Emergency Response**

Columbia Gas personnel responded several hours after the venting started and isolated the system.

**Summary of initial start-up plan and return-to-service, including preliminary safety measures**

The Columbia Gas root cause analysis identified the following improvements that were implemented.

1. Modify the electrical control for the new air compressors to allow the units to remain on during brief power interruption.
2. Enable station alarms to alert Monitoring Center of low air pressure condition.
3. Open valve to allow both safety air systems to work together.
4. Modify electrical control on air systems to interlock block valve / blowdown valve combination.

**Investigation Findings & Contributing Factors**

Five causal factors contributed to this incident.

1. The loss of service of the new air compressors
2. No alarms were sent to the Monitoring Center upon loss of new air compressor service or for low instrument air pressure
3. There was no backup supply of pressurized instrument air to the new facilities
4. The block valves associated with the new building shutdown system were not equipped with spring loaded actuators
5. The building shutdown vent valves were not interlocked with the building shutdown block valves.

**Appendices**

- |   |                               |
|---|-------------------------------|
| 1 | Email Notification 901801     |
| 2 | Incident Report 20090041-7021 |
| 3 | Root Cause Analysis           |
| 4 | NRC Report 901801             |
| 5 | Map                           |

**Hippchen, David**

---

**From:** dino.rathod@dot.gov  
**Sent:** Monday, April 06, 2009 6:42 AM  
**To:** Hippchen, David  
**Cc:** stephen.gliebe@dot.gov; Mike.Yazemboski@dot.gov  
**Subject:** FW: NRC#901801: Release of natural gas from transmission pipeline in Charleston, WV

I e-mailed you earleir during the weeknd thru my Blackberry. Please review and follow-up. I will appreciate your e-mail update

**Dino N. Rathod, P.E.**  
**State Liaison Rep-Eastern Region**  
**Pipeline & Hazardous Materials Safety Administration**  
**U S Dept of Transportation**  
**Te:202-260-8505 (W)**  
**202-368-5514 (cell)**  
**e-mail: [dino.rathod@dot.gov](mailto:dino.rathod@dot.gov)**

---

**From:** CMC-01 <OST>  
**Sent:** Saturday, April 04, 2009 9:47 AM  
**To:** PHP Accident/Incident Cadre <PHMSA>; PHMSA PHP100 EASTERN  
**Cc:** CMC-01 <OST>; CMC-02 <OST>; Dick Gray; Golas, Gary <OST>; Plummer, Douglas <OST>; Powell, Winslow <OST>; Stuckey, William <OST>  
**Subject:** NRC#901801: Release of natural gas from transmission pipeline in Charleston, WV

What: A caller is reporting that a compressor malfunctioned on a natural gas pipeline causing a release of an unknown quantity of natural gas into the atmosphere.

When: Charleston, WV

Where: 04-APR-09 at 07:30 local incident time

---

NATIONAL RESPONSE CENTER 1-800-424-8802  
 \*\*\*GOVERNMENT USE ONLY\*\*\*GOVERNMENT USE ONLY\*\*\*  
 Information released to a third party shall comply with any applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 901801

INCIDENT DESCRIPTION

\*Report taken by: E4 NICHOLAS PROCKO at 08:58 on 04-APR-09  
 Incident Type: PIPELINE  
 Incident Cause: EQUIPMENT FAILURE  
 Affected Area:  
 Incident was discovered on 04-APR-09 at 07:30 local incident time.  
 Affected Medium: AIR INTO THE ATMOSPHERE

## 128518 Appendix 1 - Email Notification 901801

## REPORTING PARTY

Name: MARY FRIEND  
 Organization: COLUMBIA GULF TRANSMISSION  
 Address: 1700 MACORKLE AVE  
 CHARLESTON, WV  
 COLUMBIA GULF TRANSMISSION reported for the responsible party.  
 PRIMARY Phone: (304)3895222  
 Type of Organization: PRIVATE ENTERPRISE

## SUSPECTED RESPONSIBLE PARTY

Name: MARY FRIEND  
 Organization: COLUMBIA GULF TRANSMISSION  
 Address: 1700 MACORKLE AVE  
 CHARLESTON, WV  
 PRIMARY Phone: (304)3895222

## INCIDENT LOCATION

1700 MACORKLE AVE County: PENDLETON  
 City: CHARLESTON State: WV

## RELEASED MATERIAL(S)

CHRIS Code: ONG Official Material Name: NATURAL GAS  
 Also Known As:  
 Qty Released: 0 UNKNOWN AMOUNT

## DESCRIPTION OF INCIDENT

THE CALLER IS REPORTING THAT A COMPRESSOR MALFUNCTIONED ON A NATURAL GAS PIPELINE CAUSING A RELEASE OF AN UNKNOWN QUANTITY OF NATURAL GAS INTO THE ATMOSPHERE.

## SENSITIVE INFORMATION

## INCIDENT DETAILS

Pipeline Type: TRANSMISSION  
 DOT Regulated: UNKNOWN  
 Pipeline Above/Below Ground: BELOW  
 Exposed or Under Water: NO  
 Pipeline Covered: UNKNOWN

## IMPACT

Fire Involved: NO Fire Extinguished: UNKNOWN

INJURIES: NO	Hospitalized:	Empl/Crew:	Passenger:
FATALITIES: NO	Empl/Crew:	Passenger:	Occupant:
EVACUATIONS:NO	Who Evacuated:	Radius/Area:	

Damages: NO

Closure Type	Description of Closure	Hours Closed	Direction of Closure
Air:	N		
Road:			Major Artery:N

128518 Appendix 1 - Email Notification 901801

N  
Waterway:  
N  
Track:

Environmental Impact: UNKNOWN  
Media Interest: NONE Community Impact due to Material:

---

REMEDIAL ACTIONS

THE STATION WAS SHUT-IN.  
Release Secured: YES  
Release Rate:  
Estimated Release Duration:

---

WEATHER

Weather: CLEAR, °F

---

ADDITIONAL AGENCIES NOTIFIED

Federal: NONE  
State/Local: NONE  
State/Local On Scene: NONE  
State Agency Number: NONE

---

NOTIFICATIONS BY NRC

ATLANTIC STRIKE TEAM (MAIN OFFICE)  
04-APR-09 09:05 (609)7240008  
USCG ICC (ICC ONI)  
04-APR-09 09:05 (301)6693363  
CG INVESTIGATIVE SERVICE BALTIMORE (MAIN OFFICE)  
04-APR-09 09:05 (410)5762555  
INFO FOR CRITICAL MFG SECTOR (MAIN OFFICE)  
04-APR-09 09:05 (703)2353049  
DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE)  
04-APR-09 09:05 (202)3661863  
U.S. EPA III (MAIN OFFICE)  
(215)8149016  
NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE)  
04-APR-09 09:05 (202)2829201  
NOAA RPTS FOR WV (MAIN OFFICE)  
04-APR-09 09:05 (206)5264911  
SECTOR OHIO VALLEY (COMMAND CENTER)  
04-APR-09 09:05 (502)7795422  
VA DEPT EMERGENCY MANANGEMENT (MAIN OFFICE)  
04-APR-09 09:05 (804)6742400  
WEST VIRGINIA DEP (MAIN OFFICE)  
04-APR-09 09:05 (304)5585938  
WV DEP ATTN: DUTY OFFICER (MAIN OFFICE)  
04-APR-09 09:05 (800)6423074  
WV DEP SPILL LINE (MAIN OFFICE)  
04-APR-09 09:05 (304)3683960

---

ADDITIONAL INFORMATION

THE CALLER HAD NO ADDITIONAL INFORMATION.

---

\*\*\* END INCIDENT REPORT #901801 \*\*\*

Report any problems by calling 1-800-424-8802  
PLEASE VISIT OUR WEB SITE AT <http://www.nrc.uscg.mil>

 <p>U.S Department of Transportation Pipeline and Hazardous Materials Safety Administration</p>	<b>INCIDENT REPORT – GAS TRANSMISSION AND GATHERING SYSTEMS</b>	Report Date	April 28, 2009
	Report format corresponds to Form PHMSA F 7100.2 (01-2002)	No.	20090041 - 7021

PART A – GENERAL INFORMATION					
N	Original Report	Y	Supplemental Report	Y	Final Report
<b>1. Operator Name and Address</b>					
a. Operator's 5-digit Identification Number			2616		
b. If Operator does not own the pipeline, enter Owner's 5-digit Identification Number (when known)					
c. Name of Operator			COLUMBIA GAS TRANSMISSION CORP		
d. Operator street address			1700 MACCORKLE AVE SE		
e. Operator address	City		CHARLESTON		
	County or Parish		KANAWHA		
	State		WV		
	Zip code		25314		
<b>2. Time and date of the incident</b>					
	Hour		07:12		
	Date of the incident		4/4/2009		
<b>3. Location of incident</b>					
a. Street or nearest street or road			RT 28		
b. City			SENECA ROCKS		
	County or Parish		PENDLETON		
c. State			WV		
	Zip Code		26884		
d. Mile Post/Valve Station			SENECA COMPRESSOR STATION		
e. Survey Station No					
f. Latitude			38.8813		
	Longitude		-79.3762		
g. Class location description					
	Onshore (Class Location)		1		
	Offshore		N		
	Area				
	Block #				
	State				
	Outer Continental Shelf		N		
	h. Accident on Federal Land other than Outer Continental Shelf		N		
	i. Is pipeline Interstate		Y		
<b>4. Type of leak or rupture</b>					
	Leak or Rupture		OTHER		
	Type of Leak				
	- Puncture, diameter	(inches)			
	Type of Rupture				
	- Tear/Crack, length	(inches)			
	- Propagation Length, total, both sides	(feet)			
	Other (specify)		COMPRESSOR STATION BUILDING BLOW DOWN		
<b>5. Consequences</b>					
a. Fatality			No		
	Total number of people		0		
	Employees		0		
	General Public		0		
	Non-employee Contractors		0		
b. Injury requiring inpatient hospitalization			No		
	Total number of people		0		

**128518 Appendix 2 - Incident Report 20090041-7021**

Employees	0
General Public	0
Non-employee Contractors	0
c. Property damage/loss (estimated)	Yes
Total	\$ 101,335
Gas loss	\$ 101,335
Operator damage	\$ 0
Public/private property damage	\$ 0
d. Release Occurred in a 'High Consequence Area'	N
e. Gas Ignited / Gas did not ignite	Gas did not Ignite
f. Explosion / No Explosion	NO EXPLOSION
g. Evacuation ( <i>general public only</i> )	N
Number of people	0
Evacuation Reason	
<b>6. Elapsed time until area was made safe</b>	
Hours	2
Minutes	40
<b>7. Telephone Report</b>	
NRC Report Number	901801
Date	4/4/2009
<b>8. Pressure</b>	
a. Estimated pressure at point and time of incident (PSIG)	731.00
b. Max. allowable operating pressure (MAOP) (PSIG)	1000.00
c. MAOP established by 49 CFR section	49 CFR 192.619(a)(2)
d. Did an over pressurization occur relating to the incident?	N
<b>PART B – PREPARER AND AUTHORIZED SIGNATURE</b>	
Preparer's Name	MARK NEWMAN
Preparer's Title	
Area Code and Telephone Number	3047228475
Preparer's E-mail Address	MNEWMAN@NISOURCE.COM
Area Code and Facsimile Number	3047228420
<b>PART C – ORIGIN OF THE INCIDENT</b>	
1. Incident occurred on	TRANSMISSION
2. Failure occurred on	OTHER
Other (specify)	LOST ELECTRICAL POWER
3. Material involved ( <i>pipe, fitting, or other component</i> )	STEEL
Plastic failure was	
a. ductile	N
b. brittle	N
c. joint failure	N
Material other than plastic or steel	
4. Part of the system involved in incident	COMPRESSOR
Other (specify)	
5. Year the pipe or component which failed was installed	2008
<b>PART D – MATERIAL SPECIFICATION</b>	
1. Nominal pipe size (NPS) (inches)	
2. Wall thickness inches	
3. Specification	SMYS
4. Seam type	
5. Valve type	
6. Pipe or valve manufactured by	
in year	
<b>PART E - ENVIRONMENT</b>	
1. Area of incident	OTHER
Other (specify)	COMPRESSOR STATION

**128518 Appendix 2 - Incident Report 20090041-7021**

Depth of cover	(inches)	
<b>PART F – APPARENT CAUSE</b>		
<b>F1 – CORROSION</b>		
1. External Corrosion		
2. Internal Corrosion		
<b>Complete items a-e where applicable</b>		
a. Pipe Coating		
b. Visual Examination		
Other (specify)		
c. Cause of Corrosion		
Other (specify)		
d. Was corroded part of pipeline considered to be under cathodic protection prior to discovering incident?		
Year Protection Started		
e. Was pipe previously damaged in the area of corrosion?		
How long prior to incident?		Years
		Months
<b>F2 – NATURAL FORCES</b>		
3. Earth Movement		
Description		
Other (specify)		
4. Lightning		
5. Heavy Rains/Floods		
Description		
Other (specify)		
6. Temperature		
Description		
Other (specify)		
7. High Winds		
<b>F3 - EXCAVATION</b>		
8. Operator Excavation Damage (including their contractors) / Not Third Party		
9. Third Party Excavation Damage		
a. Excavator group		
b. Type		
Other (specify)		
c. Did operator get prior notification of excavation activity?		
Date received		mo.      day      yr.
Notification received from		
d. Was pipeline marked?		
Temporary markings		
Permanent markings		
Marks were		
Were marks made within required time?		
<b>F4 – OTHER OUTSIDE FORCE DAMAGE</b>		
10. Fire/Explosion as primary cause of failure		
Description		
11. Car, truck or other vehicle not relating to excavation activity damaging pipe		
12. Rupture of Previously Damaged Pipe		
13. Vandalism		
<b>F5 – MATERIAL AND WELDS</b>		
<b>Material</b>		
14. Body of Pipe		
Description		
Other (specify)		
15. Component		
Description		
Other (specify)		

**128518 Appendix 2 - Incident Report 20090041-7021**

16. Joint	
Description	
Other (specify)	
<b>Weld</b>	
17. Butt	
Description	
Other (specify)	
18. Fillet	
Description	
Other (specify)	
19. Pipe Seam	
Description	
Other (specify)	
<b>Complete a-g if you indicate any cause in part F5</b>	
a. Type of failure	
Construction Defect	NO DATA
Description	
Material Defect	NO DATA
b. Was failure due to pipe damage sustained in transportation to the construction or fabrication site?	
c. Was part which leaked pressure tested before incident occurred?	
d. Date of test	
	Month
	Day
	Year
e. Test medium	
Other (specify)	
f. Time held at test pressure	hr
g. Estimated test pressure at point of incident	
	(PSIG)
<b>F6 – EQUIPMENT AND OPERATIONS</b>	
20. Malfunction of Control/Relief Equipment	Yes
Description	OTHER
Other (specify)	COMPRESSOR STATION BUILDING BLOW DOWN
21. Threads Stripped, Broken Pipe Coupling	
Description	
Other (specify)	
22. Ruptured or Leaking Seal/Pump Packing	
23. Incorrect Operation	
a. Type	
Other (specify)	
b. Number of employees involved who failed post-incident test	
Drug test	
Alcohol test	
c. Were most senior employee(s) involved qualified?	
d. Hours on duty	
<b>F7 – OTHER</b>	
24. Miscellaneous	
Description	
25. Unknown	
Description	
<b>PART G – NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTING TO THE EVENT</b>	
<p>DURING THE NIGHT, THE COMMERCIAL POWER TO THE STATION WAS BRIEFLY INTERRUPTED. THE POWER LOSS CAUSED THE AIR COMPRESSORS TO TURN OFF. DUE TO A SLOW LEAK SLOW LEAK, THE PRESSURE FELL ON THE AIR SYSTEM, AT WHICH POINT THE VENT VALVES OPENED, BLOWING DOWN ONE COMPRESSOR BUILDING AND THE ASSOCIATED FUEL GAS SYSTEM. CONTROLS TO AIR COMPRESSOR HAVE BEEN MODIFIED TO ALLOW UNITS TO STAY ON DURING BRIEF INTERRUPTIONS IN ELECTRIC POWER. COLUMBIA'S MONITORING CENTER IS ALSO NOW</p>	

**128518 Appendix 2 - Incident Report 20090041-7021**

ABLE TO MONITOR STATION AIR PRESSURE WHICH IS USED TO ACTIVATE THE STATION ESD SYSTEM.

## Appendix 3 Root Cause Analysis

### Columbia Gas Transmission Root Cause Analysis

This document is on file at PHMSA



Pipeline & Hazardous Materials Safety Administration

(Version 3.4.04 PROD)

HMIS->INCIDENTS->TELEPHONICS

Rules of Behavior

Home

Logout

Menu

[Return to Search]

<< Previous

1..1 of 1

>> Save >>

Rescinded Comments (max 250 characters)

NRC Number: 901801 Call Time: 08:58:59  
Call Date: 04/04/2009

Caller Information

First Name: MARY Last Name: FRIEND  
Company Name: COLUMBIA GULF TRANSMISSION  
Address: 1700 MACORKLE AVE  
City: CHARLESTON State: WV  
Country: USA Zip:   
Phone 1: 3043895222 Phone 2:   
Organization Type: PRIVA Is caller the spiller?  Yes  No  No Response  
Confidential:  Yes  No  No Response

Discharger Information

First Name: MARY Last Name: FRIEND  
Company Name: COLUMBIA GULF TRANSMISSION  
Address: 1700 MACORKLE AVE  
City: CHARLESTON State: WV  
Country: USA Zip:   
Phone 1: 3043895222 Phone 2:   
Organization Type: PRIVA

Spill Information

State: WV County: PENDLETON  
Nearest City: CHARLESTON Zip Code:   
Location: 1700 MACORKLE AVE

Spill Date: 04/04/2009 (mm/dd/yyyy) Spill Time: 07:30:00 (24hh:mm:ss)  
DTG Type: DISCOVERED  
Incident Type: PIPELINE Reported Incident Type: PIPELINE

https://nhmhanwas003/hmis/telenhonics/Teledetail.aspx?showresult=Y&ReceivedDate=&ReceivedDa... 9/27/2010

128518 Appendix 4 - NRC Report 901801

Description

THE CALLER IS REPORTING THAT A COMPRESSOR MALFUNCTIONED ON A NATURAL GAS PIPELINE CAUSING A RELEASE OF AN UNKNOWN QUANTITY OF NATURAL GAS INTO THE ATMOSPHERE.

Materials Involved

Material / Chris Name	Chris Code	Total Qty.	Water Qty.
NATURAL GAS	ONG	0 UNKNOWN AMOUNT	

Medium Type:

AIR

Additional Medium Information:

INTO THE ATMOSPHERE

Injuries:  Fatalities:

Evacuations:  Yes  No  Unknown No. of Evacuations:

Damages:  Yes  No  Unknown Damage Amount:

Federal Agency Notified:  Yes  No  Unknown State Agency Notified:  Yes  No  Unknown

Other Agency Notified:  Yes  No  Unknown

Remedial Actions

THE STATION WAS SHUT-IN.

Additional Info

THE CALLER HAD NO ADDITIONAL INFORMATION.

Latitude

Degrees:  Minutes:  Seconds:  Quadrant:



Longitude

Degrees:  Minutes:  Seconds:  Quadrant:

Distance from City:   Direction:

Section:  Township:

Range:  Milepost:



128518 Appendix 5 - Map

