

# Pipeline Failure Investigation Report

**Pipeline System:** Houstonia 200 Line                      **Operator:** Panhandle Eastern Pipeline Company, LP  
**Location:** Mile Post 21.6                                      **Date of Occurrence:** 8/25/2008  
**Medium Released:** Natural gas                              **Quantity:** 13,518,578 CF

**PHMSA Arrival Time & Date:** 8/25/08 1:00 p.m.                      **Total Damages \$** 1,046,359

**Investigation Responsibility:**     State     PHMSA     NTSB    Other \_\_\_\_\_

**Company Reported Apparent Cause:**     Corrosion                       Excavation  
 Natural Forces                       Incorrect Operation                       Other Outside Force Damage  
 Material and/or Welds                       Equipment and Operations                       Other \_\_\_\_\_

Rupture             Yes     No  
 Leak                 Yes     No  
 Fire                 Yes     No  
 Explosion         Yes     No  
 Evacuation       Yes     No            Number of Persons \_\_\_\_\_ Area \_\_\_\_\_

***Narrative Summary***

Short summary of the Incident/Accident which will give interested persons sufficient information to make them aware of the basic scenario and facts.

Panhandle Eastern Pipeline Company (PEPL) experienced failure of the Houstonia 200 line near Mile Post 21.6. There were no evacuations, road closings, fires, injuries or fatalities as a result of the failure. The failure did not occur in a high consequence area (HCA).

The failure occurred on August 25, 2008, at approximately 8:51 a.m. CDT. The failure is located on a rocky hillside in a rural area west of Pilot Grove, Missouri in Cooper County. The failure was identified by PEPL when Houston Gas Control detected a pressure drop in the Houstonia 200 Line. The failure was located at approximately 9:00 a.m. when a PEPL field technician reported gas blowing near Mile Post 21.6. PEPL isolated the segment at approximately 9:30 a.m., by manually closing mainline valves 2 Gate and 3 Gate. The distance between 2 Gate and 3 Gate is approximately 16 miles.

The pipeline experienced a longitudinal rupture in the pipe body. The rupture created a 50 feet by 33 ft by 7 feet deep crater in the ground. Two pipeline segments totalling 28 feet in length and a coupling were ejected from the crater a distance up to 300 feet from the rupture site. The failure origin was a 16 inch long area of reduced wall thickness located at the 6:00 orientation.

The portion of the pipeline containing the failure is comprised of 24-inch diameter by 0.281-inch wall thickness, API 5L-X48, manufactured by A.O. Smith and contains a longitudinal electric flash welded (EFW) seam. The reported maximum allowable operating pressure (MAOP) is 800 psig, which corresponds to 71% of the specified minimum yield strength (SMYS). The pressure at the time and location of failure was 795 psig, which corresponds to 70% of the SMYS (99% of MAOP). The MAOP was established in accordance with 192.619 ( c ), the highest actual operating pressure to which the segment was subjected during the five years preceding July 1, 1970. A hydrostatic test of the pipeline was performed in 1955. Details of the hydrostatic test are unknown.

The pipeline, installed in 1937, is joined by circumferential girth welds and Dresser couplings. The pipeline external coating is coal tar. The pipeline has an impressed current cathodic protection system that was reportedly energized in 1955.

The findings of PEPL's investigation are as follows:

- 1) The failure occurred due to tensile overload at a region of wall thinning caused by external corrosion.
- 2) The maximum wall loss measured at the rupture surface was 0.21 inches depth (75% of wall thickness).

## Pipeline Failure Investigation Report

PEPL submitted a return to service plan to PHMSA that included a temporary 20% pressure reduction and remediation of anomalies found in a high resolution MFL tool run. They subsequently remediated 30 anomalies with RPR less than 1.15 and replaced 912 feet of pipe. On 12/19/2009 the temporary pressure restriction was removed.

ACTIVITY #: 122653

OPERATOR ID #: 15105

UNIT ID #: 4093

NRC REPORT #: 881717

INCIDENT REPORT # (FORM 7100.2): 20090030 -- 5319

Region/State Central

Reviewed by: David Barrett *original initialed*

Principal Investigator: Roger Sneegas

Title: Director – Central Region

Date: 10/12/2010

Date: 10/13/2010

## Pipeline Failure Investigation Report

<b>Failure Location &amp; Response</b>			
Location (City, Township, Range, County/Parish): Pilot Grove, Missouri			(Acquire Map)
Address or M.P. on Pipeline: 21.6	(1)	Type of Area (Rural, City): Rural	(1)
Date: 8/25/2008	Time of Failure: 8:51 a.m.		
Time Detected: 9:00 a.m.	Time Located: 9:10 a.m.		
How Located: A technician - Jerry Miller - heard the pipeline blowing from the nearest road at about 9:00 a.m. Gas control had previously noted a pressure drop at 8:51 a.m.			
NRC Report #: 881717	(Attach Report)	Time Reported to NRC: 10:15 a.m. on 8/25/2008	Reported by: Liz Rutherford
<b>Type of Pipeline:</b>			
<b>Gas Distribution</b>	<b>Gas Transmission</b>	<b>Hazardous Liquid</b>	<b>LNG</b>
<input type="checkbox"/> LP	<input checked="" type="checkbox"/> Interstate Gas	<input type="checkbox"/> Interstate Liquid	<input type="checkbox"/> LNG Facility
<input type="checkbox"/> Municipal	<input type="checkbox"/> Intrastate Gas	<input type="checkbox"/> Intrastate Liquid	
<input type="checkbox"/> Public Utility	<input type="checkbox"/> Jurisdictional Gas Gathering	<input type="checkbox"/> Offshore Liquid	
<input type="checkbox"/> Master Meter	<input type="checkbox"/> Offshore Gas	<input type="checkbox"/> Jurisdictional Liquid Gathering	
	<input type="checkbox"/> Offshore Gas - High H <sub>2</sub> S	<input type="checkbox"/> CO <sub>2</sub>	
Pipeline Configuration (Regulator Station, Pump Station, Pipeline, etc.): Mainline Houstonia 200			

<b>Operator/Owner Information</b>	
Owner: Panhandle Eastern Pipeline Address: 5444 Westheimer Road Houston TX  Company Official: Eric Amundsen Phone No.: 713-989-7460      Fax No.:	Operator: Panhandle Eastern Pipeline Address: 5444 Westheimer Road Houston TX  Company Official: Eric Amundsen Phone No. 713-989-7460      Fax No.
<u>Drug and Alcohol Testing Program Contacts</u>	
Drug Program Contact & Phone: Brett Laaser Alcohol Program Contact & Phone: 713-989-7549	
<input type="checkbox"/> N/A	

<b>Damages</b>			
Product/Gas Loss or Spill <sup>(2)</sup>	13,518,578 CF	Estimated Property Damage \$	25,000
Amount Recovered	0	Associated Damages <sup>(3)</sup> \$	628,063

- 1 Photo documentation  
 2 Initial volume lost or spilled  
 3 Including cleanup cost

## Pipeline Failure Investigation Report

<i>Damages</i>	
Estimated Amount \$	393,296
Description of Property Damage: The failure caused a crater in the right-of-way measuring about 50 X 33 feet and 7 feet deep. Two segments of pipe (46 feet total) were ejected from the crater.	
Customers out of Service:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No      Number: _____
Suppliers out of Service:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No      Number: _____

<i>Fatalities and Injuries</i>					
Fatalities:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Company: _____	Contractor: _____	Public: _____
Injuries - Hospitalization:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Company: _____	Contractor: _____	Public: _____
Injuries - Non-Hospitalization:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Company: _____	Contractor: _____	Public: _____
Total Injuries (including Non-Hospitalization):			Company: _____	Contractor: _____	Public: _____
Name	Job Function	Yrs w/ Comp.	Yrs. Exp.	Type of Injury	

<i>Drug/Alcohol Testing</i>					<input type="checkbox"/> N/A
Were all employees that could have contributed to the incident, post-accident tested within the 2 hour time frame for alcohol or the 32 hour time frame for all other drugs? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No					
Job Function	Test Date & Time	Location	Results		Type of Drug
			Pos	Neg	
Gas System Controller	8/25/2008	Houston TX	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	

## Pipeline Failure Investigation Report

<i>System Description</i>
Describe the Operator's System: The Houstonia 200 line runs from Liberal KS to Howell MI. It is 24-inch diameter 0.281-inch wall X48 pipe installed in 1937.

<i>Pipe Failure Description</i>	<input type="checkbox"/> N/A
Length of Failure (inches, feet, miles): 46 feet	(1)
Position (Top, Bottom, include position on pipe, 6 O'clock): Bottom 6 O'clock	Description of Failure (Corrosion Gouge, Seam Split): External corrosion.
Laboratory Analysis: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Performed by: CC Technologies Inc.	
Preservation of Failed Section or Component: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
If Yes - Method: Wrapped	
In Custody of: Panhandle	
Develop a sketch of the area including distances from roads, houses, stress inducing factors, pipe configurations, etc. Bar Hole Test Survey Plot should be outlined with concentrations at test points. Direction of Flow.	

<i>Component Failure Description</i>	<input checked="" type="checkbox"/> N/A
Component Failed:	(1)
Manufacturer:	Model:
Pressure Rating:	Size
Other (Breakout Tank, Underground Storage):	

<i>Pipe Data</i>	<input type="checkbox"/> N/A
Material: steel	Wall Thickness/SDR: 0.281- inch
Diameter (O.D.): 24-inch	Installation Date: 1937
SMYS: 48,000	Manufacturer: A. O. Smith
Longitudinal Seam: Electric Flash Weld	Type of Coating: Coal Tar
Pipe Specifications (API 5L, ASTM A53, etc.): API 5L, X48	

<i>Joining</i>	<input type="checkbox"/> N/A
Type: Girth weld with Coupling every other joint	Procedure:
NDT Method: Unknown	Inspected: <input type="checkbox"/> Yes <input type="checkbox"/> No

## Pipeline Failure Investigation Report

<i>Pressure @ Time of Failure @ Failure Site</i>				
Pressure @ Failure Site: 795 psig at the Houstonia Station			Elevation @ Failure Site: 660	
Pressure Readings @ Various Locations:			Direction from Failure Site	
Location/M.P./Station #	Pressure (psig)	Elevation (ft msl)	Upstream	Downstream
N/A				

<i>Upstream Pump Station Data</i>	
Type of Product:	API Gravity:
Specific Gravity:	Flow Rate:
Pressure @ Time of Failure <sup>(4)</sup>	Distance to Failure Site:
High Pressure Set Point:	Low Pressure Set Point:

<i>Upstream Compressor Station Data</i>	
Specific Gravity: .55	Flow Rate:
Pressure @ Time of Failure <sup>(4)</sup> 795 psig	Distance to Failure Site: 21.6 miles
High Pressure Set Point: 830 psig	Low Pressure Set Point:

<i>Operating Pressure</i>	
Max. Allowable Operating Pressure: 800 psig	Determination of MAOP: 192.619 (c)
Actual Operating Pressure: 795 psig	
Method of Over Pressure Protection: Engine safeties - first engine speed and torque, then shutdown.	
Relief Valve Set Point: 830 psig	Capacity Adequate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

<i>Integrity Test After Failure</i>	
Pressure Test Conducted in place? (Conducted on Failed Components or Associated Piping):	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
If NO, Tested after removal?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Method: N/A	
Describe any failures during the test.	

<i>Soil/water Conditions @ Failure Site</i>	
Condition of and Type of Soil around Failure Site (Color, Wet, Dry, Frost Depth): <b>Dry and very rocky</b>	
Type of Backfill (Size and Description): <b>Rock</b>	

4 Obtain event logs and pressure recording charts

## Pipeline Failure Investigation Report

<i>Soil/water Conditions @ Failure Site</i>		<input type="checkbox"/> N/A
Type of Water (Salt, Brackish): N/A	Water Analysis <sup>(5)</sup> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<i>External Pipe or Component Examination</i>		<i>N/A</i>
External Corrosion? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>(1)</sup>	Coating Condition (Disbonded, Non-existent): <sup>(1)</sup> Coal tar - some disbonded	
Description of Corrosion: The failed pipeline segments showed multiple areas of external corrosion with reduced wall thickness.		
Description of Failure Surface (Gouges, Arc Burns, Wrinkle Bends, Cracks, Stress Cracks, Chevrons, Fracture Mode, Point of Origin): A 23 foot section of pipe was ejected and completely ruptured by the failure. Chevrons along the rupture pointed toward the origin in an area of external corrosion with reduced wall thickness.		
Above Ground: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <sup>(1)</sup>	Buried: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <sup>(1)</sup>	
Stress Inducing Factors: <sup>(1)</sup>	Depth of Cover: 6 feet <sup>(1)</sup>	
<i>Cathodic Protection</i>		<input type="checkbox"/> N/A
P/S (Surface): Readings taken this Spring were adequate - > .85 V - Recent reading in the area -2.1 V 3/26/08	P/S (Interface): Not taken	
Soil Resistivity: No soil - rock                      pH:	Date of Installation: 1955	
Method of Protection: <b>Rectifiers</b>		
Did the Operator have knowledge of Corrosion before the Incident? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
How Discovered? (Close Interval Survey, Instrumented Pig, Annual Survey, Rectifier Readings, ECDA, etc): <b>A close interval survey was performed in 2000 from 2 Gate to 3 Gate. Some areas of low pipe to soil potential were found but not in the area of the failure. See Appendix D.</b>		
<i>Internal Pipe or Component Examination</i>		<input type="checkbox"/> N/A
Internal Corrosion: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <sup>(1)</sup>	Injected Inhibitors: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Type of Inhibitors: N/A	Testing: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Results (Coupon Test, Corrosion Resistance Probe): N/A		
Description of Failure Surface (MIC, Pitting, Wall Thinning, Chevrons, Fracture Mode, Point of Origin): <b>The cause of the failure was external corrosion with reduced wall thickness.</b>		
Cleaning Pig Program: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Gas and/or Liquid Analysis: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

5 Attach copy of water analysis report

## Pipeline Failure Investigation Report

<i>Internal Pipe or Component Examination</i>		<input type="checkbox"/> N/A
Results of Gas and/or Liquid Analysis <sup>(6)</sup> N/A		
Internal Inspection Survey: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Results <sup>(7)</sup> ILI had been scheduled but not done.	
Did the Operator have knowledge of Corrosion before the Incident? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
How Discovered? (Instrumented Pig, Coupon Testing, ICDA, etc.): N/A		

<i>Outside Force Damage</i>		<input checked="" type="checkbox"/> N/A
Responsible Party:	Telephone No.:	
Address:		
Work Being Performed:		
Equipment Involved: <sup>(1)</sup>	Called One Call System? <input type="checkbox"/> Yes <input type="checkbox"/> No	
One Call Name:	One Call Report # <sup>(8)</sup>	
Notice Date:	Time:	
Response Date:	Time:	
Details of Response:		
Was Location Marked According to Procedures? <input type="checkbox"/> Yes <input type="checkbox"/> No		
Pipeline Marking Type: <sup>(1)</sup>	Location: <sup>(1)</sup>	
State Law Damage Prevention Program Followed? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> No State Law		
Notice Required: <input type="checkbox"/> Yes <input type="checkbox"/> No	Response Required: <input type="checkbox"/> Yes <input type="checkbox"/> No	
Was Operator Member of State One Call? <input type="checkbox"/> Yes <input type="checkbox"/> No	Was Operator on Site? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Did a deficiency in the Public Awareness Program contribute to the accident? <input type="checkbox"/> Yes <input type="checkbox"/> No		
Is OSHA Notification Required? <input type="checkbox"/> Yes <input type="checkbox"/> No		

6 Attach copy of gas and/or liquid analysis report  
 7 Attach copy of internal inspection survey report  
 8 Attach copy of one-call report

## Pipeline Failure Investigation Report

<i>Natural Forces</i> <span style="float: right;"><input checked="" type="checkbox"/> N/A</span>
Description (Earthquake, Tornado, Flooding, Erosion):

<i>Failure Isolation</i> <span style="float: right;"><input type="checkbox"/> N/A <sup>(1)</sup></span>	
Squeeze Off/Stopple Location and Method: <b>Panhandle isolated the failure by manually closing 2 Gate and 3 Gate.</b>	
Valve Closed - Upstream: 2 Gate Time: 9:38 AM	I.D.: M.P.: 12.97
Valve Closed - Downstream: 3 Gate Time: 9:23	I.D.: M.P.: 28.43
Pipeline Shutdown Method: <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Automatic <input type="checkbox"/> SCADA <input type="checkbox"/> Controller <input type="checkbox"/> ESD	
Failed Section Bypassed or Isolated: Isolated	
Performed By: Field Tech.	Valve Spacing: 16 miles

<i>Odorization</i> <span style="float: right;"><input checked="" type="checkbox"/> N/A</span>	
Gas Odorized: <input type="checkbox"/> Yes <input type="checkbox"/> No	Concentration of Odorant (Post Incident at Failure Site):
Method of Determination: <input type="checkbox"/> Yes <input type="checkbox"/> No	% LEL: <input type="checkbox"/> Yes <input type="checkbox"/> No    % Gas In Air: <input type="checkbox"/> Yes <input type="checkbox"/> No
	Time Taken: <input type="checkbox"/> Yes <input type="checkbox"/> No
Was Odorizer Working Prior to the Incident? <input type="checkbox"/> Yes <input type="checkbox"/> No	Type of Odorizer (Wick, By-Pass):
Odorant Manufacturer: Model:	Type of Odorant:
Amount Injected:	Monitoring Interval (Weekly):
Odorization History (Leaks Complaints, Low Odorant Levels, Monitoring Locations, Distances from Failure Site):	

# Pipeline Failure Investigation Report

<i>Odorization</i>		<input checked="" type="checkbox"/> N/A

<i>Weather Conditions</i>		<input type="checkbox"/> N/A
Temperature: 85 F	Wind (Direction & Speed): light	
Climate (Snow, Rain): Sunny	Humidity:	
Was Incident preceded by a rapid weather change? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Weather Conditions Prior to Incident (Cloud Cover, Ceiling Heights, Snow, Rain, Fog): <b>Clear</b>		

<i>Gas Migration Survey</i>		<input checked="" type="checkbox"/> N/A
Bar Hole Test of Area: <input type="checkbox"/> Yes <input type="checkbox"/> No	Equipment Used:	
Method of Survey (Foundations, Curbs, Manholes, Driveways, Mains, Services) <sup>(9)</sup> <span style="float: right;">(1)</span>		

<i>Environment Sensitivity Impact</i>		<input checked="" type="checkbox"/> N/A
Location (Nearest Rivers, Body of Water, Marshlands, Wildlife Refuge, City Water Supplies that could be or were affected by the medium loss): <span style="float: right;">(1)</span>		
OPA Contingency Plan Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	Followed? <input type="checkbox"/> Yes <input type="checkbox"/> No	

<i>Class Location/High Consequence Area</i>		<input type="checkbox"/> N/A
Class Location: 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> Determination: _____	HCA Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A Determination: _____	
Odorization Required? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A		

<i>Pressure Test History</i> <small>(Expand List as Necessary)</small>		<input type="checkbox"/> N/A

9 Plot on site description page

## Pipeline Failure Investigation Report

<b>Pressure Test History</b> <span style="float: right;"><input type="checkbox"/> N/A</span>						
<i>(Expand List as Necessary)</i>						
	Req'd <sup>(10)</sup> Assessment Deadline Date	Test Date	Test Medium	Pressure (psig)	Duration (hrs)	% SMYS
Installation	N/A					
Next	N/A	1955	Water	Unknown	Unknown	Unknown
Next						
Most Recent						
Describe any problems experienced during the pressure tests. <b>Hydrostatic test done in 1955 - details unknown.</b>						

<b>Internal Line Inspection/Other Assessment History</b> <span style="float: right;"><input type="checkbox"/> N/A</span>					
<i>(Expand List as Necessary)</i>					
	Req'd <sup>(10)</sup> Assessment Deadline Date	Assessment Date	Type of ILI Tool <sup>(11)</sup>	Other Assessment Method <sup>(12)</sup>	Indicated Anomaly If yes, describe below
Initial	<b>2012</b>				<input type="checkbox"/> Yes <input type="checkbox"/> No
Next					<input type="checkbox"/> Yes <input type="checkbox"/> No
Next					<input type="checkbox"/> Yes <input type="checkbox"/> No
Most Recent					<input type="checkbox"/> Yes <input type="checkbox"/> No
Describe any previously indicated anomalies at the failed pipe, and any subsequent pipe inspections (anomaly digs) and remedial actions. <b>Not scheduled until 2012. Not in top 50%. Gauge tool run already.</b>					

<b>Pre-Failure Conditions and Actions</b> <span style="float: right;"><input type="checkbox"/> N/A</span>
Was there a known pre-failure condition requiring <sup>(10)</sup> the operator to schedule evaluation and remediation? <input type="checkbox"/> Yes (describe below or on attachment) <input checked="" type="checkbox"/> No
If there was such a known pre-failure condition, had the operator established and adhered to a required <sup>(10)</sup> evaluation and remediation schedule? Describe below or on attachment. <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Prior to the failure, had the operator performed the required <sup>(10)</sup> actions to address the threats that are now known to be related to the cause of this failure? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A List below or on an attachment such operator-identified threats, and operator actions taken prior to the accident.
Describe any previously indicated anomalies at the failed pipe, and any subsequent pipe inspections (anomaly digs) and remedial actions. <b>N/A</b>

<b>Maps &amp; Records</b> <span style="float: right;"><input type="checkbox"/> N/A</span>
---

10 As required of Pipeline Integrity Management regulations in 49CFR Parts 192 and 195

11 MFL, geometry, crack, etc.

12 ECDA, ICDA, SCCDA, "other technology," etc.

## Pipeline Failure Investigation Report

Are Maps and Records Current? <sup>(13)</sup> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Comments:
--

<b>Leak Survey History</b>	<input type="checkbox"/> N/A
Leak Survey History (Trend Analysis, Leak Plots): <b>Leak survey on 6/25/2007. No leaks were found in the area of the failure.</b>	

<b>Pipeline Operation History</b>	<input type="checkbox"/> N/A
Description (Repair or Leak Reports, Exposed Pipe Reports): <b>N/A</b>	
Did a Safety Related Condition Exist Prior to Failure? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    Reported? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Unaccounted For Gas: <b>None before the incident.</b>	
Over & Short/Line Balance (24 hr., Weekly, Monthly/Trend):	

<b>Operator/Contractor Error</b>		<input checked="" type="checkbox"/> N/A
Name:	Job Function:	
Title:	Years of Experience:	
Training (Type of Training, Background):		
Was the person "Operator Qualified" as applicable to a precursor abnormal operating condition? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		
Was qualified individual suspended from performing covered task <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		
Type of Error (Inadvertent Operation of a Valve):		
Procedures that are required:		
Actions that were taken:		
Pre-Job Meeting (Construction, Maintenance, Blow Down, Purging, Isolation):		
Prevention of Accidental Ignition (Tag & Lock Out, Hot Weld Permit):		
Procedures conducted for Accidental Ignition:		
Was a Company Inspector on the Job? <input type="checkbox"/> Yes <input type="checkbox"/> No		
Was an Inspection conducted on this portion of the job? <input type="checkbox"/> Yes <input type="checkbox"/> No		

13 Obtain copies of maps and records

## Pipeline Failure Investigation Report

<i>Operator/Contractor Error</i>					<input checked="" type="checkbox"/> N/A
Additional Actions (Contributing factors may include number of hours at work prior to failure or time of day work being conducted):					
Training Procedures:					
Operation Procedures:					
Controller Activities:					
Name	Title	Years Experience	Hours on Duty Prior to Failure	Shift	
Alarm Parameters:					
High/Low Pressure Shutdown:					
Flow Rate:					
Procedures for Clearing Alarms:					
Type of Alarm:					
Company Response Procedures for Abnormal Operations:					
Over/Short Line Balance Procedures:					
Frequency of Over/Short Line Balance:					
Additional Actions:					

<i>Additional Actions Taken by the Operator</i>	<input type="checkbox"/> N/A
Make notes regarding the emergency and Failure Investigation Procedures (Pressure reduction, Reinforced Squeeze Off, Clean Up, Use of Evacuators, Line Purging, closing Additional Valves, Double Block and Bleed, Continue Operating downstream Pumps):	

## Pipeline Failure Investigation Report

### *Additional Actions Taken by the Operator*

N/A

The failure was detected by Gas Control in Houston at 8:51 a.m. on 8/25/2008. Field crews located the failure at 9:10 a.m. The failure was isolated by closing valves at about 9:30 a.m. Panhandle sent a team to investigate the failure on 8/26/08. After the initial investigation, the pipeline was repaired and returned to service at 80% of the pressure at the time of the incident (795 psi) pending the results of the investigation.

## Pipeline Failure Investigation Report

<b>Photo Documentation <sup>(1)</sup></b>					
Overall Area from best possible view. Pictures from the four points of the compass. Failed Component, Operator Action, Damages in Area, Address Markings, etc.					
Photo No.	Description	Roll No.	Photo No.	Description	Roll No.
1	View looking west at the crater		1		
2	East view of exposed pipe in crater		2		
3	West view of exposed pipe in crater		3		
4	View of longer ejected pipe segment		4		
5	Close view of longer segment		5		
6	View of shorter ejected segment		6		
7	Another view of shorter segment		7		
8	Possible failure origin on shorter segment		8		
9	Side view of possible failure.		9		
10	View of coupling ejected into the woods		10		
11	Close up of corrosion at possible failure origin.		11		
12	View of another area of external corrosion near the failure origin		12		
13	View of failure origin after the pipe was moved.		13		
14			14		
15			15		
16			16		
17			17		
18			18		
19			19		
20			20		
21			21		
22			22		
23			23		
24			24		
25			25		
26			26		
27			27		
28			28		
29			29		
30			30		
Type of Camera:					

## Pipeline Failure Investigation Report

<i>Photo Documentation <sup>(1)</sup></i>
Film ASA:
Video Counter Log (Attach Copy):

<i>Additional Information Sources</i>			
Agency	Name	Title	Phone Number
Police:	<b>Cooper County Sheriff</b>		
Fire Dept.:	<b>Pilot Grove Fire Dept</b>		
State Fire Marshall:			
State Agency:	<b>Missouri DOT Emergency Response Team</b>		
NTSB:			
EPA:			
FBI:			
ATF:			
OSHA:			
Insurance Co.:			
FRA:			
MMS:			
Television:	<b>No</b>		
Newspaper:			
Other:			

## ***Pipeline Failure Investigation Report***

<b><i>Persons Interviewed</i></b>		
Name	Title	Phone Number
<b>Brad Howard</b>	<b>Operations Specialist</b>	<b>660-568-1221</b>
<b>Mike Dawson</b>		
<b>Steve Atkinson</b>	<b>Technical Specialist</b>	<b>913-906-1522</b>
<b>Jerry Rau</b>	<b>Director Pipeline Integrity</b>	<b>713-989-7417</b>
<b>Rob Wesch</b>		
<b>Liz Rutherford</b>		
<b>Brian Kraft</b>	<b>Measurement Tech</b>	
<b>Dan Corpening</b>	<b>Area Director</b>	
<b>Ross Cummins</b>	<b>CP Tech</b>	
<b>Richard Gifford</b>	<b>Corrosion Tech</b>	
<b>Gerald Moore</b>	<b>Environmental Coordinator</b>	







# Pipeline Failure Investigation Report

## Site Description

Provide a sketch of the area including distances from roads, houses, stress inducing factors, pipe configurations, etc. Bar Hole Test Survey Plot should be outlined with concentrations at test points. Photos should be taken from all angles with each photo documented. Additional areas may be needed in any area of this guideline.

The Failure location was about two miles northwest of Pilot Grove (Cooper County) Missouri near Highway HH. The location was near milepost 21.6 on the Houstonia 200 line on a rocky hillside in a rural area. No structures were close to the failure location. The following page shows a sketch of the location provided by Panhandle. The image below shows the Panhandle system map.

### ***Panhandle Eastern Pipe Line Company, LP***

Panhandle Eastern Pipe Line Company operates a 6,500-mile pipeline system with access to diverse supply sources and can deliver 2.8 Bcf/d of natural gas to Midwest and East Coast markets. Tie-ins to Chicago, Dayton and Cincinnati have added to a Midwest customer base that includes some of the nation's largest utility and industrial natural gas users. We lead the way in offering competitive rates and a constantly evolving array of customer-friendly service options.

#### ***Panhandle Eastern provides:***

- Access to diverse Midcontinent and Canadian supply sources and to major Midwest and Northeast markets.
- Access to 74 Bcf of storage facilities.



To request a receipt and delivery point map, please contact Customer Service at 1-800-275-7375.



***Pipeline Failure Investigation Report***

**Appendix A**

**Houstonia 200 failure Pictures – 8/25/08 near Pilot Grove MO.**

## ***Pipeline Failure Investigation Report***



8/25/08 – #1- views looking West at the crater caused by the Houstonia 200 failure.

## ***Pipeline Failure Investigation Report***



8/25/08 #2 - East view of the exposed pipe.



8/25/08 #3 - West close up.

## ***Pipeline Failure Investigation Report***



8/25/08 #4 - One of two pipe sections ejected – the longer one – about 30 feet.



8/25/08 #5 -Closer view of the longer ejected section.

## ***Pipeline Failure Investigation Report***



8/25/08 #6 -View of the shorter section ejected – about 23 feet – ruptured full length.



8/25/08 #7 -Another view of same looking north.

## ***Pipeline Failure Investigation Report***



#8 - Areas with external corrosion and reduced wall thickness – possible failure origin.



8/25/08 #9 -Side view of the failure origin site with reduced wall thickness.

## ***Pipeline Failure Investigation Report***



8/25/08 #10 -View of coupling ejected from pipeline.



8/25/08 #11 -Close up of external corrosion on the possible origin site.

## Pipeline Failure Investigation Report



8/25/08 #12 - Another area of external corrosion on the shorter section near the possible failure.



8/26/08 #13 - Different view of the possible failure origin after the pipe was turned over.

*Pipeline Failure Investigation Report*

# Appendix B

## **Panhandle Incident Report**



## INCIDENT REPORT - GAS TRANSMISSION AND GATHERING SYSTEMS

Report Date \_\_\_\_\_  
 No. \_\_\_\_\_  
(DOT Use Only)

### INSTRUCTIONS

**Important:** Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the Office Of Pipeline Safety Web Page at <http://ops.dot.gov>.

### PART A – GENERAL REPORT INFORMATION

Check one or more boxes as appropriate:

Operator Name and Address	Original Report	Supplemental Report	Final Report
a. Operator's 5-digit Identification Number (when known) _____/			
b. If Operator does not own the pipeline, enter Owner's 5-digit Identification Number (when known) _____/			
c. Name of Operator _____			
d. Operator street address _____			
e. Operator address _____ <small>City, County or Parrish, State and Zip Code</small>			

<p>2. Time and date of the incident                  _____/_____/_____/_____  <small>hr. month day year</small></p> <p>3. Location of incident</p> <p>a. _____  <small>Nearest street or road</small></p> <p>b. _____  <small>City and County or Parrish</small></p> <p>c. _____  <small>State and Zip Code</small></p> <p>d. Mile Post/Valve Station _____</p> <p>e. Survey Station No. _____</p> <p>f. Latitude: _____ Longitude: _____  <small>(if not available, see instructions for how to provide specific location)</small></p> <p>g. Class location description                  Onshore: Class 1 Class 2 Class 3 Class 4                  Offshore: Class 1 <small>(complete rest of this item)</small>                  Area _____ Block # _____                  State _____/ or Outer Continental Shelf</p> <p>h. Incident on Federal Land other than Outer Continental Shelf                  Yes No</p> <p>i. Is pipeline Interstate Yes No</p> <p>4. Type of leak or rupture</p> <p>Leak: Pinhole Connection Failure <small>(complete sec. F5)</small>                  Puncture, diameter <small>(inches)</small> _____</p> <p>Rupture: Circumferential – Separation                  Longitudinal – Tear/Crack, length <small>(inches)</small> _____                  Propagation Length, total, both sides <small>(feet)</small> _____</p> <p>N/A                  Other: _____</p>	<p>5. Consequences <small>(check and complete all that apply)</small></p> <p>a. Fatality Total number of people: _____/</p> <p>Employees: _____/ General Public: _____/</p> <p>Non-employee Contractors: _____/</p> <p>b. Injury requiring inpatient hospitalization Total number of people: _____/</p> <p>Employees: _____/ General Public: _____/</p> <p>Non-employee Contractors: _____/</p> <p>c. Property damage/loss <small>(estimated)</small> Total \$ _____</p> <p>Gas loss \$ _____ Operator damage \$ _____</p> <p>Public/private property damage \$ _____</p> <p>d. Release Occurred in a 'High Consequence Area'</p> <p>e. Gas ignited – No explosion f. Explosion</p> <p>g. Evacuation <small>(general public only)</small> _____/ people</p> <p>Reason for Evacuation:                  Emergency worker or public official ordered, precautionary                  Threat to the public Company policy</p> <p>6. Elapsed time until area was made safe:                  _____/ hr. _____/ min.</p> <p>7. Telephone Report                  _____/_____/_____/_____  <small>NRC Report Number month day year</small></p> <p>8. a. Estimated pressure at point and time of incident:                  _____ PSIG</p> <p>b. Max. allowable operating pressure <small>(MAOP)</small>: _____ PSIG</p> <p>c. MAOP established by 49 CFR section:                  192.619 (a)(1) 192.619 (a)(2) 192.619 (a)(3)                  192.619 (a)(4) 192.619 (c)</p> <p>d. Did an overpressurization occur relating to the incident? Yes No</p>
--	--

### PART B – PREPARER AND AUTHORIZED SIGNATURE

(type or print) Preparer's Name and Title _____	_____
	<small>Area Code and Telephone Number</small>
Preparer's E-mail Address _____	_____
	<small>Area Code and Facsimile Number</small>
Authorized Signature _____	_____
<small>(type or print) Name and Title</small>	<small>Date</small>
	<small>Area Code and Telephone Number</small>



**F5 – MATERIAL AND WELDS**

**Material**

- 14. Body of Pipe => Dent                      Gouge                      Wrinkle Bend                      Arc Burn                      Other: \_\_\_\_\_
- 15. Component => Valve                      Fitting                      Vessel                      Extruded Outlet                      Other: \_\_\_\_\_
- 16. Joint => Gasket                      O-Ring                      Threads                      Other: \_\_\_\_\_

**Weld**

- 17. Butt => Pipe                      Fabrication                      Other: \_\_\_\_\_
- 18. Fillet => Branch                      Hot Tap                      Fitting                      Repair Sleeve                      Other: \_\_\_\_\_
- 19. Pipe Seam => LF ERW                      DSAW                      Seamless                      Flash Weld                      Other: \_\_\_\_\_
- HF ERW                      SAW                      Spiral

Complete a-g if you indicate **any** cause in part F5.



a. Type of failure:

- Construction Defect =>      Poor Workmanship                      Procedure not followed                      Poor Construction Procedures
- Material Defect

b. Was failure due to pipe damage sustained in transportation to the construction or fabrication site?      Yes      No

c. Was part which leaked pressure tested before incident occurred?      Yes, complete d-g      No

d. Date of test:      /      / mo.      /      / day      /      / yr.

e. Test medium:      Water      Natural Gas      Inert Gas      Other: \_\_\_\_\_

f. Time held at test pressure:      /      / hr.

g. Estimated test pressure at point of incident: \_\_\_\_\_ PSIG

**F6 – EQUIPMENT AND OPERATIONS**

- 20. Malfunction of Control/Relief Equipment =>      Valve      Instrumentation      Pressure Regulator      Other: \_\_\_\_\_
- 21. Threads Stripped, Broken Pipe Coupling =>      Nipples      Valve Threads      Mechanical Couplings      Other: \_\_\_\_\_
- 22. Ruptured or Leaking Seal/Pump Packing

23. Incorrect Operation

- a. Type:      Inadequate Procedures      Inadequate Safety Practices      Failure to Follow Procedures      Other: \_\_\_\_\_
- b. Number of employees involved who failed post-incident drug test: /      /      Alcohol test: /      /
- c. Were most senior employee(s) involved qualified?      Yes      No      d. Hours on duty: /      /

**F7 – OTHER**

- 24. Miscellaneous, describe: \_\_\_\_\_
- 25. Unknown
- Investigation Complete      Still Under Investigation (submit a supplemental report when investigation is complete)

**PART G – NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTING TO THE EVENT**

(Attach additional sheets as necessary)

*Pipeline Failure Investigation Report*

# Appendix C

## **Panhandle Failure Analysis**

# Metallurgical Analysis of 24-Inch Houstonia 200 Service Failure at MP 21.6 (8/25/08)

Panhandle Eastern Pipe Line Company, LP  
Final Report – 813 8385 1  
October 29, 2008

Metallurgical Analysis of 24-Inch Houstonia  
200 Service Failure at MP 21.6 (8/25/08)  
for


Panhandle Eastern Pipe Line Company, L.P.  
5444 Westheimer, Suite 432  
Houston, TX 77056

5777 Frantz Road  
Dublin, Ohio 43017-1386  
U.S.A.


Tel: (614) 761-1214  
Fax: (614) 761-1633  
www.dnv.com  
www.cctechnologies.com

Summary: Final Report

Prepared by: Gregory T. Quickel, M.S.  
Staff Engineer



Reviewed by: John Beavers, Ph.D., FNACE .  
Director – Failure Analysis



Approved by: Patrick H. Vieth  
Senior VP – Integrity & Materials



Date of Issue: October 29, 2008

Project Number: 813 8385 1

- No distribution without permission from the client or responsible organizational unit (however, free distribution for internal use within DNV after 3 years)
- No distribution without permission from the client or responsible organizational unit
- Strictly confidential
- Unrestricted distribution

All copyrights reserved CC Technologies, Inc. This publication, or parts thereof, may not be reproduced or transmitted in any form or by any means, including photocopying or recording, without the prior written consent of CC Technologies, Inc.

## Disclaimer

This report documents work performed by CC Technologies, Inc. (*CC Technologies*) Dublin, Ohio, for Panhandle Eastern Pipe Line Company, L.P. (*Panhandle*) Houston, Texas. Neither CC Technologies nor any person acting on behalf of CC Technologies:

- assumes any liability for consequences or damages resulting from the use, misuse, or reliance upon the information disclosed in this report.
- makes any warranty or representations that the use of any information, apparatus, method, or process disclosed in this report may not infringe on privately-owned rights.

## Executive Summary

Panhandle Eastern Pipe Line Company, L.P. (*Panhandle*) retained CC Technologies, Inc. (*CC Technologies*) to perform a metallurgical analysis on a section of pipe from the 24-inch diameter Houstonia 200 natural gas pipeline that failed during service. The failure occurred on August 25, 2008 near Pilot Grove (Cooper County), Missouri at milepost (MP) 21.6.

The portion of the pipeline containing the failure is comprised of 24-inch diameter by 0.281-inch wall thickness line pipe with an estimated yield strength (EYS) of 48.0 ksi that was manufactured by A.O. Smith and contains an electric flash welded (EFW) longitudinal seam. The maximum allowable operating pressure (MAOP) and normal operating pressure are 800 psig, which corresponds to 71.2% of the EYS. The operating pressure at the time and location of the failure was 790 psig, which corresponds to 70.3% of the EYS.

The pipeline was installed in 1937 and was reportedly externally coated with a bitumastic pipe wrap. The pipeline has an impressed current cathodic protection (CP) system that was installed between 1951 and 1953. CP readings taken on March 25<sup>th</sup>, 2008 in the vicinity of the failure were -4.162 V (on) and -1.320 V (off).

A hydrostatic pressure test was performed in 1955 on Segments 1031+39 to 1317+15, which encompasses the failure site.

Four segments of line pipe steel, one which contained the failure origin, were delivered to CC Technologies for analysis. The received segments consisted of: a segment that contained the upstream (U/S) girth weld and failure origin, a mating downstream (D/S) segment, the D/S arrest segment from the joint that failed, and a segment of pipe from the joint D/S of the joint that failed. The objective of the analysis was to document the factual metallurgical evidence.

The pipe segments were visually examined and photographed in the as-received condition. Scale samples were removed from the external pipe surface, at and away from a region of wall loss near the failure origin. The following was performed on the scale samples: elemental analysis using energy-dispersive spectroscopy (EDS) with a scanning electron microscope (SEM), bacteria culture inoculation using a serial dilution technique, and qualitative spot testing using 2N HCl for the presence of carbonates and/or sulfides. A grid with 1-inch by 1-inch divisions was drawn on the internal surface of the pipe near the failure origin where external wall loss was present. Wall thickness values were recorded every 1 inch (measured on the internal surface) with an ultrasonic testing (UT) gauge and/or with calipers. Calipers were used where the UT gauge could not be used, because of sharp bends in the pipe. The external surface at the wall loss region near the failure origin was cleaned with a soft bristle brush and inhibited acid. Magnetic particle inspection (MPI) was performed on the external surface at the wall loss region near the failure origin to identify any indications. Transverse cross-sections were removed from the failure origin and seam weld, mounted, polished, and etched. Light photomicrographs were taken to document the corrosion morphology and steel microstructure.

## Executive Summary (continued)

A pipe sample for chemical analysis was removed from the joint that failed to determine the composition. Transverse pipe samples for mechanical (duplicate tensiles and Charpy V-notch impact) testing were removed from the base metal of the downstream joint.

The predicted burst pressure for the region of wall loss that contained the rupture was calculated using the RSTRENG effective area method embodied in CorLAS™. Two flaw profiles were obtained. The first flaw profile (profile 1) was obtained by using a modified river bottom method. A second flaw profile (profile 2) was constructed by measuring the wall thicknesses at the edge of the counter-clockwise fracture surface. A flow strength of the measured yield stress (MYS)+10 ksi was used for the calculation.

Below is a summary of our preliminary observations and conclusions:

- The failure occurred at a region of external wall loss from corrosion.
- The maximum depth of wall loss at the rupture surface was 0.210 inches (74.7% of wall thickness).
- Bacteria did not likely play a role in the external corrosion based on the morphology of the corrosion and the results of the bacteria culture testing.
- The morphology of the fracture surfaces suggests that the failure initiated in a ductile manner.
- The morphology of the seam weld is consistent with an EFW seam.
- The microstructure and steel composition are consistent with line pipe steel.
- The results of the tensile and Charpy testing are consistent with this vintage of line pipe steel.
- The estimated burst pressure ranged between 663 psig to 868 psig, compared to an actual failure pressure of 790 psig.

## Contents

1.0	BACKGROUND .....	1
2.0	APPROACH .....	1
3.0	RESULTS AND DISCUSSION.....	2
3.1	Optical Examination .....	2
3.2	Magnetic Particle Inspection (MPI) .....	3
3.3	Metallurgical Analysis.....	3
3.4	Energy Dispersive Spectroscopy (EDS) .....	4
3.5	Qualitative Spot Test.....	4
3.6	Bacteria Culture Testing.....	4
3.7	Mechanical Test Results .....	4
3.8	Chemical Analysis.....	5
3.9	Predicted Burst Pressure .....	5
4.0	CONCLUSIONS.....	5

## Tables

Table 1.	Summary of the results (in areas of minimal or no corrosion) of wall thickness measurements performed on the pipe segments.....	7
Table 2.	Results of elemental analysis of scale samples removed from the external pipe surface using energy dispersive spectroscopy (EDS). ....	7
Table 3.	Results of bacteria analysis performed on scale samples removed from the external surfaces, at and away from the region of external corrosion.....	8
Table 4.	Results of tensile tests performed on transverse samples from Pipe Segment C (D/S of failure joint). ....	8
Table 5.	Results of Charpy V-notch impact tests performed on samples removed from the base metal of Pipe Segment C. ....	9
Table 6.	Results of analysis of the Charpy V-notch impact energy and percent shear plots.....	9
Table 7.	Results of chemical analysis of a pipe steel sample from Pipe Segment A2 (failure joint) by optical emission spectroscopy (OES) removed from the joint that ruptured. ....	10

## Figures

Figure 1.	Photograph of Pipe Segment A1 (internal surface) in the as-received condition.....	11
Figure 2.	Photograph of Pipe Segment B1 in the as-received condition.....	12
Figure 3.	Photograph of Pipe Segment C in the as-received condition.....	13
Figure 4.	Photograph of Pipe Segment A2 (external surface) in the as-received condition.....	14
Figure 5.	Photograph of the external surface of Pipe Segment A2 on the clockwise side of rupture.....	15
Figure 6.	Photograph of the external surface of Pipe Segment A2 on the counter-clockwise side of rupture.....	16
Figure 7.	Remaining wall in the region of the probable failure origin. ....	17
Figure 8.	Stereo light photomicrograph of a transverse cross-section removed from the rupture near the failure origin (Mount M1, 4% Nital Etchant).....	18
Figure 9.	Stereo light photomicrograph of the rupture area indicated in Figure 8 (Mount M1, 4% Nital Etchant). ....	19
Figure 10.	Light photomicrograph of the external surface of the pipe in Mount M1 (4% Nital Etchant, area indicated in Figure 8).....	19
Figure 11.	Stereo light photomicrograph of the seam weld cross-section (Mount M2, 4% Nital Etchant). ....	20
Figure 12.	Light photomicrograph of the typical base metal microstructure from Mount M2 (4% Nital Etchant). ....	20
Figure 13.	EDS spectrum of scale that was removed from the external surface. ....	21
Figure 14.	Plot of percent shear from Charpy V-notch tests as a function of temperature for samples removed from Pipe Segment C.....	22
Figure 15.	Plot of Charpy V-notch impact energy as a function of temperature for samples removed from Pipe Segment C. ....	22
Figure 16.	Flaw depth vs. length profile of the measured flaws. ....	23

## 1.0 BACKGROUND

Panhandle Eastern Pipe Line Company, L.P. (*Panhandle*) retained CC Technologies, Inc. (*CC Technologies*) to perform a metallurgical analysis on a section of pipe from the 24-inch diameter Houstonia 200 natural gas pipeline that failed during service. The failure occurred on August 25<sup>th</sup>, 2008 near Pilot Grove (Cooper County), Missouri at milepost (MP) 21.6.

The portion of the pipeline containing the failure is comprised of 24-inch diameter by 0.281-inch wall thickness line pipe with an estimated yield strength (EYS) of 48.0 ksi that was manufactured by A.O. Smith and contains an electric flash welded (EFW) longitudinal seam. The maximum allowable operating pressure (MAOP) and normal operating pressure are 800 psig, which corresponds to 71.2% of the EYS. The operating pressure at the time and location of the failure was 790 psig, which corresponds to 70.3% of the EYS.

The pipeline was installed in 1937 and was reportedly externally coated with a bitumastic pipe wrap. The pipeline has an impressed current cathodic protection (CP) system that was installed between 1951 and 1953. CP readings taken on March 25<sup>th</sup>, 2008 in the vicinity of the failure were -4.162 V (on) and -1.320 V (off).

A hydrostatic pressure test was performed in 1955 on Segments 1031+39 to 1317+15, which encompasses the failure site.

Four segments of line pipe steel, one which contained the failure origin, were delivered to CC Technologies for analysis. The received segments consisted of a segment that contained the upstream (U/S) girth weld and failure origin, a mating downstream (D/S) segment, the D/S arrest segment from the joint that failed, and a segment of pipe from the joint D/S of the joint that failed. The objective of the analysis was to document the factual metallurgical evidence.

## 2.0 APPROACH

The procedures used in the analysis were in accordance with industry accepted standards. Six of the general standards governing terminology, chemical analysis, mechanical testing, and specific metallographic procedures used are as follows:

- ASTM E3, “Standard Methods of Preparation of Metallographic Specimens.”
- ASTM E7, “Standard Terminology Relating to Metallography.”
- ASTM E8, “Test Methods for Tension Testing of Metallic Materials.”
- ASTM E23, “Standard Test Methods for Notched Bar Impact Testing of Metallic Materials.”
- ASTM A751, “Standard Test Methods, Practices, and Terminology for Chemical Analysis of Steel Products.”
- ASTM G15, “Standard Terminology Relating to Corrosion and Corrosion Testing.”

The pipe segments were visually examined and photographed in the as-received condition. Scale samples were removed from the external pipe surface, at and away from a region of wall loss near the failure origin. The following was performed on the scale samples: elemental analysis using energy-dispersive spectroscopy (EDS) with a scanning electron microscope (SEM), bacteria culture inoculation using a serial dilution technique, and qualitative spot testing using 2N HCl for the presence of carbonates and/or sulfides. A grid with 1-inch by 1-inch divisions was drawn on the internal surface of the pipe near the failure origin where external wall loss was present. Wall thickness values were recorded every 1 inch (measured on the internal surface) with an ultrasonic testing (UT) gauge and/or with calipers. Calipers were used where the UT gauge could not be used, because of sharp bends in the pipe. The external surface at the wall loss region near the failure origin was cleaned with a soft bristle brush and inhibited acid. Magnetic particle inspection (MPI) was performed on the external surface at the wall loss region near the failure origin to identify any indications. Transverse cross-sections were removed from the failure origin and seam weld, mounted, polished, and etched. Light photomicrographs were taken to document the corrosion morphology and steel microstructure. A pipe sample for chemical analysis was removed from the joint that failed to determine the composition. Transverse pipe samples for mechanical (duplicate tensiles and Charpy V-notch impact) testing were removed from the base metal of the downstream joint.

The predicted burst pressure for the region of wall loss that contained the rupture was calculated using the RSTRENG effective area method embodied in CorLAS™. Two flaw profiles were obtained. The first flaw profile (profile 1) was obtained by using a modified river bottom method. A second flaw profile (profile 2) was constructed by measuring the wall thicknesses at the edge of the counter-clockwise fracture surface. A flow strength of the measured yield stress (MYS)+10 ksi was used for the calculation.

### **3.0 RESULTS AND DISCUSSION**

#### **3.1 Optical Examination**

Figure 1 through Figure 4 are photographs of the four as-received pipe segments. The pipe segments were designated as Pipe Segment A1, A2, B1, and C and by Panhandle personnel. Pipe Segments A1, B1, and A2 contained portions of the rupture paths. Pipe Segment C did not contain a rupture path and was used for mechanical testing. None of the pipe segments contained in-tact coating (in the as-received condition) and all segments, except for Segment C, contained localized regions of wall loss. Top-dead-center (TDC) was not indicated on the pipe segments. Flow direction was not identified on the pipe segments but is labeled on pipe segments that ruptured.

The wall thicknesses were measured at four equally spaced locations on the pipe segments. The wall thickness values for the segments are shown in Table 1. The wall thickness values were consistent with a nominal wall thickness of 0.281 inches.

Figure 1 is a photograph of the internal surface of Pipe Segment A1 in the as-received condition. The pipe segment was approximately 6.5 feet in length and was the D/S mating

segment to Segment A2. The seam weld is located between the two rupture faces. The orientation of the chevron markings on the rupture surfaces indicated that the failure origin was U/S.

Figure 2 is a photograph of the external and internal surfaces of Pipe Segment B1 in the as-received condition. Pipe Segment B1 was approximately 11 feet in length from the joint that ruptured, and contained the D/S portion of rupture arrest. Again, the orientation of the chevron markings on the rupture surfaces indicated that the failure origin was U/S of this segment.

Figure 3 is a photograph of the external surface of Pipe Segment C in the as-received condition. The pipe segment was approximately 1.5 feet in length, was from the joint D/S of the joint that ruptured, and was intact. The diameter of the pipe segment was 23.9 inches, which is consistent with a nominal diameter of 24 inches.

Figure 4 is a photograph of Pipe Segment A2 in the as-received condition. The pipe segment was approximately 4.2 feet in length and U/S of Pipe Segment A1. Chevron markings that were located on the fracture surfaces pointed to a rupture origin in the segment. Figure 5 and Figure 6 are photographs of the external pipe surface on the clockwise and counter-clockwise side of the rupture path, respectively. Corrosion wall loss is located on the external pipe surface on adjacent surfaces. The corroded region extended 0.5 feet to 1.79 feet from the U/S girth weld and the fracture surface within the region was at a 45° angle, indicating a shear type of failure. Outside of the region, the fracture surface contained chevron marks and was predominantly perpendicular to the pipe surface.

Figure 7 shows remaining wall produced from wall thickness measurements obtained. The measurements were recorded from approximately 34 to 47 inches clockwise of the seam weld and from 6 to 25-inches D/S of the U/S girth weld. The rupture surface regions were located approximately 40 to 41 inches clockwise of the seam weld (looking D/S). This figure shows that the maximum depth of attack ranges from 0.05 to 0.1 inches and the deepest portions of the attack are at/near the fracture surface. Based on a wall thickness of 0.281 inches, the maximum depth of wall loss was 0.188 inches (66.9% of wall thickness).

### **3.2 Magnetic Particle Inspection (MPI)**

MPI was performed on the external pipe surface in the region of wall loss associated with the failure origin. No evidence of linear indications was identified on the pipe body.

### **3.3 Metallurgical Analysis**

Figure 8 is a photograph of the mounted transverse cross-section (Mount M1) removed near the rupture origin (see Figure 5 and Figure 6 for location). The cross-section shows significant wall loss. Figure 9 is a stereo light photomicrograph of the area indicated in Figure 8. The rupture surfaces are at approximately a 45° angle to each other and there is evidence of necking near the rupture surfaces. Both observations are indicative of a ductile overload failure. Figure 10 is a light photomicrograph showing the cross-section of Mount M1 near the external surface. The

figure shows a banded microstructure and there was no evidence in the cross-section of morphology that is indicative of microbial influenced corrosion (MIC).

Figure 11 is a stereo light photomicrograph of the mounted cross-section that was removed from the seam weld. The morphology of the weld is consistent with an EFW seam.

Figure 12 is a light photomicrograph of the typical microstructure of the base metal from Mount M2. The microstructure consists of ferrite (white areas), pearlite (dark areas consisting of lamellae), and inclusions. This microstructure is typical for this vintage and grade of line pipe steel.

### 3.4 Energy Dispersive Spectroscopy (EDS)

Table 2 is a summary of the EDS results of the scale samples removed from the external pipe surface; see Figure 5 for the locations where the scale was removed. Sample A was removed from the region of wall loss and Sample B was removed away from the region of wall loss. Figure 13 shows a representative EDS spectrum. High amounts of oxygen (O) and iron (Fe), lesser amounts of sodium (Na), magnesium (Mg), aluminum (Al), silicon (Si), sulfur (S), potassium (K), calcium (Ca), manganese (Mn), and carbon (C) were found in the samples.

The Fe and O were likely in the form of an iron oxide and other elements are commonly found in soils.

### 3.5 Qualitative Spot Test

Spot tests for the presence of carbonates and/or sulfides were performed on scale at locations where samples were removed for elemental analysis. The deposits were positive for the presence of carbonates (bubbling) and negative for the presence of sulfides (no rotten egg odor). Carbonates are commonly associated with CP.

### 3.6 Bacteria Culture Testing

Scale samples were removed from the external surface, inoculated, and incubated for the presence of aerobic, anaerobic, sulfate-reducing (SRB), acid-producing (APB), and iron-related bacteria (IRB) in concentrations ranging from 1-99,999 bacteria per mL. The samples were removed from the same locations where samples were removed for elemental analysis. Table 3 shows the results of the bacteria testing for the scale samples. The scale samples removed from both locations were positive for the presence of aerobic bacteria, anaerobic bacteria, and acid-producing bacteria (APB) in very high (10,000 – 99,999 bacteria per mL) concentrations. The fact that there was no evidence of an increased concentration of the bacteria near the failure site suggests that bacteria did not play a role in the failure.

### 3.7 Mechanical Test Results

The results of the tensile testing for samples removed from the Segment C (D/S joint) are shown in Table 4. The MYS and ultimate tensile strength (UTS) for the pipe segment were

determined to be 51.8-ksi and 71.5-ksi, respectively, compared to an EYS of 48.0-ksi. The failure joint was not tested since it was deformed during the failure event.

Table 5 summarizes the results of the Charpy testing while Figure 14 and Figure 15 show the Charpy percent shear and impact energy curves, respectively. An analysis of the data indicates that the 85% FATT is 96.8°F and the upper shelf Charpy energy is 38.8-ft·lbs, full size. The CVN test results can be adjusted to account for material constraint effects by applying temperature shifts to the data.\* The modified transition temperatures (brittle-to-ductile fracture initiation temperature) for the pipe segment were estimated as 90.4°F, based on a pipe wall thickness of 0.281 inches; see Table 6. Based on this analysis, the tested material is expected to exhibit ductile fracture propagation behavior above 90.4°F.

### 3.8 Chemical Analysis

The results of the chemical composition analysis conducted on a sample removed from the pipe section that ruptured are shown in Table 7. The composition is consistent with this vintage of line pipe steel.

### 3.9 Predicted Burst Pressure

The predicted burst pressure for the region of wall loss that contained the rupture was calculated using the RSTRENG effective area method embodied in CorLAS™. The predicted burst pressure relied upon the remaining wall thicknesses measurements at and near the rupture of flaw profile 1 and 2, the average mechanical properties from the mechanical testing, and the pipe dimensions; see Figure 16 for flaw profiles. The results of the analysis are summarized in Appendix A. The maximum depth of wall loss in flaw profile 1 and 2 were 0.188 inches (66.9% of wall thickness) and 0.210 inches (74.7% of wall thickness), respectively. The estimated burst pressure ranged between 663 psig to 868 psig, compared to an actual failure pressure of 790 psig.

## 4.0 CONCLUSIONS

Below is a summary of our preliminary observations and conclusions:

- The failure occurred at a region of external wall loss from corrosion.
- The maximum depth of wall loss at the rupture surface was 0.210 inches (74.7% of wall thickness).
- Bacteria did not likely play a role in the external corrosion based on the morphology of the corrosion and the results of the bacteria culture testing.
- The morphology of the fracture surfaces suggests that the failure initiated in a ductile manner.

\* "A Simple *Procedure* for Synthesizing Charpy Impact Energy Transition Curves from Limited Test Data," Michael J. Rosenfeld, International Pipeline Conference – Volume 1, ASME 1996, p. 216.

- The morphology of the seam weld is consistent with an EFW seam.
- The microstructure and steel composition are consistent with line pipe steel.
- The results of the tensile and Charpy testing are consistent with this vintage of line pipe steel.
- The estimated burst pressure ranged between 663 psig to 868 psig, compared to an actual failure pressure of 790 psig.

Table 1. Summary of the results (in areas of minimal or no corrosion) of wall thickness measurements performed on the pipe segments.

Segment ID	Description	Wall Thickness 1 (inches)	Wall Thickness 2 (inches)	Wall Thickness 3 (inches)	Wall Thickness 4 (inches)
A1	D/S of and cut from Segment A2	0.271	0.275	0.281	0.280
A2	Segment that contained U/S girth weld and failure origin	0.282	0.281	0.278	0.275
B1	D/S arrest segment	0.279	0.276	0.280	0.280
C	Segment for mechanicals	0.281	0.281	0.282	0.283

Table 2. Results of elemental analysis of scale samples removed from the external pipe surface using energy dispersive spectroscopy (EDS).

	Location A, Corroded Region (wt %)	Location B, Non-Corroded Region (wt %)
O	26	68
Na	<1	-
Mg	<1	3.4
Al	<1	1.6
Si	<1	5.6
S	<1	<1
K	<1	<1
Ca	1.5	4.3
Mn	1.3	-
C	-	15
Fe	69	2.1

Table 3. Results of bacteria analysis performed on scale samples removed from the external surfaces, at and away from the region of external corrosion.

	Scale from Location A		Scale from Location B	
	Test Result	Bacteria Concentration	Test Result	Bacteria Concentration
Aerobic	positive	Very High	positive	Very High
Anaerobic	positive	Very High	positive	Very High
Acid-Producing	positive	Very High	positive	Very High
Sulfate-Reducing	negative	-	negative	-
Iron-Related	negative	-	negative	-

**Bacteria Concentration Key:**

Very Low	(1 – 9 bacteria per mL),
Low	(10 – 99 bacteria per mL),
Moderate	(100 – 999 bacteria per mL),
High	(1,000 – 9,999 bacteria per mL),
Very High	(10,000 – 99,999 bacteria per mL)

Table 4. Results of tensile tests performed on transverse samples from Pipe Segment C (D/S of failure joint).

	Pipe Segment C
Yield Strength, ksi	51.8
Tensile Strength, ksi	71.5
Elongation in 2 inches, %	33.0
Reduction of Area, %	52.0

Table 5. Results of Charpy V-notch impact tests performed on samples removed from the base metal of Pipe Segment C.

Sample ID	Temperature, °F	Sub-size Impact Energy, ft-lbs	Full Size Impact Energy, ft-lbs	Shear, %	Lateral Expansion, mils
1	-30	2	3.5	0	0
2	-5	3	5.3	5	0
3	20	4	7	15	1
4	45	10	17.6	40	9
5	70	16	28.1	60	22
6	95	21	36.9	85	30
7	120	22	38.7	95	31
8	145	21.5	37.8	98	31

Table 6. Results of analysis of the Charpy V-notch impact energy and percent shear plots.

	Pipe Segment C
Upper Shelf Impact Energy (Full Size), Ft-lbs	38.8
85% FATT, °F	96.8
Maxey Adjusted 85% FATT, °F	90.4

Table 7. Results of chemical analysis of a pipe steel sample from Pipe Segment A2 (failure joint) by optical emission spectroscopy (OES) removed from the joint that ruptured.

<b>Element</b>	<b>Base Metal (Wt. %)</b>
C (Carbon)	0.287
Mn (Manganese)	1.07
P (Phosphorus)	0.011
S (Sulfur)	0.029
Si (Silicon)	0.008
Cu (Copper)	0.023
Sn (Tin)	0.002
Ni (Nickel)	0.014
Cr (Chromium)	0.015
Mo (Molybdenum)	0.000
Al (Aluminum)	0.002
V (Vanadium)	0.001
Nb (Niobium)	0.002
Zr (Zirconium)	0.001
Ti (Titanium)	0.001
B (Boron)	0.0002
Ca (Calcium)	0.0000
Co (Cobalt)	0.003
Fe (Iron)	Balance
Carbon Equivalent ( $CE_{IIW}$ )	0.47




Figure 1. Photograph of Pipe Segment A1 (internal surface) in the as-received condition.



Figure 2. Photograph of Pipe Segment B1 in the as-received condition.



Figure 3. Photograph of Pipe Segment C in the as-received condition.




Figure 4. Photograph of Pipe Segment A2 (external surface) in the as-received condition.




Figure 5. Photograph of the external surface of Pipe Segment A2 on the clockwise side of rupture.




Figure 6. Photograph of the external surface of Pipe Segment A2 on the counter-clockwise side of rupture.




Figure 7. Remaining wall in the region of the probable failure origin.




Figure 8. Stereo light photomicrograph of a transverse cross-section removed from the rupture near the failure origin (Mount M1, 4% Nital Etchant).



Figure 9. Stereo light photomicrograph of the rupture area indicated in Figure 8 (Mount M1, 4% Nital Etchant).




Figure 10. Light photomicrograph of the external surface of the pipe in Mount M1 (4% Nital Etchant, area indicated in Figure 8).




Figure 11. Stereo light photomicrograph of the seam weld cross-section (Mount M2, 4% Nital Etchant).




Figure 12. Light photomicrograph of the typical base metal microstructure from Mount M2 (4% Nital Etchant).




Figure 13. EDS spectrum of scale that was removed from the external surface.




Figure 14. Plot of percent shear from Charpy V-notch tests as a function of temperature for samples removed from Pipe Segment C.




Figure 15. Plot of Charpy V-notch impact energy as a function of temperature for samples removed from Pipe Segment C.




Figure 16. Flaw depth vs. length profile of the measured flaws.

**APPENDIX A**  
**DESCRIPTION OF CORLAS™**

## APPENDIX A Description of CorLAS™

The CorLAS™ computer program was developed by CC Technologies to evaluate crack-like flaws in pipelines based on inelastic fracture mechanics. Using the effective area of the actual, measured crack length-depth profile, an equivalent semi-elliptical surface flaw is modeled and used to compute the effective stress and the applied value of J for internal pressure loading. The effective stress and applied J are then compared with the flow strength ( $\sigma_{fs}$ ) and fracture toughness ( $J_C$ ), respectively, to predict the failure pressure.

The program also contains a similar inelastic fracture mechanics analysis for through-wall flaws. The fracture toughness of the steel can be estimated from Charpy data or measured by means of a  $J_{IC}$  test. In the most recent version of CorLAS™, the fracture toughness analysis automatically checks for plastic instability and only the fracture toughness curve needs to be considered for crack-like flaws. The actual tensile and Charpy properties of the pipe joint, measured from the samples removed, can be used for the critical leak/rupture length calculation.

\*\*\*\*\*

Houstonia 200 :SEMI-ELLIPTICAL FLAW PROFILE  
EST YS 48 ksi

UTS, psi = 71500. YS, psi = 51750. FS, psi = 61750.  
E, ksi = 29500.  $\nu_{exp}$  = 0.110  $J_C$ , lb/in = 1935.  
Thin-wall (OD) formula for hoop stress  $T_{mat}$  = 62.5  
OD, in. = 24.00 Wall Thickness, in. = 0.281

SUMMARY OF RESULTS FOR EFFECTIVE-AREA METHOD  
Flaw: Start, in. = 4.000 Length, in. = 9.000 Area, in.^2 = 1.283  
Depth, in.: Maximum = 0.188 Equivalent Flaw = 0.182  
Failure Stress, psi = 37048. Failure Pressure, psig = 867.53

\*\*\*\*\* Input Flaw Profile Data \*\*\*\*\*

Length, in.	Depth, in.
0	0
1	0.052
2	0.061
3	0.059
4	0.138
5	0.132
6	0.188
7	0.158
8	0.155

9	0.086
10	0.126
11	0.145
12	0.173
13	0.102
15	0.071
16	0.079
17	0.096
18	0.03
19	0.029
20	0.021
21	0

\*\*\*\*\* Effective Flaw Results \*\*\*\*\*

	Flaw Start, in.	Flaw Length, in.	Effective Area, in.^2	Flow Failure Stress, psi	Japplied, lb/in	Tapplied	Failure Pressure, psig
THOSE BELOW ARE FOR FLOW-STRENGTH FAILURE CRITERION							
1	4	9	1.283	37048	4278.6	1794.1	867.5

\*\*\*\*\*

Houstonia 200 :SEMI-ELLIPTICAL FLAW PROFILE  
 EST YS 48 ksi  
 UTS, psi = 71500. YS, psi = 51750. FS, psi = 61750.  
 E, ksi = 29500. nexp = 0.110 Jc, lb/in = 1935.  
 Thin-wall (OD) formula for hoop stress Tmat = 62.5  
 OD, in. = 24.00 Wall Thickness, in. = 0.281

SUMMARY OF RESULTS FOR EFFECTIVE-AREA METHOD  
 Flaw: Start, in. = 5.000 Length, in. = 8.000 Area, in.^2 = 1.480  
 Depth, in.: Maximum = 0.210 Equivalent Flaw = 0.236  
 Failure Stress, psi = 28328. Failure Pressure, psig = 663.34

\*\*\*\*\* Input Flaw Profile Data \*\*\*\*\*

Length, in.	Depth, in.
0	0
1	0.094
2	0.119
3	0.139
4	0.131
5	0.126

6	0.21
7	0.201
8	0.192
9	0.179
10	0.188
12	0.189
13	0.139
15	0.076
16	0.071
17	0.051
18	0.054
19	0.051
20	0.032
21	0

\*\*\*\*\* Effective Flaw Results \*\*\*\*\*

	Flaw Start, in.	Flaw Length, in.	Effective Area, in.^2	Flow Failure Stress, psi	Japplied, lb/in	Failure Pressure, psig
THOSE BELOW ARE FOR FLOW-STRENGTH FAILURE CRITERION						
i	1	5	8	1.48	28328	10025.2
					6519.7	663.3

## CC Technologies / Det Norske Veritas

CCT/DNV is a leading provider of technology in managing corrosion and materials risks. As one of the few firms to combine practical engineering solutions with state-of-the-art research and testing, we can offer our clients innovative, cost effective solutions. We specialize in engineering, research and testing for corrosion control and monitoring, fitness-for-service, pipeline/plant integrity analysis, materials evaluation and selection, failure analysis, litigation support, management systems approaches and instrumentation and software design and development.

***Pipeline Failure Investigation Report***

**Appendix D**

**Panhandle Close Interval Survey**

**CLOSE INTERVAL POTENTIAL SURVEY**

**LINE 200 24 INCH 2 GATE TO 3 GATE**

**FROM**

**EAST EDGE RIVER**

**TO**

**TS 24.4**

**FOR**

**CMS PANHANDLE EASTERN**


**BY**

**CORRPRO COMPANIES, INC.**

**HOUSTON, TEXAS**


**NOVEMBER, 2000**

Pipe/Soil Potential (mv)




Distance (feet)


Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)



Distance (feet)

-300

-600


-900

-1200

-1500


-1800

Pipe/Soil Potential (mv)






Pipe/Soil Potential (mv)



Distance (feet)


Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)

Distance (feet)	-3000	-6000	-9000	-12000	-15000	-18000	Potential (mv)	
							Left	Right
1076+00							-2138	-2140
1077+00							-2206	-2132
							-2145	-2156
							-2138	-2143
1078+00							-2172	-2132
							-2130	-2135
							-2124	-2135
1079+00							-2151	-2130
							-2130	-2138
							-2124	-2124
1080+00							-2190	-2111
							-2124	-2153
							-2116	-2109
1081+00							-2169	-2109
							-2116	-2116
							-2103	-2116
1082+00							-2167	-2103
							-2103	-2111
							-2106	-2106
1083+00							-2101	-2101
							-2103	-2103
							-2103	-2103
1084+00						-2103	-2103	


Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)

Distance (feet)	-300	-600	-900	-1200	-1500	-1800	
1130+00							-2109
1130+56 CROP EDGE							-2285
							-2362
1131+00							-2247
							-2547
							-2602
							-2660
							-2697
1132+00							-2425
							-2752
							-2755
							-2774
							-2787
							-2760
							-2816
							-2803
							-2803
1133+00							-2824
							-2816
							-2813
							-2702
							-2708
							-2774
1134+00							-2795
							-2837
							-2847
							-2721
							-2668
							-2510
							-2679
							-2697
							-2539
							-2717
							-2708
1135+00							-2826
							-2896
1135+41 C/L CREEK							-2981
							-3175
							-3222
							-3341
							-3373
1136+00							-3428
1136+24 CROP EDGE							-3477
							-3562
							-3568
							-3510
							-3428
							-3336
							-3423
1137+00							-3489
							-3528
1137+61 CROP EDGE							-3560
							-3557
							-3555
							-3697
1138+00							-3575



Pipe/Soil Potential (mv)

Distance (feet)	-300		-600		-900		-1200		-1500		-1800		
1139+00													-4001
													-4106
	1137+76	TS 21.3 FG ON- 3547											-4109
		OFF-1349 NG ON-3781											-4162
		OFF-1327 IR ON+225											-4220
		OFF-24 RECT 21.3 VOLTS											-4156
		21.3 AMPS 46.0 EOS											-4022
	1137+76	CMS PANHANDLE EASTERN 2											-3845
		GATE TO 3 GATE LINE 200											-3980
		24 IN COATED GS TS 21.3											-3980
1140+00		NG ON-3781 OFF-1327											-4064
	1138+31	C/L ASPHALT RD											-4075
	1138+84	MARKER											-3995
	1138+96	C/L FIELD RD											-3961
	1140+26	TOP OF HILL											-3966
	1140+36	FENCE/MARKER											-3824
1141+00													-3940
													-3895
	1141+28	BOTTOM OF HILL											-2681
													-3916
													-3964
													-3929
1142+00													-3858
													-3990
													-4127
													-4188
													-2164
													-4222
													-4217
1143+00													-4228
													-4217
													-4206
													-4209
													-4206
													-4217
													-4204
													-4185
1144+00													-4177
													-4151
													-4048
													-3914
													-3885
													-3850
1145+00													-3766
													-3795
													-3724
													-3731
													-3713
													-3721
1146+00	1145+86	TOP OF HILL											-3733
													-3739
													-3763
													-3774
													-3784
													-3792
													-3787
1147+00													

Distance (feet)

Pipe/Soil Potential (mv)

Distance (feet)	-300	-600	-900	-1200	-1500	-1800		
1148+00							-3739	
							-3753	
							-3737	
							-3695	
							-3642	
							-3644	
							-3615	
1149+00							-3576	
							-3523	
							-3492	
							-3489	
							-3494	
							-3462	
							-3446	
1150+00							-3417	
							-3382	
							-3362	
							-2130	
							-2335	
							-3299	
1151+00							-3264	
							-3264	
							-3256	
							-3262	
							-3235	
							-3209	
							-3151	
1152+00	1152+01 TOP OF HILL							-3180
							-3172	
							-3172	
							-2291	
							-3159	
							-3154	
							-3061	
1153+00							-3167	
							-3169	
							-3164	
							-3095	
							-3143	
							-2317	
							-3138	
							-3148	
1154+00							-3159	
							-3148	
							-3148	
							-3161	
							-3156	
							-3156	
							-2370	
1155+00							-3135	
							-3130	
							-3151	
							-3151	
							-3156	
							-3090	
							-3146	
							-3138	
1156+00							-3090	

Pipe/Soil Potential (mv)

Distance (feet)	-300	-600	-900	-1200	-1500	-1800	
1157+00							-3090
							-3077
							-3077
							-2958
							-3056
1158+00							-3016
							-3011
							-3006
							-2987
							-2987
							-3000
							-2971
							-2958
1159+00							-2903
							-2898
							-2874
							-2855
							-2847
							-2797
1160+00							-2766
							-2752
							-2723
							-2713
							-2681
							-2655
							-2610
							-2586
1161+00							-2549
							-2515
							-2486
							-2454
							-2423
							-2343
							-2341
1162+00							-2288
							-2272
							-2214
							-2214
							-2201
							-2203
							-2174
1163+00							-2114
							-2130
							-2108
1164+00							-2169
							-2225
							-2174
							-2246
							-2256
							-2301
							-2322
1165+00							-2349

1162+76 TOP OF HILL

1164+24 TS NO NUMBER FG ON-2303  
 OFF-1130 NG ON-2156 OFF-  
 1125 IR ON-143 OFF-3  
 RECON WIRE

Distance (feet)

Pipe/Soil Potential (mv)

Distance (feet)	-300	-600	-900	-1200	-1500	-1800	Potential (mv)	
							Left	Right
1166+00							-2438	-2438
1167+00							-2465	-2446
							-2444	-2436
							-2407	-2407
							-2412	-2412
							-2404	-2412
1168+00							-2423	-2430
							-2462	-2454
							-2430	-2425
							-2412	-2415
							-2436	-2445
1169+00							-2457	-2459
1170+00							-2494	-2536
							-2557	-2568
							-2568	-2565
							-2475	-2523
							-2528	-2491
1171+00							-2504	-2502
							-2499	-2504
							-2404	-2510
							-2520	-2507
							-2502	-2499
1172+00							-2528	-2510
							-2512	-2502
							-2504	-2504
							-2196	-2504
							-2504	-2507
1173+00							-2507	-2483
							-2507	-2483
							-2507	-2483
							-2507	-2483
							-2507	-2483
1174+00							-2483	

1168+86 C/L DITCH BOTTOM OF HILL


Distance (feet)

Pipe/Soil Potential (mv)


Distance (feet)	-300	-600	-900	-1200	-1500	-1800	Potential (mv)	
							Left	Right
1175+00							-2481	
1174+64 TOP OF HILL							-2457	
							-2452	
							-2446	
							-2417	
							-2438	
							-2272	
							-2452	
1176+00							-2457	
1176+78 FENCE							-2491	
							-2467	
							-2467	
							-2512	
							-2496	
1177+00							-2499	
							-2499	
							-2536	
							-2507	
							-2507	
1178+00							-2515	
							-2515	
							-2520	
							-2515	
							-2520	
1179+00							-2523	
							-2520	
							-2520	
							-2523	
							-2515	
1179+84 BOTTOM OF HILL							-2523	
							-2557	
							-2520	
							-2552	
							-2512	
1180+00							-2525	
							-2504	
							-2504	
							-2496	
							-2167	
1181+00							-2486	
							-2491	
							-2483	
							-2454	
							-2275	
1182+00							-2433	
							-2399	
							-2404	
							-2401	
							-2388	
1183+00							-2370	
							-2335	
							-2335	
							-2317	
							-2301	
1183+00							-2304	
							-2304	
							-2293	
							-2280	
							-2264	
1183+00							-2248	
							-2248	
							-2243	
							-2203	
							-2156	




Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)




Distance (feet)

Pipe/Soil Potential (mv)




Pipe/Soil Potential (mv)




200B14  
11\*30\*00 DRY  
200\*B14 FIELD

Distance (feet)


Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)



Pipe/Soil Potential (mv)

