

(4) The servicemember of veteran may revoke at any time a transfer described in either paragraph (a)(2) or (3) of this section.

(5) If a veteran attempts to transfer entitlement after 10 years have elapsed from the date he or she has retired, has been discharged or has otherwise been separated from active duty, the transfer shall be null and void.

(10 U.S.C. 2147(a), 2148; Pub. L. 96-342, Pub. L. 99-145)

* * * * *

[FR Doc. 87-15646 Filed 7-9-87; 8:45 am]

BILLING CODE 8320-01-M

FEDERAL MARITIME COMMISSION

46 CFR Part 586

[Docket No. 87-6]

Actions To Adjust or Meet Conditions Unfavorable to Shipping in the United States-Peru Trade

AGENCY: Federal Maritime Commission.

ACTION: Proposed rule—further extension of time to comment.

SUMMARY: Pursuant to a request from three Peruvian-flag carriers, the Federal Maritime Commission is extending the period for filing comments in this proceeding.

DATE: Comments due on or before July 31, 1987 or a date fourteen (14) days after the receipt by the Commission of Memorandum of Understanding regulations promulgated by the Government of Peru, whichever date is the earlier. The earlier comment date, if necessary, will be announced in the Federal Register.

ADDRESS: Send comments (original and 15 copies) to: Joseph C. Polking, Secretary, Federal Maritime Commission, 1100 L Street NW., Washington, DC 20573 (202) 523-5725.

FOR FURTHER INFORMATION CONTACT: Robert D. Bourgoins, General Counsel, Federal Maritime Commission, 1100 L Street NW., Washington, DC 20573 (202) 523-5740.

SUPPLEMENTARY INFORMATION: The Commission instituted this proceeding by Notice published in the Federal Register on April 13, 1987 (52 FR 11832) to address apparent conditions unfavorable to shipping in the United States/Peru trade ("the Trade") pursuant to section 19(1)(b) of the Merchant Marine Act, 1920, 46 U.S.C. app. 876. Comments on the proposed rule were originally due May 13, 1987, however, by Notice of May 11, 1987 ("May Notice") (52 FR 18408) this period was extended until July 3 1987.

In its May Notice, the Commission took note of the Memorandum of Understanding ("MOU") reached between the Government of Peru and the Government of the United States on May 1, 1987. The Commission recognized that the MOU appeared to be a significant development which may be expected to affect access of non-Peruvian-flag carriers to the Trade. Accordingly, the Commission extended the comment period in order to "obtain the views of interested persons on this recent development."

Three Peruvian-flag carriers, Compania Peruana de Vapores, Naviera Neptuno, S.A., and Empresa Naviera Santa, S.A. ("Petitioners"), have now jointly filed a Petition to extend the time for comments "until July 31, 1987, or a date fourteen (14) days after the receipt by the Commission of the regulations promulgated by the Government of Peru to implement the MOU, whichever is the earlier." Petitioners contend that while the proposed regulations from the Government of Peru are under active consideration "it is not anticipated that such regulations will be promulgated sufficiently in advance of July 3, 1987" to allow interested persons to comment.

The U.S. Department of Transportation has advised that discussions with the Government of Peru are ongoing and "if the Commission desires to keep the docket open in order to place the Peruvian regulations in the docket for comment, we would not object to a brief extension of the comment period."

Therefore, the time within which interested parties may file comments in the proceeding is extended to July 31, 1987, or a date fourteen (14) days after the receipt by the Commission of the MOU regulations promulgated by the Government of Peru, whichever date is the earlier.

By the Commission.

Tony P. Kominoth,

Assistant Secretary.

[FR Doc. 87-15710 Filed 7-9-87; 8:45 am]

BILLING CODE 6730-01-M

DEPARTMENT OF TRANSPORTATION

Research and Special Programs Administration

49 CFR Part 178

[Docket No. HM-176A]

DOT 3AL Aluminum Cylinders; Safety Problems

AGENCY: Research and Special Programs Administration (RSPA), DOT.

ACTION: Safety advisory and advance notice of proposed rulemaking.

SUMMARY: Cylinders made of aluminum alloy 6351 manufactured by Luxfer USA Limited in accordance with DOT Specification 3AL (49 CFR 178.46) have developed cracks during service, which occasionally result in leakage and the loss of cylinder contents. The purpose of this notice is to inform all persons that possess DOT 3AL cylinders of the problems, to identify those cylinders at risk, to suggest steps that should be taken to minimize risks, and to request comments concerning the extent of the problem and how to resolve it.

DATE: Comments must be received by August 10, 1987.

ADDRESS: Address comments to: Dockets Unit (DHM-30), Office of Hazardous Materials Transportation, RSPA, U.S. Department of Transportation, Washington, DC 20590. Comments should identify the docket and be submitted, if possible, in five copies. Persons wishing to receive confirmation of receipt of their comments should include a self-addressed stamped postcard. The Dockets Unit is located in Room 8428, Nassif Building, 400 Seventh Street SW., Washington, DC 20590. Public Dockets may be reviewed between the hours of 8:30 a.m. and 5:00 p.m., Monday through Friday.

FOR FURTHER INFORMATION CONTACT: Charles H. Hochman, Technical Division, Office of Hazardous Materials Transportation (OHMT), Research and Special Programs Administration, U.S. Department of Transportation, 400 Seventh Street SW., Washington, DC 20590, (202) 366-4545. Office Hours are 8:30 a.m. to 5:00 p.m.

SUPPLEMENTARY INFORMATION: RSPA is aware of incidents of cracks in the neck and threaded areas of DOT 3AL cylinders manufactured by Luxfer USA Limited (Luxfer) from aluminum alloy 6351. The cracking was first brought to RSPA's attention by persons retesting cylinders under the periodic retest procedures of 49 CFR 173.34.

Five cylinders suspected of having cracks were sent by RSPA to the National Bureau of Standards (NBS) for analysis. They had marked service pressures ranging from 1800 through 2200 pounds per square inch gauge (psig) and were made of both high lead content (100 parts per million or more) and low lead content (less than 100 ppm) varieties of aluminum alloy 6351. The NBS inspection and examination confirmed that each of the five cylinders

exhibited crack-like indications which were at least 0.050 inch deep.

Following the NBS analysis, RSPA requested that Luxfer provide available information concerning leaks or cracks in DOT 3AL cylinders. Luxfer provided information on the number of cylinders returned because of cracks or leakage. This information revealed the following:

(1) Of 3,278 cylinders made of high lead aluminum alloy 6351 and with tapered threads, at least 33 (1.0%) are known to have leaked or had neck or shoulder flaws (i.e., cracks).

(2) Of 60,000 cylinders made of low lead aluminum alloy with tapered threads, 23 (0.038%) are known to have leaked or had neck or shoulder flaws.

(3) Of 312,000 cylinders made of high lead aluminum alloy 6351 with straight threads, 268 (0.086%) are known to have leaked or had neck or shoulder flaws.

(4) Of approximately 5.02 million cylinders made of low lead aluminum alloy 6351 with straight threads, 106 (0.002%) are known to have leaked or had neck or shoulder flaws.

RSPA believes that the above statistics underrepresent the extent of the cracking and leakage problems since NBS noted in its report that identification of cracking is very difficult even when an individual is specifically looking for cracks.

Work performed by Luxfer on neck cracking of DOT exemption hoop wrapped composite cylinders made of aluminum alloy 6351 (which have neck and shoulder areas identical to DOT 3AL cylinders but operated at a higher operating stress level) indicated that cracking is a time dependent phenomenon that is accelerated when the lead content of the alloy exceeds 100 ppm. Further, it was found that the probability of cracking increases with an increase in stress level. Analysis of the stress levels present in the necks of DOT 3AL cylinders indicated that higher stress levels are present in cylinders with tapered threads. This analysis, confirmed by the in-service data, shows that the probability of neck cracking is much higher in DOT 3AL cylinders with tapered threads. Based on Luxfer's analysis and testing, it is anticipated that the frequency of cracks and leakage will increase with the length of time these cylinders are in service. Analysis and testing performed by Luxfer also shows that, for typical DOT 3AL cylinders made of aluminum alloy 6351 (service pressure less than or equal to 3000 psig), the failure mode is by leakage of the cylinder contents and not by bursting. It should be noted that at the present time, only DOT 3AL cylinders made by Luxfer of aluminum alloy 6351 have been reported to RSPA

as having leaked or had neck or shoulder flaws (cracks). Other manufacturers of DOT 3AL cylinders made of aluminum alloy 6351 using different manufacturing processes have reported no leaks or neck or shoulder flaws in a total population in excess of 1 million cylinders. Further, all of the information available to RSPA indicates that cylinders made of aluminum alloy 6061, the other alloy authorized by specification DOT 3AL, are not susceptible to the cracking problems that have arisen in cylinders made aluminum alloy 6351.

DOT 3AL cylinders are authorized to be manufactured from two aluminum alloys, 6061 and 6351. Based on information presently available to DOT, the overwhelming majority of DOT 3AL cylinders produced have been made of aluminum alloy 6351. However, the number identifying the alloy used is not required to be stamped on the cylinder. The only way to determine which alloy was used to manufacture a DOT 3AL cylinder is through the cylinder manufacture using the serial number applied by the manufacturer when the cylinder was made.

DOT 3AL cylinders are authorized and used for the transportation of a number of extremely hazardous materials. These include poisonous and flammable gases, liquids which are toxic by inhalation (see 49 CFR 173.3a) and oxygen. It should be noted that tapered threads are required on cylinders used for Poison A materials, but not for other toxic gases that are not identified as Poison A materials such as diborane or hydrogen selenide.

RSPA is initiating rulemaking to correct any regulatory deficiencies concerning the manufacture, maintenance and use of cylinders made under specification DOT 3AL. In the interim, this notice serves to inform all persons in possession of DOT 3AL cylinders of the cracking problem, and recommends that those persons take the following steps to minimize risks:

DOT 3AL Cylinders Made of High Lead Aluminum Alloy 6351 With Tapered Threads

DOT 3AL cylinders made of high lead (greater than 100 ppm) aluminum alloy 6351 manufactured by Luxfer USA Limited in 1982 and 1983 bearing the serial numbers which appear in Appendix A to this document should not be refilled or used in hazardous materials service. Both RSPA and Luxfer have been in contact with the original purchasers of these cylinders and requested that the cylinders be removed from service and returned to Luxfer as soon as practicable. Persons in

possession of a cylinder listed in Appendix A should contact the cylinder supplier for proper disposition of the cylinder.

All DOT 3AL Cylinders Made of Aluminum Alloy 6351

DOT 3AL cylinders which presently contain Poison A materials, flammable gases, pyrophoric liquids or gases, liquids toxic by inhalation or highly toxic gases other than Poison A should be stored in well ventilated areas. Additionally, DOT 3AL cylinders containing oxygen, if stored or used in confined spaces, should be checked for leakage to prevent the possibility of an oxygen enriched environment.

Each person possessing a leaking DOT 3AL cylinder which contains a Poison A material, a flammable gas, a pyrophoric liquid or gas, liquids toxic by inhalation or a toxic gas other than Poison A, should contact the material supplier (the name and address of the supplier is found on the shoulder decal of the cylinder) or the cylinder manufacturer. Leaking cylinders may not be offered for transportation.

Advance Notice of Proposed Rulemaking

RSPA is requesting additional information from manufacturers and users of DOT 3AL cylinders. RSPA requests that anyone having information on cracked or leaking DOT 3AL cylinders provide this information to RSPA in written form. Additionally, comments are solicited on ways to address the cracking problem in DOT 3AL cylinders and controls that may be necessary for the continued use of existing cylinders.

Issued in Washington, DC, on July 6, 1987 under authority delegated in 49 CFR Part 106, Appendix A.

Alan I. Roberts,
Director, Office of Hazardous Materials
Transportation.

PART 178—[AMENDED]

APPENDIX A—DOT 3AL CYLINDERS, MADE OF HIGH LEAD ALUMINUM ALLOY 6351 WITH TAPERED THREADS

Serial No.	Cast code
ALQ 11-64.....	897-898
ALQ 82.....	897
SG 201-301.....	129-132
SG 303-368.....	131-133
SG 377.....	934
SG 381-382.....	934
SG 392.....	934
SG 395-396.....	933-934
SG 416.....	934
SG 421.....	934
SG 425-431.....	932-934
SG 433-449.....	931-933
SG 451-453.....	932-933
SG 455-459.....	932-933

APPENDIX A—DOT 3AL CYLINDERS MADE OF
HIGH LEAD ALUMINUM ALLOY 6351 WITH
TAPERED THREADS—Continued

Serial No.	Cast code
SG 461-474.....	932-934
SG 476.....	934
SG 480-482.....	934
SG 484.....	934
SG 486-487.....	934
SG 489.....	933
SG 503-510.....	933-934
SG 520-521.....	934
SG 525-528.....	934
SG 531-532.....	934
SG 534-535.....	934
SG 538.....	934
SG 544.....	933
SG 548-582.....	931-932
SG 584.....	931
SG 586-589.....	932
SG 591-594.....	931-932
SG 596-620.....	129-132/931-932
SG 622-635.....	129-133
SG 637-661.....	130-133
SG 665.....	931
SG 667.....	934
SG 689.....	934
SG 703.....	934
SG 706-725.....	131-132
AL 554.....	932
AL 577-589.....	932-933
AL 591-593.....	933
AL 595-617.....	932-933
AL 619.....	934
AL 621-623.....	934
AL 628-631.....	934
AL 633-635.....	934
AL 675.....	934
AL 677-678.....	934/129
AL 681.....	132
AL 683.....	129
AL 685-686.....	129/132
AL 688-692.....	120/132
AL 698.....	934
AL 701.....	130
AL 704.....	934
AL 706-735.....	129-130
AL 738.....	129
AL 740-741.....	130
AL 743.....	130
AL 745.....	129
AL 748.....	130
AL 753.....	130
AL 756.....	130
AL 766.....	129
AL 768-722.....	129
AL 774-776.....	129
AL 88001-88013.....	897-898
AL 88015-88041.....	897-898
AL 88043-88048.....	897-898
AL 88050.....	897
AL 88091-88093.....	898-899/64
LL 1142-1149.....	850/897
LL 1151-1177.....	897
LL 1270.....	899
LL 1287.....	34
LL 1290.....	33
LL 1294-1295.....	952/32
LL 1303.....	953
LL 1312.....	897
LL 1314-1315.....	897
LL 17990-18010.....	897-898
LL 18012-18015.....	898
LL 18018-18031.....	897-898
LL 18106.....	898
LL 18158-18160.....	897
LL 18172-18251.....	897-898/850
LL 18253-18276.....	897-898
LL 18280-18290.....	897-898/850
LL 18292-18315.....	897-898/850
LL 18318-18321.....	897-898/850
LL 18323-18328.....	897-898/850
LL 18330-18334.....	897-898
LL 18336-18350.....	897-898/850
LL 18352-18359.....	897-898/850
LL 18361-18368.....	897-898
LL 18453-18459.....	897-898/850
LL 18463-18478.....	897-898/850
LL 18481-18496.....	897-898/850
LL 18498-18500.....	897-898
LL 18502-18507.....	897-898
LL 18510-18512.....	898

APPENDIX A—DOT 3AL CYLINDERS MADE OF
HIGH LEAD ALUMINUM ALLOY 6351 WITH
TAPERED THREADS—Continued

Serial No.	Cast code
LL 18516-18587.....	897-898
LL 18589-18636.....	897-898/850
LL 18638-18639.....	897-898
LL 18641-18653.....	897-898
LL 18655-18657.....	897-898
LL 18757.....	898
LL 18760-18763.....	898-899
LL 18765.....	899
LL 18772-18773.....	899
LL 18775.....	898
LL 18787-18788.....	899/953
LL 18792-18793.....	898
LL 18811.....	953
LL 18818.....	899
LL 31845.....	132
IL 2038.....	931
IL 2041-2042.....	931-932
IL 2044.....	931
IL 2051.....	931
IL 2064.....	932
IL 2070-2071.....	931-932
IL 2098.....	932
IL 2168.....	932
IL 2170-2173.....	931
IL 2177.....	931
IL 2183.....	931
IL 2188.....	931
IL 2193.....	931
IL 2198-2199.....	931-932
IL 2287.....	931
IL 2291-2292.....	931
IL 2294-2295.....	931
IL 2297.....	931
IL 2300.....	931
IL 2307.....	931
IL 2614.....	934
IL 2629.....	934
IL 2633-2634.....	934
IL 2643.....	934
IL 2645-2648.....	934
IL 2650-2652.....	934
IL 2654.....	934
IL 2657-2659.....	934
IL 2662.....	934
IL 2666.....	934
BAL 3007.....	64
BAL 3023.....	953
BAL 3202.....	897
BAL 3280.....	953
AAL 10256-10295.....	931-932
AAL 10306-10313.....	931-932
AAL 10321-10322.....	931
AAL 10325.....	931
AAL 10340-10367.....	931
AAL 10369.....	932
AAL 10374.....	932
AAL 10376-10455.....	931-933
AAL 10463.....	932
AAL 10475-10476.....	931
AAL 10528-10567.....	931-933
AAL 10569-10570.....	932-933
AAL 10572.....	933
AAL 10575-10576.....	933
AAL 10579-10584.....	933
AAL 10587.....	933
AAL 10589-10637.....	932-933
AAL 10639-10691.....	931-933
AAL 10693-10707.....	932-933
AAL 10709-10807.....	931-933
AAL 10809-10814.....	933
AAL 10816-10905.....	931-933
AAL 10909.....	934
AAL 10911-10913.....	934
AAL 10920.....	934
AAL 10927-10928.....	934
AAL 10946.....	932
AAL 10966.....	934
AAL 10975.....	934
AAL 10982.....	934
AAL 10991.....	934
AAL 10993.....	934
AAL 11001.....	934
AAL 11004.....	934
AAL 11009.....	934
AAL 11019.....	934
AAL 11025.....	934
AAL 11032.....	934
AAL 11043.....	934
AAL 11045-11046.....	934

APPENDIX A—DOT 3AL CYLINDERS MADE OF
HIGH LEAD ALUMINUM ALLOY 6351 WITH
TAPERED THREADS—Continued

Serial No.	Cast code
AAL 11048-11050.....	934
AAL 11053-11058.....	934
AAL 11060-11061.....	934
AAL 11070.....	934
AAL 11072-11073.....	934
AAL 11076-11080.....	934
AAL 11082-11097.....	934
AAL 11100.....	934
AAL 11102-11113.....	934
AAL 11119.....	934
AAL 11121.....	934
AAL 11128-11131.....	934
AAL 11133.....	934
AAL 11135.....	934
AAL 11141.....	934
AAL 11143-11146.....	934
AAL 11170.....	934
AAL 11184.....	934
AAL 11187-11188.....	934
AAL 11190-11191.....	934
AAL 11193.....	934
AAL 11197.....	934
AAL 11199-11200.....	934
AAL 11204.....	934
AAL 11208-11209.....	934
AAL 11214.....	934
AAL 11217-11219.....	934
AAL 11228-11229.....	934
AAL 11255.....	934
AAL 11278-11280.....	934
AAL 11282.....	934
AAL 11286-11289.....	934
AAL 11291-11297.....	934
AAL 11299.....	934
AAL 11305.....	934
AAL 11308.....	934
AAL 11310-11314.....	931-934
AAL 11316-11329.....	932-934
AAL 11336-11337.....	934
AAL 11340.....	934
AAL 11342-11348.....	934
AAL 11351.....	934
AAL 11364-11411.....	129-132
AAL 11413-11420.....	129-130
AAL 11422-11431.....	129-130/934
AAL 11433.....	130
AAL 11435-11470.....	130/933
AAL 11472-11478.....	129-130
AAL 11480-11481.....	130
AAL 11483-11484.....	130
AAL 11486.....	932
AAL 11488.....	130
AAL 11490.....	130
AAL 11492.....	130
AAL 11494-11498.....	129-130
AAL 11502-11504.....	132/932
AAL 11506.....	931
AAL 11512-11515.....	130/931/937
AAL 11517-11541.....	129/133/932-933
AAL 11543-11545.....	129
AAL 11549-11553.....	129
AAL 11558-11583.....	129-130/132-133/934
AAL 11586-11590.....	934
AAL 11604-11627.....	129/131-133/932-933
AAL 11629-11771.....	129/131-133/169-172
AAL 11774.....	129
AAL 11780.....	130
AAL 11787.....	130
AAL 11790.....	129
AAL 11792.....	130
AAL 11795.....	129
AAL 11802-11881.....	168-172
AAL 12068-12092.....	168-172
AAL 12097-12099.....	170-171
AAL 12106-12119.....	168-171
SX 16567-16573.....	931-932
SX 16579.....	931
SX 16581.....	931
SX 16584-16587.....	927/931
SX 16597.....	931
SX 16607.....	931
SX 16612.....	931
SX 16615.....	932
SX 16617-16618.....	932
SX 16620.....	932

APPENDIX A—DOT 3AL CYLINDERS MADE OF
HIGH LEAD ALUMINUM ALLOY 6351 WITH
TAPERED THREADS—Continued

Serial No.	Cast code
SX 16623.....	932
SX 16627-16757.....	129-133/932-932
SX 16759-16841.....	129-133/931-932
SX 16843-16966.....	129-130/132/169-172/934
SX 17003.....	133
SX 17829.....	898
SX 17831.....	898
SX 17833-17839.....	897-898
SX 17841-17845.....	897-898
CC 30704-30705.....	931
CC 30708-30709.....	931
CC 30712-30714.....	931
CC 30716-30729.....	931-932
CC 30774-30748.....	931-932
CC 30750.....	931
CC 30752-30754.....	931
CC 30756-30758.....	931-932
CC 30969.....	934
CC 31003-31007.....	934
CC 31032-31033.....	933-934
CC 31040.....	934
CC 31048.....	934
CC 31051.....	934
CC 31054.....	934
CC 30158.....	934
CC 31062.....	934
CC 31066-31067.....	934
CC 31070-31072.....	934
CC 31074-31076.....	934
CC 31082.....	934
CC 31084-31090.....	934
CC 31092.....	934
CC 31103.....	934
CC 31107.....	934
CC 31124-31126.....	934
CC 31128-31130.....	934
CC 31132.....	934
CC 31135.....	934
CC 31137-31138.....	934
CC 31142-31144.....	934
CC 31146.....	934
CC 31180.....	934
CC 31182.....	934
CC 31186.....	934
CC 31712.....	934
CC 31715-31717.....	934
CC 31719.....	934
CC 31722-31725.....	933-934
CC 31727-31729.....	934
CC 31732-31735.....	934
CC 31846-31857.....	131-132/932/934
CC 31860-31861.....	933-934
CC 31863.....	934
CC 31866.....	934
CC 31921-31940.....	129-130/132
CC 31942-32020.....	129-130/132
CC 32022-32051.....	130-132/934
CC 32070.....	129
CC 32899.....	131
CC 32939.....	131
CC 36643-36667.....	169-171
CC 36673-36772.....	169-172
CC 36774-36780.....	169-171
CC 36782-36835.....	169-172
CC 36837-36840.....	170
CC 36842-36847.....	170-171
CC 36849-36922.....	169-171
MM 217833-217857.....	1/4/999
MM 220349-220350.....	262
MM 220353-220354.....	262
MM 220358.....	262
MM 220362-220365.....	262
MM 220367-220371.....	261-262

DEPARTMENT OF THE INTERIOR

Fish and Wildlife Service

50 CFR Parts 13 and 21

**Availability of a Draft Environmental
Assessment on Falconry and Raptor
Propagation Regulations**

AGENCY: Fish and Wildlife Service,
Interior.

ACTION: Notice of availability.

SUMMARY: This Notice advises the public that a Draft Environmental Assessment on Falconry and Raptor Propagation Regulations is available for public review. Comments and suggestions are requested.

FOR FURTHER INFORMATION: Dr. Rollin D. Sparrowe, Chief, Office of Migratory Bird Management, U.S. Fish and Wildlife Service, Department of the Interior, Washington, DC 20240 (202-254-3207).

ADDRESSES: Copies of the Draft Assessment can be obtained by writing to Director (FWS/MBMO), Room 536 Matomic Bldg., U.S. Fish and Wildlife Service, Washington, DC 20240, or by visiting the Office of Migratory Bird Management, U.S. Fish and Wildlife Service, Room 536 Matomic Building, 1717 H Street NW., Washington, DC 20240. Written comments can be sent to the same address.

DATE: Written comments are requested by September 30, 1987.

SUPPLEMENTARY INFORMATION: The Fish and Wildlife Service (Service) had announced its intention to evaluate the subject on May 22, 1986 (51 FR 18812) in accordance with National Environmental Policy Act procedures. A public meeting was held June 24, 1986, in Washington, DC to obtain comments and suggestions for the scope and content of the evaluation.

The Draft Assessment reviews regulations governing falconry and raptor propagation, discusses the current status of raptor populations and proposes changes to the regulations. Three general areas of contention are addressed: the regulations per se, the provision allowing the sale of captive-produced raptors, and resuming take of arctic peregrine falcons for falconry. The Service's proposed action is to simplify the falconry regulations, to retain the sale provision and to retain the ban on taking arctic peregrine falcons. Seven alternatives to this proposed action are considered.

Dated: July 2, 1987.

Frank Dunkle,
Director, U.S. Fish and Wildlife Service.
[FR Doc. 87-15612 Filed 7-9-87; 8:45 am]
BILLING CODE 4310-55-M

50 CFR Part 17

**Endangered and Threatened Wildlife
and Plants; Proposal To Determine
Amsonia Kearneyana To Be an
Endangered Species**

AGENCY: Fish and Wildlife Service,
Interior.

ACTION: Proposed rule.

SUMMARY: The U.S. Fish and Wildlife Service proposes to determine that a plant, *Amsonia kearneyana* (Kearney's blue-stem), is an endangered species. This plant is known from a single canyon on the western slopes of the Baboquivari Mountains on the Tohono O'odham (formerly Papago) Indian Reservation in Arizona. The entire population consists of eight plants and is currently being threatened by habitat degradation from cattle grazing and possibly by insect predation on the seeds. A final determination that *Amsonia kearneyana* is endangered will implement the protection provided by the Endangered Species Act of 1973 (Act), as amended. The Service seeks data and comments from the public on this proposal.

DATES: Comments from all interested parties must be received by September 8, 1987. Public hearing requests must be received by August 24, 1987.

ADDRESSES: Comments and materials concerning this proposal should be sent to the Regional Director, U.S. Fish and Wildlife Service, P.O. Box 1306, Albuquerque, New Mexico 87103. Comments and materials received will be available for public inspection, by appointment, during normal business hours at the Service's Regional Office of Endangered Species, 500 Gold Avenue, SW., Room 4000, Albuquerque, New Mexico.

FOR FURTHER INFORMATION CONTACT: Sue Rutman, Endangered Species Botanist, Albuquerque, New Mexico (See "ADDRESSES" above) (505/766-3972 or FTS 474-3972).

SUPPLEMENTARY INFORMATION:

Background

Amsonia kearneyana is a herbaceous perennial that is endemic to a single west-draining canyon in the Baboquivari Mountains, southern Pima County, Arizona. *Amsonia kearneyana* grows in the riparian vegetation zone lining a dry,

[FR Doc. 87-15684 Filed 7-9-87; 8:45 am]

BILLING CODE 4910-60-M