

## Table of Contents

| Section                                                                                                     | Page No. |
|-------------------------------------------------------------------------------------------------------------|----------|
| 1.0 INTRODUCTION.....                                                                                       | 1        |
| 2.0 BACKGROUND .....                                                                                        | 1        |
| 2.1 <u>Significance of the Problem</u> .....                                                                | 1        |
| 2.2 <u>Methods of Inspection</u> .....                                                                      | 2        |
| 2.2.1 Visual Testing (VT).....                                                                              | 2        |
| 2.2.2 Eddy Current Testing (ET).....                                                                        | 3        |
| 2.2.3 Ultrasonic Testing (UT).....                                                                          | 3        |
| 3.0 TEST PROCEDURE.....                                                                                     | 6        |
| 3.1 <u>Nondestructive Testing</u> .....                                                                     | 6        |
| 3.2 <u>Destructive Analysis</u> .....                                                                       | 8        |
| 4.0 RESULTS.....                                                                                            | 18       |
| 4.1 <u>Detectability</u> .....                                                                              | 18       |
| 4.2 <u>Flaw Sizing (Comparison with Etching Procedure)</u> .....                                            | 19       |
| 4.3 <u>EDM Results</u> .....                                                                                | 31       |
| 5.0 CONCLUSIONS AND RECOMMENDATIONS .....                                                                   | 34       |
| Appendix A Glossary of Terms                                                                                |          |
| Appendix B: Bryant-Lee Associates Data Report on EDM and Measurement of Cracks on Aluminum Cylinder Samples |          |
| Appendix C: Data Sheets                                                                                     |          |

## List of Figures

| Figure No.                                                                                                            | Page No. |
|-----------------------------------------------------------------------------------------------------------------------|----------|
| 2-1 Illustration of the Site of Crack Initiation and its Propagation through the Cylinder.....                        | 2        |
| 2-2 VT Equipment used to Visually Inspect the Compressed Gas Cylinders for this Project.....                          | 2        |
| 2-3 Orientation of the Flaw with Respect to the Eddy Currents has a Direct Bearing on the Detection of the Flaw ..... | 3        |
| 2-4 Eddy Current Equipment used in the Project .....                                                                  | 4        |
| 2-5 Closeup of an Eddy Current Probe .....                                                                            | 4        |

|      |                                                                                                                                                   |    |
|------|---------------------------------------------------------------------------------------------------------------------------------------------------|----|
| 2-6  | UT Inspection System, Consisting of One Pitch and One Catch Probe<br>Inside a Fluid-Filled Wheel.....                                             | 5  |
| 2-7  | Example of a UT Inspection In Progress.....                                                                                                       | 5  |
| 3-1  | Illustration of the Test Progression Used in the Project.....                                                                                     | 7  |
| 3-2  | Each Cylinder Head was Cut to Isolate the Cracks of Interest .....                                                                                | 9  |
| 3-3  | The Apparatus used to Break Open the Cracks in a Cylinder Head.....                                                                               | 10 |
| 3-4  | Close up View of the Crack Opening Procedure .....                                                                                                | 10 |
| 3-5  | Screen Shot of the Java Application ImageJ Produced by NIH, being used<br>to Find the Cross-sectional Area of a Crack in a SCUBA Cylinder .....   | 11 |
| 3-6  | Measuring the Extent of a Crack. The highlighted region shows the<br>approximate extent of the crack along the line in the upper left image. .... | 12 |
| 3-7  | Photographs of the Red-Dye Penetrant Indication for (A) Cylinder<br>Samples T94863 and (B) P4205. Arrows indicate cracks.....                     | 14 |
| 3-8  | Sketch Showing how the EM Wafers were Taken .....                                                                                                 | 15 |
| 3-9  | Photographs of Cylinder Sample T94863 and P4205 Showing (a) the OD<br>Surface and (b) the ID Surface .....                                        | 16 |
| 3-10 | EDM Set-Up for Cylinder Sample.....                                                                                                               | 17 |
| 4-1  | Reported Flaw Size for the Crack in SCUBA Cylinder P157756 for Each<br>Inspection.....                                                            | 22 |
| 4-2  | Average Flaw Sizes for the Crack in P157756 for Technique and Skill<br>Level .....                                                                | 22 |
| 4-3  | Reported Flaw Size for the Crack in SCUBA Cylinder P16297 for Each<br>Inspection.....                                                             | 23 |
| 4-4  | Average Flaw Sizes for the Crack in P16297 for Technique and Skill Level .....                                                                    | 23 |
| 4-5  | Reported Flaw Size for the First Crack in SCUBA Cylinder P101050 for<br>Each Inspection.....                                                      | 24 |
| 4-6  | Average Flaw Sizes for the First Crack in P101050 for Technique and Skill<br>Level .....                                                          | 24 |

|      |                                                                                                                                                                                                                                                                                            |    |
|------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| 4-7  | Reported Flaw Size for the Second Crack in SCUBA Cylinder P101050 For Each Inspection.....                                                                                                                                                                                                 | 25 |
| 4-8  | Average Flaw Sizes for the Second Crack in P101050 for Technique and Skill Level.....                                                                                                                                                                                                      | 25 |
| 4-9  | Reported Flaw Size for the First Crack in SCBA Cylinder T58636 for Each Inspection.....                                                                                                                                                                                                    | 26 |
| 4-10 | Average Flaw Sizes for the First Crack in T58636 for Technique and Skill Level .....                                                                                                                                                                                                       | 26 |
| 4-11 | Reported Flaw Size for the Second Crack in SCBA Cylinder T58636 for Each Inspection.....                                                                                                                                                                                                   | 27 |
| 4-12 | Average Flaw Sizes for the Second Crack in T58636 for Technique and Skill Level.....                                                                                                                                                                                                       | 27 |
| 4-13 | Mean Absolute Discrepancy (MAD) Results by Inspection.....                                                                                                                                                                                                                                 | 28 |
| 4-14 | Mean Absolute Discrepancy (MAD) Results by Technique and Skill Level.....                                                                                                                                                                                                                  | 28 |
| 4-15 | Production of the UT Calibration Curve .....                                                                                                                                                                                                                                               | 30 |
| 4-16 | Photomicrographs of the (a) apparent Crack Tip at 0.490-inch from Bore ID and (b) Crack Tip Region at 0.665-inch from Bore ID for Wafer A5.....                                                                                                                                            | 33 |
| 5-1  | Summary of the Test Results, Plotting Each Technique's Mean Absolute Discrepancy (MAD) Against it's Reliability Index (RI). An ideal technique would be plotted at the origin (0,0), representing a technique that has no false calls and that perfectly sizes every flaw it detects. .... | 36 |
| 5-2  | Average Performances Across Technique and Skill Level. As in Figure 5-1 the ideal case is to be at the origin (0,0). ....                                                                                                                                                                  | 36 |

### List of Tables

| Table No. |                                                                                  | Page No. |
|-----------|----------------------------------------------------------------------------------|----------|
| 3-1       | Nine Different NDT Inspections were Conducted for each of the 51 Cylinders ..... | 6        |
| 4-1       | Summary of Results Using an Angular Width of $\pm 20^\circ$ .....                | 18       |
| 4-2       | Summary of Results Using an Angular Width of $\pm 30^\circ$ .....                | 19       |

|     |                                                                                                                              |    |
|-----|------------------------------------------------------------------------------------------------------------------------------|----|
| 4-3 | Cylinders Chosen for the Flaw Sizing Analysis .....                                                                          | 20 |
| 4-4 | Summary of the Flaw Sizing Study .....                                                                                       | 21 |
| 4-5 | Example of the Aspect Ratios Seen During the Flaw Sizing Study .....                                                         | 30 |
| 4-6 | Wafer Location and Crack Depth for T94863 .....                                                                              | 31 |
| 4-7 | Wafer Location and Crack Depth for P4205 .....                                                                               | 32 |
| 4-8 | Reported Flaw Size for the Flaw in SCBA Cylinder T94863, for Which the<br>Actual Flaw Size is Approximately 14 Threads ..... | 34 |
| 4-9 | Reported Flaw Size for the Flaw in SCBA Cylinder T94863, for Which the<br>Actual Flaw Size is Approximately 14 Threads ..... | 34 |