



## Enforcement Notice

### Pipeline and Hazardous Materials Safety Administration Calendar Year 2010 Notice of Hazardous Materials Regulations Enforcement

The Pipeline and Hazardous Materials Safety Administration (PHMSA) today gave notice to the regulated industry and its stakeholders of the 510 hazardous materials civil penalty actions it closed in calendar year 2010 and collected \$1,533,278 in penalties.

It is the task of PHMSA's Hazardous Materials Field Operations staff to improve compliance with the safety and training standards of the HMR by inspecting companies and individuals who offer hazardous materials for transportation or who manufacture, maintain, repair, recondition or test packages authorized for transporting hazardous materials.

Company	SUMMARY	Penalty
Mace Security International, Inc. Bennington VT (Shipper Inspection (Explosive))	Offered consumer commodity ORM-D packaged in containers not marked as meeting the DOT-2P or DOT-2Q certification, therefore, shipped an unauthorized packaging. [173.306(a)] Case No: 09-0032-SC-EA	\$ 1,000
I-K-I Manufacturing Co., Inc. Edgerton WI (Shipment Observation (General))	Offered oxygen, compressed, 2.2 (5.1), in unauthorized specification DOT 2Q metal inner receptacles. [173.22(a)(2); 173.302(a); 173.302a(a)] Case No: 09-0145-SC-EA	\$ 5,250
Precision Hydro Testing, LLC Lawrenceville GA (Cylinder Retester)	Failed to provide employee general awareness and security awareness training, or create and retain records of training testing; failed to condemn a cylinder having excessive permanent expansion. [180.205(i)(1)(iv); 172.702(a); 172.704(a)(1) and (4); 172.704(d)] Case No: 05-0491-CR-SO	\$ 5,000
A-One Chemicals & Equipment Company, Inc. Deer Park TX (Shipper)	Failed to develop a security plan that addresses personnel security, unauthorized access, and en- route security and failed to have a risk assessment associated with the security plan; failed to properly mark the packagings; offered and transported hazardous materials, accompanied by shipping papers that failed to	\$ 7,174

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	include (1) a shipping description that is not in the required sequence, (2) additional information interspersed within the basic description, (3) no or incorrect packing group and (4) the number and type of packages for the material. Failed to remove bulk containers from the motor vehicle prior to discharging the contents of the containers. [172.201(a)(4); 172.202(a)(4) and (7); 172.202(b); 172.301(b); 172.302(a) and (b); 172.406(e); 172.800(a); 177.834(h)] Case No: 09-0138-SDIBC-SW	
Shorty USA, Inc., dba Airsoft USA Newark DE (Shipper)	Failed to provide general awareness, function-specific, safety and security awareness training; offered petroleum gases liquefied, 2.1, when the material was not properly classed, therefore, failed to mark, label, and describe the material as specified when emergency response information, including an emergency response telephone number were not provided. [172. 200; 172. 300; 172.400; 102/602; 172.604; 172.702(a)] Case No: 07-0129-SB-EA	\$ 8,835
Superior Manufacturing Detroit MI (Shipper)	Offered trichloroethylne, 6.1, in an overpack and failed to mark boxes with orientation arrows and the word "OVERPACK"; failed to provide general awareness, function-specific, security awareness training and in-depth security training; offered amines, liquid, corrosive, n.o.s. (contains isophorone diamine), 8, in an unauthorized non-UN combination packaging, when specification packaging is prescribed; offered amines, liquid, corrosive, n.o.s. (contains isophorone diamine), 8, and trichloroethelyne, 6.1, accompanied by shipping papers that failed to describe proper shipping name of the hazardous material. [172.704(a)(1), (2), (4) and (5); 172.704(d); 172.702(a); 173.203(b); 173.22(a)(1); 173.24(c); 173.25(a)(3) and (4); 173.22; 177.801; 172.201(a); 172.202(a)(1)and (2)] Case No: 09-0053-SPB-CE	\$ 2,970
Monfredo, Anthony, d/b/a Hamilton Fire & Safety Equipment Richland NJ (Cylinder Retester)	Failed to maintain complete and accurate records of cylinder requalification; failed to calibrate its test equipment each day before testing; failed to maintain hazardous materials training records; failed to notify the Associate Administrator for Hazardous Materials Safety, in writing, of a change in personnel performing cylinder requalification testing. [180.205(g)(3) and (4); 180.215(b)(2); 107.805(g); 172.704(d)] Case No: 07-0180-CR-EA	\$ 1,000
Atlas Chemical, Inc. San Diego	Failed to provide recurrent general awareness, function-specific, safety, and security awareness training; filled	3,300

## PHMSA Notice of Hazardous Materials Regulations Enforcement

CA (Shipper)	and offered RQ sodium hydroxide, solution, PG II' in a non UN specification packaging when specification packaging is prescribed; filled and offered hazardous materials, in UN-certified 5-gallon plastic jerri-cans that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(2); 173.24(c); 173.202(a); 173.203; 173.22(a)(4); 173.24(f)(2); 172.202; 172.702(b);172.704(a)(2)(i)] Case No: 08-0106-SD-SW	
Rick's LP Gas dba Ozark Mountain Propane Little Rock AR (Carrier)	Transported propane, 2.1, in a non-DOT/UN standard storage tank designed for permanent installation when the tank was charged to more than five percent of its water capacity; Failed to provide initial and recurrent general awareness , function-specific, safety, and security awareness training; filled and offered a cylinder with compressed gas when the cylinder is overdue for periodic requalification; offered liquefied petroleum gas, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [173.315(j)(4); 173.301(a)(6); 180.205(c); 172.201(d); 172.604(b); 172.702(b);172.704(a)(1)-(4); 172.704(c)(2)] Case No: 08-0172-CC-SW	\$ 9,720
MO Valley AG Rock Port MO (Shipper)	Offered and transported ammonia, anhydrous, 2.2, in an unauthorized packaging. [173.22(a), 173.24(c); 173.315(a), 173.315(a)(2); 173.315(m)] Case No: 09-0052-SNT-CE	\$ 2,975
Clawson Container Company Clarkston MI (Package Purchasing)	Respondent represented, marked, certified and sold a hazardous materials packaging when the specific design type was not capable of passing the required tests; respondent created test reports for design qualification testing of hazardous materials packagings when the reports contained inaccurate information and did not contain all required information. [178.801, 178.810; 178.819; 178.703(a)(1)(viii); 178.801(l)(1)] Case No: 04-548-IBCM-SW	\$ 9,463
Caribsupply, Inc. Christiansted VI (Cylinder Retester)	Offered acetylene, 2.2, and other gases, accompanied by shipping papers, which contained an unauthorized emergency response telephone number; failed to maintain complete and accurate records of cylinder requalification; offered acetylene, 2.1, among others, accompanied by a shipping paper that failed to list the hazard class or listing an incorrect hazard class for the material; represented, certified and marked DOT specification cylinders as having been successfully requalified and failed to maintain a current requalifiers identification number (RIN) issued by the US DOT	\$ 8,640

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	PHMSA Approvals Office; failed to maintain copies of the applicable sections of the regulations at its retest facility, a copy of Special Permit 9791 and information contained in each CGA pamphlet applicable to the requalifier's activities; failed to provide recurrent general awareness and security awareness training. [107.805(a); 180.205(b); 172.604(b); 180.215(b)(2); 180.215(a)(4)-(6); 172.702(a); 172.704(a)(1) and (4); 172.202(a)(3)] Case No: 08-0032-CR-SO	
Dettmer Farm Service Auburn NE (Shipper)	Offered ammonia, anhydrous, 2.2, in an unauthorized packaging. [173.22(a)(2); 173.24(c); 173.315(a); 173.315(a)(2); 173.315(m)] Case No: 09-0033-SNT-CE	\$ 1,500
Shamrock Fiberglass Lafayette CA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training. [172.702(a); 172.704(a)(1)-(4); 172.704(c)(1) and (d)] Ticket No: 09T-0399-SD-WE	\$ 720
Sungas Services Miami FL (Shipper)	Offered liquefied petroleum gas, 2.1, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; failed to provide function-specific training concerning requirements contained in the Special Permit 14296; offered liquefied petroleum gas, 2.1, and failed to provide (1) a copy of Special Permit 1426 to the carrier before or at the time of shipment, and (2) to maintain a copy of the special permit at the facility where the package was offered for transportation; failed to register with PHMSA. [173.22a(b) and (c); DOT-SP 14296 Special Provisions (8)(c) and (10)(a); 172.203(a); 172.704(a)(2); DOT-SP 14296(11)(b); 107.608(a) and (b)] Ticket No: 09T-0438-SSP-SO	\$ 2,275
Celebration Fireworks, Inc. Kutztown PA (Shipper Inspection (Explosive))	Offered fireworks, 1.3G, accompanied by a shipping paper that did not have the basic description in the proper sequence; reshipper offered fireworks, 1.3G, that were not approved by the Associate Administrator, therefore, shipping unapproved fireworks; offered fireworks, 1.3G, and failed to include the explosive approval number either on the shipping paper or the package for the material. [173.56(b) and (j); 172.202(a) and (b); 172.320(a) and (b)] Ticket No: 09T-0408-SB-EA	\$ 3,150
Fire Safety First (The Brethern d.b.a.) Santa Ana CA (Cylinder Retester)	Failed to maintain complete and accurate records of cylinder requalification; failed to provide general awareness training. [180.215(b)(2); 172.702(b); 172.704(a)(1); 172.704(c)(2) and (d)] Ticket No: 09T-0362-CR-WE	\$ 580

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Spang Fuel, Inc. Kennebunkport ME (Carrier)	Offered in a bulk packaging, fuel oil, and failed to create a proper shipping paper to document a shipment of hazardous materials; failed to provide general awareness, function-specific, safety, security awareness, and in-depth security training; failed to register with PHMSA. [107.608(a) and (b); 177.200(a); 172.702(a); 172.604(b); 172.702(a); 172.704(a),(1)-(5); 172.704(c)(1)] Ticket No: 09T-0381-SCT-EA	\$ 2,440
American Etching & Manufacturing Pacoima CA (Shipper)	Failed to provide initial security awareness training and recurrent in-depth security training. [172.702(b); 172.704(a)(4) and (5); 172.704(c)(1), (2) and (d)] Ticket No: 09T-0416-SS-WE	\$ 180
Fredriksen Fire Equipment Co. Bensenville IL (Cylinder Retester)	Failed to condemn cylinders consistent with the requirements of the regulations by stamping X's over the specification marking, stamping "condemned" onto the cylinder, or rendering the cylinder incapable of holding pressure; failed to maintain complete and accurate records of visual cylinder requalification. [180.205(i)(2)(i); 180.215(b)(2)] Ticket No: 10T-0004-CRS-CE	\$ 1,120
Frontier Paper Inc. Anchorage AK (Shipper)	Offered and transported a material as a hazardous material, when the material was not hazardous; failed to provide recurrent general awareness, function-specific, safety, and security awareness training. [172.702(b); 172.704(a)(1)-(4); 172.200(a); 172.201(a) and (d); 172.202(a)(1), (2), (3) and (4)] Ticket No: 09T-0411-SD-WE	\$ 1,184
Kemko A.M.A Corp Deerfield Beach FL (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 09T-0440-REG-SO	\$ 400
Austin Welding Supply, Inc. dba Texas Welding Supply Company Austin TX (Shipper)	Offered various 2.1 and 2.2 compressed gases, accompanied by shipping papers which failed to include an authorized emergency response telephone number; failed to register with PHMSA; failed to provide general awareness, function-specific, safety, and security awareness training. [172.604(b); 107.608(a) and (b); 172.704(d); 172.702(a); 172.704(a)(1)-(4)] Ticket No: 09T-0286-SC-SW	\$ 1,886.11
Ecolab City of Industry CA (Shipper)	Offered sulfuric acid solution, 8, in UN-certified 55-gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification. [173.22 (a)(4); 173.24 (f)(2)] Ticket No: 09T-0401-SD-WE	\$ 1,000
Pool Chlor of	Failed to register with PHMSA. [107.608(a) and	\$ 400

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Tucson Tucson AZ (Toxic Inhalation Hazard Shipper)	(b)]Ticket No: 09T-0412-SC-WE	
Rexcel Coatings Corporation El Paso TX (Shipper)	Offered paint related materials, 3, in UN-certified 55-gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification; failed to provide general awareness, function-specific and safety training. [173.22(a)(4); 173.24(f)(2); 172.702(b); 172.704(a)(1)-(3)] Ticket No: 09T-0254-SD-SW	\$ 950
Argo Chemical, Inc. Bakersfield CA (Shipper)	Offered ammonia solution, 8, in UN-certified 55-gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification; offered ammonia solution, 8, UN2672, PG III, accompanied by a shipping paper that failed to include the proper shipping name for the material. [173.22(a)(4); 173.24(f)(2); 172.202(a)(2)] Ticket No: 09T-0419-SD-WE	\$ 1,320
Greenville Colorants, LLC Greenville SC (Shipper)	Failed to provide initial general awareness, function-specific, safety, security awareness, and in-depth security training; failed to register with PHMSA. [107.608(a) and (b); 172.702(a); 172.704(c)(1); 172.704(a)(1)-(5)] Ticket No: 09T-0428-TREG-SO	\$ 1,500
Floratine, Inc. Collierville TN (Shipper)	Offered hydrogen peroxide, aqueous solution, 5.1(8), and failed to mark the proper shipping name on the package; failed to provide recurrent general awareness, function-specific and security awareness training; offered hydrogen peroxide, aqueous solutions, 5.1 (8), in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [173.22(a)(4); 173.24(f)(2); 172.704(c)(2); 172.301(a)] Ticket No: 09T-0436-SB-SO	\$ 2,120
IPC Cal Flex, Inc. Anaheim CA (Shipper)	Offered waste corrosive liquid, acidic, inorganic, n.o.s. (sulfuric acid, copper), 8, among others, accompanied by a shipping paper that that provided an unauthorized emergency response telephone number; failed to provide initial security awareness training and recurrent general awareness, function-specific and safety training. [172.604(b); 172.702(b); 172.704(a)(1)-(4); 172.704(c)(2)] Ticket No: 09T-0414-SI-WE	\$ 1,760
BWay Packaging, Inc. Memphis TN (Metal J-Can Manufacturer)	Represented, manufactured and marked 1-gallon F-style metal cans and 1-quart F-style (oblong) metal cans when the current design qualification records lacked sufficient information and provided incorrect information concerning weights of the cans and stacking weights.	\$ 1,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	[178.2(b)(1) and (2); 178.601(d) and (e); 178.601(l)] Ticket No: 09T-0434-JCM-SO	
Siegwerk USA Co. Des Moines IA (Shipper)	Offered resin solution, 3, and printing ink, 3, in UN-certified 55 gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 09T-0283-SD-CE	\$ 1,000
Liquid Transport, LLC Cheshire CT (Shipment Observation (General))	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 09T-0277-CT-EA	\$ 513.08
Bay Ship & Yacht Co. Alameda CA (Shipper)	Failed to provide recurrent general awareness, safety, and security awareness training. [172.702(b); 172.702(a)(1), (2), and (4); 172.704(c)(2) and (d)] Ticket No: 09T-0374-SD-WE	\$ 540
Providence Alaska Medical Center Anchorage AK (Shipper)	Offered category B infectious substance, when failed to (1) securely close and label the completed package, and (2) list the name and telephone number who has emergency response and incident mitigation information for the material; offered hazardous waste, accompanied by a shipping paper that failed to provide (1) the proper shipping name, (2) hazard class, (3) identification number, and (4) packing group for the material. [172.202(a)(1)-(4); 172.204(a); 172.604(b); 173.199(a)(4), (5), (7), and (10)] Ticket No: 09T-0413-SB-WE	\$ 2,400
Marchem Pacific, Inc. Orange CA (Shipper)	Offered other regulated substances, liquid, n.o.s. (dicyclohexyl-methane-4, 4' diisocyanate), 9, accompanied by a shipping paper that failed to list the shipping description in the proper sequence; failed to provide initial security awareness training. [172.200(a); 172.202(b); 172.702(b); 172.704(a)(4)] Ticket No: 09T-0418-SI-WE	\$ 380
Browne Laboratories, Inc. Chattanooga TN (Shipper)	Offered caustic alkali liquids, n.o.s. (sodium 2-mercaptobenzothiazole), 8, and others, in UN-certified 275-gallon composite intermediate bulk containers that were not closed in accordance with the manufacturer's closure notification; offered oxidizing solid, n.o.s. (bromochloro-5, 5-dimethylhydantoin) 8, in UN packaging that failed to mark the proper shipping name and the identification number on the package. [173.22(a)(4); 173.24(f)(2); 172.301(a)(1)] Ticket No: 09T-0427-SIBC-SO	\$ 2,200
Fire Boss, Inc,	Failed to condemn cylinders consistent with the	\$ 320

## PHMSA Notice of Hazardous Materials Regulations Enforcement

dba Dragon Fire Systems Freeport TX (Cylinder Retester)	requirements of the regulations by stamping X's over the specification marking, stamping "condemned" onto the cylinder, or rendering the cylinder incapable of holding pressure. [180.205(i)(2)(i)] Ticket No: 09T-0429-CR-SW	
Custom Chemical Services Medley FL (Shipper)	Failed to provide recurrent general awareness, function-specific, safety, security awareness, and in-depth security training; offered flammable liquid, n.o.s. (ethanol), 3, in packages that were not marked with the proper shipping name and UN identification number for the material; offered phosphoric acid, liquid, 8, and others, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.301(a)(1); 172.702(a); 172.704(c)(2); 172.704(a)(1)-(5); 172.604(b)] Ticket No: 09T-0292-SD-SO	\$ 2,920
Alaska Regional Hospital Anchorage AK (Shipper)	Failed to provide recurrent hazardous materials function-specific training; offered category B infectious substance, and failed to mark the package with the proper shipping name and UN identification number. [173.199(a)(5); 172.702(a); 172.704(a)(2); 172.704(c)(2)] Ticket No: 09T-0392-SB-WE	\$ 1,380
Umpqua Valley Fire Services dba A-1 Fire Protection Springfield OR (Cylinder Retester)	Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; marked a cylinder with a star (*) sign, when the cylinder was manufactured prior to December 31, 1945. [180.205(g)(3)(i); 180.209(b)(1)(i); 180.213(f)(2)] Ticket No: 09T-0398-CR-WE	\$ 1,640
Associate Chemical & Supply Honolulu HI (Shipper)	Offered corrosive liquid, acidic, inorganic, n.o.s. (phosphoric acid), 8, and failed to provide a proper shipping paper for a shipment of hazardous materials; failed to provide initial general awareness, function-specific and security awareness training. [172.201(a); 172.202(a)(1)-(4); 172.702(a); 172.704 (a)(1), (2) and (4)] Ticket No: 09T-0410-SD-WE	\$ 1,740
L3 Power Paragon Anaheim CA (Shipper)	Failed to provide initial security awareness training. [172.702(b); 172.704(a)(4)] Ticket No: 09T-0415-SD-WE	\$ 180
Groves Industrial Supply Corp. Houston TX (Shipper)	Failed to provide initial general awareness, function-specific, safety, security awareness, and in-depth security training; offered paint, 3, accompanied by shipping papers that (1) listed an incorrect packing group for the material, (2) failed to list the type of package and contained an unauthorized emergency	\$ 990

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	response telephone number. [172.702(b); 172.704(a)(1)-(5); 172.202(a)(4) and (7); 172.604(b)] Ticket No: 09T-0424-SBD-SW	
SMI Companies, Inc. Franklin LA (Tank Manufacturer (Im, Portable, Dot 51))	Offered various hazardous materials accompanied by shipping papers that included (1) unauthorized additional information interspersed within the basic shipping description and (2) listed an unauthorized emergency response telephone number. [172.202(b); 172.604(b)] Ticket No: 10T-0003-SC-SW	\$ 520
All Aviation, Inc. Miami, FL (Cylinder Retester)	Offered fire extinguishers, 2.2, DOT-SP 7945 and failed to provide a copy of the corresponding special permit to an air carrier; represented, certified and marked DOT specification cylinders as having been successfully re-tested when re-testing was not performed; offered fire extinguishers, 2.2, DOT-SP 7945, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; offered fire extinguishers, 2.2, DOT-SP 7945 and failed to mark the outer packaging with a DOT Special Permit number. [180.2(a) and (b); 180.3(a); 180.205(b), (c), (g), and (f); 172.203(a); 172.301(c); 173.22a(b); DOT-SP 7945] Case No: 08-0179-CR-SO	\$ 2,688
Suntech Group, Inc., dba St. Croix & St. Thomas Gas St. Croix VI (Shipper)	Failed to develop and adhere to a security plan; offered liquefied petroleum gas, 2.1, accompanied by shipping papers that failed to provide a 24-hour emergency response telephone number; offered liquefied petroleum gas, 2.1, and failed to provide a shipping paper for hazardous materials; failed to provide general awareness and security awareness training; transported liquefied petroleum gas, 2.1, and failed to placard the vehicle on all four sides; failed to register with PHMSA. [172.800(a); 172.802(a) and (b); 172.200(a); 172.202(a); 107.608(a) and (b); 172.604(b); 172.702(a); 172.704(a)(1) and (4); 172.504(a)] Case No: 08-0031-SC-SO	\$ 7,775
SOTEC Fire Protection, LLC New Orleans LA (Cylinder Retester)	Failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values; failed to maintain complete and accurate records of cylinder requalification; Representing, marking, and certifying a DOT special permit cylinders as having been successfully requalified in accordance with the HMR, while failing to perform requalifications; failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; after	\$ 5,440

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	<p>equipment malfunction, conducted a second test at the same pressure, rather than at 10 percent or 100 pi higher (whichever is lower); failed to provide recurrent hazmat training; Representing, marking and certifying DOT specification cylinders as having been successfully requalified in accordance with the HMR, while the calibrated cylinder showed permanent expansion during calibration; representing, marking, and certifying DOT specification cylinders as having been successfully requalified in accordance with the HMR, while failing to report a change in testing personnel to the Associate Administrator within 20 days of the change; failed to perform hydrostatic requalification on DOT cylinders at the minimum test pressure of 5/3 the service pressure; failed to maintain at the requalification facility a current copy of a DOT special permit governing cylinders requalified at that facility. [180.205(g)(4); 180.205(g)(3); 180.3(a); 180.205(c); DOT-SP 10915; DOT-SP 11194; 180.205(g)(3)(i); 180.205(g)(5); 180.209(a)(1); 180.215(b); 180.215(a); 107.805(g); 172.702(b); 172.704(c)] Case No: 08-0118-CR-SW</p>	
<p>Carter Fire Protection, Inc., dba Integrated Fire &amp; Safety Ventura CA (Cylinder Retester)</p>	<p>Failed to condemn cylinders when the hydrostatic retest results showed that the permanent expansion of the cylinders exceeded ten percent of the total expansion; after equipment malfunction, conducted a second test at the same pressure, rather than at 10 percent or 100 pi higher (whichever is lower); failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values; failed to maintain copies of the special permits at its retest facility applicable to the requalifier's activities; failed to provide general awareness, function-specific, and security awareness training and to provide recurrent hazmat training at least once every three years; failed to maintain complete and accurate records of visual inspection and cylinder requalification; failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; failed to report in writing to the Associate Administrator, changes in personnel performing hydrostatic cylinder requalifications. [180.205(i)(1)(iv); 180.205(g)(4); 180.205(g)(3)(i); 180.215(a)(5); 180.205(g)(5); 180.215(b)(1) and (2); 172.702(b); 172.704(a)(1), (2) and (4); 172.704(c)(2); 107.805(g)] Case No: 09-0039-CR-SW</p>	\$ 12,569
American	Filled and offered paint, 3, contained in intermediate	\$ 2,460

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Coatings, Inc. Tomball TX (Shipper)	bulk containers (IBCs) for which the periodic retest and inspection had not been performed; failed to provide function-specific training. [173.35(a); 178.813(a); 180.352(a) and (b); 172.202(b); 172.704(a)(2)] Case No: 08-0113-SIBC-SW	
Maumee Valley Bottlers, Inc dba Culligan Bottled Water Service Napoleon OH (Shipper)	Offered and transported hypochlorite solution, 8, under the provisions of DOT SP-12412 and failed to comply with the special permit; failed to create and maintain records of hazardous materials training; offered hypochlorite solution, 8, under the provisions of DOT SP-12412 after the special permit had expired. [173.22a(b); 177.801; SP 12412; 173.22a(b); 177.801; SP 12412; 172.702(a); 172.704(a)(1)-(4); 172.704(c)(2); 172.704(d)] Case No: 08-0116-SB-CE	\$ 750
North Atlantic Fire & Safety Equipment, Inc. Hopedale MA (Cylinder Retester)	Failed to calibrate its test equipment each day prior to testing and to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig. [180.205(g)(3) and (4)] Case No: 09-0108-CR-EA	\$ 2,000
Capital Drum, Inc. Roseville CA (Steel Drum Manufacturer)	Represented and certified UN standard steel drums and failed to (1) conduct design qualification testing with sufficient weight, (2) properly mark and test UN standard 55-gallon steel drums to the UN standard marked on the drum, and (3) to maintain accurate test records of design qualification testing; failed to provide initial function-specific training. [173.28(d); 178.601(c)(4); 178.601(g)(8)(v); 178.601(l); 178.2(b); 178.601(e); 178.602(b); 178.606(a) and (c); 172.702(a); 172.704(a)(2)] Case No: 09-0022-DM-WE	\$ 4,050
Miami Products & Chemicals Co. Dayton OH (Shipper)	Offered sulfuric acid, 8, II, and hypochlorite solution, 8, in UN-certified combination packages and jerricans that were not closed in accordance with the package manufacturer's notification; offered hypochlorite solution, 8, in an overpack that failed to be (1) properly marked with the proper shipping name and identification number and labeled with the proper hazard warning label. Filled, offered and transported hypochlorite solution, 8, in reused UN certified jerricans that had not been subjected to or marked as having successfully passed the leakproofness testing. [173.28(b)(1),(2),(4) and (7); 177.801; 173.22(a)(4); 173.24(f)(2); 178.601(b); 173.1(b); 177.801; 173.22(a); 173.25; 173.25(a)(2)] Case No: 09-0004-SD-CE	\$ 5,850
Farmway CO-OP, Inc. Beloit	Offering for transportation and transporting in commerce a hazardous material, UN1005, Ammonia,	\$ 8,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

KS (Shipper)	<p>anhydrous, 2.2, in nurse tanks that requires “Inhalation Hazard” markings, a proper shipping name, and non-flammable gas placards under the provisions of the HMR, while failing to maintain the markings and placards durability and legibility; transporting in commerce a Division 2.1 hazardous material contained in cargo tank motor vehicle in which the company failed to create and maintain a monthly delivery hose assembly inspection report; offered and transported ammonium nitrate based fertilizer, 5.1, accompanied by shipping papers that failed to (1) list the proper UN identification number, (2) include the packing group of the material (3) retain copies of hazardous materials shipping papers that contained all the required information; offering for transportation and transporting in commerce hazardous materials, while failing to retain shipping papers with all of the required information; shipping name, identification number, quantity transported, and date of shipment; offering for transportation and transporting in commerce a Division 2.1 hazardous material contained in cargo tank motor vehicle that is required to be equipped with an off-truck remote shut-off device, which failed to test or failed to work when activated. [180.416(d); 172.201(e); 177.840(o); 172.304(a)(1); 172.313(a); 172.516(c)(6); 177.823(a); 172.328(a and b)] Case No: 09-0037-SNT-SW</p>	
Handy Fertilizer, Inc. Millstadt IL (Shipper)	<p>Offered and transported ammonium nitrate based fertilizer, 5.1, accompanied by shipping papers that failed to (1) list the proper UN identification number, (2) include the packing group of the material (3) retain copies of hazardous materials shipping papers that contained required information; offered anhydrous ammonia, 2.2, for a non-agricultural purpose, rendering the nurse tanks as unauthorized packaging; failed to mark a nurse tank operating under DOT-SP 13554 with the test dates near the specification plate, the special permit number marking, or on the front head after it has passed testing; failed to complete and submit a DOT form 5800.1 Hazardous Materials Incident Report within 30 days of a reportable hazardous materials incident; failed to provide recurrent hazardous materials training and to retain current records of hazardous materials training. [DOT – SP 13554; 172.200(a); 172.202(a)(1) and (4); 177.817(a); 173.22(a)(2); 173.22a(a); 173.315(m); 180.415(b)(1); DOT-SP 13554; 172.702(a); 172.704(c) and (d); 172.201(d);</p>	\$ 10,357

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	172.604(a)(3)(ii)] Case No: 09-0045-SNT-CE	
A-1 Plating, Inc. Henderson NV (Shipper)	Failed to provide general awareness, function-specific, safety, and security awareness training. [172.702(b); 172.704(a)(1)-(4)] Ticket No: 09T-0313-SD-WE	\$ 450
Sankyo- America, Inc. Indianapolis IN (Shipment Observation (General))	Offered adhesive, 3, in packages that were not marked with the proper shipping name and UN identification number for the material; failed to register with PHMSA. [172.301(a)(1); 107.608(a) and (b)] Ticket No: 09T-0437-SD-SO	\$ 1,600
A-1 Fire Equipment Co., Inc. Houston TX (Cylinder Retester)	Failed to provide function-specific training. Offered fire extinguishers, 2.2, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; offered fire extinguishers, 2.2, accompanied by shipping papers that failed to contain (1) the proper shipping name and hazard class for the material, (2) a signed shipper's certification, and (3) and included additional information interspersed within the shipping description. [172.702(b); 172.704(a)(2); 172.604(b); 172.201(a)(4); 172.202(a)(2) and (3); 172.204(d)] Ticket No: 10T-0016-SC-SW	\$ 1,890
American Eurocopter, LLC DFW Airport TX (Shipper)	Failed to provide general awareness, safety, function-specific, and security awareness training; offering organic peroxide type D, solid, 5.2, accompanied by a shipping paper that failed to (1) list the technical name and concentration in parentheses, and (2) offered cartridges, power device, 1.4C and 1.4S, and failed to create hazardous material shipping papers for the shipment. [172.702(b); 172.704(a)(1)-(4); 172.200(a); 172.202(a); 172.203(k)] Ticket No: 10T-0010-SB-SW	\$ 1,625
Draeger Safety, Inc. Pittsburgh PA (Cylinder Retester)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0032-SC-EA	\$ 400
Acme Soap Inc. San Antonio TX (Shipper)	Failed to develop and adhere to a security plan; failed to provide general awareness, function-specific, safety, security awareness and in-depth security training. [172.800(a); 172.802(a) and (b); 172.702(b); 172.704(a)(1)-(5)] Ticket No: 09T-0430-SD-SW	\$ 2,520
Marisco, LTD Kapolei HI (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 09T-0332-SIBC-WE	\$ 425.40
National Oilwell Varco Larose LA (Recertifier/Ret	Failed to provide general awareness, function-specific, safety, security awareness and in-depth security training; filled and offered diesel fuel, 3, in UN standard portable tanks that (1) were out of test, (2) had not received an	\$ 2,470

## PHMSA Notice of Hazardous Materials Regulations Enforcement

ester/Repairer (Tanks, Ibc's))	internal and external inspection or a leak test once every 2.5 years from the initial testing date of manufacturer and (3) failed to perform a five year periodic inspection and test; offered diesel fuel, 3, accompanied by a shipping paper that failed to include (1) the proper shipping name for the material and (2) the type of package covered by the basic shipping description. [173.32(a)(2); 180.605(c)(1), (d), (e), and (h); 172.702(b); 172.704(a)(1)-(5); 172.202(a)(2); 172.202(a)(7)] Ticket No: 10T-0017-PTR-SW	
Gemini Industries, Inc. Dallas TX (Shipper)	Offered RQ, waste paint related materials, 3, in UN-certified 55 gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0030-SD-SW	\$ 935
The Flamemaster Corporation Pacoima CA (Shipper)	Failed to provide recurrent security awareness training. [172.702(a); 172.704(a)(4); 172.704(c)(2) and (d)] Ticket No: 09T-0384-SI-WE	\$ 180
Lehigh Valley Hospital & Health Network, Inc. Allentown PA (Shipment Observation (General))	Failed to provide general awareness, function-specific, safety and security awareness training. [172.702(a); 172.704(a)(1)-(5)] Ticket No: 09T-0409-SBG-EA	\$ 840
Lamp Environmental Industries, Inc. Independence LA (Fitness Inspection)	Failed to provide function-specific training requirements of DOT-SP 12496 and DOT-SP 12842. [172.704(a)(2)(i); DOT-SP 11296; DOT-SP 12842] Ticket No: 10T-0012-CD-SW	\$ 450
American Marine Holdings, Inc. d/b/a Donzi Marine Sarasota FL (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 09T-0383-SD-SO	\$ 400
Grose Fire Protection, Inc. Mason TN (Cylinder Retester)	Represented, certified, and marked cylinders as having been successfully requalified but failed to (1) maintain complete and accurate daily records of retest, (2) document low pressure requalification records, and (3) not listing calibration of the test equipment; failed to mark the required requalification markings on the low pressure cylinder by not marking the RIN number,	\$ 3,200

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	month/year and “S” as required; represented, certified, and marked DOT cylinders as having been successfully retested but failed to comply with the requirements of special permits 11194 and 10915. [180.205(c); SP 11194 and 10915; 180.213(d) and (f)(4); 180.215(b)(1) and (2)] Ticket No: 09T-0435-CR-SO	
American Eurocopter, LLC Grand Prairie TX (Shipper)	Offered waste solid containing flammable liquid n.o.s., 4.1, accompanied by a shipping paper which failed to (1) follow one or more of the three approved formats for listing a hazardous material and (2) to list the packing group of the material; failed to provide general awareness, function-specific, safety, and security awareness training. [172.702(b); 172.704(a)(1)-(4); 172.201(a)(1); 172.202(a)(4)] Ticket No: 10T-0011-SB-SW	\$ 1,100
Albemarle Corporation Baton Rouge LA (Other)	Imported ethylene dibromide, 6.1, poison-inhalation hazard zone B, into the United States, and failed to provide timely and complete written notification of requirements related to shipping paper, marking, and packaging requirements for poisonous by inhalation materials. [171.22(f)(1); 171.23(b)(10); 172.313; 173.227(b)] Case No: 08-0082-SD-EA	\$ 7,500
Dixon Investments, Inc dba ARI Orchard Hills GA (Aerosol Filler/Shipper)	Filled and offered a limited quantity of a compressed gas in a metal container for the purpose of propelling a non poisonous material and failed to heat the cylinder until the pressure inside the cylinder has reached 130 degrees Fahrenheit. [173.306(a)(3)(iii)(v)] Case No: 09-0149-SC-SO	\$ 3,400
Advanced Fire Equipment Company, Inc. Greensburg PA (Cylinder Retester)	Failed to maintain copies of the applicable sections of the regulations at its retest facility; failed to provide recurrent hazardous materials training and to maintain training records; Represented, marked and certified DOT specification cylinders as having been successfully requalified when the cylinders were not hydrottested in accordance to the regulations; failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; failed to maintain complete and accurate records of cylinder requalification. [180.215(a); 180.205(g)(1); 180.205(g)(3); 180.215(b)(2); 172.702(a); 172.704(c);172.704(d)] Case No: 07-0033-CR-EA	\$ 6,360
Woodstock Gas and Oil Company Woodstock GA (Carrier)	Transported liquefied petroleum gas, 2.1, in non-DOT/UN standard storage tanks exceeding five percent of their water capacity. [173.315(j)(4)] Case No: 09-0082-SPT-SO	\$ 5,950

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Akzo Nobel Paints, LLC formerly ICI Paints, Inc. Huron OH (Shipment Observation (General))	Offered paint, 3, in non-specification 5-gallon steel pails. [173.22(a)(2); 173.203(a)] Case No: 09-0112-SP-SO	\$ 5,625
Superior Gas, Inc. Piedmont AL (Carrier)	Offered and transported liquefied petroleum gas, 2.1, in approved ASME tanks with greater than 125 gallon capacity and the tanks were charged with LP gas with a quantity greater than 5%. [173.315(j)(4)] Case No: 09-0161-CAR-SO	\$ 5,950
Star-Tex Propane, Inc. Waco TX (Carrier)	Transported propane, 2.1, in a non-DOT/UN standard storage tank designed for permanent installation, when the tank was charged to more than five percent of its water capacity. [173.315(j)(4)] Case No: 09-0152-CC-SW	\$ 6,650
Lovelace Gas Service, Inc. Orlando FL (Visual Requalifier Inspection)	Offered liquefied petroleum gas, 2.1, in a non-specification fixed storage container removed from a customer's premises when the container was charged in excess of 5% gas; failed to maintain copies of the applicable sections of the regulations at its facility.[173.315(j)(4); 180.215(a)(6)] Case No: 09-0104-SPT-SO	\$ 6,080
Viking Life Saving Equipment Miami FL (Box Manufacturer (Fiber))	Offered signals, smoke (cruise ship flares), 1.4G, in an unauthorized UN specification package; transported carbon dioxide, 2.2 and failed to describe the hazardous material in the manner required by the HMR; offered signals, smoke (cruise ship flares), 1.4G, and failed to ensure the organization capable of providing detailed information concerning emergency response was provided current information on hazardous materials prior to offering for transportation; offered signals, smoke (cruise ship flares), 1.4G, and failed to affix a warning label in association with an exemption; transported one (1) class 2.2 high pressure cylinder, carbon dioxide, 2.2, in the cab of a company truck and failed to restrain the cylinders in an up-right or horizontal position. [173.22(a)(2); 173.173(b)(1); 173.202(a) and (b); 178.504(a); 178.601(a); EX2002040262; 177.840(a)(1); 172.202(a); 172.604(b)] Case No: 06-0189-SB-SO	\$ 6,175
Smurfit-Stone Container Corp. Lexington NC	Represented, marked, certified, sold and offered a packaging that was removed from the Hazardous Materials Regulations, therefore, manufacturing	\$ 6,720

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Shipper)	unauthorized packaging. [178.2(f)] Case No: 09-0146-PM-EA	
Farmers Cooperative Company Tecumseh NE (Shipper)	Offered ammonia anhydrous, 2.2, in a nurse tank that did not meet the requirements of Section VIII of the ASME Code (American Standard of Metalurgical Engineers); Offered ammonia anhydrous, 2.2, in a nurse tank with wear and abrasion that could substantially reduce the effectiveness or integrity of the package; offered ammonia anhydrous, 2.2, UN1005, in a nurse tank and failed to mark and placard the tank on both sides and each end. [173.22(a); 173.24(a),(b) and (c); 173.33(a); 173.315(a) and (m); 173.22(a); 173.24(a),(b) and (c); 173.33(a); 173.315(a) and (m); 172.302(a)(1); 172.328(a)(2); 172.504(a)] Case No: 09-0050-SNT-CE	\$ 5,580
Koetter Fire Equipment, W.F. Wichita Falls TX (Cylinder Retester)	Failed to properly mark each cylinder with the month and year of requalification or to have an approval issued by the Associate Administrator authorizing in writing a variation from the marking requirements; failed to maintain complete and accurate records of cylinder requalification; failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values and to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig. [180.205(g)(3)(i); 180.205(g)(1), (3) and (4); 180.3(a); 180.213(d); 180.213(d)(1); 180.215(b)(1); 180.215(b)(2)] Case No: 09-0062-CR-SW	\$ 5,580
Northwest Butane Gas Co, Inc. dba Northwest Propane Gas Co Dallas TX (Carrier)	Filled and transported liquefied petroleum gas in a cargo tank that was overdue the prescribed periodic retest; failed to provide recurrent hazardous materials training; failed to (1) condemn cylinders consistent with the requirements of the regulations by stamping X's over the specification marking, stamping "condemned" onto the cylinder, or rendering the cylinder incapable of holding pressure and (2) provide written notification of the condemned cylinder to the cylinder's owner; failed to have a current Requalification Identification Number (RIN) at the time of inspection. [173.33(a)(3); 173.315(K); 180.407(a) and (c); 172.704(c)(2); 180.205(i)(2)(i); 180.205(i)(3); 180.205(b)] Case No: 09-0155-CCT-SW	\$ 6,800
Conam Inspections, Inc. Pasadena TX (Shipper Inspection)	Offered radioactive material, in Type B(U) packages containing Iridium-192, 7, in packages (1) affixed with an incorrect category of label and (2) that failed to provide the activity in the appropriate units of measure. [172.403(b); 172.403(g)(2); 172.403(c)] Ticket No:	\$ 2,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Ram))	10T-0028-RMS-SW	
Draeger Interservices, Inc. Pittsburgh PA (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0027-SC-EA	\$ 400
Apria Healthcare Suwanee GA (Shipper)	Offered oxygen compressed, 2.2 (5.1), accompanied by a shipping paper that failed to indicate an emergency response telephone number; offered oxygen compressed, 2.2 (5.1), accompanied by a shipping paper that failed to indicate the subsidiary hazard class for the material. [172.604(b); 172.202(a)(3)] Ticket No: 09T-0441-SC-SO	\$ 1,440
Environmental Industries, LP Addison TX (Shipper)	Offered waste flammable solid, inorganic, n.o.s. (xylene/acetone), 4.1, and others, in UN-certified 55-gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.24(f)(2); 173.22(a)(4)] Ticket No: 10T-0039-SD-SW	\$ 935
SAS Shoemakers, Inc. San Antonio TX (Shipper)	Offered various hazardous materials, accompanied by multiple shipping papers that (1) provided an unauthorized emergency response telephone number, (2) contained incorrect packing group for the material; and failed to include the required technical name in parenthesis for a listed "n.o.s." material; failed to provide general awareness, function-specific, safety, and security awareness training; failed to retain copies of hazardous materials shipping papers for a minimum of two years. [172.202(a)(4); 172.203(k); 172.604(b); 172.702(b); 172.704(a)(1)-(4); 172.201(e); 177.817(f)] Ticket No: 10T-0052-SBD-SW	\$ 2,015
Stone Manufacturing and Supply Kansas City MO (Undeclared Shipper Inspection)	Failed to provide initial or refresher general awareness, function-specific, safety and security awareness training. [172.702(a); 172.704(a)(1)-(4); 172.704 (d)] Ticket No: 10T-0025-SB-CE	\$ 720
CMC Construction Services Houston TX (Shipper)	Offered amines, liquid, corrosive, n.o.s., 8, accompanied by shipping papers that failed to provide (1) the proper shipping name, (2) identification number, (3) packing group for the material, and (4) to include a required technical name in parentheses. [172.202(a)(1), (2), and (4); 172.203(k)] Ticket No: 10T-0001-SP-SW	\$ 1,200
Process Innovation, Inc.	Offered oxidizing liquid, corrosive, nos,(ferric nitrate, nitric acid), 5.1,(8), accompanied by shipping papers	\$ 2,874.34

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Charlotte NC (Shipper)	that failed to (1) list the description of the material in the proper sequence, (2) provide the unit of measure and quantities, (3) provide the type package and weights of the materials, (4) list an emergency number and (5) contain a signed shipper's certification; offered oxidizing liquid, corrosive, nos (ferric nitrate, nitric acid), 5.1, (8), and others, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; failed to provide general awareness, safety, function-specific and security awareness training; failed to register with PHMSA. [172.604(b); 107.608(a) and (b); 172.202(a); 172.604(b); 172.702(b); 172.704(a)(1)-(4)] Ticket No: 09T-0133-SD-SO	
Myers Container Portland OR (Steel Drum Manufacturer)	Failed to maintain accurate test records; represented, marked, certified, and sold UN packagings when design qualification testing was not performed with the correct amount of samples or with the approval of the Associate Administrator. [178.601(d), (f) and (k); 178.601(l)(9)] Ticket No: 09T-0224-DM-WE	\$ 1,240
BAE Systems, Inc. Austin TX (Shipper)	Offered waste flammable liquids, n.o.s. (xylene, methyl ethyl ketone), 3, among others, in UN-certified 55-gallon open-head and closed head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Case No: 10T-0048-SD-SW	\$ 935
Hoyer Global (USA), Inc. Houston TX (NVOCC)	Failed to provide initial and recurrent general awareness, function-specific, safety, security awareness and in-depth security training. [172.702(b); 172.704(a)(1)-(5); 172.704(c)(2)] Ticket No: 10T-0013-NVO-SW	\$ 540
Cooperative Propane, Inc. Ozark AL (Carrier)	Offered liquefied petroleum gas, 2.1, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b)] Ticket No: 10T-0014-SPT-SO	\$ 1,040
Columbus Fire & Safety, Inc. Columbus GA (Cylinder Retester)	Failed to maintain complete and accurate records of cylinder requalification by failing to document condemned cylinders. [180.205(c); 180.205(i)(1)(vii); 180.215(b)(2)] Ticket No: 10T-0029-CR-SO	\$ 400
P & M Welding Supply, Inc. Miami FL (Carrier)	Failed to provide initial general awareness, function-specific and safety training, and recurrent security awareness and in-depth security training. [172.702(a); 172.704(a)(1)-(5); 172.704(c)(1) and (2)] Ticket No: 10T-0042-TRN-SO	\$ 540
Amrep Marietta GA (Aerosol)	Failed to provide initial general awareness, function specific and safety training. [172.704(a)(1)-(3)] Ticket	\$ 540

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Filler/Shipper)	No: 10T-0045-TRN-SO	
Diversified Distributing, Inc. West Des Moines IA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training. [172.702(a); 172.704(a)(1)-(4) and (d)] Ticket No: 10T-0019-SB-CE	\$ 540
Canadian General-Tower Limited Cambridge XX (Shipment Observation (General))	Offered flammable liquid n.o.s., (2-methoxy-1-methyl ethyl acetate), 3, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0020-SB-CE	\$ 1,000
Laser International Freight Transport Miami FL (NVOCC)	Failed to provide initial general awareness, function-specific and safety training; offering liquefied petroleum gas, 2.1, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; offered liquefied petroleum gas, 2.1, under the provisions of DOT-SP 14296, and failed to (1) provide a copy of the special permit to the carrier before or at the time of shipment and (2) to maintain a copy of the special permit at the facility where the package was offered for transportation; failed to register with PHMSA. [173.22a(b) and (c); DOT-SP 14296(8)(b), (c) and (10)(a); 172.203(a); 172.702(a); 172.704(a)(1)-(3); DOT-SP 14296(11)(b); 107.608(a) and (b)] Ticket No: 10T-0033-NVO-SO	\$ 1,580
G & S Marine, Inc. Lockport LA (Tank Manufacturer (IM, Portable, Dot 51))	Failed to (1) provide recurrent training and security awareness training and (2) represented, marked, sold, certified, and offered UN standard portable tanks and failed to properly document annual welding performance tests for welding procedures. [172.702(b); 172.704(a)(4); 172.704(c)(2); 178.275; 178.276(b)(2)(i)] Ticket No: 10T-0018-ITM-SW	\$ 540
Eagle Industries, Inc. Midwest City OK (Cylinder Retester)	Failed to (1) verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values and (2) calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig. [180.205(g)(3)(i); 180.205(g)(3)(i)] Case No: 07-0104-CR-SW	\$ 3,900
JT Farm Service Verdon NE (Shipper)	Offered anhydrous ammonia, 2.2, in an unauthorized non-standard or non-specification packaging; offered and transported ammonium nitrate based fertilizer, 5.1, accompanied by shipping papers that failed to list the (1) proper shipping name, (2) hazard class, (3) UN identification number, and (4) packing group of the	\$ 7,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	material and to retain copies of hazardous materials shipping papers for a minimum of two years; failed to register with PHMSA. [172.200(a); 171.201(e) and 172.202(a)(1) and (4); 177.817(a); 173.22(a)(2); 173.22a(a); 107.608(a) and (b)] Case No: 09-0150-SNT-CE	
Hagemeyer North America Corpus Christi TX (Cylinder Retester)	Failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values; failed to condemn DOT Special Permit cylinders when the recorded permanent expansion exceeded five percent of the recorded total expansion. [180.205.(i)(1)(vii); 180.205(g)(1), (3) and (4); 180.215(b)(2)] Case No: 09-0139-CR-SW	\$ 7,691
Theochem Laboratories, Inc. Atlanta GA (Shipper)	Offered sodium hydroxide, solid, 8, in an unauthorized non-UN DOT packaging. [173.22(a)(2); 173.24(c); 173.212] Case No: 08-0051-SD-SO	\$ 4,716
Chilton Propane Gas Clanton AL (Shipper)	Transported liquefied petroleum gas, 2.1", in non-DOT/UN standard storage tanks exceeding five percent of their water capacity.[173.315(j)(4); SP 13341] Case No: 09-0158-SPT-SO	\$ 5,950
Airgas South- Miami Miami FL (Accident/Failure Investigation)	Offered argon, refrigerated liquid, 2.2, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; offered argon, refrigerated liquid, 2.2, in a packaging under the provisions of a DOT Special Permit 11186, accompanied by a shipping paper that failed to document the additional information on the shipping papers prior to shipment; offered argon, refrigerated liquid, 2.2, under the provisions of DOT Special Permit 11186 and failed to provide function-specific training concerning requirements contained in the Special Permit that are specifically applicable to the functions the employee performs for shipment of hazardous materials in that packaging; offered argon, refrigerated liquid, 2.2, under the terms of a DOT special permit while failing to provide a copy of DOT-SP 11186 to the carrier before or at the time of shipment; offered argon, refrigerated liquid, 2.2, in a portable tank which contained (1) an identification number on an orange panel that was not legible, (2) an obscure proper shipping name and (3) a damaged placard for the material; offered argon, refrigerated liquid, 2.2, in an unauthorized DOT-SP 11186 Special Permit portable tank which had a pressure relief system with external adjustment valves with	\$ 229,050

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	<p>broken tamper evident seals; failed to conduct an external inspection of all emergency devices of a portable tank for corrosion, distortion, or any damage or defect that could prevent their normal operation prior to offering the portable tank for transportation.</p> <p>[173.22a(b) and (c); DOT-SP 11186(8)(b) and (10)(a); 172.200(a); 172.203(a); 173.22a(b); DOT-SP 11186(10)(b)(2) and (3); 173.22(a)(2)(i)(v); 173.22a(b), 173.32(e)(3)(4); 173.318(b)(1)(ii); 173.318(b)(7)(iii); 173.318(b)(10)(ii); DOT-SP 11186(7)(c)(1); 173.301(a)(1); 172.326(a); 172.332(a); 172.504(a),172.516(c)(1); 172.702(a); 172.704(a)(2) and (d); 173.22a(b); DOT-SP 11186(11)(b)] Case No: 08-0185-SIT-SO</p>	
Hansen Fire Equipment San Leandro CA (Cylinder Retester)	Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig. [180.205(g)(3)(i)] Ticket No: 10T-0087-CR-WE	\$ 840
Regal Chemical Company, Inc. Alpharetta GA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Failed to register with PHMSA. [107.608(a) and (b); 172.702(a); 172.704(c)(1); 172.704(a)(1)-(4)] Ticket No: 10T-0070-TREG-SO	\$ 1,120
I.V.C. South, Inc. Lawrenceville GA (Shipper)	Offered paint, 3, and others, in UN-certified 55-gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification; failed to create and retain current records of hazardous materials training. [173.22(a)(4); 173.24(f)(2); 172.702(b); 172.704(d)] Ticket No: 10T-0049-SD-SO	\$ 1,275
Gans Ink & Supply Co., Inc. Los Angeles CA (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0091-SD-WE	\$ 400
Hurley Packaging of Texas, Inc. Lubbock TX (Box Manufacturer (Fiber))	Failed to provide initial and recurrent security awareness training. [172.702(b); 172.704(a)(4); 172.704(c)(2)] Ticket No: 10T-0061-BM-SW	\$ 675
Red River Pharmacy Services, Inc. Texarkana TX (Shipper)	Offered radioactive material, type A package, 7, in DOT specification 7A, Type A packagings, and failed to maintain on file complete documentation of tests and an engineering evaluation or comparative data showing that the construction methods, packaging design and	\$ 1,310

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Inspection (Ram))	materials of construction comply with that specification; offered radioactive material type A packaging, 7, in metal packages in a configuration that had not been tested or evaluated to meet the DOT specification 7A, Type A packaging requirements. [173.461(a); 173.465; 173.415(a)] Ticket No: 10T-0157-RMS-SW	
Half Price Fireworks West Harrison IN (Shipper Inspection (Explosive))	Offered fireworks, 1.4G, and failed to provide a hazardous materials shipping paper; failed to register with PHMSA. [172.202(a)(1) through (5); 172.604(b); 107.608(a) and (b)] Ticket No: 10T-0008-SE-CE	\$ 2,400
Blalock Equipment Corporation Sevierville TN (Shipper Inspection (Explosive))	Offered hazardous materials and failed to provide a shipping paper to document the hazardous materials shipment. [172.200(a); 172.201(a) and (e); 177.817(a) and (f)] Ticket No: 10T-0046-SPT-SO	\$ 1,200
Motion Picture F/X Company Burbank CA (Shipper)	Offered resin solution, 3, and aerosols, 2.2, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b)] Ticket No: 10T-0089-SB-WE	\$ 1,040
World Laboratories, LTD Sun Valley CA (Shipper)	Offered corrosive liquid, n.o.s. (contains 1-hydroxyethane-1, 1-di-phosphonic acid), 8, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0074-SB-WE	\$ 1,000
Rust-Oleum Corporation Somerset NJ (Shipper)	Failed to maintain hazardous materials training records; offered paint, 3, in UN-certified 55 gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification; offered paint, 3, accompanied by a shipping paper and the certification on the shipping paper did not include a signature of the person certifying the compliance. [173.22(a)(4); 173.24(f)(2); 172.204(d); 172.702(a); 172.704(d)] Ticket No: 10T-0031-SP-EA	\$ 1,820
Quality Distribution, Inc. Salt Lake City UT (Shipper)	Failed to provide recurrent hazardous materials security awareness and in-depth security training; offered flammable liquid, corrosive n.o.s., (ethanol, aromatic sulfonic acid), 3, that failed to indicate the subsidiary hazard class for the material. [172.702(a); 172.704(a)(4) and (5); 172.202(a)(3)] Ticket No: 10T-0151-SD-WE	\$ 940
AAA Quality Services, Inc.	Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig;	\$ 2,760

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Bakersfield CA (Cylinder Retester)	failed to maintain complete and accurate records of cylinder requalification; represented, marked, and certified special permit cylinders when the cylinder had not been re-qualified with the requirements of the special permit; failed to provide recurrent general awareness, function-specific, safety and security awareness training. [180.205(c); DOT-E-10915; 180.205(g)(3)(i); 180.215(b)(2); 172.702(b); 172.704(a)(1)-(4); 172.704(c)(2)] Ticket No: 10T-0077-CR-WE	
Reliable Motor Freight, Inc. Omaha NE (Carrier)	Transported corrosive liquid, basic, inorganic, n.o.s. (sodium hydroxide), 8, accompanied by shipping papers that failed to (1) provide the complete proper shipping description, (2) use parentheses for the technical name, (3) include the emergency response telephone number, (4) sign the shippers certification, and (5) abbreviated the proper shipping name and technical name when not authorized; failed to provide initial and recurrent general awareness, function-specific, safety, and security awareness training. [172.702(a); 172.704(a)(1)-(4),(c)(2) and (4); 172.200(a); 172.201(a) and (d); 172.202(a),(d) and (k); 172.204(a); 177.817(a) and (b)] Ticket No: 10T-0037-SD-CE	\$ 3,150
Precision Additives, Inc. Houston TX (Shipper)	Failed to provide general awareness, function-specific, safety, security awareness and in-depth security training. Offered combustible liquid, n.o.s (distillates, petroleum, hydro-treated light), accompanied by shipping papers that failed to indicate (1) an emergency response telephone number and (2) the number and types of packages of the material; failed to register with PHMSA. [172.702(b); 172.704(a)(1)-(5); 107.608(a) and (b); 172.604(a); 172.202(a)(7)] Ticket No: 09T-0255-SIBC-SW	\$ 1,866.78
Omega Chemical Co., Inc. Ralston NE (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training; offered corrosive liquid, basic, inorganic, n.o.s. (sodium hydroxide), 8, amongst others, but failed to provide shipping papers for the shipments of hazardous materials and to retain the shipping papers them for two years. [172.200(a); 172.201(a) and (e); 177.817(a) and (e); 177.817(a) and (e); 172.702(a); 172.704(a)(1)-(4) and (d)] Ticket No: 10T-0054-SB-CE	\$ 2,520
Superior Transportation Fort Morgan CO (Hmi)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0175-HMI-CE	\$ 500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Ticket)		
Dalmatian Fire Equipment Inc. Windsor CO (Cylinder Retester)	Failed to condemn cylinders consistent with the requirements of the regulations by stamping X's over the specification marking, stamping "condemned" onto the cylinder, or rendering the cylinder incapable of holding pressure; failed to maintain complete and accurate records of visual cylinder requalification. [180.205(i)(2)(i); 180.215(b)(2)] Ticket No: 10T-0075-CR-WE	\$ 720
Adams Manufacturing Company Lubbock TX (Aerosol Filler/Shipper)	Failed to provide recurrent hazardous materials training and to provide initial in-depth security training; offered resin solution, 3, and failed to mark the packages with the correct UN identification number for the material and package orientation markings; offered resin solution, 3, PGIII, accompanied by shipping papers which listed an incorrect identification number and packing group for the material. [172.702(b); 172.704(a)(5); 172.704(c)(2); 172.202(a)(3) and (4); 172.300(a); 172.301(a); 172.312(a)(2)] Ticket No: 10T-0050-SBD-SW	\$ 1,520
Alliance Solvents & Chemical Company dba Alliance Chemical, Inc. Taylor TX (Shipper)	Offered isopropanol, 3, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification; offered various hazardous materials, accompanied by shipping papers that listed an unauthorized emergency response telephone number. [173.22(a)(4); 173.24(f)(2); 172.201(d); 172.604(b)] Ticket No: 10T-0057-SBD-SW	\$ 1,910
JPS Express VA, Inc. Portsmouth VA (Carrier)	Transported corrosive solid, basic, inorganic, n.o.s. (disodium metasilicate, sodium hydroxide), 8, without an accompanying hazardous materials shipping paper; failed to register with PHMSA. [172.202(a); 172.604(b); 177.817(a); 107.608(a) and (b)] Ticket No: 10T-0026-CBG-EA	\$ 2,750
Amico Educational Concepts Crestwood IL (Undeclared Shipper Inspection)	Offered, marked, labeled, documented and transported a material as a hazardous material, when the material was not hazardous; failed to provide initial or recurrent general awareness, function-specific, safety, security awareness and in-depth security training. [172.303(a); 172.704(d); 172.704(a)(1)-(5); 172.702(a)] Ticket No: 10T-0044-SB-CE	\$ 860
ABC Fire Extinguisher, Inc. Portland OR (Cylinder Retester)	Failed to maintain complete and accurate records of cylinder requalification. [180.215(b)(2)] Ticket No: 10T-0081-CR-WE	\$ 400

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Trigon Refrigerant Sarasota FL (Shipper)	Offered refrigerant gas R-22, 2.2, and failed to create and retain copies of hazardous materials shipping papers for a minimum of two years; offered refrigerant gas R-22, 2.2, accompanied by shipping papers that failed to have the proper shipping description of the material in the proper sequence; failed to register with PHMSA. [172.202(a)(1)-(3); 107.608(a) and (b); 177.817(f)] Ticket No: 10T-0063-SC-SO	\$ 1,120
Hexion Specialty Chemicals, Inc. Springfield OR (Shipper)	Offered resin solution, 3, in UN-certified 5-gallon plastic jerrycans that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0079-SD-WE	\$ 1,000
Pool & Spa Warehouse Toledo OH (Shipper)	Offered and transported hypochlorite solution, 8, PG III, in a non-specification cargo tank, and failing to show the proper identification number on the vehicle; filled and offered hypochlorite solution, 8, in UN-certified 5-gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification; offered hypochlorite solution, 8, and failed to provide a shipping paper for a shipment of hazardous materials; offered and transported hypochlorite solution, 8, in packages that failed to display the proper shipping name and identification number of the material; offered hypochlorite solution, 8, PG III, in a bulk package and failed to placard the vehicle with the appropriate class placard for the material; offered and transported hypochlorite solution, in packages that were improperly labeled with a primary hazard label; failed to provide general awareness, function-specific, safety, and security awareness training. [172.200(a); 172.201(d); 172.202(a)(1)-(4); 172.604(b); 177.800(a); 172.702(a); 172.704(a)(1)-(4); 172.704(c); 172.500(a); 172.504(a) and (c); 172.506(a)(1); 172.514(a) and (b); 172.558(b); 172.400(a); 172.406(a) and (f); 172.442(b); 172.411(d); 172.302(a),(b) and (d); 172.328(a); 177.800(a); 172.301(a); 172.304(a); 173.22(a)(4); 173.24(f)(2)] Ticket No: 09T-0020-SD-CE	\$ 1,950
Northeast Industrial Floorings, Inc. Windsor Locks CT (Carrier)	Failed to provide recurrent general awareness, function-specific, and safety training; failed to register with PHMSA. [107.608(a) and (b); 172.702(a); 172.704(a)(1)-(4); 172.704(c)(2)] Ticket No: 10T-0066-SD-EA	\$ 940
County Soda Systems, Inc. Pompano Beach	Offered carbon dioxide, 2.2, in excess of 1,001 pounds, and failed to placard the vehicle with the appropriate placard; offered carbon dioxide, 2.2, and failed to retain	\$ 1,940

## PHMSA Notice of Hazardous Materials Regulations Enforcement

FL (Carrier)	copies of hazardous materials shipping papers for a minimum of two years; failed to provide initial general awareness, function-specific, safety, security awareness and in-depth security training; failed to register with PHMSA. [107.608(a) and (b); 172.504(a) and (e); 172.702(a); 172.704(a)(1)-(5); 172.704(c)(1); 172.201(e); 177.817(f)] Ticket No: 10T-0186-CAR-SO	
RMS of Georgia, LLC Alpharetta GA (Cylinder Retester)	Failed to provide function-specific training; failed to renew the retester's identification number (RIN); failed to register with PHMSA. [180.205(b); 107.608(a) and (b); 172.702(a); 172.704(a)(2)] Ticket No: 10T-0056-CR-SO	\$ 1,675
Florida Flame Fire & Safety Equipment Company, Inc. N. Miami Beach FL (Cylinder Retester)	Represented, certified, and marked low pressure DOT-4B and 4BW specification cylinders as having been successfully requalified and failed to mark the Requalifiers Identification Number (RIN) on those cylinders. [180.213(a), (c)(1) and (d)] Ticket No: 10T-0076-CR-SO	\$ 320
TCI Coatings, Inc. Austin TX (Aerosol Filler/Shipper)	Filled and offered a compressed gas in metal containers (aerosols) without properly performing the hot water bath test to assure that the internal temperature has reached at least 55 °C (131 °F). [173.306(a)(3)(v)] Ticket No: 10T-0067-SC-SW	\$ 560
American Fuji Seal, Inc. Anaheim CA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training; offered waste printing ink, 3, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b); 172.702(b); 172.704(a)(1)-(4)] Ticket No: 10T-0177-SD-WE	\$ 1,760
Sercel, Inc. Houston TX (Shipper)	Failed to provide general awareness, function-specific and security awareness training; failed to register with PHMSA. [172.702(b); 172.704(a)(1), (2) and (4); 107.608(a) and (b)] Ticket No: 10T-0150-SD-SW	\$ 825
JSP (Jeweldent Inc. d.b.a.) Vernon CA (Shipper)	Offered corrosive liquids, n.o.s. (nitric acid, hydrochloric acid), 8, in small quantities, and failed to ensure that each inner receptacle with a removable closure had its closure held securely in place with wire, tape, or other positive means; failed to provide general awareness, function-specific, safety, and security awareness training. [172.702(b); 172.704(a)(1)-(4); 173.4(a)(3)] Ticket No: 10T-0182-SB-WE	\$ 940
MacCarb, Inc. Genoa IL (Shipper)	Failed to provide general awareness, function-specific, safety and security awareness training. [172.702(a); 172.704(a)(1)-(4); 172.704(d)] Ticket No: 09T-0346-SB-CE	\$ 727.21

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Viking Packing Specialist Tulsa OK (Box Manufacturer (Fiber))	Marked combination packagings with an infectious substance label that does not meet the label requirements. [178.432(a)] Ticket No: 10T-0008-SB-CE	\$ 650
Miller Machinery & Supply Co. Miami FL (Shipper)	Failed to create and retain current records of general awareness, function-specific, safety, and security awareness training; offered anhydrous ammonia, 2.2, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b); 172.702(a); 172.704(a)(1)-(4); 172.704(c)(2) and (d); 172.800(c)] Ticket No: 10T-0065-SC-SO	\$ 1,840
H & S Supply of Utah Salt Lake City UT (Shipper)	Failed to create and retain current records of hazardous materials training. [172.702(b); 172.704(d)] Ticket No: 10T-0148-SB-WE	\$ 540
Lone Star Welding Supply Co. Inc. Houston TX (Shipper)	Offered various Division 2.1 and 2.2 compressed gases, accompanied by shipping papers that (1) provided an unauthorized emergency response telephone number, (2) failed to include proper shipping name, (3) hazard class for the material and (4) type of package utilized. [172.202(a)(2), (3) and (7); 172.604(b)] Ticket No: 10T-0002-SC-SW	\$ 1,500
Bio-Spec, Inc. Dover FL (Shipper)	Failed to create and maintain current records of general awareness, function-specific, and safety training. [172.702(a); 172.704(a)(1)-(3) and (d); 177.800(c)] Ticket No: 10T-0040-SMW-SO	\$ 750
Pyramyd Air Cleveland OH (Shipper)	Offered petroleum gases liquified, 2.1, and failed to provide a hazardous materials shipping paper that included the (1) proper shipping name, (2) hazard class, (3) identification number for the material and to include a (4) valid emergency response telephone number; offered petroleum gases liquified, 2.1, inn packages that failed to be properly labeled for the material; failed to provide general awareness, function-specific, safety, security awareness training and training was not conducted regarding SP-11217 and SP-10232; offered liquified petroleum gas, 2.1 and 1,1,1,2-Tetrafluoroethane, 2.2, and failed to comply with the provisions of the special permit, SP 11917 and the DOT E-10323; offered petroleum gases liquified, 2.1, in packages that failed to be marked with the proper shipping name, identification number, special permit and exemption number. [172.301(a) and (c); 173.23(h); 172.202(a)(1)-(4); 172.604(b); 172.400(a);	\$ 8,675

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	172.406(a)(1); 173.22a(b); SP 11917; DOT-E 10323; 172.702(a); 172.704(a)(1)-(4); 172.704(c); DOT-E 10232; SP-11917] Ticket No: 09T-0118-SCB-CE	
Clayton Corporation dba Convenience Products Pacific MO (Accident/Failure Investigation)	Offered consumer commodity ORM-D, in aerosol cans and failed to subject them to testing in a hot water bath of 55 degrees C (131° F) minimum. [173.306(a)(3)(v)] Ticket No: 10T-0043-SB-CE	\$ 1,875
Corkle Oil Co. LLC Walden CO (HMI Ticket)	Failed to submit a Hazardous Materials Incident Report within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0116-HMI-EA	\$ 500
Boost Oxygen, LLC Bridgeport CT (Shipper)	Offered oxygen, compressed, 2.2 (5.1), in packagings that are unauthorized for non liquified gases; failed to provide recurrent general awareness, function-specific, and safety training and initial security awareness training; offered oxygen, compressed, 2.2 (5.1) and failed to properly mark, label the packages, and to identify the material as a hazardous material by improperly classifying the material as a consumer commodity. [173.22(a)(1); 172.200(a); 172.300(a); 172.400(a); 173.22(a)(2); 173.24(c); 173.302(a); 173.302a(a); 172.702(a); 172.704(a)(1)-(4); 172.704(c)(2)] Case No: 09-0148-SC-EA	\$ 950
West Texas Propane, Inc. Clint TX (Carrier)	Failed to develop and adhere to a security plan; failed to provide general awareness and security awareness training; failed to (1) create and maintain a monthly delivery hose assembly inspection report that contains all the required information, and (2) carry on or within the cargo tank motor vehicle written emergency discharge control procedures for all delivery operations; transported propane, 2.1, in a non-DOT/UN standard storage tank designed for permanent installation, when the tank was charged to more than five percent of its water capacity. [173.315(j)(4); 172.702(a); 172.704(a)(1) and (4); 172.800(a); 172.802(a) and (b); 180.416(d);177.840(l)] Case No: 09-0042-CCT-SW	\$ 9,110
Estes-Cox Corp dba Estes Industries Penrose CO (Shipment Observation (Explosive))	Offered class 1.4S hazardous materials as Division 4.1 materials, under the provisions of DOT SP-7887 and failed to satisfy the requirements outlined in the special permit. [173.22(a)(2)(v); DOT SP-7887] Case No: 09-0106-SE-CE	\$ 1,250

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Cintas Fire Protection San Jose CA (Cylinder Retester)	Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; offered a hazardous material accompanied by a shipping paper that failed to contain a signed shipper's certification; offered hazardous material accompanied by shipping papers that failed to include the proper shipping name, hazard class, identification number and packing group for the material. [180.205(g)(3)(i); 172.202(a)(1)-(4); 172.201(a); 172.204(d)] Ticket No: 10T-0082-CR-WE	\$ 2,360
PM Testing Laboratory, Inc. Tacom WA (Shipper Inspection (Ram))	Offered waste corrosive liquids, n.o.s., 8, accompanied by a shipping paper that failed to include a required technical and/or chemical group name in parenthesis for a listed generic or "n.o.s." material; offered waste nitric acid, 8 (5.1), and waste corrosive liquids, n.o.s., 8, among others, accompanied by a shipping paper that failed to list an authorized emergency response telephone number, and/or listed an incorrect or non-working emergency response number; failed to register with PHMSA. [172.604(b); 107.608(a) and (b); 172.203(k)] Ticket No: 10T-0172-SB-WE	\$ 1,840
Kinder Morgan Cincinnati OH (HMI Ticket)	Failed to file a detailed written Incident Report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0166-HMI-CE	\$ 500
Wechem, Inc. Harahan LA (Shipper)	Offered hazardous materials accompanied by shipping papers that contain additional information before, instead of after the basic description; offered compound cleaning liquid (potassium hydroxide), 8, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [173.22(a)(4); 173.24(f)(2); 172.201(a)(4); 172.202(b)] Ticket No: 10T-0199-SB-SW	\$ 1,335
Mendes Supply Company Eureka CA (Shipper)	Offered hypochlorite solution, 8, and failed to provide a proper shipping paper for a shipment of hazardous materials. [172.200(a); 172.201(a) and (d); 172.202(a); 172.604(b)] Ticket No: 10T-0206-SD-WE	\$ 1,200
Matheson Tri-Gas, Inc. Miami FL (Shipper)	Offered oxygen, refrigerated liquid, 2.2, 5.1, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; failed to provide function-specific training concerning the Special Permit 11186; offered oxygen, refrigerated liquid, 2.2, 5.1, under the provision of DOT-SP 11186 and failed annotate the one-way-travel-time requirement of the shipping paper. [172.200(a); 172.203(a); 173.22a(b); DOT-SP 11186 (10)(b)(2); 172.704(a)(2) and (d); 173.22a(b); DOT-SP 11186-(11)(b)] Ticket	\$ 915

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	No: 10T-0036-EX-SO	
ARC Products, Inc. Dallas TX (Shipper)	Offered hazardous materials, accompanied by a shipping paper that provided an unauthorized emergency response telephone number and failed to list the technical name of an n.o.s. material in parentheses for the material. [172.201(d); 172.604(b); 172.203(k)] Ticket No: 10T-0191-SDIBC-SW	\$ 975
Elite Crete Systems Valparaiso IN (Other Priority Investigation Type)	Failed to provide general awareness, function-specific, safety, security awareness, and in depth security initial or refresher training. [172.702(a);172.704(a)(1)-(5);172.704(c)(1) and (2);172.704(d)] Case No: 10T-0158-SBP-CE	\$ 720
CHS Pasco WA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0176-HMI-CE	\$ 500
Imperial Transport Cumberland Gap TN (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0107-HMI-EA	\$ 500
Linden Bulk Transportation Linden NJ (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0110-HMI-EA	\$ 500
Associated Paint, Inc. Medley FL (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0041-REG-SO	\$ 400
Pima Chemical, LLC Tucson AZ (Toxic Inhalation Hazard Shipper)	Offered chlorine, 2.3, (8), Poison-Inhalation Hazard Zone B, accompanied by a shipping paper that (1) included unauthorized information interspersed in the basic description, and (2) failed to include the words "Poison-Inhalation Hazard" and "Zone B" for the material. [172.200(a); 172.202(b); 172.203(m)] Ticket No: 10T-0171-SC-WE	\$ 720
Yoshis Inc. (d.b.a. Balloon Specialties) Tacoma WA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training; offered helium, compressed, 2.2, and carbon dioxide, 2.2, accompanied by a shipping paper that failed to indicate an emergency response telephone number. [172.604(b); 172.702(b); 172.704(a)(1)-(4)] Ticket No: 10T-0078-SC-WE	\$ 1,580
Royal Chemical Company Macedonia OH	Offered corrosive solids, n.o.s. (sodium hydroxide), 8, when the overpack not properly marked. [173.25(a)(4)] Ticket No: 10T-0051-SBG-EA	\$ 1,200

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Shipment Observation (General))		
Water Warehouse, LLC Kenosha WI (Undeclared Shipper Inspection)	Failed to provide general awareness, function specific, safety and security awareness training. [172.704(a)(1)-(4); 172.704(d); 172.704(c)(1); 172.702(a)] Ticket No: 10T-0154-sb-ce	\$ 540
Allstate Insurance Co. Northbrook IL (Undeclared Shipper Inspection)	Failed to provide general awareness, function-specific and security awareness training. [172.704(a)(1),(2) and (4); 172.704(c)(1); 172.702(a)] Ticket No: 10T-0174-SD-CE	\$ 675
Lee Transport Elmer NJ (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0101-HMI-EA	\$ 500
Precision Hydro Citrus Heights CA (Cylinder Retester)	Represented, certified, marked and offered DOT specification cylinders as having been successfully retested without holding a current retesters identification number (RIN); failed to provide general awareness, function-specific, safety and security awareness training. [173.34(e)(2); 180.205(b); 172.704(a)(1)-(4); 172.702(b)] Ticket No: 10T-0146-CR-WE	\$ 1,520
Gorman Company Naples FL (Shipper)	Failed to create and maintain records of general awareness, function-specific, safety, and security awareness training. [172.702(a); 172.704(a)(1)-(4); 172.704(c)(2) and (d); 177.800(c)] Ticket No: 10T-0143-SB-SO	\$ 800
Sparkman Industries, Inc. Victoria TX (Recertifier/Retester/Repairer (Tanks, Ibc))	Failed to provide initial function-specific and security awareness training and recurrent general awareness training; failed to register with PHMSA.[107.608(a) and (b); 172.702(b); 172.704(a)(1),(2) and (4); 172.204(c)(2)] Ticket No: 10T-0060-IBCR-SW	\$ 825
Frontier Tank Lines Mckinney TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0134-HMI-EA	\$ 500
Benchmark Distribution Services Houston TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0131-HMI-EA	\$ 500
Eureka	Failed to calibrate test equipment at a pressure within	\$ 1,240

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Humboldt Fire Extinguisher Co, Inc. Arcata CA (Cylinder Retester)	500 psig of actual test pressure at or above 3000 psig; failing to register with PHMSA. [180.205(g)(3)(i); 107.601(a)(6); 107.608(a) and (b); 107.612(d)] Ticket No: 10T-0179-CR-WE	
Varian, Inc. Lake Forrest CA (Shipper)	Offered flammable liquid, n.o.s., (25% Acetonirile) 3, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0088-SB-WE	\$ 1,000
Hexcel West Valley City UT (Shipper)	Offered self reactive liquid, type E, temperature controlled (glycidyl amine resin <= 100%), 4.1 and failed to mark the outer package with the DOT Approval No. CA2004070006; failed to provide recurrent hazardous materials security awareness training; offered waste solid n.o.s. (methyl ethyl ketone, acetone) accompanied by a shipping paper that failed to provide the proper shipping name for the material. [172.702(a); 172.704(a)(4); 172.201(a) and (d); 172.202(a)(2); Approval CA2004070006; 172.301] Ticket No: 10T-0201-SB-WE	\$ 1,800
Enor International, Inc. La Puente CA (Shipper)	Offered lighters, 2.1", accompanied by a shipping paper that provided an unauthorized emergency response telephone number; failed to register with PHMSA; failed to provide general awareness, function-specific, safety, and security awareness training. [172.604(b); 107.608(a) and (b); 107.612(d); 172.702(a); 172.704(a)(1)-(4); 172.704(c)(1)] Ticket No: 10T-0086-SB-WE	\$ 2,160
Orica USA, Inc. Watkins CO (Shipment Observation (Explosive))	Offered explosive, blasting, type E, 1.1D, in UN standard packaging with improper sized hazardous warning labels attached to the package; offered explosive, blasting, type E, 1.1D, in UN standard packaging that exceeded the marked weight capacity, therefore shipping in unauthorized packaging. [173.22(a); 173.24(a); 173.62(a); 172.400(a); 172.407(c)] Ticket No: 10T-0015-SE-EA	\$ 2,720
GCI Fowarding, Inc. Metairie LA (Freight Forwarder)	Failed to provide general awareness, function-specific, safety, and security awareness training; failed to register with PHMSA. [172.702(b); 172.704(a)(1)-(4); 107.608(a) and (b)] Ticket No: 10T-0203-FF-SW	\$ 1,140
AFA, dba AAA Fire Extinguisher, Company Lubbock TX	Failed to provide recurrent hazardous material training and initial security awareness training. [172.702(b); 172.704(a)(4); 172.704(c)(2)] Ticket No: 10T-0062-CR-SW	\$ 505

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Cylinder Retester)		
Raytheon Systems Company Tucson AZ (Box Manufacturer (Fiber))	Offered hazardous materials packaged in UN-certified 55 gallon closed-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0170-SD-WE	\$ 1000
Frends Beauty Supply North Hollywood CA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training and recurrent general awareness, function-specific, and safety training; offered acetone, 3, accompanied by a shipping paper that failed to indicate an emergency response telephone number, listed multiple telephone numbers that are not monitored 24 hours, and/or listed an unauthorized emergency response number. [172.604(b); 172.702(b); 172.704(a)(1)-(4); 172.704(c)(2)] Ticket No: 10T-0147-SB-WE	\$ 1,760
Doheny Enterprises Kenosha WI (Undeclared Shipper Inspection)	Failed to provide general awareness, function-specific, safety and security awareness training. [172.704(a)(1)-(4); 172.704(d); 172.704(c)(1); 172.702(a)] Ticket No: 10T-0155-SB-CE	\$ 720
JC Hunt Blanding UT (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0135-HMI-EA	\$ 500
Cactus Transport Inc. Tolleson AZ (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0124-HMI-EA	\$ 500
Cleveland Steel Container Corporation Kilgore TX (Steel Drum Manufacturer)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0160-DM-SW	\$ 475
Valley Fire Control, Inc. Albany OR (Cylinder Retester)	Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; failed to retain copies of hazardous materials shipping papers for a minimum of two years. [180.205(g)(3)(i); 172.201(e)] Ticket No: 10T-0080-CR-WE	\$ 1,240
H&W Petroleum Company, Inc.	Offered kerosene, 3, and failed to describe the hazardous material on the shipping paper, and failed to provide the carrier placards and identification numbers for the	\$ 1,900

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Houston TX (Shipper)	material: failed to provide general awareness, function-specific, safety, and security training. [172.200(a); 172.202(a); 172.331(a); 172.506(a); 172.702(b); 172.704(a)(1-5)] Ticket No: 10T-0149-SD-SW	
Arizona Polymer Flooring, Inc. Glendale AZ (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0153-REG-WE	\$ 400
Matheson Tri- Gas, Inc. Jupiter FL (Shipper)	Offered oxygen, refrigerated liquid, 2.2, 5.1, and failed to provide a copy of DOT-SP 11186 to the carrier before or at the time of shipment; offered oxygen, refrigerated liquid, 2.2, 5.1, under the provisions of DOT-SP 11186 and failed to annotate the one-way-travel time requirement on the shipping paper; failed to provide function-specific training concerning the Special Permit 11186. [173.22a(b) and (c); DOT-SP 11186(8)(b) and (10)(a); 173.22a(b); DOT-SP 11186(10)(b)(2); 172.704(a)(2) and (d); 173.22a(b); DOT-SP 11186 Section (11)(b)] Ticket No: 10T-0034-EX-SO	\$ 915
L&M Renner, Inc. Eureka CA (Shipper)	Offered kerosene, 3, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; offered kerosene, 3, accompanied by shipping papers which included unauthorized information before the basic shipping description. [172.604(b); 172.201(a)(4); 172.202(b)] Ticket No: 10T-0183-SB-WE	\$ 1,360
Stetson Building Products, Inc. Maquoketa IA (Other Priority Investigation Type)	Offered adhesives, 3, among others, accompanied by shipping papers that failed to include (1) the number and type of packages and (2) the hazard class number for the material; failed to provide general awareness, function-specific, safety, security awareness and in-depth security training. [172.202(a)(7); 172.202(a)(3); 172.704(a)(1)-(5); 172.704(c)(1); 172.702(a)] Ticket No: 10T-0165-SDB-CE	\$ 1,120
Midwest Energy Cape Girardeau MO (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0167-HMI-CE	\$ 500
Betts Oil & Butane, Inc. Weslaco TX (Shipper)	Transported Division 2.1 hazardous materials contained in cargo tank motor vehicle and failed to create and maintain a monthly delivery hose assembly inspection report; offered and transported Division 2.1 hazardous materials contained in cargo tank motor vehicle that was required to be equipped with an off-truck remote shut-off device and failed to work when activated; developed	\$ 17,715

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	a security plan that failed to include a written assessment of transportation security risks; transported Division 2.1 hazardous material contained in cargo tank motor vehicle in which the company failed to carry on or within the cargo tank motor vehicle written emergency discharge control procedures for all delivery operations. [180.416(d); 177.840(l); 173.315(n)(2); 177.840(o); 172.802(a) and (b)] Case No: 09-0198-CC-SW	
Pickin's Company, Inc. Hampton VA (Shipper)	Failed to develop and adhere to a security plan; failed to protect the valves and other fittings while in transportation; failed to maintain records of hazardous materials training and to conduct security awareness training; failed to register with PHMSA; failed to retain copies of hazardous materials shipping papers for a minimum of two years. [177.834(a); 172.704(a)(4); 172.702(a); 172.704(d); 107.608(a) and (b); 172.201(e); 172.800(a); 172.802(a) and (b)] Case No: 09-0128-SC-EA	\$ 950
Farmers Cooperative Association Red Cloud NE (Carrier)	Offered and transported propane, 2.1, in MC 331 cargo tanks and failed to mark the tanks inlet and outlet valves and the emergency shut off device; offered hazardous materials, accompanied by a shipping paper which failed to include an authorized emergency response telephone number; transported a Division 2.1 hazardous material contained in cargo tank motor vehicle that is required to be equipped with an off-truck remote shut-off device, that failed to work when activated, and failed to check and test the off-truck remote shut-off device daily; transported a Division 2.1 hazardous material contained in cargo tank motor vehicle in and failed to create and maintain a monthly delivery hose assembly inspection report; filled and transported gasoline and diesel fuel in a DOT 406 cargo tank that was overdue the prescribed periodic retest; offered and transported ammonia, anhydrous, 2.2, and failed to apply and/or maintain the proper markings, shipping name, and placards to its nurse tanks; transported propane, 2.1, in a non-DOT/UN standard storage tank designed for permanent installation, when the tank was charged to more than five percent of its water capacity; failed to provide general awareness, function-specific, safety, security awareness, and in-depth security training; filled and transported propane, 2.1, in an unauthorized non-DOT specification cargo tank; failed to retain copies of hazardous materials shipping papers for a minimum of	\$ 20,774

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	two years; transported and offered ammonia anhydrous, 2.2, in unauthorized non-specification cargo tanks for agricultural purposes; failed to register with PHMSA. [173.315(j)(4); 173.33(a)(1); 173.315(k); 173.22(a)(2); 172.328(d); 178.337-9(c); 177.840(o); 172.201(e); 173.315(m)(1) and (6); 172.304(a)(1); 172.313(a); 172.516(c)(6); 180.416(d); 173.33(a)(3); 180.407(a) and (c); 172.702(a); 172.704(a)(1)-(5); 107.608(a) and (b); 172.201(d); 172.604(b)] Case No: 09-0194-CCT-SW	
Ortiz International, Inc. Laredo TX (Freight Forwarder)	Failed to register with PHMSA. [107.608(a) and (b)] Case No: 09-0135-FF-SW	\$ 2,000
Bud's Boat Rental, LLC Belle Chasse LA (Carrier)	Accepted for transportation and transported hazardous materials and failed to provide a dangerous cargo manifest, list, or stowage plan for shipments transported by oceangoing vessel; failed to provide general awareness, function-specific, safety, security awareness, and in-depth security training. [176.30; 176.13; 172.702; 172.704(a)(1)-(5)] Case No: 09-0122-CC-SW	\$ 1,410
Velsicol Chemical Corporation, Inc. Memphis TN (Shipper)	Offered hexachlorocyclopentadiene, 6.1, PG I, PIH Zone B, and failed to adhere to their transportation security plan. [172.800(b)(7); 172.802(a).] Case No: 09-0216-SPIH-SO	\$ 6,750
Carl Pool Products Gladewater TX (Shipper)	Failed to provide general awareness, function-specific, safety, security awareness and in-depth security training; offered ammonium nitrate and failed to mark the packages with the materials identification number; offered ammonium nitrate, accompanied by a shipping paper that failed to include the type of packages for the materials; failed to register with PHMSA. Offered ammonium nitrate, in non-UN Standard plastic bags when a UN Standard 5H4 design type packaging is required by the HMR. [107.608(a) and (b); 172.22(a)(2); 173.212(a); 173.212(c); 172.200(a); 172.202(a)(6); 172.300(a); 172.301(a)(1); 172.702(b); 172.704(a)(1)-(5)] Case No: 09-0100-SBG-SW	\$ 5,258
Momar, Inc. Atlanta GA (Shipper)	Offered water reactive, solid, corrosive, nos (sodium hydroxide), Aluminum, 4.3 and 8, and corrosive solid, nos (sodium hydroxide), 8, in non-specification packagings. [173.22(a)(2); 173.24a(b)(3)(iii); 173.212(a)] Case No: 09-0063-SP-SO	\$ 6,300
Distribution Technologies,	Represented, marked and certified intermediate bulk containers (IBCs) as being properly retested, when	\$ 4,050

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Inc. d/b/a Manfredi Special Services Cleveland OH (Shipment Observation (General))	packages were marked with an improper test date and the thickness verification inspection was not conducted. [180.3(a); 180.352(b)(3)(ii)] Case No: 08-0085-SIBC-EA	
Jones Chemicals, Inc. Jacksonville FL (Cylinder Retester)	Representing and certifying DOT specification 3A cylinders as having been successfully re-qualified in accordance with the Hazardous Materials Regulations (HMR), when testing was performed with test equipment which had not had its accuracy verified within + or -1%, by use of a calibrated cylinder. [180.205(g)(3) and (4)] Case No: 09-0248-CR-SO	\$ 4,150
Air Jamaica Cargo Miami FL (Carrier)	Offered corrosive liquid, acidic, inorganic, n.o.s. (corrosive sulfamic acid), in an unauthorized non-UN DOT packaging, when specification packaging is prescribed. Offered corrosive liquid, acidic, inorganic, n.o.s. (corrosive sulfamic acid), and failed to mark the packages with authorized package orientation arrows.[173.22(a)(2);173.24(c);173.202(b);ICAO Packing Instruction 812;171.22(a) and (b);172.312(a);ICAO 4.1.1.13] Case No: 09-0119-SB-SO	\$ 8,075
Calfrac Well Services Corporation Beebe AR (Shipper Inspection (Ram))	Offered radioactive material, type A package, 7, and failed to mark the package with the materials assigned proper shipping name, identification number, and DOT specification markings; offered radioactive material, type A package, 7, accompanied by a shipping paper that failed to marked with the correct transport index for the material; offered radioactive material, type A package, 7, and failed to affix the package with two Class 7 hazardous materials warning labels. [172.438; 172.403(g); 173.407; 172.301(a); 178.350; 172.203(d)(5)] Ticket No: 10T-0240-RMS-SW	\$ 2,250
Newport Metal Finishing (Brasstech, Inc. d.b.a.) Santa Ana CA (Shipper)	Failed to provide initial security awareness training and to create and retain current records of hazmat training. [172.702(b); 172.704(a)(4); 172.704(d)] Ticket No: 09T-0365-SD-WE	\$ 828.67
Zebra Technology Corp. Vernon Hills IL (Other Priority	Failed to provide general awareness, function-specific, safety and security awareness training. [172.704(a)(1)-(4); 172.702(a); 172.704(c)(1)] Ticket No: 10T-0162-SD-CE	\$ 720

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Investigation Type)		
Quarles Petroleum Inc. Fredericksburg VA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0138-HMI-EA	\$ 500
McKenzie Tank Lines Inc. Tallahassee FL (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0096-HMI-EA	\$ 500
Green Motor Lines Richmond VA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0133-HMI-EA	\$ 500
Superior Chrome San Jose CA (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0207-SD-WE	\$ 600
TRInternational, Inc. Seattle WA (Shipment Observation (General))	Offered sodium hydroxide, solid, 8, when the overpack was not properly marked indicating it was an overpack. [173.25(a)(4)] Ticket No: 10T-0047-SBG-EA	\$ 1,200
K.P. McNamara Company Fontana CA (Recertifier/Retester/Repairer (Tanks, Ibc))	Failed to provide initial security awareness and in-depth security training; offered waste corrosive liquids, n.o.s. (potassium hydroxide, sodium hydroxide), 8, accompanied by a shipping paper that failed to list an authorized emergency response telephone number. [172.702(b); 172.704(a)(4) and (5); 172.604(b)] Ticket No: 10T-0152-SD-WE	\$ 1,400
W.C. Richards Company Alsip IL (Fitness Inspection)	Offered paint, 3, in UN-certified 55 gallon open-head steel drums/composite intermediate bulk containers that were not closed in accordance with the manufacturer's closure notification.[173.22(a)(4);173.24(f)(2)] Case No: 10T-0180-SD-CE	\$ 1250
3 D Imaging, LLC Little Rock AR (Shipper Inspection (Ram))	Offered radioactive material, in DOT specification 7A, Type A packages and failed to maintain on file complete documentation of tests and an engineering evaluation or comparative data showing that the construction methods, packaging design and materials of construction comply with that specification; offered radioactive material, in packages with labels that did not conform to the minimum size requirements and failed to be marked with the activity in SI units first followed by the customary units marked within parenthesis; offered	\$ 2,060

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	radioactive materials, in a DOT specification 7A Type A package not marked with the materials assigned proper shipping name. [173.415(a); 173.461; 172.301(a)(1); 172.304(a)(1); 172.403(g)(2); 172.407(c)(1); 172.450(a)(1)] Ticket No: 10T-0247-RMS-SW	
Advanced Chemistry & Technology, Inc. dba A.C. Tech Garden Grove CA (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0205-REG-WE	\$ 400
Prep, Inc. Ralston NE (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Offered corrosive liquid, basic, inorganic, n.o.s. (sodium hydroxide), 8, accompanied by shipping papers that failed to (1) provide the complete proper shipping description, (2) use parentheses for the technical name or to include the technical name, (3) include the emergency response telephone number and (4) sign the shippers certification. [172.200(a); 172.201(a) and (d); 172.202(a), (d) and (k); 172.204(a); 172.702(a); 172.704(a)(1)-(5), and (d)] Ticket No: 10T-0053-SB-CE	\$ 550
Safiedine Oil Company Roseville MI (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.15; 171.16] Ticket No: 10T-0093-HMI-EA	\$ 500
SAIA Transportation Duluth GA (HMI Ticket)	Fail to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0105-HMI-EA	\$ 500
CARTERSVILLE MEDICAL CENTER CARTERSVILLE GA (Shipper)	Failed to provide general awareness and security awareness training. [172.702(a); 172.704(a)(1) and 4)] Ticket No: 10T-0185-RMW-SO	\$ 450
Capweld Jackson MS (Cylinder Retester)	Represented, certified, marked, and offered DOT cylinders as having been requalified in accordance with a DOT special permit, and failed to comply with minimum test time criteria: failed to create and retain current records of hazardous materials training. [180.3(a); 180.205(c); DOT-SP 7277; 172.702(b); 172.704(d)] Ticket No: 10T-0184-CR-SO	\$ 1,750
Explosive	Offered nitrites, inorganic, aqueous solution, n.o.s.	\$ 1,520

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Contractors Inc - Hollister Hollister MO (Shipper Inspection (Explosive))	(contains sodium nitrite), 5.1, accompanied by a shipping paper that failed to include the proper shipping description for the material; offered oxidizing liquid, n.o.s. (contains ammonium nitrate solution), 5.1, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers. [173.22 (a)(1); 172.203(a); 173.22(a)(1)] Ticket No: 10T-0234-SE-HQ	
Brite-Line Technologies LLC Denver CO (Shipper)	Offered adhesives, containing a flammable liquid, 3, accompanied by a shipping paper which failed to follow one or more of the three approved formats for listing hazardous materials on a shipping paper; failed to create and retain current records of hazardous materials training. [172.201(a)(1); 172.702(b); 172.704(d)] Ticket No: 10T-0145-SD-WE	\$ 1,200
Tractor Supply Company Pendleton IN (Shipper)	Failed to retain copies of hazardous materials shipping papers for a minimum of two years; failed to provide recurrent general awareness, function specific, safety, security awareness, and in-depth security training. [172.201(e); 172.702(a); 172.704(a)(1)-(5); 172.704(c)(2)] Ticket No: 10T-0189-SB-CE	\$ 1,400
ITW TACC Rockland MA (Shipment Observation (General))	Offered adhesives, 3, in UN-certified 55 gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0224-SD-SO	\$ 1,000
Energetic Materials Research & Testing Ctr Socorro NM (Fitness Inspection)	Failed to provide hazardous materials employee training who performs a function subject to Approval CA-0007005, on the requirements and conditions of the approval. [Approval CA-0007005, para 7.b.] Ticket No: 10T-0237-SE-HQ	\$ 720
Eveready Freight Service Inc. Denver CO (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0129-HMI-EA	\$ 500
Intercontinental Terminals Company Deer Park TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0193-HMI-CE	\$ 500
SW Motor Transport San Antonio TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0168-HMI-CE	\$ 500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Callahans Gas, Inc. Centreville MD (Cylinder Retester)	Represented, marked, and certified DOT Specification 4BA cylinders when their approval expired and the company was no longer authorized to test cylinders. [180.205(b)] Ticket No: 10T-0204-CR-EA	\$ 800
LaFrance Equipment Corporation Elmira NY (Cylinder Retester)	Failed to provide initial and recurrent general awareness, safety, and security awareness training. [172.702(a); 172.704(a)(1), (3), and (4); 172.704(c)(1) and (2)] Ticket No: 10T-0208-CR-EA	\$ 450
Key Polymer Corporation Lawrence MA (Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0214-SD-EA	\$ 400
RL Jordan Oil Company Spartanburg SC (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0136-HMI-EA	\$ 500
Simons Petroleum Oklahoma City OK (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0114-HMI-EA	\$ 500
Lincoln Manufacturing, Inc. Lincoln RI (Shipment Observation (General))	Offered flammable liquid, n.o.s., 3, and failed to mark the packages with the proper shipping name, technical name, and identification number. [172.300(a); 172.301(a) and (b)] Ticket No: 10T-0216-SD-SW	\$ 1050
Wyle Laboratories, Inc. Huntsville AL (Third Party Testing Laboratory)	Failed to adequately provide sufficient number of test samples to conduct performance tests. [178.2(b)(1); 178.601(d)] Ticket No: 10T-0229-PC-HQ	\$ 800
WES&T, LLC Tulsa OK (Carrier)	Offered hazardous waste, accompanied by a shipping paper that failed to (1) identify the materials in the proper format for a hazardous materials shipping document, (2) include a required technical name for an n.o.s. material, (3) include the actual concentration or the concentrating range organic peroxides in parentheses, (4) list a hazardous waste as a hazardous substance with the letters "RQ" before or after the basic description. [172.203(c) and (k); 172.201(a); 172.202(b); 172.200(a)] Ticket No: 10T-0194-SDIBC-SW	\$ 1,275

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Safety Consulting Engineers, Inc Schaumburg IL (Fitness Inspection)	Failed to provide Annual Activity Reports to the Office of Special Permits and Approvals by February 1st, for each previous calendar year; failed to provide function-specific training. [Approval CA-9908004, para 5.e.; Approval CA-9908004, para 7.b.; 172.704(a)(2)] Ticket No: 10T-0235-SE-HQ	\$ 1,200
Continental Industrial Coatings, Inc. Belle Chasse LA (Shipper)	Failed to provide initial general awareness, function-specific and in-depth security and recurrent training in safety and security awareness training. [172.704(a)(1)-(5); 172.704(c)(1) and (2)] Ticket No: 10T-0202-SP-SW	\$ 540
Triumvirate Environmental Somerville MA (Carrier)	Failed to provide recurrent general awareness, function-specific, and safety training. [172.702(a); 172.704(a)(1)-(3); 172.704(c)(2)] Ticket No: 10T-0059-CB-EA	\$ 540
SAIA Transportation Duluth GA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0195-HMI-CE	\$ 500
Petroleum Transport Inc. Troy MI (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0122-HMI-EA	\$ 500
Pendleton Grain Growers, Inc. Pendleton OR (Shipper)	Offered ammonia, anhydrous, 2.2, RQ, in an unauthorized non UN standard/non-DOT packaging; failed to remove bulk containers from the motor vehicle prior to discharging the contents of the containers; offered ammonia, anhydrous, 2.2, RQ, in a non-specification cargo tank, and failed (1) to identify the materials as poisonous by inhalation and (2) to identify the material by the proper shipping name; failed to conduct a monthly inspection on the discharge system of a cargo tank in liquefied compressed gas service transporting ammonia, anhydrous, 2.2 RQ, Inhalation Hazard; failed to permanently mark a delivery hose on a cargo tank in compressed liquefied gas service; discharged ammonia, anhydrous, 2.2 RQ, Inhalation Hazard from a specification cargo tank that did not have emergency discharge control capability. [173.22(a)(2), 173.24(c), 173.33(a)(1); 173.315(a), 173.315(a)(2), 173.315(m); 177.801, 177.800(a); 177.801; 177.834(h); 173.315(m); 177.800(a); 177.801; 172.302(b) and (d); 172.213(a); 172.328(b); 177.315(m)(1); 173.315(n)(2); 177.801; 180.405(m)(1); 180.3(a); 180.416(d)(1)-(5); 180.416(a) and b)] Case No: 09-0051-SNT-CE	\$ 16,425
Champion	Offered methanol, 3, UN1230, PGII, in packaging that	\$ 13,300

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Packaging & Distribution Inc. Woodridge IL (Shipper)	was improperly labeled for the material; offered methanol, 3, in packaging that failed to mark the proper shipping name for the material; offered flammable liquids, n.o.s. (methanol), 3, among others, in UN-certified 55-gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification; filled and offered flammable liquids, n.o.s. (methanol), 3, in reused UN certified 55-gallon plastic drums, that had not been subjected to performance leakproofness testing and had not been marked as having successfully passed the leakproofness testing. [172.301(a); 173.22(a)(1) and (2); 172.400(a); 172.402(a)(1); 173.22(a)(1) and (2); 173.28(b)(1), (2), (4) and (7); 177.801; 173.22(a)(4); 173.24(b) and (f)(1); 178.2(b)(2)] Case No: 09-0085-SD-CE	
Best Fire Tech Corp. San Juan PR (Cylinder Retester)	Failed to provide recurrent general awareness, safety and function specific training and initial security awareness training was not conducted; failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; failed to condemn DOT cylinders for excessive permanent expansion; offered carbon dioxide, 2.2, and fire extinguishers, 2.2, accompanied by shipping papers that failed to properly identify and describe the hazardous materials. [180.205(g)(3)(i); 180.205(i)(1)(iv); 172.202(a)(1); 172.200(a); 172.704(a)(4); 172.704(d); 172.704(c)(2); 172.700; 172.702(a)(4)] Case No: 08-0092-CRS-CE	\$ 3,950
Corp Production Services Huntingdon TN (Shipper)	Offered anhydrous ammonia, 2.2, in unauthorized non-DOT specification cargo tanks, when the tanks did not conform to the American Society of Mechanical Engineers (ASME) Code and therefore not in conformance with the requirements in the Hazardous Materials Regulation. [ 173.315(m)(1) and Section VIII of the ASME Code-Markings and Reports.]	\$ 9,000
Chemical Products Corporation Cartersville GA (Shipper)	Offered sodium sulfide, hydrated, 8, in 50-pound UN standard 5H4 plastic film bags while failed to conduct a periodic retest once every 12 months; offered corrosive liquid, toxic, n.o.s., 8 (6), accompanied by a shipping paper that failed to provide (1) the correct subsidiary hazard class for the material and (2) to indicate the quantity dictated the material was for a "Cargo Aircraft Only". [173.22(a)(4); 178.601(e); 172.202(a)(2) and (d); 172.101(j)(4)] Ticket No: 10T-0270-SD-SO	\$ 2,640
Unelko Corp. Scottsdale AZ (Shipper)	Offered and transported flammable liquid n.o.s. (alcohol), 3, and failed to mark the package with proper shipping name and UN identification number; offered	\$ 2,980

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	flammable liquid n.o.s. (alcohol), 3, accompanied by a shipping paper that failed to (1) follow one or more of the three approved formats for listing hazardous materials on a shipping paper, and contained unauthorized information preceding the proper shipping name; failed to create and retain current records of hazardous materials training and to provide security awareness training; failed to register with PHMSA. [172.702(b); 172.704(a)(1)-(4); 172.704(d); 172.201(a)(1); 172.202(b); 107.608(a) and (b); 172.301(a)] Ticket No: 10T-0169-SP-WE	
Valley Paint Manufacturing Woods Crossing UT (Shipper)	Offered paint, 3, in UN-certified 55-gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification; failed to provide general awareness, function-specific, safety and security awareness training; offered paint, 3, accompanied by a shipping paper that variously failed to provide (1) the proper shipping name, (2) hazard class and division number, (3) UN identification number, and (4) packing group for the materials; offered paint, 3, and failed to mark the packages with the proper shipping name and UN identification number of the material; failed to register with PHMSA. [172.300(a); 172.301(a); 107.608(a) and (b); 173.22(a)(4); 173.24(f)(2); 172.702(a); 172.704(a)(1)-(4); 172.200(a); 172.202(a)(1)-(4)] Ticket No: 10T-0215-SD-WE	\$ 3,460
Action Fire & Safety, Inc. Kirkwood NY (Cylinder Retester)	Failed to provide recurrent general awareness, function-specific and security awareness training. [172.702(a); 172.704(a)(1), (2) and (4); 172.704(c)(2)] Ticket No: 10T-0252-CR-EA	\$ 450
National Fire Fighter Corp. Portland OR (Cylinder Retester)	After equipment malfunction, conducted a second test at the same pressure, rather than at 10 percent or 100 pi higher (whichever is lower). [180.205(g)(5)] Ticket No: 10T-0250-CR-WE	\$ 1,240
Jake's Fireworks, Inc. Pittsburg KS (Shipper Inspection (Explosive))	Offered fireworks, 1.4G, accompanied by a shipping paper that failed to list a legible and/or complete authorized emergency response telephone number; offered fireworks 1.4G, but failed to mark the package with the EX-number for each substance, article, or device contained therein or show in association with the proper shipping description. [172.320(a) and (d); 172.202(a); 172.604(b)] Ticket No: 10T-0096-SE-CE	\$ 1,650
Wampum Hardware	Offered explosives and explosive devices in non-bulk packages and explosives, 1.5D and oxidizers, 5.1,	\$ 1,120

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Company New Galilee PA (Shipper Inspection (Explosive))	accompanied by a shipping paper that failed to indicate the number and type of packages used for the material. [173.22(a)(1); 172.202(a)(7)] Ticket No: 10T-0231-SE-HQ	
Explosives Bureau Short Hills NJ (Fitness Inspection)	Failed to provide function-specific training on the requirements and conditions of Approval CA-1996060007. [CA-199606007, para 7.b.;172.704(a)(2)(d)] Ticket No: 10T-0238-SE-HQ	\$ 720
Tenergy Corporation dba All-Battery.com Fremont CA (Lithium Battery Mfg/Shipper)	Offered lithium batteries, 9, accompanied by shipping papers containing an unauthorized emergency response telephone number; offered lithium batteries, 9, PG II", in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [173.22(a)(4); 173.24(f)(2); 172.604(b)] Ticket No: 10T-0209-BAT-WE	\$ 1,520
Gator Center Fort Dodge IA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0241-HMI-CE	\$ 500
Granite Northwest Inc. Yakima WA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0104-HMI-EA	\$ 500
Southline Metal Products Company Houston TX (Steel Drum Manufacturer)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0258-DM-SW	\$ 560
Goodrich Phoenix AZ (Cylinder Retester)	Failed to provide recurrent general awareness and function-specific training; after equipment malfunction, conducted a second test at the same pressure, rather than at 10 percent or 100 pi higher (whichever is lower). [180.205(c); 180.205(g)(5); DOT-SP 10915; 172.704(a)(1) and (2); 172.704(c)(2)] Ticket No: 10T-0200-CR-WE	\$ 1,160
KMI Kleen Machine Battle Creek MI (Other Priority Investigation Type)	Failed to maintain hazardous materials training records for DOT general awareness, function specific, safety, security awareness, and in-depth security training. [172.702(a)(1)-(5); 172.704(d)] Ticket No: 10T-0190-SD-CE	\$ 250
WESTAIR GASES & EQUIPMENT,	Failed to create and retain current records of hazardous materials training. [172.702(b); 172.704(d)] Ticket No: 10T-0254-SC-WE	\$ 200

## PHMSA Notice of Hazardous Materials Regulations Enforcement

INC. SAN DIEGO CA (Shipper)		
Hawks Express, Inc. Harrison NJ (Shipper)	Offered barium compounds, n.o.s., 6.1, and sodium nitrate, 5.1, when the materials were reshipped in packages that were filled to a gross mass greater than the maximum gross mass marked on the packaging, therefore shipping in unauthorized packages: offered barium compounds, n.o.s., 6.1, and sodium nitrate, 5.1, accompanied by shipping papers that failed to include a shipper's certification and for containing additional information interspersed within a basic shipping description. [173.22(a)(2); 173.24a(b)(2); 173.213(a) and (c); 172.204(a); 172.202(b)] Ticket No: 09T-0238-SD-EA	\$ 1,332.25
Boren Explosives Company, Inc. Parrish AL (Fitness Inspection)	Offered and transported ammonium nitrate-fuel oil mixture, 1.5D, under the provisions of DOT-SP 8554, and failed to mark the special permit number on the package: offered and transported ammonium nitrate-fuel oil mixture, 1.5D, accompanied by a shipping paper that contained (1) an incorrect identification number for the material, (2) failed to indicate the net explosive mass, and (3) and to indicate the EX number on the package, or, alternatively, on the shipping papers.[172.302(c); 173.22(a)(2)(v); DOT-SP 8554(8)(e); 172.202(a)(1) and (5)(i); 172.320(a) and (d)] Ticket No: 10T-0074-EX-SO	\$ 1,880
Safety Management Services, Inc West Jordan UT (Fitness Inspection)	Failed to provide function-specific training. [172.704(a)(2); Approval CA-9908005, para 7.b.;172.704 (d)] Ticket No: 10T-0236-SE-HQ	\$ 720
MFR Transport, Inc. Bayanon PR (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0098-HMI-EA	\$ 500
International Polymer & Adhesives, Inc. Marietta GA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Failed to register with PHMSA; offered adhesives, 3, and others, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.702(a); 172.704(a)(1)-(4); 107.608(a) and (b); 172.604(b)] Ticket No: 10T-0227-SD-SO	\$ 2,160
Johnson Controls Inc. Milwaukee WI	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0139-HMI-EA	\$ 500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(HMI Ticket)		
Dura Technologies Bloomington, CA (Shipper)	Failed to create and maintain records of recurrent hazardous materials training. [172.702(b); 172.704(c)(2); 172.704(d)] Ticket No: 10T-0275-MD-We	\$ 400
House of Batteries, Inc. Fountain Valley CA (Accident/Failure Investigation)	Offered lithium batteries, 9, in unauthorized packagings. Offered lithium batteries, 9, and (1) failed to retain copies of hazardous materials shipping papers for a minimum of two years and failed to provide shippers certifications on the shipping papers. [173.22(a)(2) and (a)(4); 173.185(e)(4); 173.185(j); 178.601(a) and 178.601(c)(4); 178.601(g)(2)(iii); 172.201(e); 172.204(a); 173.185(j)] Ticket No: 10T-0230-BAT-HQ	\$ 3,200
Champion Energy Corporation New Rochelle NY (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0125-HMI-EA	\$ 500
ERA A Waters Company dba Environmental Resource Associates Arvada CO (Shipper)	Failed to provide recurrent general awareness, function-specific, safety, and security awareness training; offered acetic acid solution, 8, accompanied by a shipping paper which failed to describe the material as a limited quantity for the material. [172.702(a); 172.704(a)(1)-(4); 172.200(a); 172.203(b)] Ticket No: 10T-0257-SB-WR	\$ 920
Supreme LLC dba Roy Honstein Oil Company Española NM (Carrier)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 09T-0290-SCT-SW	\$ 827.63
AA PORTABLE POWER CORP dba BATTERYSPACE.COM RICHMOND CA (Lithium Battery Mfg/Shipper)	Offered lithium battery, 9, (prototype) and failed to ship the battery as a class 9 regulated material; offered batteries (wet filled), non-spillable, 8, and lithium batteries, 9, and failed to label the packages with the required labels of non-spillable and forbidden on passenger aircraft. [173.185(e); 173.159a(c); Special Provisions 188] Ticket No: 10T-0226-BAT-SO	\$ 4,400
Global Petroleum Revere MA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0213-HMI-CE	\$ 500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Pine Knoll Construction Company, Inc. Winchester VA (Shipper Inspection (Explosive))	Offered articles, explosive, n.o.s. (HMX & aluminum), 1.4S, accompanied by shipping papers that failed to indicate the net explosive mass and the applicable unit of measurement for the material; offered articles, explosive, n.o.s. (HMX and alum powder), 1.4S, accompanied by shipping papers that failed to indicate the type of package by description for the material; offered explosive, blasting, type B, 1.5D, accompanied by shipping papers that failed to provide the proper shipping name and division number for the material. [172.202(a)(7); 173.22(a); 172.202(a)(5)(i); 173.22(a); 172.202(a)(1) and (3); 173.22(a)] Ticket No: 10T-0232-SE-HQ	\$ 1,120
Allbrite Car Care Products Anaheim CA (Shipper)	Offered corrosive liquids, poisonous, n.o.s. (hydrofluoric and sulfuric acid solution), 8(6.1), accompanied by a shipping paper that failed to include the subsidiary hazard class for the material; offered corrosive liquids, poisonous, n.o.s. (hydrofluoric and sulfuric acid solution), 8(6.1), and failed to label the package with a subsidiary hazard label for the material; offered hazardous materials in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification; failed to provide function-specific and safety training. [173.22(a)(4); 173.24(f)(2); 172.200(a); 172.202(a)(3); 172.702(b); 172.704(a)(2) and (3); 172.400(a); 172.402(a)] Ticket No: 10T-0173-SB-WE	\$ 2,060
PermaFix of Orlando, Inc. Orlando FL (Carrier)	Failed to notify persons to whom the packaging is transferred of all the requirements not met at the time of transfer, including closure instructions needed to satisfy and maintain performance test requirements. [178.2(c)] Ticket No: 10T-0187-SD-SO	\$ 1,000
Company	SUMMARY	Penalty
Desert Cylinder, Inc. Barstow CA (Cylinder Retester)	Failed to possess a re-qualifier's identification number (RIN) issued by the US DOT PHMSA Approvals office and stamped a RIN number which had expired; failed to test cylinders in accordance to the special permit requirements; failed to maintain complete and accurate daily records of retest. [180.205(b); 180.205(c); 180.215(a)(5); SP-9421 and SP-9370; 180.215(b)(1) and (2)] Case No: 07-0117-CR-SO	\$ 10,160
Labsco Indianapolis IN (Shipper)	Offered methanol, 3, and failed to label or mark the proper shipping name, package orientation arrows, and identification number of the material on the package; offered methanol, 3, in unauthorized non-UN standard or non-specification packaging; Offered ethanol, 3, and	\$ 16,300

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	<p>xylene, 3, accompanied by shipping papers that failed to list the correct proper shipping name and include the hazard class of the materials; offered ethanol, 3, accompanied with a shipping paper that contained additional information inconsistent with the required description and placed other than after the basic description; offered methanol, 3, but failed to retain copies of hazardous materials shipping papers for a minimum of two years; failed to provide function-specific and in-depth security training. [173.22(a)(2); 173.24(a)(1)-(3) and (c)(1); 172.300(a), 172.301(a); 173.312(a); 172.400(a)(1); 172.702(a); 172.704(a)(2) and (5) and (d); 172.200(a) and 171.201(e); 172.202(a)(1) and (4); 177.817(f); 172.201(a)(4); 177.817(a); 172.202(a)(2) and (3); 177.817(a)] Case No: 09-0193-SB-CE</p>	
<p>Splash Pool Service (Splash Pool Chemicals, Inc. d.b.a.) Las Vegas NV (Shipper)</p>	<p>Offered hypochlorite solution, 8, in non-UN standard packaging when a UN-standard package is required; offered hypochlorite solution, 8, and hydrochloric acid solution, 8, in packages that failed to be marked with the proper shipping name and identification number for the material; offered hypochlorite solution, 8, and failed to label the packages with the appropriate hazard warning label for the material; offered hypochlorite solution, 8, hydrochloric acid solution, 8, and trichloroisocyanuric acid, dry, 5.1, and failed to provide a proper shipping paper for a shipment of hazardous materials. [173.1(b); 173.22(a); 173.203(a); 172.400(a); 172.300(a); 172.301(a); 172.200(a); 172.202(a)] Case No: 09-0175-SD-WE</p>	<p>\$ 9,000</p>
<p>Firex, Inc. Portsmouth RI (Cylinder Retester)</p>	<p>Failed to maintain complete and accurate records of cylinder requalification; failed to notify the Associate Administrator for Hazardous Materials Safety, in writing, of a change in personnel performing cylinder requalification testing; failed to provide general awareness and security awareness training; failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig. [180.205(g)(3); 180.215(b)(1); 180.215(b)(2); 107.805(g); 172.702(a); 172.704(a)(1), (4); 172.704(c)(1)] Case No: 09-0012-CR-EA</p>	<p>\$ 4,312</p>
<p>Staples, Inc. Ithaca NY (Freight Terminal Inspection)</p>	<p>Accepted and offered air bag modules, 9, when the materials were not (1) properly marked and labeled and accompanied by shipping papers that failed to (2) properly describe the hazardous material and (3) provide the emergency response information, including an</p>	<p>\$ 11,250</p>

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	emergency response telephone number; accepted and offered air bag modules, 9, in quantities that exceeded the allowable number of bags in a single non UN-standard combination package. [172.200(a), 172.300(a), 172.400(a); 172.602, 172.604 and 173.22(a)(1); 173.22(a)(2), 173.24(c), 173.166(d)(4) and (e)] Case No: 08-0177-SB-EA	
Forto Chemical Corp. Guaynabo PR (Shipper)	Offered corrosive liquid, n.o.s.,(contains phosphoric acid), 8, among others, in a re-usable container that had not been subjected to a leak proof test prior to each re-use; Offered corrosive liquid, n.o.s.,(contains phosphoric acid), 8, and corrosive liquid, n.o.s., (contains sodium hydroxide), 8, in UN-certified 35 and 55-gallon closed-head plastic drums, respectively, and terpene hydrocarbons, n.o.s., 3, in UN-certified 55-gallon closed-head steel drums that were not closed in accordance with the manufacturer's closure notification; offered hydrochloric acid, solution, 8, and failed (1) to mark a package with the correct proper shipping name and (2) to label the package using the required background color for corrosive hazard labels; offered sulfuric acid, 8, and failed to mark a package containing liquid hazardous materials with required orientation arrows on two opposite sides of package; offered corrosive liquid, basic, inorganic, n.o.s. (contains sodium hydroxide), 8, in an unauthorized non-UN standard, non-DOT packaging; offered hydrochloric acid solution, 8, among others, accompanied by shipping papers that failed to include the basic shipping description for the material; [173.22(a)(2); 173.24(c); 173.202; 173.28(b); 173.28(b); 173.22(a)(4); 173.24(b) and (f)(1); 178.2(b)(2); 172.300(a); 172.442(b); 172.400(a); 172.407(d)(2)(ii) ; 172.312(a)(2); 172.202(a)(1)-(4); 172.203(b)] Case No: 08-0094-SPBD-CE	\$ 5,000
NOTTINGHAM COMPANY ATLANTA GA (Shipper)	Offered corrosive liquid, n.o.s. (contains sodium hydroxide), 8, and others, in UN-certified 275 gallon composite intermediate bulk containers that were not closed in accordance with the manufacturer's closure notification; failed to create and retain current records of security awareness training. [173.22(a)(4); 173.24(f)(2); 172.702(b); 172.704(a)(4); 172.704(d)] Ticket No: 10T-0268-SD-SO	\$ 1,275
PVS Transportation, Inc. Detroit MI	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0302-HMI-SI	\$ 500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(HMI Ticket)		
Conway Freights Fontana CA (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0289-HMI-SI	\$ 500
International Packaging & Container Corporation Stevensville MD (Packaging Distribution/Bro ker)	Represented, certified and sold UN certified packages with another company's manufacturing symbol; failed to provide general awareness, function-specific and security awareness training. [178.503(a)(8); 178.3(d); 172.702(a); 172.704(a)(1), (2) and (4)] Ticket No: 10T-0259-SB-EA	\$ 3,440
Kentucky Oil Refining Betsilayne KY (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0290-HMI-SI	\$ 500
Safeware, Inc. Round Rock TX (Cylinder Retester)	Failed to provide written notification of the condemned cylinder to the cylinder's owner; failed to maintain complete and accurate records of cylinder requalification: failed to maintain copies of each CGA pamphlet applicable to the requalifier's activities. [180.205(i)(3); 180.215(b)(2); 180.215(a)(6)] Ticket No: 10T-0055-CR-SW	\$ 1,387.15
Fiberglass Pool Resurfacing, Inc. Martinez CA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training; offered resin solution, 3, and others, and failed to retain copies of hazardous materials shipping papers for a minimum of two years. [172.704(c)(1); 172.704(a)(1)-(4); 172.702(a); 172.201(e); 177.817(f)] Ticket No: 09T-0423-SD-WE	\$ 1,477.30
AmSan, LLC Spokane WA (Shipper)	Offered compound cleaning liquid, 8, in UN-certified 55 gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification; offered a hazardous material accompanied by a shipping paper which included additional information within the basic description; offered compounds, cleaning liquid, 8, accompanied by a shipping paper that failed to provide a proper shipping description for a shipment of hazardous materials; failed to provide initial security awareness and in-depth security training. [172.200(a); 172.202(a)(1)-(4); 173.22(a)(4); 173.24(f)(2); 172.702(b); 172.704(a)(4) and (5); 172.201(a)(4)] Ticket No: 10T-0320-SBD-WE	\$ 2,920
PRINTEX, INC. POWAY	Offered ethanol, 3, in UN-certified combination packages that were not closed in accordance with the	\$ 1,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

CA (Shipper)	package manufacturer's notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0251-SB-WE	
River City Fire Equipment Co., Inc. West Sacramento CA (Cylinder Retester)	Offered a hazardous material, accompanied by a shipping paper that failed to contain a signed shipper's certification; offered nitrogen, compressed, 2.2, accompanied by shipping papers that failed to include the proper identification number for the material; failed to provide general awareness, function-specific, safety and security awareness training. [172.202(a)(1); 172.204(d); 172.702(b); 172.704(a)(1)-(4)] Ticket No: 10T-0314-SCR-WE	\$ 1,360
Harvey & Price Company Eugene OR (Cylinder Retester)	Failed to have a retesters identification number (RIN) issued by the Pipeline & Hazardous Materials Safety Administration (PHMSA). [173.34(e)(2); 180.205(b)] Ticket No: 10T-0217-CR-WE	\$ 1,600
Desert Industrial X-Ray, LP Beebe AR (Shipper Inspection (Ram))	Offered radioactive material, type B (U) package, 7, Iridium-192, accompanied by a shipping paper that failed to (1) provide the proper shipping name of the material, (2) number and type of packages, and (3) to mark the category of label applied to each package and (4) provide for USNRC packages, a notation of the package identification marking; offered radioactive materials type B (U), (Iridium-192), 7, in packagings affixed with Class 7 labels that failed to conform to the label standards and to mark the materials activity and transport index on the label; offered radioactive materials, type B (U), 7, in packages that failed to be marked with the materials assigned proper shipping name and identification number. [172.301(a); 172.202(a)(2) and (7); 172.203(d)(5); 172.203(d)(7); 172.407; 172.403(g)] Ticket No: 10T-0221-RMS-SW	\$ 2500
E. W. Smith Chemical Company Chino CA (Shipper)	Offered hydrochloric acid solution, UN1789, in UN-certified 55 gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0273-SD-WE	\$ 1,000
Kellner's Fireworks, Inc. Harrisville PA (Shipper Inspection (Explosive))	Failed to provide recurrent hazardous materials training to hazmat employees; offered fireworks, 1.3G, fireworks, 1.4G, and fuse, safety, 1.4S, accompanied by shipping papers that failed to include the (1) net explosive mass, (2) packing group and (3) explosive approval number. [172.702(a); 172.704(c)(2); 172.200(a); 172.202(a)(4); 172.202(a)(5)(i)] Ticket No: 10T-0261-SE-EA	\$ 1,700
Neo Solutions,	Offered corrosive liquid, acidic, inorganic, n.o.s. (ferric	\$ 1,400

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Inc. Newell PA (Shipper)	sulfate), 8, and corrosive liquids, n.o.s. (contains sodium tolyltriazole), 8, accompanied by shipping papers that failed to contain a shipper certification; offered corrosive liquid, acidic, inorganic, n.o.s. (ferric sulfate), 8, in UN-certified 55 gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2); 172.202(a)(5); 172.204(a)(1)] Ticket No: 10T-0223-SD-EA	
Mann Chemical, LLC Warwick RI (Shipment Observation (General))	Offered potassium hydroxide, solid, 8, in an overpack that was not properly marked. [173.25(a)(4)] Ticket No: 10T-0222-SB-EA	\$ 1,200
Spokane Transfer & Storage Co. Spokane WA (Carrier)	Failed to create and retain current records of hazardous materials training. [172.702(b); 172.704(d)] Ticket No: 10T-0307-SB-WE	\$ 320
Suburban Propane, Inc. Athens TN (Carrier)	Failed to comply with the requirements of the special permit by not maintaining a copy of the special permit in the transport vehicle during activities of transportation; failed to (1) properly mark DOT cylinders with the year of retest, and (2) from a different location and marking the RIN number in a straight line. [180.213(d) and (f)(5); V# RIN letter; SP 13341] Ticket No: 09T-0382-CAR-SO	\$ 2,429.27
Velvin Oil Company, Inc. Henderson TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0283-HMI-SI	\$ 500
Harris Fire Protection Co., Inc. Baltimore MD (Cylinder Retester)	Failed to provide recurrent general awareness and function-specific training. [172.704(a)(1) and (2); 172.704(c)(2)] Ticket No: 10T-0269-CR-EA	\$ 450
GNA Brook Fire Protection, Inc. Glendora CA (Cylinder Retester)	Failed to provide recurrent general awareness, function-specific, safety, security awareness, and in-depth security training. [172.704(a)(1)-(4); 172.704(c)(2)] Ticket No: 10T-0312-SR-WE	\$ 720
BeautyCo USA, Inc. Santa Ana CA (Shipper)	Offered paint, 3, accompanied by a shipping paper that failed to contain a signed shipper's certification; failed to provide recurrent general awareness, function-specific, safety, and security awareness training. [172.704(d); 172.702(b); 172.704(a)(1)-(4); 172.204(d)] Ticket No:	\$ 1,040

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	10T-0256-SB-WE	
IRIX Manufacturing, Inc. GREENVILLE SC (Shipper)	Offered waste, flammable liquid, n.o.s. (acetone, isopropanol), 3, and others, in UN-certified 55 gallon open-head steel drums were not closed in accordance with the manufacturer's closure notification; failed to provide recurrent hazardous materials training. [173.22(a)(4); 173.24(f)(2); 172.702(a); 172.704(c)(2)] Ticket No: 10T-0305-SD-SO	\$ 1,275
GATEWAY CHEMICALS OF JACKSONVILLE INC JACKSONVILLE FL (Shipper)	Failed to remove bulk containers from the motor vehicle prior to discharging the contents of the containers; offered potassium hydroxide, solution, 8, in UN-certified 330- gallon composite intermediate bulk containers that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2); 177.834(h)] Ticket No: 10T-0274-IBC-SO	\$ 1,400
Occidental Chemical Corporation Deer Park TX (Shipment Observation (General))	Offered potassium hydroxide, solid, 8, on pallets that were stretch wrapped but failed to mark the package "OVERPACK". [173.25(a)(4)] Ticket No: 10T-0263-SBG-EA	\$ 1,200
Harcros Chemicals, Inc. Nashua NH (Shipment Observation (General))	Offered potassium permanganate, 5.1, and failed to properly mark the overpack. [173.24(a)(4)] Ticket No: 10T-0262-SP-EA	\$ 1,200
UPS Chicago IL (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0242-HMI-CE	\$ 500
B-Line Carriers, Inc. Brooksville FL (HMI Ticket)	Failed to report or file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.15; 171.16] Ticket No: 10T-0303-HMI-SI	\$ 500
Jim Speth Transport, Inc. Selmar TN (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident; failed to register with PHMSA. [171.16; 107.608(a) and (b)] Ticket No: 10T-0142-HMI-EA	\$ 1,000
OMI Huntsville AL (Shipper Inspection (Ram))	Offered radioactive materials, type A package, special form, 7, and failed to have the transport index on the shipping paper correspond with the transport index marked on the package; offered radioactive materials, type A package, special form, 7, accompanied by a shipping paper that failed to list the correct proper	\$ 2,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	shipping name and UN identification number for the material. [172.202(a)(1) and (2); 172.203(d)(5); 172.403(b)] Ticket No: 10T-0228-RMS-HQ	
Bronco Transport, Inc. Tampa FL (Carrier)	Failed to provide general awareness, function-specific, safety, security awareness and in-depth security training; failed to register with PHMSA.[107.608(a) and (b); 172.702(a); 172.704(a)(1)-(5); 172.704(c)(1)] Ticket No: 10T-0266-NVO-SO	\$ 1,300
Lubbock Welding Supply, Inc. Lubbock TX (Cylinder Retester)	Represented, marked and certified DOT specification cylinders and failed to properly mark the hazardous materials packagings; failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values; failed to maintain complete and accurate records of visual or cylinder requalification; failed to conduct a complete visual external and internal examination before pressure testing cylinders; failed to provide recurrent general awareness, function-specific, safety, and security training. Represented marked, and certified a cylinder with a plus sign when the elastic expansion exceeded the REE. [180.205(g)(4); 173.302a(b)(2); 180.209(b); 173.302a(b)(2); 180.205(f)(1); 180.215(b)(1) and (2); 172.702(b); 172.704(a)(1)-(4); 172.704(c)(2)] Case No: 09-0222-CR-SW	\$ 12,390
Total Safety U.S., Inc. Broussard LA (Cylinder Retester)	Failed to condemn cylinders when the hydrostatic retest results showed that the permanent expansion of the cylinders exceeded ten percent of the total expansion and five percent for exemption or special permit cylinders; failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; after equipment malfunction, conducted a second test at the same pressure, rather than at 10 percent or 100 pi higher (whichever is lower). [180.205(i)(1)(iv); 180.205(c); DOT-SP 7235; DOT-SP 9634; 180.205(g)(3)(i); 180.205(g)(5)] Case No: 09-0058-CR-SW	\$ 13,703
Melrose South Pryotechnics Inc Catawba SC (Shipper Inspection (Explosive))	Offered fireworks, 1.3G, with an explosive approval number not assigned for that material; offered fireworks, 1.3G, accompanied by a shipping paper that failed to contain the explosive approval number for the material; offered fireworks, 1.3G, that failed to be examined, classed or approved by a laboratory authorized by the Associate Administrator for Hazardous Materials Safety to conduct explosive classification testing. [173.51 (a); 173.54 (a); 173.56 (a); 172.320 (a)-(d); 172.320(a)-(d)] Case No: 10-0092-SE-HQ	\$ 5,940

## PHMSA Notice of Hazardous Materials Regulations Enforcement

<p>Mid-West Fertilizer Inc. dba Nortonville Farmers Supply Nortonville KS (Shipper)</p>	<p>Offered and transported anhydrous ammonia, 2.2, in a bulk package (cargo tank) and failed to mark the packages with the special permit number; offered and transported anhydrous ammonia, 2.2, in a bulk package (cargo tank) without marking proper shipping name on all sides of the package; offered and transported anhydrous ammonia, 2.2, in a bulk package (cargo tank) that was an unauthorized non-standard or non-DOT specification packaging. [173.22(a)(2); 173.22a(a); 173.315(m); 172.302(a); 172.313(a); 172.328(b)(1); 173.315(m); 172.300(a); 172.302(b) and (c)] Case No: 09-0176-NT-WE</p>	<p>\$ 4,180</p>
<p>Permian Basin Chemical, dba Pipeline Chemical Midland TX (Shipper)</p>	<p>Represented and certified UN standard intermediate bulk containers (IBCs) when records of periodic retests and inspections failed to include the design types, packaging specifications and address of the test inspection; offered flammable liquid, corrosive, n.o.s., 3, (8), in intermediate bulk containers and failed to remove bulk containers from the motor vehicle prior to discharging the contents of the containers; failed to provide security awareness and in-depth security training. [177.834(h); 180.352(g); 172.702(b); 172.704(a)(4) and (5); 172.704(d)] Case No: 09-0186-SIBC-SW</p>	<p>\$ 4,065</p>
<p>Tote Detailing Specialists, Inc. Joliet IL (Recertifier/Retester/Repairer (Tanks, IBCs))</p>	<p>Represented, marked and certified packagings when the packagings were certified with an unauthorized manufacturers mark and failed to properly mark a specification intermediate bulk container to the required 12 mm marking height requirement; failed to properly mark a specification intermediate bulk container to the required 12 mm marking height requirement; failed to properly mark a specification intermediate bulk container as having passed inspection and retest; represented and offered a UN certified packaging and failed to notify persons to whom the packaging is transferred of all the requirements not met at the time of transfer, including closure instructions needed to satisfy and maintain performance test requirements. [173.24(f)(2); 178.2(c); 178.2(c)(1), (2) and (3); 178.2(b), (1) and (2); 178.3(a)-(d); 178.703(a), (1) and (b); 178.703(b)(1) and (b)(6); 180.3(a); 178.2(b); 178.703(a)(1); 180.3(a); 178.3(a); 178.703(b); 180.352(f)] Case No: 09-0078-IBCR-CE</p>	<p>\$ 1,400</p>
<p>Southern States Cooperative, Inc. Trenton FL</p>	<p>Offered anhydrous ammonia, 2.2, in an unauthorized non-DOT specification cargo tank. [173.315(m)(1)] Case No: 09-0162-SPT-SO</p>	<p>\$ 5,600</p>

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Shipper)		
Niagara National Corporation Atlanta GA (Shipper)	Offered corrosive liquids, n.o.s. (contains hydrofluoric and sulfuric acids), 8, PGII”, and others, in an unauthorized, non-UN standard packaging; failed to provide initial general awareness, function-specific, safety, security awareness, and in-depth security training; offered corrosive liquids, n.o.s. (contains potassium hydroxide), 8, and others, in Intermediate Bulk Containers (IBC), and failed to remove bulk containers from the motor vehicle prior to discharging the contents of the containers. [173.22(a)(2) and (4); 173.24(b) and (f)(2); 173.28(a)-(c); 173.202(a); 177.834(h); 172.702(a); 172.704(a)(1)-(5)] Case No: 09-0234-SD-SO	\$ 6,080
Gramm Industries, LLC Perrysburg OH (Shipper)	Offered sulfuric acid, 8, accompanied by a shipping paper that failed to (1) provide the proper shipping name and UN identification number, (2) have the proper sequence for the shipping description, (3) include a valid emergency response telephone number and (4) mark the letters “RQ” for each hazardous substance; failed to register with PHMSA; filled and offered sulfuric acid, 8, in a UN specification intermediate bulk container that had not been subjected to periodic inspection and retesting; offered sulfuric acid, 8, in UN-certified composite intermediate bulk containers that were not closed in accordance with the manufacturer's closure notification; failed to provide general awareness, function-specific, safety, and security awareness training. [180.352(a); 180.352(b)(1); 180.352(b)(2); 180.352(b)(3); 173.22(a)(4); 173.24(f)(2); 107.608(a) and (b); 172.702(a); 172.704(a)(1)-(4); 172.704(c); 172.201(a)(4); 172.604(b); 172.201(d); 172.203(c)(2); 172.202(a)(1)-(5)] Case No: 08-0108-SIBC-CE	\$ 3,600
Robstown Bulk Plant, Inc. Robstown TX (Carrier)	Failed to provide general awareness, function-specific, safety, security awareness and in-depth security training; failed to develop and adhere to a security plan; filled and transported gasoline, 3, and diesel fuel, 3, in a MC 306 cargo tank that was overdue the prescribed periodic retest; offered and transported gasoline, 3, and diesel fuel, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; failed to register with PHMSA; offered and transported gasoline, 3, diesel fuel, 3, accompanied by shipping papers that failed to include the hazard class of the material, number and type of packages, required shipper’s certification, and listed shipping descriptions	\$ 8,617.97

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	that included additional unauthorized information. [173.33(a)(3); 180.407(a) and (c); 172.604(b); 172.702(b); 172.704(a)(1)-(5); 107.608(a) and (b); 172.201(a)(4); 172.202(a); 172.204; 172.800(a); 172.802(a) and (b)] Case No: 09-0181-CCT-SW	
Scholl Fertilizer, Inc. Falls City NE (Shipper)	Offered anhydrous ammonia, 2.2, in an unauthorized non-standard or non-specification nurse tank; offered anhydrous ammonia, 2.2, in a (cargo tank) bulk package that failed to be properly marked and/or placarded for the material; failed to register with PHMSA. [173.22(a)(2); 173.22a(a); 107.608(a) and (b); 172.302(a); 172.313(a); 172.328(a)(2) and (b)(1); 172.519(d)(3), 172.504(a) and 172.516(c)(6); 173.315(m); 177.823(a)] Case No: 09-0151-SNT-CE	\$ 7,979
TradeWind Enterprises Hillsboro OR (Shipment Observation (Ram))	Failure to placard a vehicle containing Radioactive Yellow III hazardous materials. Failure to adhere to the security plan; failed to secure Class 7 (radioactive materials) to prevent shifting during normal transportation. [172.504(a); 172.504(e); 173.448(a); 177.842(d); 172.800(b)] Case No: 07-0059-RMC-HQ	\$ 2,869
Blue Flame Gas, Inc. Powder Springs GA (Carrier)	Represented, certified, marked and offered DOT specification cylinders as having been successfully retested and failed to maintain a current and valid requalifiers identification number (RIN); failed to provide recurrent training; represented, certified and marked DOT-4E240 specification cylinders and failed to (1) mark the V# RIN on the cylinders and (2) place the "E" mark prior to the month/year marking; failed to maintain copies of the applicable sections of the regulations at its retest facility; offered and transported liquefied petroleum gas, 2.1, in approved ASME tanks with greater than 125 gallon capacity, while transported the tanks charged with LP gas with a quantity greater than 5 percent. [173.315(j)(4); V# RIN letter; 172.702(a); 172.704(c)(2); 180.215(a)(4); 180.205(b)] Case No: 09-0074-SPT-SO	\$ 8,890
Klotz Special Formula Products Inc. Fort Wayne IN (Serious Incident Inspection)	Failed to provide initial or refresher general awareness, function-specific, safety, security awareness, and in-depth security training; offered petroleum distillate, n.o.s, 3, accompanied by a shipping paper that had additional information before the shipping description; offered flammable liquid n.o.s., 3, in 55-gallon drums, accompanied with Respondent's competent authority approval that specified jerricans, and was altered by Respondent to specify drums, resulting in an unauthorized package. [173.22(a)(2)(iv); 172.702(a);	\$ 6,800

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	172.704(a)(1)-(5); 172.704(d); 172.200; 172.201(a) Case No: 09-0218-DMS-CE	
Chemject International, Inc. Conroe TX (Shipper)	Offered hazardous materials, accompanied by various shipping papers that failed to (1) list an authorized emergency response telephone number, (2) mark the technical name of an n.o.s. material in parentheses, (3) list the hazardous material in the tree approved DOT methods, (4) list the hazard class numerically and (5) used an incorrect identification number for the material; failed to remove drums and bulk containers from the motor vehicle prior to discharging the contents of the containers. [172.203(k); 172.202(a)(1) and (3); 172.201(a) and (d); 172.604(b); 177.834(h)] Case No: 10-0072-SDIBC-SW	\$ 4,760
Empresas De Gas Company, Inc. Baymon PR (Shipper)	Filled and offered liquefied petroleum gas, 2.1, (1) packaged in DOT-4 series cylinders that were past due for periodic requalification, and (2) cylinders that were missing the DOT or ICC specification and date of manufacture; offered and transported liquefied petroleum gas, 2.1, in a non-DOT/UN standard storage tank charged to greater than five percent of the tank's water capacity; offered and transported liquefied petroleum gas, 2.1, in a non-DOT/UN standard storage tanks, and failed to provide shipping papers for shipments of hazardous materials; failed to provide in-depth security training. [173.301(a)(1) and (2); 173.301(a)(6); 173.301(j); 173.304a(a)(1); 180.209(G); 173.315(j); 172.200(a); 172.201(a); 172.202(a); 172.604(b); 172.702(b); 172.704(a)(5)] Case No: 09-0213-SC-SW	\$ 19,000
Southern Aerosols, Inc. Cleveland NC (Aerosol Filler/Shipper)	Failed to create and retain current records of hazardous materials training; offered a limited quantity of a compressed gas in a metal container for the purpose of propelling a non-poisonous material, while failing to heat the DOT 2Q cylinder until the pressure is equivalent to the equilibrium pressure at 130° F. [173.306(a)(3); 172.702(b); 172.704(a)(1)-(4); 172.704(d)] Case No: 10-0064-SA-SO	\$ 3,400
Ed's Drilling & Blasting Company Washington MO (Shipper Inspection (Explosive))	Offered Division 1.1D, 1.4B, 1.4S, 1.5D, 5.1 and Class 8, under the provisions of DOT SP-11579, on a single transport vehicle, in containers or compartments that failed to meet the minimum construction requirements of the Institute of Makers of Explosives and failed to satisfy all of the requirements outlined in Special Permit 11579. [171.7; 173.22(a); 173.63(f)(2); 177.835(g)(3)(i) and (ii)] Case No: 09-0217-SE-CE	\$ 7,425

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Innospec Active Chemicals, LLC Salisbury NC (Shipper)	Offered corrosive liquids, n.o.s. (contains diethanolamine), 8, and others, in non-UN certified steel and fiber drums; failed to provide initial general awareness, function-specific, security awareness and in-depth security training. [173.22(a)(2); 173.203(a); 172.702(a); 172.704(c)(1); 172.704(a)(1), (2), (4) and (5)] Case No: 10-0075-SD-SO	\$ 5,440
Zenith Specialties, LP Clinton MO (Shipment Observation (Explosive))	Offered fireworks, 1.4G, accompanied by a shipping paper that contained an incorrect explosive approval number for the material; offered fireworks, 1.4G, that had not been examined, classed or approved by a laboratory authorized by the Associate Administrator for Hazardous Materials Safety. [173.54 (a); 173.51(a); 173.56(a); 172.320(a) and (d); 173.22(a)(1)] Case No: 10-0095-SE-HQ	\$ 4,350
Florex Explosives, Inc. Crystal River FL (Fitness Inspection)	Failed to provide function specific training; offered explosive, blasting type E, 1.5D, under the terms of special permit 8815, and transported other explosive products on the same vehicle when not authorized; offered explosives, blasting type E, 1.5D, under the terms of DOT-SP 11579 and failed to mark the DOT-SP number on the cargo tank; offered explosive blasting type E, 1.5D, under the terms of DOT-SP 11579 and failed to indicate the special permit number on a shipping paper; offered explosives, blasting type E, 1.5D, accompanied by various shipping papers that failed to provide the Explosive Approval number and the special permit number on the shipping documents. [173.22(a)(2); DOT-SP 8815; 172.203(a); DOT-SP 11579; 172.320(a) and (d); 172.302(c); 172.203(a); 172.704(a)(2); DOT-SP 8815] Case No: 09-0210-SE-SO	\$ 7,785
Titan Propane, LLC dba Synergy Gas Fort Smith AR (Carrier)	Offered propane, 2.1, in a non-DOT/UN standard storage tank designed for permanent installation, when the tank was charged to more than five percent of its water capacity; failed to provide function-specific training for DOT-SP 13341; failed to develop the personnel security, unauthorized access and en-route security components to their security plan. [DOT-SP 13341; DOT-SP 13341; 172.704(a)(2)(i); 172.800(b)] Case No: 09-0067-CC-SW	\$ 13,892
Argyle Welding Supply, Inc. Albuquerque NM (Cylinder Retester)	Represented, marked and certified DOT specification cylinders when the calibrated cylinder showed permanent expansion; after equipment malfunction, conducted a second test at the same pressure, rather than at 10 percent or 100 pi higher (whichever is lower).	\$ 5,967

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	[180.205(g)(4); 180.205(g)(5)] Case No: 10-0051-CR-SW	
Silvan Industries, Inc. Marinette WI (Ibc Manufacturer (Rigid))	Represented, marked and certified packagings when the packagings were certified with an unauthorized manufacturers mark; failed to properly mark a specification intermediate bulk container with the required markings to be a minimum of 0.47 inches; failed to provide general awareness and security awareness training; represented, marked and certified packagings as a DOT Specification package when the packagings were not authorized for manufacture after January 1, 2003; represented, marked and certified UN packagings when the packagings were not subjected to periodic design requalification; offered paint related materials, 3, in UN-certified 55-gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification. [178.2(a) and (b); 178.801(a) and (e); 173.22(a)(4); 173.24(f)(2); 178.2(b)(1) and (2); 178.3(b); 178.703(a)(1); 178.703(b)(1) and (b)(6); 173.32(c)(2); 172.702(a); 172.704(a)(1) and (4); 172.704(c); 172.704(d); 178.2(b); 178.3(a)(1)-(4); 178.703(a)(1); 180.3(a)] Case No: 09-0079-IBCR-CE	\$ 13,425
Ritway, Inc. Knoxville TN (Shipper)	Failed to provide initial general awareness, function-specific, and security awareness training; offered flammable solids, organic, n.o.s., 4.1, and failed to label an Overpack as required by the HMR; offered flammable solids, organic, n.o.s., 4.1, and failed to (1) mark the UN identification number and proper shipping name on the package and (2) to comply with marking and shipping paper requirements found in DOT-SP 7887; offered flammable solids, organic, n.o.s., 4.1, in an unauthorized non-UN packaging. [173.22(a)(2); 173.24(c); 173.212; DOT-SP 7887; 172.203(a); 172.300(a); 172.301(a) and (c); 172.400(a); 173.25(a); 172.702(a); 172.704(a)(1), (2) and (4)] Case No: 08-0145-SB-SO	\$ 6,094
Paramount Can Co., Inc. (PCI) La Mirada CA (Package Purchasing)	Represented, marked, certified, sold and offered combination packages when the packages were not capable of passing the drop and hydrostatic tests. [178.2(b); 178.601(b); 178.603(a); 178.605(a)] Case No: 10-0085-BM-HQ	\$ 8,400
Auto B Clean, Inc. Newman Lake WA (Shipper)	Offered corrosive liquid, toxic, n.o.s. (hydrofluoric acid) 8 (6.1), and failed to provide a proper shipping paper for a shipment of hazardous materials; failed to provide general awareness, function-specific and security	\$ 1,740

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	awareness training. [172.200(a); 172.202(a); 172.702(b); 172.704(a)(1), (2) and (4)] Ticket No: 10T-0306-SD-WE	
Wren Oilfield Services, Inc White Oak TX (Shipper Inspection (Ram))	Offered radioactive material type A package, special form, 7 and failed to have the emergency response telephone number monitored at all times by a person who has knowledge of the hazardous material placed into transportation; offered radioactive material type A package, special form, 7 and failed to maintain a file with the current Special Form Certificate; offered radioactive material type A package, special form, 7 and failed to maintain complete documentation of tests and an engineering evaluation or comparative data; offered radioactive material type A package, special form, 7 and displayed labels that were damaged, partially obscured altered and missing required information; offered radioactive material type A package, special form, 7 and mark the package with the incorrect UN identification number and incorrect proper shipping name for the material. [173.415(a); 172.407(a); 172.406(f); 172.403(b); 172.403(g)(1)-(3); 172.301(a)(1); 173.476(a); 172.604(a)(1)] Ticket No: 10T-0347-RMS-SI	\$ 3,200
Rho-Chem, LLC Inglewood CA (Shipper)	Offered lithium batteries for disposal for which each battery has not been protected from short circuit. [173.24; 173.24a; 173.159(e); 173.185(d)] Ticket No: 10T-0267-BAT-SW	\$ 1,125
Honeywell Specialty Materials, LLC Claymont DE (Toxic Inhalation Hazard Shipper)	Offered boron trifluoride, compressed, 2.3, (8), poison inhalation hazard, zone B, in DOT specification cylinders when the stars marked on the cylinders were not obliterated as required; offered boron trifluoride, compressed, 2.3, (8), poison inhalation hazard, zone B, under the terms of a DOT special permit and failed to (1) provide a copy of the special permit to the motor carrier, (2) provide function-specific training concerning the special permit and (3) indicate the special permit on the shipping papers; offered combustible liquids, n.o.s. (hexane), in UN-certified 55 gallon open-head steel drums/composite intermediate bulk containers that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2); 172.203(a); 173.22a(b); Paragraphs 10 and 11 of DOT-SP 11667 and 12184; 173.22(a)(2); 173.301(a)(1) and (b); 173.302(a)] Ticket No: 10T-0304-SIIBC-EA	\$ 2,650
KEY SAFETY SYSTEMS,	Offered air bag inflators, 9, accompanied by a shipping paper that failed to (1) list the emergency response	\$ 1,200

## PHMSA Notice of Hazardous Materials Regulations Enforcement

INC. LAKELAND FL (Box Manufacturer (Fiber))	telephone number, (2) the packing group for the material, (3) a signed shippers certification and (4) having the shipping description out of sequence. [172.201(d); 172.202(a)(4) and (b); 172.204(a); 172.200(a)] Ticket No: 10T-0265-BM-SO	
Newark Beth Israel Medical Center Newark NJ (Shipment Observation (General))	Offered regulated medical waste, 6.2, in packagings with closures that were not secure and leakproof. [173.22(a)(2); 173.24(b); 173.197(e)(1)(i) and (ii)] Ticket No: 10T-0260-SBG-EA	\$ 2,800
The Zitek Corporation dba H.O. Trerice Co. Oak Park MI (Special Permit Renewal)	Offered hazardous materials under the terms of a DOT special permit after their authority had expired. [173.306(a); 173.150(b); 173.306(a)(1); 173.222(c); 173.322] Ticket No: 10T-0334-ESF-SI	\$ 500
Carolina Tank Lines Burlington NC (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16; 171.15] Ticket No: 10T-0330-HMI-SI	\$ 500
Amerigas Portland OR (Cylinder Retester)	Failed to maintain complete and accurate records of cylinder requalification. [180.215(b)(2)] Ticket No: 10T-0253-CR-WE	\$ 400
FBL & Associates, Inc Bossier City LA (Shipper Inspection (Ram))	Offered radioactive material, type A package, special form, 7, accompanied by a shipping paper that listed an incorrect proper shipping name and UN ID number for the material; offered radioactive material, type A package, special form, 7, and failed to mark the transport index on the radioactive Yellow II label affixed to the package. [172.202(a)(1) and (2); 172.403(g)3] Ticket No: 10T-0349-RMS-SI	\$ 1,280
Safety & Environmental Assoc., Inc. Little Rock AR (Special Permit Renewal)	Offered anhydrous ammonia, 2.2, under the provisions of DOT-SP 12009 after their authority had expired. [173.304a(a)(2)] Ticket No: 10T-0336-ESF-SI	\$ 500
Tee Group Films Ladd IL (Accident/Failur e Investigation)	Offered radioactive material excepted package-instruments, 7, and ailed to retain copies of hazardous materials shipping papers for a minimum of two years; offered radioactive material excepted package-instruments, 7, and failed to ensure the external surface of the package did not exceed 0.5mR/hr; failed to	\$ 1,520

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	provide general awareness, function-specific, safety and security awareness training. [172.702(a); 172.704(a)(1)-(4); 173.424(e); 173.424(f); 172.201(e); 173.424] Ticket No: 10T-0352-RMS-SI	
EVERLUBE PRODUCTS PEACHTREE CITY GA (Other Priority Investigation Type)	Offered paint related material, 3, and others, in UN-certified 55 gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification; failed to create and retain current records of hazardous materials training. [173.22(a)(4); 173.24(f)(2); 172.702(b); 172.704(d)] Ticket No: 10T-0272-SD-SO	\$ 1,720
Lichti Brothers Oil Co., Inc. Shickley NE (Hmi Ticket)	Fail to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16; 171.15] Ticket No: 10T-0300-HMI-SI	\$ 500
MAYS CHEMICAL COMPANY OF PR INC CATANO PR (Shipper)	Offered sulfuric acid, 8, and others, in UN-certified 55 gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0342-SD-SO	\$ 1,000
Evike.com San Gabriel CA (Shipper)	Failed to provide general awareness, function-specific and safety training. [172.702(b); 172.704(a)(1)-(3); 172.704(d)] Ticket No: 10T-0316-SB-WE	\$ 540
Glorious Company Hong Kong XX (Shipment Observation (Explosive))	Offered fireworks, 1.3G, EX-9309011, after the Competent Authority Approval for the fireworks had expired. [173.51(a); 173.54(a); 173.56(b) or (j); 173,22(a)(1)] Ticket No: 10T-0233-SE-HQ	\$ 400
Spaceway Oil Co Union MS (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0281-HMI-SI	\$ 500
HOUGHTON CHEMICAL CORPORATION ALLSTON MA (Shipper)	Offered dichloromethane, 6.1, and others, in UN-certified 55 gallon closed-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0371-SD-SO	\$ 1,000
Berthold Technologies Oakridge TN (Shipper Inspection (Ram))	Offered radioactive material, type A package, 7, and failed to mark the gross mass on the outside of each package in the shipment in excess of 110 lbs; offered radioactive material, type A package, 7, and failed to maintain emergency response information for the material being transported in the transport vehicle and at the facility where it is received, shipped and stored; failed to re-register with PHMSA; offered radioactive	\$ 3760

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	material, type A package, 7, and failed to label each package with the hazardous warning label. [107.608(a) and (b); 172.602(c)(1) and (2); 172.400(b); 172.310(a)] Ticket No: 10T-0359-RMS-SI	
ColorChem International Corp. Atlanta GA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training; offered environmentally hazardous substance, solid, nos (containing zinc oxide), 9, accompanied by a shipping paper which failed to show the basic description in the specified sequence; offered environmentally hazardous substance, solid, nos (containing zinc oxide), 9, accompanied by a shipping paper that failed to indicate an emergency response telephone number. [172.604(b); 172.201(a)(4); 172.202(a) and (b); 172.702(a); 172.704(a)(1)-(4); 172.704(c)(1) and (d)] Ticket No: 10T-0372-SD-SO	\$ 2,095
ARG Trucking Phelps NY (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0329-HMI-SI	\$ 500
Rhodia, Inc. Houston TX (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0331-HMI-SI	\$ 500
Sacramento Fire Extinguisher Company, Inc. Sacramento CA (Cylinder Retester)	Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; failed to maintain complete and accurate records of cylinder requalification. [180.205(g)(3)(i); 180.215(b)(2)] Ticket No: 10T-0315-SR-WE	\$ 1,240
Warlick Paint Company, Inc. dba Crossroads Coatings Statesville NC (Aerosol Filler/Shipper)	Offered paint, 3, in UN-certified 55-gallon open-head steel drums that were not closed in accordance with the manufacturer's closure notification; failed to create and retain current records of hazardous materials training. [173.22(a)(4); 173.24(f)(2); 172.702(b); 172.704(d)] Ticket No: 10T-0079-SD-SO	\$ 1,275
ADMYR Wireline, Inc Monroe LA (Shipper Inspection (Ram))	Offered radioactive material, type A packaging, special form, RQ, accompanied by shipping papers that failed to contain (1) the proper shipping name and UN identification number for the material, and (2) to contain the letters "RQ" in association to the proper shipping name to identify that the material is a hazardous substance; offered a DOT specification 7A packaging without maintaining complete records of testing or comparative data shipping radioactive materials; offered and transported special form radioactive materials without maintaining a complete safety analysis of	\$ 5,680

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	<p>certificate of competent authority; failed to provide general awareness, function-specific, safety, and security training; offered radioactive material, type A packaging, special form, RQ, and failed to label package with the proper hazardous warning label and required additional entries; offered radioactive material, type A packaging, special form, and failed to mark the packages with (1) the proper shipping name, (2) UN identification number for the material and (3)“RQ” in association with the proper shipping name to identify that the material is a hazardous substance; offered radioactive material, type A packaging, special form, RQ, and failed to meet one or more of the general design requirements for a package used to ship radioactive materials. [172.704(a)(1)-(4); 172.702(a); 172.203(c)(2); 172.202(a)(1) and (2); 172.324; 172.301; 172.400; 172.403(g); 173.410(f); 172.415; 172.476] Ticket No: 10T-0326-RMS-SI</p>	
Shreveport Nuclear Pharmacy Shreveport LA (Shipper Inspection (Ram))	<p>Offered radioactive material type A package,7, and failed to mark “RQ” on a package containing a hazardous substance. Offered radioactive material type A package, 7, and failed to retain copies of hazardous materials shipping papers for a minimum of two years; failed to maintain hazardous materials training records; offered radioactive material type A package,7 accompanied by shipping papers that failed to include “RQ” in the shipping description to identify a material that is a hazardous substance; offered radioactive material type A package,7, accompanied by a shipping paper that failed to indicate an emergency response telephone number; offered radioactive material type A package,7, accompanied by shipping papers that failed to include a hazard class/division number of the material in the shipping description. [172.201(e); 172.704(d); 172.203(c)(2); 172.202(a)(3); 172.604(b); 172.201 (d); 172.324(b)] Ticket No: 10T-0364-RMS-SI</p>	\$ 2,540
Hasa Inc Saugus CA (Hmi Ticket)	<p>Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0301-HMI-SI</p>	\$ 500
Jung Oil, Inc San Antonio TX (Hmi Ticket)	<p>Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0287-HMI-SI</p>	\$ 500
Autozone, Incorporated Memphis TN (Shipment	<p>Offered batteries, wet, filled with acid, 8, and failed to prepare the pallets to prevent the batteries from damage and short circuit. [173.21(c); 173.159(e)(2)] Case No: 10-0073-SBAT-CE</p>	\$ 5,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Observation (General))		
Spectrum Chemical Laboratory Products, Inc., d/b/a Spectrum Chemical & Laboratory Products New Brunswick NJ (Shipper)	Represented, marked and certified combination packagings when design qualification testing was not conducted as required. [178.601(d); 178.603;178.606] Case No: 09-0113-BMS-EA	\$ 7,140
Ultra Pure, LLC. Darien CT (Shipment Observation (General))	Represented, certified and offered UN4G combination packagings when the periodic testing was not conducted; offered ethanol, 3, II, in combination packagings which were not subjected to the design qualification testing, therefore, shipping in unauthorized packagings; represented, certified and offered UN4G combination packagings when the packaging design was not subjected to the drop and stacking tests; failed to register with PHMSA. [178.601(d); 173.22(a)(2); 173.202(a); 178.601(e); 107.608(a) and (b)] Case No: 09-0006-BSM-EA	\$ 5,000
Emco Chemical Distributors, Inc. North Chicago IL (Shipment Observation (General))	Offered acetone, 3, in an unauthorized non-UN standard combination packaging. [173.22(a)(2); 173.24(f)(2)] Case No: 09-0055-SB-EA	\$ 5,600
Technical Chemical Company Cleburne TX (Aerosol Filler/Shipper)	Failed to create and maintain function-specific training records and to provide in-depth security training; filled and offered a cylinder with a compressed gas when the cylinder was overdue for periodic requalification; developed a security plan that failed to include a written assessment of transportation security risks; offered hazardous materials accompanied by shipping papers that failed to include the identification number, proper shipping name, hazard class, packing group of the material; Failed to (1) mark packages with the proper shipping name and identification number, (2) mark an overpack with the word "OVERPACK", and marked a package with ORM-D when the package did not contain an ORM-D material; filled and offered a compressed gas in metal containers (aerosols) without properly performing the hot water bath test to assure that the	\$ 13,040

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	internal temperature has reached at least 55° C (131° F); offered sodium hydroxide solution, 8, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [172.301(a); 172.316(c); 173.25(a)(4); 173.22(a)(4); 173.24(f)(2); 172.702(a)(5); 172.704(d); 173.301(a)(6); 172.202(a)(1)-(4); 173.306(a)(3)(v); 172.802(a) and (b)] Case No: 09-0090-SC-SW	
Ninyo & Moore Las Vegas NV (Shipper Inspection (Ram))	Failed to list the contents, activity and transport index on the shipping papers for the radioactive material; failed to provide initial general awareness, function-specific, safety and security awareness training; failed to have emergency response telephone number monitored while hazardous material is in transportation by listing multiple telephone numbers without times for each; offered radioactive materials, accompanied by a shipping paper that failed to include "RQ" in the shipping description to identify a material that is a hazardous substance. [172.704(a)(1)-(4); 172.20(c)(2); 172.604(a)(1) and (2); 172(g)(1)-(3)] Ticket No: 10T-0356-RMS-SI	\$ 1,960
Welenco Inc Bakersfield CA (Shipper Inspection (Ram))	Failed to maintain Type "A" package documents; failed to insure labels were durable on packages with the writing in black ink; failed to maintain testing documents of IAEA certificate for Class 7 (radioactive) material placed in transportation; offered radioactive materials, 7, accompanied by a shipping paper that failed to provide the proper shipping name for the material; failed to provide emergency response information with on or in a shipping paper; failed to round the Transport Index to the next 10th. [172.407; 172.438; 172.203; 172.403; 173.469; 173.476; 172.202(a)(2); 172.602; 173.461; 173.415] Ticket No: 10T-0323-RMS-SI	\$ 4,515
Summit Engineering Corporation Reno NV (Shipper Inspection (Ram))	Offered radioactive material type A package special form, 7 and failed to maintain complete documentation of tests and an engineering evaluation or comparative data on file of the Type A package used for transport. [173.415(a)] Ticket No: 10T-0350-RMS-SI	\$ 1,400
Buffalo Creek Explosives, Inc. Garrett PA (Shipper Inspection)	Offered articles, explosive, n.o.s., 1.4S, accompanied by a shipping paper that failed to enter the technical name for the hazardous material in parenthesis; offered ammonium nitrate -fuel oil mixture, 1.5D, accompanied by a shipping paper that failed to include in parenthesis	\$ 1,500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Explosive))	"(containing only prilled ammonium nitrate and fuel oil)" for the material; offered various hazardous materials accompanied by multiple shipping papers that failed (1) to list the proper shipping name and UN identification number for the material; (2) indicate the number of packages used, (3) to enter the technical name for the hazardous material in parenthesis and (4) to include in the parenthesis (containing only prilled ammonium nitrate and fuel oil) for the material; offered explosives and explosive devices, accompanied by a shipping paper that failed to indicate the number of packages used to protect and confine the hazardous materials during transportation. [172.101 - Table; DOT SP 11156 - Section 6; 173.22(a)(1); 172.202(a)(1), (2), and (7); 173.22(a)(1); 173.203(k)] Ticket No: 10T-0383-SE-SI	
Truck-Rail Handling, Inc. Tacoma WA (Shipper)	Offered combustible liquid, n.o.s. (xylene, petroleum distillates), 3, and failed to include the name of the hazardous substance and the letters "RQ" in the shipping description and to include the technical and/or chemical name in parenthesis for a listed generic or "n.o.s." material; offered combustible liquid, n.o.s. (xylene, petroleum distillates), 3, accompanied by a shipping paper that failed to list an authorized emergency response telephone number. [172.201(d); 172.604(b); 172.200(a); 172.203(c)(1) and (2); 172.203(k)] Ticket No: 10T-0380-SCT-WE	\$ 1,440
Chemical Specialties, LLC Memphis TN (Shipper)	Offered sodium hydroxide solution, 8, and hydrogen peroxide, aqueous solutions, 5.1, accompanied by shipping papers that had two or more elements of the shipping description that were incorrect; offered sodium hydroxide solution, 8, and hydrogen peroxide, aqueous solutions, 5.1, in a packaging that has been successfully tested to an applicable UN standard but failed to mark the packaging with the appropriate UN markings. [173.202; 178.3(a); 178.503(a); 172.200(a); 172.202(a)(1)-(4)] C Ticket No: 10T-0322-SB-SO	\$ 2,790
Nonweiler, A.P., Company, Inc. Oshkosh WI (Shipment Observation (General))	Offered paint, 3, and failed to mark the proper shipping name and UN identification number on the UN package. [172.301(a)(1)] Ticket No: 10T-0339-SP-SO	\$ 1,200
Colonial Bag Company Lake Park GA	Manufactured, marked and sold UN packagings when the Performance Oriented Package Testing Certification Report showed that the package had been tested at one	\$ 240

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Shipment Observation (General))	weight and marked at a higher gross weight. [178.503(a)(4)(ii)] Ticket No: 10T-0382-SBG-SI	
Tama-Benton Cooperative Dysart IA (Special Permit Renewal)	Offered anhydrous ammonia in non-DOT specification cargo tanks without the required ASME identification plates after their authority under DOT-SP 13554 had expired. [173.315(m)(1)] Ticket No: 10T-0335-ESF-SI	\$ 500
MAINTENANCE CHEMICAL, INC. BROCKTON MA (Other Priority Investigation Type)	Offered methanol, 3, and others, and failed to provide hazardous materials shipping papers. Failed to provide initial general awareness, function-specific, safety, and security awareness training. [172.200; 172.202; 172.702(a); 172.704(a)(1)-(4); 172.704(c)(1)] Ticket No: 10T-0373-SD-SO	\$ 1,920
Fire Safety Industries Albuquerque NM (Cylinder Retester)	Conducted hydrostatic retests and visual inspections under an expired requalification identification number (RIN). [180.3.;180.205(b)] Ticket No: 10T-0367-CR-SW	\$ 750
Qal Tek Associates LLC Idaho Falls ID (Shipper Inspection (Ram))	Offered radioactive materials, type "A" package, special form, 7, and failed to maintain DOT Specification 7A packaging documentation of tests on file; offered radioactive materials, type "A" package, special form, 7, accompanied by a shipping paper that listed an unauthorized emergency response telephone number. [172.604(a)(2); 173.415(a)] Ticket No: 10T-0346-RMS-SI	\$ 1,920
Spiderworks Fireworks, Inc. East Mishawaka IN (Shipper Inspection (Explosive))	Failed to provide general awareness, function-specific, safety training and security awareness training; transported fireworks, 1.4G, without a proper shipping paper for a shipment of hazardous materials that included the proper shipping name, hazard class, identification number, packing group of the material and to include a valid emergency response telephone number; failed to register with PHMSA. [172.202(a)(1)-(5); 172.604(b); 172.702(a); 172.704(a)(1)-(4); 172.704(c); 107.608(a) and (b)] Ticket No: 10T-0024-SE-CE	\$ 4,864.62
ProClean Inc. Phoenix AZ (Shipper)	Offered corrosive liquid, basic, inorganic, n.o.s. (sodium hydroxide), 8, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification. [173.22 (a)(4); 173.24 (f)(2); 173.203(a)] Ticket No: 10T-0378-SB-WE	\$ 1,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

<p>AMTI Sunbelt LLP Henderson NV (Accident/Failure Investigation)</p>	<p>Offered radioactive material type A package, special form, 7 and failed to properly block and brace the hazardous material and secure it from shifting during normal transportation; failed to provide initial general awareness, function-specific, safety, and security awareness training; offered radioactive material type A package, special form, 7 and provided an unauthorized emergency response telephone number; offered radioactive material type A package, special form, 7, and failed to retain records of shipment of the material; offered radioactive material type A package, special form, 7, and failed to provide the proper shipping name and UN ID number for the material on the shipping paper; offered radioactive material type A package, special form, 7 and failed to list the activity in the proper SI units. [172.704(a)(1)-(4); 172.702(a); 172.201(e); 172.202(a); 172.203(d)(3); 172.604(a)(1); 177.834(a); 177.842(d)] Ticket No: 10T-0361-RMS-SI</p>	<p>\$ 2,920</p>
<p>Reynolds Interstate Car Care, Inc. Amarillo TX (Visual Requalifier Inspection)</p>	<p>Failed to maintain information contained in each CGA pamphlet applicable to the requalifier's activities; failed to maintain complete and accurate records of visual cylinder requalification. [180.209(g); 180.215(a)(6)] Ticket No: 10T-0370-CR-SW</p>	<p>\$ 500</p>
<p>Griffin Fire and Safety, Inc. Hyde Park MA (Cylinder Retester)</p>	<p>Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; failed to maintain complete and accurate records of cylinder requalification; failed to maintain hazardous materials training records; failed to maintain test pressure for at least 30 seconds during cylinder requalification. [180.215(b)(2); 180.205(g)(3)(i); 172.704(d); 180.205(g)(5)] Ticket No: 08T-0362-CR-EA</p>	<p>\$ 4,081.52</p>
<p>Tech Spray, LLC Amarillo TX (Aerosol Filler/Shipper)</p>	<p>Offered isopropanol, 3, and failed to place the correct size label on the package of hazardous materials; failed to provide general awareness, function-specific, safety, and security awareness training. [172.702(b); 172.704(a)(1)-(4); 172.407(c)(1)] Ticket No: 10T-0374-SBC-SW</p>	<p>\$ 860</p>
<p>United Nuclear Laingsburg MI (Shipper)</p>	<p>Offered potassium perchlorate, 5.1, and failed to provide and retain shipping papers; failed to provide general awareness, function-specific, safety and security awareness training. [172.702(a); 172.704(a)(1)-(4); 172.704(d); 172.200(a) and (b); 172.201(e)] Ticket No: 10T-0354-RMS-SI</p>	<p>\$ 1,920</p>

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Crest Industrial Chemicals, Inc. Rosharon TX (Shipper)	Represented and certified UN standard intermediate bulk containers (IBCs) and failed to mark retested IBCs with the test dates; offered corrosive liquid, basic, organic, n.o.s. (contains methylene chloride and phenol, 8, in UN-certified 55-gallon closed-head plastic drums and 5-gallon plastic jerricans that were not closed in accordance with the manufacturer's closure notification; represented and certified UN standard intermediate bulk containers (IBCs) when records of periodic retests and inspections failed to record all the required information; failed to provide initial general awareness, function-specific, security awareness training and to provide recurrent training. [173.22(a)(4); 173.24(f)(2); 180.352(g); 178.703(b); 180.352(f); 172.702(b); 172.704(a)(1)-(5); 172.704(c)(1) and (2)] Ticket No: 10T-0366-SDIBC-SW	\$ 2,090
Jax Integrity Group Parma MI (Accident/Failure Investigation)	Offered radioactive material, type A package, special form, and failed to maintain a file of complete documentation of test and engineering evaluation for a DOT Specification 7A Type A Package; offered radioactive material, type B(U)package, special form, 7, accompanied by shipping papers that failed to have the proper shipping name and UN ID number; offered radioactive material, type B(U) package, 7, and failed to label the package with the hazardous warning labels; offered radioactive material, type B(U) package, 7, and failed to legibly and durably mark the outside of the package with the UN ID number, package type and proper shipping name; offered radioactive material, type B(U) Package, 7, and failed to list the transport index assigned to each package in the shipment; offered radioactive material, type B(U) package, 7, and failed to report within 12 hours to the National Response Center a Hazardous Materials incident with fire involving a radioactive material. [171.15(a) and (b)(2); 172.202(a)(1) and (2); 173.415(a); 172.203(d)(5); 172.400(a); 172.310(b); 172.301(a)(1); 172.304(a)(1) and (2)] Ticket No: 10T-0362-RMS-SI	\$ 6,280
Quality Carriers (747) Tampa FL (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0126-HMI-EA	\$ 500
CHS Transportation Grand Forks ND (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0332-HMI-SI	\$ 500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Sutter Buttes Fire Extinguisher Company Yuba City CA (Cylinder Retester)	Failed to calibrate test equipment at a pressure within 500 psig of actual test pressure at or above 3000 psig; failed to provide general awareness, function-specific training and security awareness training; failed to maintain complete and accurate records of cylinder and visual requalification. [180.205(g)(3)(i);172.702(b); 172.704(a)(1)-(4); 180.215(b)(2)] Ticket No: 10T-0313-CR-WE	\$ 1,780
Wildcat Wireline Marshall TX (Shipper Inspection (Ram))	Offered radioactive material type A package, special form, 7" and failed to enter the contents and activity on the radioactive Yellow III labels. [172.403(g)(1) and (2)] Ticket No: 10T-0348-RMS-SI	\$ 800
Hale Fireworks, LLC Buffalo MO (Shipper Inspection (Explosive))	Offerd fireworks, 1.4G, accompanied by a shipping paper that failed to contain a signed shipper's certification; failed to register with PHMSA. [107.608(a) and (b);172.204(a)] Ticket No: 10T-0341-SE-SO	\$ 720
SACHS CHEMICAL, INC. CAGUAS PR (Shipper)	Offered flammable liquids, n.o.s. (dialkyl ester of triethanol ammonium methyl sulphate), 3, in an unauthorized non-UN standard packaging, when specification packaging is prescribed; offered toluene, 3, in UN-certified 55 gallon closed-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(2); 173.24(c); 173.203(c); 173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0131-SD-SO	\$ 300
Dayton Superior Corporation Sumner WA (Shipper)	Offered petroleum distillates, n.o.s., accompanied by a shipping paper that failed to (1) indicate applicable units of measurement for the total quantity, (2) the number of packages, and include a shipper's certification; offered petroleum distillates, n.o.s., 3, accompanied by a shipping paper that failed to provide (1) the proper shipping name, (2) hazard class, (3) identification number, and (4) packing group for the material. [172.200(a); 172.202(a)(1)-(4); 172.200(a); 172.202(a)(5) and (7); 172.204(a)] Ticket No: 10T-0394-SD-WE	\$ 1,450
HI-TECH Testing Service Incorporated Longview TX (Shipper Inspection (Ram))	Offered radioactive material type B(U) package, 7, and failed to label radioactive material with the required Radioactive Yellow II label; offered radioactive material type B(U) package, 7, and failed to enter the contents, activity and transport index on the required Radioactive Yellow II label; offered radioactive material type B(U) package, 7, accompanied by shipping papers that failed	\$ 3,450

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	to list the transport index; offered radioactive material type B(U) package, 7, and failed to mark the letters “RQ” on the package to indicate the hazardous substance. [172.403(b); 173.403(g)(1)-(3); 172.324(b); 172.203(d)(5)] Ticket No: 10T-0355-RMS-SI	
GEC Gulf Engineers & Consultants Baton Rouge LA (Shipper Inspection (Ram))	Failed to enter contents, activity and transport index on a Radioactive Yellow II label; failed to provide general awareness, function-specific, safety, and security awareness training; failed to provide a shipping paper for a shipment of Hazardous materials; failed to maintain emergency response information as a carrier and facility operator for class 7 radioactive material. [172.702(a); 172.704(a)(1)-(4); 172.200; 172.403(g)(1)-(3); 172.603(c)(1) and (2)] Ticket No: 10T-0391-RMS-SI	\$ 3,760
Integrity Inspections Solutions, Inc Lafayette LA (Shipper Inspection (Ram))	Failed to list contents, activity and transport index on radioactive yellow III label; failure to register with PHMSA; offered radioactive materials and failed to retain copies of hazardous materials shipping papers for a minimum of two years; offered radioactive materials accompanied by a shipping paper that provided an unauthorized emergency response telephone number; failed to provide general awareness, security awareness and in-depth security training; failed to properly list the Transport Index in the shipping description on the shipping paper; offered radioactive material accompanied by a shipping paper that failed to use the proper shipping name for the material. [107.608(a) and (b); 172.201(e); 172.202(a)(2); 172.203(d)(5); 172.604(b); 172.704(a)(1), (4), and (5); 172.403(g)(1)-(3)] Ticket No: 10T-0344-RMS-SI	\$ 2,840
Maxam North America, Inc Hernshaw WV (Fitness Inspection)	Offered explosive, blasting, type B, 1.5D, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers. [172.203(a); 173.22(a)(1); 172.203(a); 173.22(a)(1)] Ticket No: 10T-0384-SE-SI	\$ 400
Precision Metal Industries, Inc. Pompano Beach FL (Metal J-Can Manufacturer)	Failed to provide initial general awareness, function-specific, and security awareness training; failed to register with PHMSA. [107.608(a) and (b); 172.702(a); 172.704(a)(1), (2) and (4); 172.704(c)(1)] Ticket No: 10T-0369-PM-SO	\$ 1,640
Speciality Pharmacy Services Temple TX (Shipper)	Transported radioactive material that have not been properly blocked and braced and secured against movement in normal transportation; offered a DOT specification 7A packaging without maintaining complete documentation of tests and an engineering	\$ 4,250

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Inspection (Ram))	evaluation or comparative data; offered radioactive material type A package, 7, and marked the package with an incorrect proper shipping name and UN identification number for the material. [173.415(a); 177.834(a); 177.842(d); 172.301(a)] Ticket No: 10T-0386-RMS-SI	
ARK LA TEX Wireline Services LLC Shreveport LA (Shipper Inspection (Ram))	Offered a DOT specification 7A packaging without maintaining complete documentation of tests; failed to maintain hazardous materials training records; failed to mark the list contents, activity and transport index on label for class 7 radioactive material; failed to durably mark a Type “A” package legibly with “TYPE A”, and the UN identification number and proper shipping name for the material; failed to replace damaged hazardous warning labels from the class 7 radioactive packages; failed to list the correct proper shipping name and UN number on shipping paper for class 7 radioactive material; offered special form material without maintaining a complete safety analysis of certificate of competent authority. [172.704(d); 172.407(a); 172.403(g); 172.310(b); 172.202(a)(1) and (2); 173.476; 173.415] Ticket No: 10T-0325-RMS-SI	\$ 5,395
Everite Machine Products Co., Inc. Philadelphia PA (Shipper)	Offered oxidizing solid, toxic, n.o.s., (sodium nitrate/sodium nitrite), 5.1 (6.1), in UN-certified combination packages that were not closed in accordance with the package manufacturer’s notification; failed to register with PHMSA. [173.22(a)(4); 173.24(f)(2); 107.608(a) and (b)] Ticket No: 10T-0311-SB-EA	\$ 1,440
Zep, Inc. Kent WA (Shipper)	Offered corrosive liquid, basic, inorganic, n.o.s. (sodium hydroxide), 8, in UN-certified combination packages that were not closed in accordance with the package manufacturer’s notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0381-SPT-WE	\$ 1,000
Layne, A. G. Los Angeles CA (Shipper)	Offered acetone, 3, in UN-certified combination packages that were not closed in accordance with the package manufacturer’s notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0405-SBD-WE	\$ 1,000
Safety Fire Extinguishers Muskogee OK (Cylinder Retester)	Failed to condemn cylinders consistent with the requirements of the regulations by stamping X’s over the specification marking, stamping “condemned” onto the cylinder, or rendering the cylinder incapable of holding pressure; failed to maintain complete and accurate records of cylinder requalification; failed to maintain copies of the applicable sections of the regulations at its retest facility and information	\$ 13,665

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	<p>contained in each CGA pamphlet applicable to the re-qualifier's activities; failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values; filled and offered a cylinder marked with manufacture date of March, 1989 with compressed gas, when the cylinder is overdue for its 12 year periodic requalification requirement; conducted hydrostatic retests and visual inspections without holding a current requalification identification number (RIN), and failed to report in writing to the Associate Administrator changes in management and testing personnel.</p> <p>[180.215(a)(1); 107.805(g); 180.205(b); 180.205(g)(3); 173.301(a)(6); 180.215(b)(1) and (2); 180.205(i)(2)(i); 180.215(a)(4) and (6)] Case No: 09-0154-CR-SW</p>	
<p>Hasse Enterprises dba Safequip Austin TX (Cylinder Retester)</p>	<p>Represented, marked, and certified DOT Special Permit cylinders as having been successfully re-qualified instead of condemning the cylinder when the hydrostatic retest results showed that the permanent expansion of the cylinder exceeded five percent of the total expansion. [180.205(i)(1)(vii)] Case No: 09-0017-CR-SW</p>	\$ 2,000
<p>Industrial Container Services-KY, LLC Louisville KY (Shipment Observation (General))</p>	<p>Remanufactured, marked, certified, sold, and offered open head steel drums as safe for the transportation of hazardous materials when the drums were damaged or defective; represented, remanufactured, marked and offered UN standard 55-gallon steel drums when the Drop and Stack Tests were not conducted properly; represented, remanufactured, marked and offered UN standard 55-gallon steel drums when the Stacking Test was not conducted properly; represented, remanufactured, marked and offered steel drums when the test reports were inaccurately prepared and maintained; represented, remanufactured, marked, and offered open head steel drums, when the design qualification tests were not conducted and did not maintain design qualification test records; failed to notify persons to whom the packaging is transferred of all the requirements not met at the time of transfer, including closure instructions needed to satisfy and maintain performance test requirements. [173.28(d); 178.504(b)(3); 173.28(d); 178.2(b)(1) and (2); 178.601(d) and (l); 173.28(d); 178.2 (b)(1) and (2); 178.601(f); 178.603(a); 173.28(d); 178.2(b)(1) and (2); 178.601(f); 178.606(b) and (c)(1); 178.601(l); 178.2(c)] Case No: 08-0089-DR-SO</p>	\$ 15,675

## PHMSA Notice of Hazardous Materials Regulations Enforcement

<p>Maurer &amp; Scott Sales, Inc. Tamaqua PA (Shipper Inspection (Explosive))</p>	<p>Offered explosive, blasting, type E, 1.5D, ammonium nitrate based fertilizer, 5.1, booster, 1.1D, and combustible liquid, n.o.s., NA1993, and transported materials that are not authorized to be loaded, transported or stored together in the same transport vehicle; offered explosive, blasting, type E, 1.5D, in a tank affixed to a Specialized Bulk Explosive Vehicle, operating under DOT-SP 8554, and failed to mark the special permit number on the truck. [173.22a (a) and (b); 173.62(a); DOT-SP 8554; DOT-SP 8723; 172.301(c)] Case No: 10-0015-SE-EA</p>	<p>\$ 5,000</p>
<p>Lee Oil Company, Inc. Alvin TX (Shipper)</p>	<p>Offered gasoline, 3, UN1203, in UN-certified 55-gallon closed-head steel drums that were not closed in accordance with the manufacturer's closure notification; offered gasoline, 3, without shipping papers, package markings, and labels, thereby creating undeclared shipments of hazardous materials; offered hazardous materials, accompanied by shipping papers that (1) listed non-working emergency response telephone numbers, (2) used shipping descriptions that included additional unauthorized information before the proper shipping description, and (3) failed to list the number and type of packages; accepted and transported gasoline, 3, and failed to properly placard the transport vehicle; failed to provide general awareness, function-specific training, safety training, security awareness training, and in-depth security training; accepted and transported gasoline, 3, and failed to have a shipping paper accompany the material that describes the hazardous material. [177.817(a); 172.500(a); 172.504(a); 177.823(a); 173.22(a)(4); 173.24(f)(2); 172.704(a)(1)-(5); 172.800(a); 172.802(a) and (b); 172.200; 172.300; 172.400; 172.604(a); 172.201(a)(4); 172.202(b); 172.202(a)(7)] Case No: 09-0153-SD-SW</p>	<p>\$ 15,800</p>
<p>Ace Polar Technology, Inc. Purto Nuevo PR (Cylinder Retester)</p>	<p>Offered chlorodifluoromethane, 2.2, among others, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; failed to maintain complete and accurate records of cylinder requalification; failed to provide general awareness, function-specific, safety, and security awareness training; offered a hazardous material, accompanied by a shipping paper, that failed to (1) include a correct proper shipping name and hazard class in the required sequence, and (2) did not include units of measurement for weight. [172.702(b); 172.704(a)(1)-(4); 172.201(d); 172.604(b); 172.200(a); 172.202(a) and</p>	<p>\$ 2,040</p>

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	(b); 180.215(b)(2)] Ticket No: 10T-0379-CR-WE	
Wood Rodgers Reno NV (Shipper Inspection (Ram))	Offered radioactive materials, 7, accompanied by a shipping paper that used an incorrect proper shipping name for the material; failed to provide initial and recurrent general awareness, function-specific, safety, and security awareness training; failed to include "RQ" before or after the basic shipping description to identify a material that is a hazardous substance; offered radioactive material, 7, accompanied by a shipping paper that failed to identify an emergency response telephone number; offered radioactive materials, 7, and failed to label a package with the hazard warning label. [172.704(c)(1) and (2); 172.702(b); 172.704(a)(1)-(4); 172.202(a); 172.203(c)(2); 172.604(a)(3); 172.400(a)] Ticket No: 10T-0392-RMS-SI	\$ 3,160
Coastal Fumigators Houston TX (Toxic Inhalation Hazard Shipper)	Offered sulfuryl fluoride, 2.3, and chloropicrin, 6.1, accompanied by a shipping paper that contained an unauthorized emergency response telephone number. [172.604(b)] Ticket No: 10T-0465-SC-SO	\$ 1,040
Pikus Transport, Inc. Sauk Rapids MN (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0457-HMI-SI	\$ 500
Ross Fogg Jr and Sons Oil Company Salem NJ (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0432-HMI-SI	\$ 500
Barfield, Inc. Miami FL (Cylinder Retester)	Offered oxygen, compressed, 2.2, 5.1, under the provisions of DOT-SP 8162 and failed to mark the packaging as required and provide a copy of DOT-SP 8162 to the carrier before or at the time of shipment; offered oxygen, compressed, 2.2, 5.1, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; failed to register with PHMSA. [107.608(a) and (b); 173.22a(b) and (c); DOT-SP 8162 Section 7.c. (5); DOT-SP 8162 Section 8.b. and Section 10; 172.200(a); 172.203(a)] Ticket No: 10T-0400-REG-SO	\$ 1,040
Steris Corporation Isomedix Services Chester NY	Offered radioactive material, 7, in a foreign-made Type B(U) package and failed to fulfill to all requirements of the foreign competent authority certificate and the U.S. Competent Authority revalidation: offered radioactive material, 7, in a foreign-made Type B(U) package and	\$ 2,320

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Shipper Inspection (Ram))	failed to register in writing with the U.S. Competent Authority as a user of the package; failed to provide initial general awareness, function-specific, safety, security awareness training. [173.473(a)(2); 172.702(a); 172.704(a)(1)-(4); 173.473(d)] Ticket No: 10T-0426-RMS-SI	
Reliance Testing & Inspection Idaho Falls ID (Shipper Inspection (Ram))	Failed to provide general awareness, function-specific, safety, and security training; offered radioactive material, type A package, special form, RQ, accompanied by shipping papers that failed to contain the proper shipping name and UN identification number for the material; offered radioactive materials, type "A" package, special form, 7, RQ, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; offered radioactive material, type A packaging, special form, 7, RQ, and failed to the mark the proper shipping name, identification number, "RQ" and Type "A" on the package; offered radioactive material, type A package, special form, 7, RQ, and failed to retain a record of each shipment made; offered radioactive materials, type "A" package, special form, 7, RQ and failed to maintain DOT Specification 7A packaging documentation of tests on file; offered radioactive material, type A packaging, special form, 7, RQ, with damaged labels affixed to the package and failed to mark the package label with the required additional entries. [172.702(a); 172.704(a) (1)-(4); 172.201(e); 177.817(f); 172.202(a)(1) and (2); 173.415(a); 172.604(b); 172.400; 172.403(g); 172.407(a); 172.301(a); 172.310(b); 172.324(b)] Ticket No: 10T-0324-RMS-SI	\$ 5,600
Kleinfelder Albuquerque NM (Shipper Inspection (Ram))	Offered radioactive materials, 7, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b); 172.201(d)] Ticket No: 10T-0422-RMS-SI	\$ 1,040
J A Cesare and Associates, Inc Henderson NV (Shipper Inspection (Ram))	Offered radioactive material type A package, special form, 7, and failed to label the package with the required radioactive Yellow II label to include contents, activity and transport index; offered radioactive material type A package, special form, 7, and failed to mark the package with the proper shipping name , UN identification number, Type "A" packaging and "RQ"; offered radioactive material type A package special form, 7, and listed an incorrect proper shipping name for the material; offered radioactive material type A package	\$ 3,720

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	special form, 7, and failed to monitor the emergency response telephone number listed on the shipping paper while the hazardous material is in transportation; failed to maintain a record of testing of hazmat employees for required training. [172.301(a)(1); 172.310; 172.324; 172.202(a)(2); 172.400(a); 172.403(b) and (g)(1)-(3); 172.704(d)(5); 172.604(a)(1)] Ticket No: 10T-0360-RMS-SI	
Champion Technologies Houston TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0447-HMI-SI	\$ 500
La Rue Lamb Trucking Inc. Myton UT (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0430-HMI-SI	\$ 500
Servi-Tech, Inc. Amarillo TX (Shipper)	Failed to register with PHMSA; failed to provide general awareness, function-specific, safety, and security awareness training. [107.608(a) and (b); 172.702(a); 172.704(a)(1)-(4)] Ticket No: 10T-0375-SD-SW	\$ 1,075
LANNING CHEMICAL COMPANY INC LOUISVILLE KY (Shipper)	Offered paint related material, 3, and others, in unauthorized 275-gallon poly intermediate bulk containers; failed to create and retain current records of hazardous materials training; offered corrosive liquids, n.o.s. (contains malic acid), 8, and others, in unauthorized, non-reconditioned UN standard packaging. [173.22(a)(2); 173.35; 173.242; 173.28(a),(b) and (c); 173.22(a)(2); 173.24; 172.702(b); 172.704(d)] Ticket No: 10T-0113-SIBC-SO	\$ 3,740
Airtech Gases Medical Products Las Vegas NV (Shipper)	Offered nitrous oxide, 2.2 (5.1), and oxygen, compressed, 2.2 (5.1), accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b)] Ticket No: 10T-0409-SC-WE	\$ 1,040
Norchem Corporation Los Angeles CA (Shipper)	Offered corrosive liquids, 8, and others, accompanied by shipping papers that failed to provide (1) the proper shipping name for the material, and (2) the proper packing group, no technical name and package type for another hazardous material. [172.200(a); 172.202(a)(2), (4) and (7)(d); 172.203(k)] Ticket No: 10T-0404-SBD-WE	\$ 1,200
Harvard Chemical Research, Inc Atlanta GA	Offered sodium hypochlorite, 8, that failed to mark the package with the the UN identification number for the material. [172.301(a)(1)] Ticket No: 10T-0417-SD-SO	\$ 660

## PHMSA Notice of Hazardous Materials Regulations Enforcement

(Shipment Observation (General))		
Lansing Trade Group Overland Park KS (Other Priority Investigation Type)	Failed to provide general awareness, function-specific, safety and security awareness training. [172.704(a)(1)-(4); 172.702(a); 172.704(c)(1)] Ticket No: 10T-0038-SC-CE	\$ 987.13
Triple Image Cosmetics Los Angeles CA (Shipper)	Offered acetone, 3, accompanied by shipping papers which included unauthorized information interspersed in the basic shipping description: failed to provide recurrent general awareness, function-specific, safety and security awareness training; offered acetone, 3, and others, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification; failed to register with PHMSA. [173.22(a)(4); 173.24(f)(2); 107.608(a) and (b); 172.201(a)(4); 172.202(b); 172.702(b); 172.704(a)(1)-(4); 172.704(c)(2)] Ticket No: 10T-0410-SB-WE	\$ 2,440
W. M. Barr & Company, Inc. Memphis TN (Shipper)	Filled and offered DOT 57 portable tanks with paint related material, 3, when the periodic inspections were past due; offered sodium hydroxide solution, 8, and hydrogen peroxide, aqueous solutions, 5.1, and failed to mark the packaging with the appropriate UN marking. [173.32(a)(2); 180.605(a) and (c)(3); 173.202; 178.3(a); 178.503(a)] Ticket No: 10T-0343-SPT-SO	\$ 2,840
HVJ Associates El Paso TX (Shipper Inspection (Ram))	Offered a DOT specification 7A packaging without maintaining complete documentation of tests and an engineering evaluation or comparative data; failed to provide recurrent general awareness, function-specific, safety and security awareness training; offered special form radioactive materials without maintaining a complete safety analysis or Certificate of Competent Authority. [172.702; 172.704(c)(2); 173.476(a); 173.415(a)] Ticket No: 10T-0365-RMS-SI	\$ 3,120
Cemex El Paso TX (Shipper Inspection (Ram))	Offered radioactive material Type A package, special form, 7, and failed to maintain on file a complete safety analysis, including documentation of any tests, demonstrating that the special form material meets the requirements of special form, or an International Atomic Energy Agency (IAEA) Certificate of Competent Authority issued for the special form material; offered radioactive material, Type A packaging, special form, 7, and failed to list the activity contained in each package	\$ 4,200

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	of radioactive material in terms of the appropriate SI units; offered for transportation in commerce “RQ, UN3332 Radioactive material, Type A package, special form, 7” in a package that failed to be securely closed by a positive fastening device; offered gas oil, combustible liquid, and radioactive material, Type A package, special form, 7” and failed to maintain a record of each shipment made. [172.200(a); 173.150(f)(3); 172.201(a), (d) and (e); 173.476(a); 172.202(a)(2) and (7); 172.203(d)(3); 173.410(a) and (f); 173.412(d)] Ticket No: 10T-0377-RMS-WE	
Neil's Controlled Blasting, L.P. Newcastle CA (Shipper Inspection (Explosive))	Failed to provide initial and recurrent in-depth security training; offered explosives, 1.1D and 1.4S and detonators, 1.4B, that failed to include the packing group for the material; offered cord, detonating, flexible, 1.1D, and articles, explosive, n.o.s. (contains HMX & aluminum powder), 1.4S, accompanied by a shipping paper that failed to indicate the type of package of the explosives; failed to provide initial and recurrent general awareness, function-specific and security awareness training; offered explosives, 1.1D and 1.4S and detonators, 1.4B, accompanied by a shipping paper that failed to indicate the Net Explosive Mass (NEM) and the applicable unit of measurement for explosive materials; offered explosives, 1.1D and 1.4S and detonators, 1.4B, accompanied by shipping papers that included unauthorized additional information interspersed within the basic description. [172.702(a); 172.704(a)(1)-(4); 172.704(c)(2) and (d); 172.704(a)(5), (c)(2) and (d); 172.800(b)(2); 172.202(a)(5)(i); 173.22(a)(1); 172.202(a)(7); 173.22(a)(1); 173.22(a)(1); 172.202(a)(4); 172.101 Table; 173.22(a)(1)] Ticket No: 10T-0427-SE-SI	\$ 1,445
Mayco Industries, Inc. Birmingham AL (Shipper)	Failed to provide general awareness, function-specific and security awareness training; offered environmentally hazardous substance, solid, nos (lead dross), 9, accompanied by a shipping paper that (1) contained additional information preceding the shipping description, (2) failed to list the packing group and type of package, (3) failed to sign the shipper's certification statement; offered environmentally hazardous substance, solid, n.o.s.(lead dross), 9, and failed to mark the package with the proper shipping name and UN identification number; offered environmentally hazardous substance, solid, nos (lead dross), 9, accompanied by a shipping paper that provided an	\$ 3,900

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	<p>unauthorized emergency response telephone number. [172.301(a)(1); 172.604(b); 172.200(a); 172.201(a)(4); 172.202(a)(4) and (7); 172.204(d); 172.702(a); 172.704(a)(1), (2) and (4)] Ticket No: 10T-0411-SD-SO</p>	
<p>Cygnat Automated Cleaning, Inc. Plymouth MI (Recertifier/Retester/Repairer (Tanks, IBCs))</p>	<p>Records of periodic retests and inspections failed to include the name and address of the test and inspection facility, the name of person performing the tests, and the results of all inspections and tests; failed to provide initial function-specific, safety, and security awareness training and recurrent general awareness training; offered waste paint related material, 3, accompanied by a shipping paper that failed to indicate an emergency response telephone number; failed to register with PHMSA. [180.352(g); 180.605(l); 172.201(d); 172.604(b); 172.704(a)(2)-(4); 172.704(c)(2); 172.702(b); 107.608(a) and (b)] Ticket No: 10T-0395-IBCR-WE</p>	\$ 3160
<p>Robinette Trucking Mount Pleasant TN (HMI Ticket)</p>	<p>Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0453-HMI-SI</p>	\$ 500
<p>Eagle Transport Rocky Mountain NC (HMI Ticket)</p>	<p>Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0464-HMI-SI</p>	\$ 500
<p>Hi-Noon Petroleum Missoula MT (HMI Ticket)</p>	<p>Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0439-HMI-SI</p>	\$ 500
<p>Headwaters Trucking Amarillo TX (HMI Ticket)</p>	<p>Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0441-HMI-SI</p>	\$ 500
<p>Turner Specialty Services, LLC Baton Rouge LA (Shipper Inspection (Ram))</p>	<p>Offered radioactive material, type B(U) package, 7, in packages that failed to have the listed contents activity and transport index on the labels; failed to provide security awareness training. [172.400(a); 172.403(b), (g)(1)-(3); 172.702(a); 172.704(a)(4)] Ticket No: 10T-0388-RMS-SI</p>	\$ 2,450
<p>Peach State Labs, Inc Columbus GA (Shipper)</p>	<p>Offered phosphoric acid solution, 8, in UN-certified 55 gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0419-SIBC-SO</p>	\$ 1,000

## PHMSA Notice of Hazardous Materials Regulations Enforcement

C&C Ventures dba Randolph Products Chicopee MA (Shipper)	Failed to provide recurrent hazardous materials training; offered paint related material, 3, in UN-certified 55-gallon closed-head steel drums containers that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2); 172.702(a); 172.704(c)(2)] Ticket No: 10T-0396-SD-EA	\$ 1,595
ARCH WOOD PROTECTION, INC. CONLEY GA (Shipper)	Offered corrosive liquid, toxic, n.o.s. (arsenic acid, chromic acid), 8,6.1, in UN-certified 55-gallon closed-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0338-SD-SO	\$ 1,000
United States Plastic Corporation Lima OH (Shipment Observation (General))	Failed to notify in writing each person to whom a packaging is transferred, of all requirements not met at the time of transfer that are needed to satisfy performance test requirements, and maintain records thereof. [178.2(c)] Ticket No: 10T-0406-PDM-SW	\$ 935
Maverick Country Stores, Inc. North Salt Lake UT (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0462-HMI-SI	\$ 500
BrownLee Farm Center, Inc. Tifton GA (Shipper)	Offered anhydrous ammonia, 2.2, in excess of 1000 pounds and failed to placard the cargo tank on all four sides and contained faded placards on the cargo tank; failed to provide initial general awareness, function-specific, safety, and security awareness training; offered anhydrous ammonia, 2.2, in unauthorized non-DOT specification cargo tanks, when the tanks do not conform to the ASME Code in that the data plate is illegible and therefore not in conformance with the requirements in the Hazardous Materials Regulations. [173.315(m)(1); Section VIII of the ASME Code; 172.504(a); 173.22(a); 172.702(a); 172.704(c)(1); 172.704(a)(1-4)] Case No: 09-0014-SPT-SO	\$ 3,000
Patterson, A. L., Inc. Fairless Hills PA (Shipper)	Offered amines, liquid, corrosive, n.o.s. (aminopropyldiethanolamine), 8, and failed to declare, mark or label the hazardous material, therefore shipping an undeclared hazardous material; offered various hazardous materials and failed to (1) maintain copies of shipping papers, (2) to include a unit of measure in association with the weight on the shipping paper, and (3) to include a 24 hour emergency response telephone number on the shipping paper. [173.154(c); 172.316(a);	\$ 6,860

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	172.200(a); 172.201(e); 172.202(a)(5); 172.604(b)] Case No: 09-0212-SB-EA	
Refinery Specialties, Inc. Hempstead TX (Shipper)	Offered and transported flammable liquids, n.o.s., 3, in an unauthorized non-UN standard packaging, when specification packaging is prescribed; transported hazardous materials, accompanied by shipping papers that failed to (1) indicate the special permit on the shipping papers, and (2) indicated a hazardous material as a hazardous substance on a shipping paper with the notation "RQ" when it is not a reportable quantity; offered corrosive liquid, n.o.s. in MC 312 and DOT 412 cargo tanks that was overdue the prescribed periodic retest; failed to remove bulk containers from the motor vehicle prior to discharging the contents of the containers; offered hazardous materials in a UN standard marked and certified packaging that had not been closed in accordance with the manufacturer's closure instructions. [173.22(a)(2); 173.24(c); 173.33(a)(3); 180.407(a) and (c); 177.834(h); 173.22(a)(4); 173.24(f)(2); 172.203(a) and (c)(2)] Case No: 09-0200-CCT-SW	\$ 15,585
Berenfield Container, Corp Mason OH (Steel Drum Manufacturer)	Failed to notify customers, in writing, of all requirements needed to satisfy performance test requirements not met at the time of transfer; represented, remanufactured, marked and offered steel drums when the test reports were not created, prepared and maintained as required. Represented, marked, certified, sold and offered fifty-five gallon steel drums when the production leakproofness test was not properly conducted; failed to provide recurrent training. [172.702(a); 172.704(c)(2); 172.704(d); 178.604(a), (b) and (d); Appendix B to Part 178; 178.601(a), (g), and (l); 178.2(a) and (b); 173.22(a)(4); 173.24(f)(2); 178.2(c); 178.601(b)] Case No: 10-0066-DMR-CE	\$ 10,675
National Welding Supply Company, Inc. New Iberia LA (Cylinder Retester)	Failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values with the calibrated cylinder showing permanent expansion; failed to maintain complete and accurate records of cylinder requalification; failed to perform hydrostatic requalification on DOT cylinders at the minimum of 5/3 times the service pressure; failed to condemn cylinders when the hydrostatic retest results showed that the permanent expansion of the cylinders exceeded ten percent of the total expansion. [180.205(g)(3) and (4); 180.205(i)(1)(iv); 180.209(a)(1); 180.215(b)(2)]	\$ 19,575

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	Case No: 09-0137-CR-SW	
Inland Empire Distribution Systems, Inc. Spokane WA (Shipper)	Offered environmentally hazardous substance, solid, n.o.s., (cupric sulfate), 9, and environmentally hazardous substance, solid, n.o.s., (copper sulfate), 9, and failed to place the correct sized hazard warning label on the package; offered RQ environmentally hazardous substance, solid, n.o.s., (cupric sulfate, zinc sulfate), 9, among others, and failed to include "RQ" in the shipping description to identify a material that is a hazardous substance; offered RQ environmentally hazardous substance, solid, n.o.s., (cupric sulfate), 9, in a non-UN standard package when a UN-standard package is required. [172.400(a); 172.407(a); 172.200(a); 172.203(c)(2); 173.22(a); 173.213(a)] Case No: 10-0110-SDB-WE	\$ 4,725
Ace Polar Technology, Inc. Purto Nuevo PR (Cylinder Retester)	Offered chlorodifluoromethane, 2.2, among others, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; failed to maintain complete and accurate records of cylinder requalification; failed to provide general awareness, function-specific, safety, and security awareness training; offered a hazardous material, accompanied by a shipping paper, that failed to (1) include a correct proper shipping name and hazard class in the required sequence, and (2) did not include units of measurement for weight. [172.702(b); 172.704(a)(1)-(4); 172.201(d); 172.604(b); 172.200(a); 172.202(a) and (b); 180.215(b)(2)] Ticket No: 10T-0379-CR-WE	\$ 2,040
Wood Rodgers Reno NV (Shipper Inspection (Ram))	Offered radioactive materials, 7, accompanied by a shipping paper that used an incorrect proper shipping name for the material; failed to provide initial and recurrent general awareness, function-specific, safety, and security awareness training; failed to include "RQ" before or after the basic shipping description to identify a material that is a hazardous substance; offered radioactive material, 7, accompanied by a shipping paper that failed to identify an emergency response telephone number; offered radioactive materials, 7, and failed to label a package with the hazard warning label. [172.704(c)(1) and (2); 172.702(b); 172.704(a)(1)-(4); 172.202(a); 172.203(c)(2); 172.604(a)(3); 172.400(a)] Ticket No: 10T-0392-RMS-SI	\$ 3,160
Coastal Fumigators Houston TX (Toxic	Offered sulfuryl fluoride, 2.3, and chloropicrin, 6.1, accompanied by a shipping paper that contained an unauthorized emergency response telephone number. [172.604(b)] Ticket No: 10T-0465-SC-SO	\$ 1,040

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Inhalation Hazard Shipper)		
Pikus Transport, Inc. Sauk Rapids MN (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0457-HMI-SI	\$ 500
Ross Fogg Jr and Sons Oil Company Salem NJ (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0432-HMI-SI	\$ 500
Barfield, Inc. Miami FL (Cylinder Retester)	Offered oxygen, compressed, 2.2, 5.1, under the provisions of DOT-SP 8162 and failed to mark the packaging as required and provide a copy of DOT-SP 8162 to the carrier before or at the time of shipment; offered oxygen, compressed, 2.2, 5.1, under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; failed to register with PHMSA. [107.608(a) and (b); 173.22a(b) and (c); DOT-SP 8162 Section 7.c. (5); DOT-SP 8162 Section 8.b. and Section 10; 172.200(a); 172.203(a)] Ticket No: 10T-0400-REG-SO	\$ 1,040
Steris Corporation Isomedix Services Chester NY (Shipper Inspection (Ram))	Offered radioactive material, 7, in a foreign-made Type B(U) package and failed to fulfill to all requirements of the foreign competent authority certificate and the U.S. Competent Authority revalidation: offered radioactive material, 7, in a foreign-made Type B(U) package and failed to register in writing with the U.S. Competent Authority as a user of the package; failed to provide initial general awareness, function-specific, safety, security awareness training. [173.473(a)(2); 172.702(a); 172.704(a)(1)-(4); 173.473(d)] Ticket No: 10T-0426-RMS-SI	\$ 2,320
Reliance Testing & Inspection Idaho Falls ID (Shipper Inspection (Ram))	Failed to provide general awareness, function-specific, safety, and security training; offered radioactive material, type A package, special form, RQ, accompanied by shipping papers that failed to contain the proper shipping name and UN identification number for the material; offered radioactive materials, type "A" package, special form, 7, RQ, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; offered radioactive material, type A packaging, special form, 7, RQ, and failed to the mark the proper shipping name, identification number, "RQ" and Type "A" on the package; offered radioactive material, type A package,	\$ 5,600

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	special form, 7, RQ, and failed to retain a record of each shipment made; offered radioactive materials, type “A” package, special form, 7, RQ and failed to maintain DOT Specification 7A packaging documentation of tests on file; offered radioactive material, type A packaging, special form, 7, RQ, with damaged labels affixed to the package and failed to mark the package label with the required additional entries. [172.702(a); 172.704(a) (1)-(4); 172.201(e); 177.817(f); 172.202(a)(1) and (2); 173.415(a); 172.604(b); 172.400; 172.403(g); 172.407(a); 172.301(a); 172.310(b); 172.324(b)] Ticket No: 10T-0324-RMS-SI	
Kleinfelder Albuquerque NM (Shipper Inspection (Ram))	Offered radioactive materials, 7, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b); 172.201(d)] Ticket No: 10T-0422-RMS-SI	\$ 1,040
J A Cesare and Associates, Inc Henderson NV (Shipper Inspection (Ram))	Offered radioactive material type A package, special form, 7, and failed to label the package with the required radioactive Yellow II label to include contents, activity and transport index; offered radioactive material type A package, special form, 7, and failed to mark the package with the proper shipping name , UN identification number, Type “A” packaging and “RQ”; offered radioactive material type A package special form, 7, and listed an incorrect proper shipping name for the material; offered radioactive material type A package special form, 7, and failed to monitor the emergency response telephone number listed on the shipping paper while the hazardous material is in transportation; failed to maintain a record of testing of hazmat employees for required training. [172.301(a)(1); 172.310; 172.324; 172.202(a)(2); 172.400(a); 172.403(b) and (g)(1)-(3); 172.704(d)(5); 172.604(a)(1)] Ticket No: 10T-0360-RMS-SI	\$ 3,720
Champion Technologies Houston TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0447-HMI-SI	\$ 500
La Rue Lamb Trucking Inc. Myton UT (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0430-HMI-SI	\$ 500
Servi-Tech, Inc. Amarillo TX (Shipper)	Failed to register with PHMSA; failed to provide general awareness, function-specific, safety, and security awareness training. [107.608(a) and (b);	\$ 1,075

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	172.702(a);172.704(a)(1)-(4)] Ticket No: 10T-0375-SD-SW	
LANNING CHEMICAL COMPANY INC LOUISVILLE KY (Shipper)	Offered paint related material, 3, and others, in unauthorized 275-gallon poly intermediate bulk containers; failed to create and retain current records of hazardous materials training; offered corrosive liquids, n.o.s. (contains malic acid), 8, and others, in unauthorized, non-reconditioned UN standard packaging. [173.22(a)(2); 173.35; 173.242; 173.28(a),(b) and (c); 173.22(a)(2); 173.24; 172.702(b); 172.704(d)] Ticket No: 10T-0113-SIBC-SO	\$ 3,740
Airtech Gases Medical Products Las Vegas NV (Shipper)	Offered nitrous oxide, 2.2 (5.1), and oxygen, compressed, 2.2 (5.1), accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b)] Ticket No: 10T-0409-SC-WE	\$ 1,040
Norchem Corporation Los Angeles CA (Shipper)	Offered corrosive liquids, 8, and others, accompanied by shipping papers that failed to provide (1) the proper shipping name for the material, and (2) the proper packing group, no technical name and package type for another hazardous material. [172.200(a); 172.202(a)(2), (4) and (7)(d); 172.203(k)] Ticket No: 10T-0404-SBD-WE	\$ 1,200
Harvard Chemical Research, Inc Atlanta GA (Shipment Observation (General))	Offered sodium hypochlorite, 8, that failed to mark the package with the the UN identification number for the material. [172.301(a)(1)] Ticket No: 10T-0417-SD-SO	\$ 660
Lansing Trade Group Overland Park KS (Other Priority Investigation Type)	Failed to provide general awareness, function-specific, safety and security awareness training. [172.704(a)(1)-(4); 172.702(a); 172.704(c)(1)] Ticket No: 10T-0038-SC-CE	\$ 987.13
Triple Image Cosmetics Los Angeles CA (Shipper)	Offered acetone, 3, accompanied by shipping papers which included unauthorized information interspersed in the basic shipping description: failed to provide recurrent general awareness, function-specific, safety and security awareness training; offered acetone, 3, and others, in UN-certified combination packages that were not closed in accordance with the package manufacturer's notification; failed to register with PHMSA. [173.22(a)(4); 173.24(f)(2); 107.608(a) and (b); 172.201(a)(4); 172.202(b); 172.702(b);	\$ 2,440

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	172.704(a)(1)-(4); 172.704(c)(2)] Ticket No: 10T-0410-SB-WE	
W. M. Barr & Company, Inc. Memphis TN (Shipper)	Filled and offered DOT 57 portable tanks with paint related material, 3, when the periodic inspections were past due; offered sodium hydroxide solution, 8, and hydrogen peroxide, aqueous solutions, 5.1, and failed to mark the packaging with the appropriate UN marking. [173.32(a)(2); 180.605(a) and (c)(3); 173.202; 178.3(a); 178.503(a)] Ticket No: 10T-0343-SPT-SO	\$ 2,840
HVJ Associates El Paso TX (Shipper Inspection (Ram))	Offered a DOT specification 7A packaging without maintaining complete documentation of tests and an engineering evaluation or comparative data; failed to provide recurrent general awareness, function-specific, safety and security awareness training; offered special form radioactive materials without maintaining a complete safety analysis or Certificate of Competent Authority. [172.702; 172.704(c)(2); 173.476(a); 173.415(a)] Ticket No: 10T-0365-RMS-SI	\$ 3,120
Cemex El Paso TX (Shipper Inspection (Ram))	Offered radioactive material Type A package, special form, 7, and failed to maintain on file a complete safety analysis, including documentation of any tests, demonstrating that the special form material meets the requirements of special form, or an International Atomic Energy Agency (IAEA) Certificate of Competent Authority issued for the special form material; offered radioactive material, Type A packaging, special form, 7, and failed to list the activity contained in each package of radioactive material in terms of the appropriate SI units; offered for transportation in commerce "RQ, UN3332 Radioactive material, Type A package, special form, 7" in a package that failed to be securely closed by a positive fastening device; offered gas oil, combustible liquid, and radioactive material, Type A package, special form, 7" and failed to maintain a record of each shipment made. [172.200(a); 173.150(f)(3); 172.201(a), (d) and (e); 173.476(a); 172.202(a)(2) and (7); 172.203(d)(3); 173.410(a) and (f); 173.412(d)] Ticket No: 10T-0377-RMS-WE	\$ 4,200
Neil's Controlled Blasting, L.P. Newcastle CA (Shipper Inspection (Explosive))	Failed to provide initial and recurrent in-depth security training; offered explosives, 1.1D and 1.4S and detonators, 1.4B, that failed to include the packing group for the material; offered cord, detonating, flexible, 1.1D, and articles, explosive, n.o.s. (contains HMX & aluminum powder), 1.4S, accompanied by a shipping paper that failed to indicate the type of package of the explosives; failed to provide initial and recurrent general	\$ 1,445

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	awareness, function-specific and security awareness training; offered explosives, 1.1D and 1.4S and detonators, 1.4B, accompanied by a shipping paper that failed to indicate the Net Explosive Mass (NEM) and the applicable unit of measurement for explosive materials; offered explosives, 1.1D and 1.4S and detonators, 1.4B, accompanied by shipping papers that included unauthorized additional information interspersed within the basic description. [172.702(a); 172.704(a)(1)-(4); 172.704(c)(2) and (d); 172.704(a)(5), (c)(2) and (d); 172.800(b)(2); 172.202(a)(5)(i); 173.22(a)(1); 172.202(a)(7); 173.22(a)(1); 173.22(a)(1); 172.202(a)(4); 172.101 Table; 173.22(a)(1)] Ticket No: 10T-0427-SE-SI	
Mayco Industries, Inc. Birmingham AL (Shipper)	Failed to provide general awareness, function-specific and security awareness training; offered environmentally hazardous substance, solid, nos (lead dross), 9, accompanied by a shipping paper that (1) contained additional information preceding the shipping description, (2) failed to list the packing group and type of package, (3) failed to sign the shipper's certification statement; offered environmentally hazardous substance, solid, n.o.s.(lead dross), 9, and failed to mark the package with the proper shipping name and UN identification number; offered environmentally hazardous substance, solid, nos (lead dross), 9, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.301(a)(1); 172.604(b); 172.200(a); 172.201(a)(4); 172.202(a)(4) and (7); 172.204(d); 172.702(a); 172.704(a)(1), (2) and (4)] Ticket No: 10T-0411-SD-SO	\$ 3,900
Cygnat Automated Cleaning, Inc. Plymouth MI (Recertifier/Retester/Repairer (Tanks, IBCs))	Records of periodic retests and inspections failed to include the name and address of the test and inspection facility, the name of person performing the tests, and the results of all inspections and tests; failed to provide initial function-specific, safety, and security awareness training and recurrent general awareness training; offered waste paint related material, 3, accompanied by a shipping paper that failed to indicate an emergency response telephone number; failed to register with PHMSA. [180.352(g); 180.605(l); 172.201(d); 172.604(b); 172.704(a)(2)-(4); 172.704(c)(2); 172.702(b); 107.608(a) and (b)] Ticket No: 10T-0395-IBCR-WE	\$ 3160
Robinette	Failed to file a detailed written report on DOT form	\$ 500

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Trucking Mount Pleasant TN (HMI Ticket)	5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0453-HMI-SI	
Eagle Transport Rocky Mountain NC (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0464-HMI-SI	\$ 500
Hi-Noon Petroleum Missoula MT (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0439-HMI-SI	\$ 500
Headwaters Trucking Amarillo TX (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0441-HMI-SI	\$ 500
Turner Specialty Services, LLC Baton Rouge LA (Shipper Inspection (Ram))	Offered radioactive material, type B(U) package, 7, in packages that failed to have the listed contents activity and transport index on the labels; failed to provide security awareness training. [172.400(a); 172.403(b), (g)(1)-(3); 172.702(a); 172.704(a)(4)] Ticket No: 10T-0388-RMS-SI	\$ 2,450
Peach State Labs, Inc Columbus GA (Shipper)	Offered phosphoric acid solution, 8, in UN-certified 55 gallon closed-head plastic drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0419-SIBC-SO	\$ 1,000
C&C Ventures dba Randolph Products Chicopee MA (Shipper)	Failed to provide recurrent hazardous materials training; offered paint related material, 3, in UN-certified 55-gallon closed-head steel drums containers that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2); 172.702(a); 172.704(c)(2)] Ticket No: 10T-0396-SD-EA	\$ 1,595
ARCH WOOD PROTECTION, INC. CONLEY GA (Shipper)	Offered corrosive liquid, toxic, n.o.s. (arsenic acid, chromic acid), 8,6.1, in UN-certified 55-gallon closed-head steel drums that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0338-SD-SO	\$ 1,000
United States Plastic Corporation Lima OH (Shipment Observation (General))	Failed to notify in writing each person to whom a packaging is transferred, of all requirements not met at the time of transfer that are needed to satisfy performance test requirements, and maintain records thereof. [178.2(c)] Ticket No: 10T-0406-PDM-SW	\$ 935

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Maverick Country Stores, Inc. North Salt Lake UT (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0462-HMI-SI	\$ 500
BrownLee Farm Center, Inc. Tifton GA (Shipper)	Offered anhydrous ammonia, 2.2, in excess of 1000 pounds and failed to placard the cargo tank on all four sides and contained faded placards on the cargo tank; failed to provide initial general awareness, function-specific, safety, and security awareness training; offered anhydrous ammonia, 2.2, in unauthorized non-DOT specification cargo tanks, when the tanks do not conform to the ASME Code in that the data plate is illegible and therefore not in conformance with the requirements in the Hazardous Materials Regulations. [173.315(m)(1); Section VIII of the ASME Code; 172.504(a); 173.22(a); 172.702(a); 172.704(c)(1); 172.704(a)(1-4)] Case No: 09-0014-SPT-SO	\$ 3,000
Patterson, A. L., Inc. Fairless Hills PA (Shipper)	Offered amines, liquid, corrosive, n.o.s. (aminopropyldiethanolamine), 8, and failed to declare, mark or label the hazardous material, therefore shipping an undeclared hazardous material; offered various hazardous materials and failed to (1) maintain copies of shipping papers, (2) to include a unit of measure in association with the weight on the shipping paper, and (3) to include a 24 hour emergency response telephone number on the shipping paper. [173.154(c); 172.316(a); 172.200(a); 172.201(e); 172.202(a)(5); 172.604(b)] Case No: 09-0212-SB-EA	\$ 6,860
Refinery Specialties, Inc. Hempstead TX (Shipper)	Offered and transported flammable liquids, n.o.s., 3, in an unauthorized non-UN standard packaging, when specification packaging is prescribed; transported hazardous materials, accompanied by shipping papers that failed to (1) indicate the special permit on the shipping papers, and (2) indicated a hazardous material as a hazardous substance on a shipping paper with the notation "RQ" when it is not a reportable quantity; offered corrosive liquid, n.o.s. in MC 312 and DOT 412 cargo tanks that was overdue the prescribed periodic retest; failed to remove bulk containers from the motor vehicle prior to discharging the contents of the containers; offered hazardous materials in a UN standard marked and certified packaging that had not been closed in accordance with the manufacturer's closure instructions. [173.22(a)(2); 173.24(c); 173.33(a)(3); 180.407(a) and (c); 177.834(h);	\$ 15,585

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	173.22(a)(4); 173.24(f)(2); 172.203(a) and (c)(2)] Case No: 09-0200-CCT-SW	
Berenfield Container, Corp Mason OH (Steel Drum Manufacturer)	Failed to notify customers, in writing, of all requirements needed to satisfy performance test requirements not met at the time of transfer; represented, remanufactured, marked and offered steel drums when the test reports were not created, prepared and maintained as required. Represented, marked, certified, sold and offered fifty-five gallon steel drums when the production leakproofness test was not properly conducted; failed to provide recurrent training. [172.702(a); 172.704(c)(2); 172.704(d); 178.604(a), (b) and (d); Appendix B to Part 178; 178.601(a), (g), and (l); 178.2(a) and (b); 173.22(a)(4); 173.24(f)(2); 178.2(c); 178.601(b)] Case No: 10-0066-DMR-CE	\$ 10,675
National Welding Supply Company, Inc. New Iberia LA (Cylinder Retester)	Failed to verify the accuracy of the test equipment to within one percent of the calibrated cylinder's pressure and corresponding expansion values with the calibrated cylinder showing permanent expansion; failed to maintain complete and accurate records of cylinder requalification; failed to perform hydrostatic requalification on DOT cylinders at the minimum of 5/3 times the service pressure; failed to condemn cylinders when the hydrostatic retest results showed that the permanent expansion of the cylinders exceeded ten percent of the total expansion. [180.205(g)(3) and (4); 180.205(i)(1)(iv); 180.209(a)(1); 180.215(b)(2)] Case No: 09-0137-CR-SW	\$ 19,575
Inland Empire Distribution Systems, Inc. Spokane WA (Shipper)	Offered environmentally hazardous substance, solid, n.o.s., (cupric sulfate), 9, and environmentally hazardous substance, solid, n.o.s., (copper sulfate), 9, and failed to place the correct sized hazard warning label on the package; offered RQ environmentally hazardous substance, solid, n.o.s., (cupric sulfate, zinc sulfate), 9, among others, and failed to include "RQ" in the shipping description to identify a material that is a hazardous substance; offered RQ environmentally hazardous substance, solid, n.o.s., (cupric sulfate), 9, in a non-UN standard package when a UN-standard package is required. [172.400(a); 172.407(a); 172.200(a); 172.203(c)(2); 173.22(a); 173.213(a)] Case No: 10-0110-SDB-WE	\$ 4,725
Earth Science Consultants associated (ESCA) Sparks	Offered a DOT specification 7A packaging without maintaining complete documentation of tests and an engineering evaluation or comparative data; placing a label on a package that is damaged and missing required	\$ 2,600

## PHMSA Notice of Hazardous Materials Regulations Enforcement

NV (Shipper Inspection (Ram))	information; offered a DOT specification 7A packaging without completing the water spray test to comply with the one prototype being used for testing. [172.403(g)(1) and (2); 172.407(a); 173.415(a); 173.465(a) and (b)] Ticket No: 10T-0140-RMS-SI	
JKJ Trucking Terry MS (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0448-HMI-SI	\$ 500
Frenz Petroleum New Castle PA (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0463-HMI-SI	\$ 500
GAC Chemical Seasport ME (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0437-HMI-SI	\$ 500
Fugro Consultants Inc Waco TX (Shipper Inspection (Ram))	Offered a radioactive material and failed to use the proper shipping name for the material; offered radioactive materials accompanied by shipping papers that listed an unauthorized emergency response telephone number for the material; offered radioactive materials that failed to provide emergency response information with or on a shipping paper. [172.602(c)(1); 172.202(a)(2); 172.604(b)] Ticket No: 10T-0389-RMS-SI	\$ 1,520
Alberto Damian's Fumigation Long Beach CA (Toxic Inhalation Hazard Shipper)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 09T-0329-SC-WE	\$ 556.25
Frenz Oil Company New Castle PA (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0434-HMI-SI	\$ 500
Gate Fuel Service Inc. Jacksonville FL (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0435-HMI-SI	\$ 500
DEPENDABLE DRUM CO., INC. TAYLORS SC (Drum Reconditioner)	Failed to register with PHMSA. [107.608(a) and (b)] Ticket No: 10T-0466-REG-SO	\$ 400
Vegrzyn, Sarver and Associates,	Place into transportation in commerce UN 3332 Radioactive material Type A Package, special form, 7,	\$ 1,520

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Inc Ottawa IL (Shipper Inspection (Ram))	RQ; failed to provide a valid special form certification on request; failed to provide recurrent training; offered radioactive material Type A Package, special form, 7, and failed to maintain a file on the Type "A" package documentation of tests. [172.702(a); 172.204(c)(2); 173.476(a); 173.415(a)] Ticket No: 10T-0385-RMS-SI	
ALPINE TECHNICAL SERVICES MIDVALE UT (Shipper)	Failed to provide recurrent hazardous materials training; offered corrosive liquids, flammable (cyclohexylamine), 8 (3), accompanied by a shipping paper which listed an incorrect proper shipping name and did not include the subsidiary hazard. [172.704(a); 172.704(a)(1)-(4); 172.704(c)(2); 172.202(a)(2) and (3)] Ticket No: 10T-0469-SD-WE	\$ 1,540
Mountain Energy Corporation Waynesville NC (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0444-HMI-SI	\$ 500
AR Sandri Inc. Greenfield MA (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0438-HMI-SI	\$ 500
Jernigan Oil Company Ahoskie NC (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0459-HMI-SI	\$ 500
Inspection Consulting, Inc. Sacramento CA (Shipper Inspection (Ram))	Failed to provide recurrent hazardous materials training; offered radioactive material, Type A package, special form, 7, accompanied by a shipping paper that failed to be marked with the material's assigned proper shipping name and identification number; offered radioactive materials, accompanied by a shipping paper that contained an unauthorized emergency response telephone number. [172.702(b); 172.704(c)(2); 172.202(a)(1) and (2); 172.604(b)] Ticket No: 10T-0408-RMS-SW	\$ 1,795
Maurice Sporting Goods McDonough GA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training; offered fire extinguishers, 2.2", signal devices, hand, 1.4S, and flares aerial, 1.4G, accompanied by a shipping paper that failed to indicate an emergency response telephone number; offered fire extinguishers, 2.2", signal devices, hand, 1.4S and flares aerial, 1.4G, accompanied by a shipping paper which used a shipping description with two or more required elements missing or incorrect. [172.202(a) and (b); 172.604(b); 172.702(a); 172.704(a)(1)-(4), (c)(1) and (d)] Ticket No: 10T-0414-	\$ 2,960

## PHMSA Notice of Hazardous Materials Regulations Enforcement

	SB-SO	
Rose Pest Solutions Troy MI (Toxic Inhalation Hazard Shipper)	Developed a security plan that failed to include a written assessment of transportation security risks and address en-route security related to shipments of hazardous materials; offered sulfuric fluoride, 2.3, accompanied by a shipping paper which failed to describe the material as a “Zone C” or Zone D” poison inhalation hazard. [172.200(a); 172.203(m); 172.800(b); 172.802(a) and (b)] Ticket No: 10T-0470-SC-WE	\$ 1,150
Cardinal Health El Paso TX (Other Priority Investigation Type)	Failed to provide initial general awareness, function-specific, safety, and security awareness training; failed to provide initial and recurrent general awareness, function-specific, safety, and security awareness training. [172.702(a); 172.704(a)(1)-(4); 172.704(c)(2); 172.702(a); 172.704(a)(1)-(4)] Ticket No: 10T-0421-RMS-SI	\$ 720
BAE Systems Kingsport TN (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0443-HMI-SI	\$ 500
ZODIAC SERVICES AMERICAS LLC COLLEGE PARK GA (Cylinder Retester)	Failed to maintain complete and accurate records of visual cylinder requalification. [180.215(b)(2)] Ticket No: 10T-0467-CR-SO	\$ 400
Johnson Controls, Inc. Cedar Creek TX (Shipper)	Failed to provide general awareness, function-specific, and security awareness training. [172.702(b); 172.704(a)(1), (2), and (4)] Ticket No: 10T-0472-SD-SW	\$ 495
Nalco Company Carson CA (Shipper)	Failed to provide initial general awareness, function-specific, safety, and security awareness training. [172.702(b); 172.704(a)(1)-(4)] Ticket No: 10T-0476-SPT-WE	\$ 1,120
Igo's Welding Supply, Co., Inc. Watertown MA (Shipper)	Offered propane, 2.1” and others, accompanied by a shipping paper that provided an unauthorized emergency response telephone number; failed to create and retain current records of hazardous materials training. [172.201(d); 172.604(b); 172.702(b); 172.704(a)(1)-(4); 172.704(d)] Ticket No: 10T-0399-SC-SO	\$ 1,636
Sherwin-Williams dba Consumer Group/Diversified Brands, Inc.	Offered aerosols, 2.1, limited quantity”, accompanied by a shipping paper that failed to list the UN identification number, proper shipping name, hazard class, and limited quantity statement for the material; offered aerosols, 2.1, limited quantity”, and failed to close the outer package	\$ 3600

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Zeeland MI (Shipment Observation (General))	in a manner that under conditions normally incident to transportation would protect its contents and to provide cylinder valve protection; offered aerosols, 2.1, Limited Quantity”, and failed to mark the outer package with the statement “INSIDE CONTAINERS COMPLY WITH THE PRESCRIBED REGULATIONS”. [173.22(a); 173.24(b); 173.24(f); 173.301(h); 172.200(a); 172.202(a)(1)-(3); 172.203(b); 173.306(a)(3)(vi); 173.22(a); 173.301(a)(9)] Ticket No: 10T-0415-SB-SO	
Caswell- Massey, LLC Edison NJ (Special Permit Renewal)	Offered certain limited quantities of liquid and solids containing ethyl alcohol after their authority under DOT-SP 9275 had expired. [Parts 100-180] Ticket No: 10T-0496-ESP-SI	\$ 500
Southwest Engineering Incorporated (SEI) Las Cruces NM (Shipper Inspection (Ram))	Offered a DOT specification 7A packaging without maintaining complete documentation of tests and an engineering evaluation or comparative data; failed to provide initial general awareness, function-specific, safety, and security awareness training; offered a radioactive material, 7, and failed to label the package; offered a radioactive material, 7, on a package that failed to contain a label with entries for the name of the radionuclide(s), activity, and transport index; offered special form radioactive materials without maintaining a complete safety analysis or Certificate of Competent Authority; failed to provide a shipping paper for a shipment of hazardous materials; failed to retain copies of hazardous materials shipping papers for a minimum of two years. [173.476(a); 173.415(a); 172.400(a); 172.403(f); 172.403(g); 172.202; 172.200(a); 177.817(f); 172.201(e); 172.702(a); 172.704(a)(1)-(4)] Ticket No: 10T-0429-RMS-SI	\$ 6,720
Integrity Oilfield Services Houma LA (Shipper Inspection (Ram))	Offered hazardous materials under the terms of a DOT special permit while failing to indicate the special permit on the shipping papers; failed to provide general awareness, function-specific, safety, and security awareness training and training on special permits 14796 and 7774; failed to provide a shipping paper for a shipment of hazardous materials. Failed to retain copies of hazardous materials shipping papers for a minimum of two years. [172.702(a); 172.704(a)(1)-(4); Special Permits 14796 and 7774; 172.201; 172.200(a); 177.817(f); 171.201(e); 172.203(a)] Ticket No: 10T-0387-RMS-SI	\$ 2,800
Sierra Pharmacy Services Reno	Offered radioactive material, Type A package, 7 , and failed to meet one or more of the general design	\$ 1,440

## PHMSA Notice of Hazardous Materials Regulations Enforcement

NV (Shipper Inspection (Ram))	requirements for a package used to ship a class 7 materials; offered radioactive material, Type A package, 7, and failed to provide emergency response information with or on a shipping paper. [172.602(a)-(c); 172.604(b); 173.410(f)] Ticket No: 10T-0351-RMS-SI	
COPACO Columbus GA (Shipper)	Offered sodium hydrochlorite and potassium hydroxide, 8, and failed to develop and retain shipping papers; offered sodium hypochlorite and failed to mark the package with the UN identification number in association with the proper shipping name. [172.201(e); 172.202(a); 172.301(a)(1)] Ticket No: 10T-0418-SD-SO	\$ 1600
AGRI-AFC Montgomery AL (Shipper)	Offered organophosphorus pesticides, liquid, toxic (tribufos), 6.1, accompanied by a shipping paper that provided an unauthorized emergency response telephone number. [172.604(b)] Ticket No: 10T-0475-SB-SO	\$ 1,040
Ducan Thompson Petroleum Atlanta TX (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0461-HMI-SI	\$ 500
Gilligan Oil Company Cincinnati OH (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0449-HMI-SI	\$ 500
Porteadores Del Noroeste SA DE CV Chula Vista CA (Hmi Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.15; 171.16] Ticket No: 10T-0451-HMI-SI	\$ 500
Mistras Group, Inc. Benicia CA (Shipper Inspection (Ram))	Offered radioactive material, Type B(U) package, accompanied by a shipping paper not marked with the number and type of package, and not marked with the proper transport index assigned to the package; offered radioactive material, Type B(U) package containing Iridium-192, 7, and failed to (1) label the package on two opposing sides and (2) to mark Radioactive Yellow-II labels with the packages correctly measured transport index (TI). [172.403(h)(3); 173.25(a)(4); 172.400(a); 172.403; 172.403(g)(3); 172.202(a)(7); 172.203(d)(5)] Ticket No: 10T-0407-RMS-SW	\$ 2,250
Daniel B Stephens and Associates Inc Albuquerque NM (Shipper)	Placed a label on Class 7 material that failed to contain legible entries for the name of the radionuclides and activity; offered a DOT specification 7A packaging without maintaining complete documentation of tests and an engineering evaluation or comparative data and	\$ 2,203.21

## PHMSA Notice of Hazardous Materials Regulations Enforcement

Inspection (Ram))	complete records were not maintained. [172.403(g)(1) and (2); 173.415(a)] Ticket No: 10T-0425-RMS-SI	
Ecotech Enterprises, Inc Scott AR (Shipper)	Offered hazardous materials accompanied by shipping papers that listed shipping descriptions not in the required sequence, included additional unauthorized information and failed to list the type of packages; failed to provide general awareness, function-specific, safety, and security awareness training. [172.702(b); 172.704(a)(1)-(4); 172.201(a)(4); 172.202(a)] Ticket No: 10T-0483-SDIBC-SW	\$ 965
SSC INDUSTRIES, LLC ATLANTA GA (Shipper)	Offered hydrochloric acid, 8, in UN-certified composite intermediate bulk containers that were not closed in accordance with the manufacturer's closure notification. [173.22(a)(4); 173.24(f)(2)] Ticket No: 10T-0416-SIBC-SO	\$ 1,000
Klemm Tank Lines Green Bay WI (HMI Ticket)	Failed to file a detailed written report on DOT form 5800.1 within thirty days of a hazardous materials incident. [171.16] Ticket No: 10T-0450-HMI-SI	\$ 500