

January 24, 1974

Mr. Dois D. Dallas  
Petroleum Engineer  
Dallas Engineering, Inc.  
P.O. Box 594  
Tioga, ND 58852

Dear Mr. Dallas:

In your letter of January 17, 1974, you ask what protection should be provided for insulated 3/4-inch metallic riser pipes. Risers are to be coated and cathodically protected as required by Section 192.455. The level of protection must meet one or more of the criteria contained in Section 192.463. The frequency for monitoring service risers is covered by Section 192.465.

We trust this answers your question. If you desire any further information, please advise.

Sincerely,

\signed\

Joseph C. Caldwell  
Director  
Office of Pipeline Safety

DALLAS ENGINEERING, INC.

January 17, 1974

Mr. Joseph C. Caldwell, Director  
Office of Pipe Line Safety  
Office of the Secretary of Transportation  
Washington, D.C. 20590

Dear Mr. Caldwell:

Thank you very much for your letter amplifying the meaning of subpart I, #192.451.

You state that metallic components of plastic pipelines are subject to these requirements. Accordingly would you please advise what protection should be provided for insulated 3/4" metallic riser pipes (service lines) which extend under ground for a total distance of not more than 3 feet?

Very truly yours,

DALLAS ENGINEERING, INC.

Dois D. Dallas  
Petroleum Engineer