



U.S. Department  
of Transportation

400 Seventh Street, S.W.  
Washington, D.C. 20590

**MAY 9 2005**

**Pipeline and  
Hazardous  
Materials Safety  
Administration**

Mr. Patrick Ginn  
Piper Metal Forming Corp.  
795 Sam T. Barkley Drive  
New Albany, MS 38652

Dear Mr. Ginn:

Your application, 14156-N, dated February 18, 2005, is returned herewith because it failed to meet the requirements of 49 CFR 107.105 by not providing the fundamental design qualifications that include the following:

- Heat treatment procedure
- Fracture performance testing
- Fatigue performance testing
- Operational and environmental testing
- Burst testing
- Mechanical test results (e.g., elongation, fracture toughness, etc.)

Please resubmit your application when it is complete.

Sincerely,

Delmer F. Billings

Director

Office of Hazardous Materials

Exemptions and Approvals

Enclosure