

U.S. Department of Transportation **Pipeline and Hazardous Materials Safety Administration**

2023 Gas State Program Evaluation

for

VERMONT DEPARTMENT OF PUBLIC SERVICE

Document Legend PART:

- O -- Representative, Dates and Title Information
- A -- Progress Report and Program Documentation Review
- B -- Program Inspection Procedures
- C -- State Qualifications
- D -- Program Performance
- E -- Field Inspections
- F -- Damage prevention and Annual report analysis



2023 Gas State Program Evaluation -- CY 2023

Gas

State Agency: Vermont Agency Status:	Rating: 60105(a): Yes 60106(a): No Interstate Agent: No
Date of Visit: 07/22/2024	
Agency Representative:	Mr. Bill Jordan, Director of Engineering
	Mr. Matt Hecklinger, Gas Engineer
	Ms. Lindsey Wells, Administrative Service Coordinator
PHMSA Representative:	Glynn Blanton, PHMSA State Liaison
Commission Chairman t	o whom follow up letter is to be sent:
Name/Title:	Ms. June Tierney, Commissioner
Agency:	Vermont Public Service Commission
Address:	112 State Street
City/State/Zip:	Montpelier, VT 05620-2601

INSTRUCTIONS:

Complete this evaluation in accordance with the Evaluator Guidance for conducting state pipeline safety program evaluations. The evaluation should generally reflect state program performance during CY 2023 (not the status of performance at the time of the evaluation). A deficiency in any one part of a multiple-part question should be scored as "Needs Improvement." Determine the answer to the question then select the appropriate point value. If a state receives less than the maximum points, include a brief explanation in the appropriate notes/comments section. If a question is not applicable to a state, select NA. Please ensure all responses are COMPLETE and ACCURATE, and they OBJECTIVELY reflect the state's program performance for the question being evaluated. Increasing emphasis is being placed on how the state pipeline safety programs conduct and execute their pipeline safety responsibilities (their performance). This evaluation, together with selected factors reported in the state's annual progress report attachments, provide the basis for determining the state's pipeline safety grant allocation.

Scoring Summary

PARTS		Possible Points	Points Scored
А	Progress Report and Program Documentation Review	0	0
В	Program Inspection Procedures	15	15
С	State Qualifications	10	10
D	Program Performance	50	49
E	Field Inspections	15	15
F	Damage prevention and Annual report analysis	10	10
ΤΟΤΑ	LS	100	99
State I	Rating		99.0



PART A - Progress Report and Program Documentation Review

1 Were the following Progress Report Items accurate? (*items not scored on progress Info Only Info Only report)

Info Only = No Points

- a. Stats On Operators Data Progress Report Attachment 1
- b. State Inspection Activity Data Progress Report Attachment 2
- c. List of Operators Data Progress Report Attachment 3*
- d. Incidents/Accidents Data Progress Report Attachment 4*
- e. Stats of Compliance Actions Data Progress Report Attachment 5*
- f. List of Records Kept Data Progress Report Attachment 6 *
- g. Staff and TQ Training Data Progress Report Attachment 7
- h. Compliance with Federal Regulations Data Progress Report Attachment 8
- i. Performance and Damage Prevention Question Data Progress Report
- Attachment 10*

Evaluator Notes:

- a. Reviewed and found data correct.
- b. Reviewed and found data correct.
- c. Reviewed and found data correct and matched PHMSA Portal.
- d. Verification of the one incident found it listed in PHMSA Portal.

e. Number of violations to be corrected at end of year is incorrect. The correct number is 165. This needs to be corrected.

f. No issues

g. Listing Director of Engineering in Inspector/Investigator category is incorrect unless % of time is provided. This item needs to be corrected.

- h. No issues.
- i. No issues.

Total points scored for this section: 0 Total possible points for this section: 0

1	Do written procedures address pre-inspection, inspection and post inspection activities for each of the following inspection types: Chapter 5.1	5	5
	Yes = 5 No = 0 Needs Improvement = 1-4 a. Standard Inspections, which include Drug/Alcohol, CRM and Public		
	Awareness Effectiveness Inspections		
	b. TIMP and DIMP Inspections (reviewing largest operator(s) plans annually)		
	c. OQ Inspections		
	d. Damage Prevention Inspections		
	e. On-Site Operator Trainingf. Construction Inspections (annual efforts)		
Evaluato			
Rev	iewed Vermont Public Service Commission Gas Pipeline Safety Inspection Procedures (GPS I ument. Pre-inspection, inspection and post inspection activities were found on pages 8-11.	P) Revised	1 2023
2	Do written procedures address inspection priorities of each operator, and if necessary each unit, based on the following elements and time frames established in its procedures?	4	4
	Chapter 5.1 Yes = 4 No = 0 Needs Improvement = 1-3		
	a. Length of time since last inspection		
	b. Operating history of operator/unit and/or location (includes leakage, incident and compliance activities)		
	c. Type of activity being undertaken by operators (i.e. construction)		
	d. Locations of operator's inspection units being inspected - (HCA's, Geographic		
	area, Population Centers, etc.) e. Process to identify high-risk inspection units that includes all threats -		
	(Excavation Damage, Corrosion, Natural Forces, Outside Forces, Material and Welds,		
	Equipment, Operators and any Other Factors)		
	f. Are inspection units broken down appropriately?		
Evaluato			
	ns a thru e were located on GPS IP pages 8-9. atisfactory.		
All	requirements for this question were found satisfied. No loss of points.		
3	(Compliance Procedures) Does the state have written procedures to identify steps to be taken from the discovery to resolution of a probable violation? Chapter 5.1	3	3
	Yes = 3 No = 0 Needs Improvement = 1-2 a. Procedures to notify an operator (company officer) when a noncompliance is		
	identified b. Procedures to routinely review progress of compliance actions to prevent		
	delays or breakdowns		
	c. Procedures regarding closing outstanding probable violations		
Evaluato			
	ru c. These items are located on page 13 of GPS IP		
	his item is located on pages 13-14.		
c. 1	hie item is located on page 14.		
All	requirements for this question were found satisfied. No loss of points.		
4	 (Incident/Accident Investigations) Does the state have written procedures to address state actions in the event of an incident/accident? Yes = 3 No = 0 Needs Improvement = 1-2 a. Mechanism to receive, record, and respond to operator reports of incidents, including after-hours reports 	3	3

b. If onsite investigation was not made, do procedures require on-call staff to obtain sufficient information to determine the facts to support the decision not to go on-site.

Evaluator Notes:

a & b. These items are located on pages 15-20 of GPS IP.

All requirements for this question were found satisfied. No loss of points.

5 General Comments:

Info Only = No Points

Evaluator Notes:

No loss of points occurred on this section of the review.

Info Only Info Only

Total points scored for this section: 15 Total possible points for this section: 15



Has each inspector and program manager fulfilled training requirements? (See Guidelines Appendix C for requirements) Chapter 4.3 Yes = 5 No = 0 Needs Improvement = 1-4	5	5
 a. Completion of Required OQ Training before conducting inspection as lead b. Completion of Required DIMP/IMP Training before conducting inspection as lead 		
c. Completion of Required LNG Training before conducting inspection as lead		
d. Root Cause Training by at least one inspector/program manager		
e. Note any outside training completed		
f. Verify inspector has obtained minimum qualifications to lead any applicable		
standard inspection as the lead inspector (Reference State Guidelines Section 4.3.1)		
Evaluator Notes:		
a. Yes Program Manager and inspector have completed all courses to meet the requirements.		
b. Satisfactory		
c. Satisfactory		
d. Program Manager has completed the root cause training course.		
e. No outside training courses were attended in this review period.		
f. Satisfactory. All requirements for this question were found satisfied. No loss of points.		
2 Did state records and discussions with state pipeline safety program manager indicate adequate knowledge of PHMSA program and regulations? Yes = 5 No = 0 Needs Improvement = 1-4	5	5
Evaluator Notes:		
Bill Jordon has been the Program Manager for five years. He demonstrated a working knowledge guidelines.	e of the program	n and
All requirements for this question were found satisfied. No loss of points.		
3 General Comments: Info Only = No Points	Info Only Info	Only
Evaluator Notes:		
No loss of points occurred in this section of the evaluation.		

Total points scored for this section: 10 Total possible points for this section: 10

1	intervals	e inspect all types of operators and inspection units in accordance with time s established in written procedures? Chapter 5.1 No = 0 Needs Improvement = 1-4	5	5
	a.	Standard (General Code Compliance)		
	b.	Public Awareness Effectiveness Reviews		
	c.	Drug and Alcohol		
	d.	Control Room Management		
	e.	Part 193 LNG Inspections		
	f.	Construction (did state achieve 20% of total inspection person-days?)		
	g.	OQ (see Question 3 for additional requirements)		
	h.	IMP/DIMP (see Question 4 for additional requirements)		
Evaluator	Notes:			
		standard inspections performed on all operators was conducted and found satisfactor		
perio	od.	public awareness inspections on all operators was conducted and found satisfactory		ired five-year
		drug & alcohol inspections were found satisfactory and completed within the five ye	ear period.	
	tisfactory	he State of Vermont.		
		a inspections were performed and met the 20% level.		
	tisfactory.	inspections were performed and met the 2070 level.		
		DIMP inspections of all operators was conducted and found satisfactory.		
All re	equiremen	ts for this question were found satisfied. No loss of points.		
	Inspection Chapter and field for each Yes = 10 a. b. c. d. e. f. g. h. Notes: they use L	 bection form(s) cover all applicable code requirements addressed on Federal on form(s)? Did State complete all applicable portions of inspection forms? 5.1. Do inspection records indicate that adequate reviews of procedures, records a activities, including notes and the appropriate level of inspection person-days inspection, were performed? No = 0 Needs Improvement = 1-9 Standard (General Code Compliance) Public Awareness Effectiveness Reviews Drug and Alcohol Control Room Management Part 193 LNG Inspections Construction OQ (see Question 3 for additional requirements) IMP/DIMP (see Question 4 for additional requirements) 	10 • findings of f	10 acts. All
3	should in (includin the oper Yes = 2 N	verifying monitoring (Protocol 9/Form15) of operators OQ programs? This nclude verification of any plan updates and that persons performing covered tasks ng contractors) are properly qualified and requalified at intervals established in ator's plan. 49 CFR 192 Part N No = 0 Needs Improvement = 1	2	2
	VT Gas Sa	afety form inspected on 10-19-2023 was reviewed and found complete. All requiren sfied. No loss of points.	nents for this	question

4	Is state verifying operator's integrity management Programs (IMP and DIMP)? This should include a review of plans, along with monitoring progress. In addition, the review should take in to account program review and updates of operator's plan(s). 49 CFR 192 Subparts O and P Yes = 2 No = 0 Needs Improvement = 1 a. Are the implementation plans of the state's large/largest operators(s) being reviewed annually to ensure they are completing full cycle of the IMP process? b. Are states verifying with operators any plastic pipe and components that have shown a record of defects/leaks and mitigating those through DIMP plan? c. Are the states verifying operators are including low pressure distribution systems in their threat analysis?	2	1
Evaluator	Notes:		
	the state's largest operator, Vermont Gas Systems, Inc., plan was not reviewed annually to e		
item.	l cycle of the DIMP process. The last review was conducted in calendar year 2021. A loss o	f one point	occurred on this
	sfactory. No cast iron or any plastic pipe have shown a record of leaks.		
	low-pressure distribution systems in the State of Vermont.		
5	Did the state review the following (these items are NTSB recommendations to PHMSA that have been deemed acceptable response based on PHMSA reviewing these items	2	2
	during the evaluation process): Chapter 5.1 Yes = 2 No = 0 Needs Improvement = 1		
	a. Operator procedures for determining if exposed cast iron pipe was examined for evidence of graphitization and if necessary remedial action was taken;		
	b. Operator procedures for surveillance of cast iron pipelines, including		
	appropriate action resulting from tracking circumferential cracking failures, study of		
	leakage history, or other unusual operating maintenance condition? (Note: See GPTC Appendix G-18 for guidance);		
	c. Operator emergency response procedures for leaks caused by excavation		
	damage near buildings and determine whether the procedures adequately address the		
	possibility of multiple leaks and underground migration of gas into nearby buildings		
	Refer to 4/12/01 letter from PHMSA in response to NTSB recommendation P-00-20		
	and P-00-21;		
	d. Operator records of previous accidents and failures including reported third-		
	party damage and leak response to ensure appropriate operator response as required by 192.617;		
	e. Directional drilling/boring procedures of each pipeline operator or its		
	contractor to determine if they include actions to protect their facilities from the		
	dangers posed by drilling and other trench less technologies;		
	f. Operator procedures for considering low pressure distribution systems in threat		
	analysis?		
	g. Operator compliance with state and federal regulations for regulators located inside buildings?		
Evaluator			
	. No cast iron pipe in the State of Vermont.		
	s item is covered under the IA question set.		
	s is covered under the standard inspection.		
	sfactory		
	ow-pressure distribution systems in the State of Vermont.	1 64	1.4
	mont Gas Systems has 43 locations containing 139 inside meters in the State of Vermont. Es l outside of the building wall and have an overpressure shut off valve.	ach of the r	egulators are
ventet	outside of the bullding wan and have an overpressure shut off varve.		
All ree	quirements for this question were found satisfied. No loss of points.		
6 Evaluator I No ad	Did the State verify Operators took appropriate action regarding advisory bulletins issued since the last evaluation? (Advisory Bulletins Current Year) Yes = 1 No = 0 Needs Improvement = .5 Notes: visory bulletins were issued in CY2023 but when a new advisory bulletin is released it is ser	1 nt to all ope	1 rators via email.

7 (Compliance Activities) Did the state follow compliance procedures (from discovery to resolution) and adequately document all probable violations, including what resolution or further course of action is needed to gain compliance? Chapter 5.1 Yes = 10 No = 0 Needs Improvement = 1-9

> Were compliance actions sent to company officer or manager/board member if a. municipal/government system?

- b. Were probable violations documented properly?
- c. Resolve probable violations
- Routinely review progress of probable violations d.
- e. Did state issue compliance actions for all probable violations discovered?
- f. Can state demonstrate fining authority for pipeline safety violations?
- Does Program Manager review, approve and monitor all compliance actions? g.

(note: Program Manager or Senior Official should sign any NOPV or related enforcement action)

Did state compliance actions give reasonable due process to all parties? h. Including "show cause" hearing, if necessary.

Within 30 days, conduct a post-inspection briefing with the owner or operator i. outlining any concerns

Within 90 days, to the extent practicable, provide the owner or operator with 1. written preliminary findings of the inspection. (Incident investigations do not need to meet 30/90-day requirement)

Evaluator Notes:

A review of 30 compliance action letters were conducted. Letters were sent via email to the company officer and identified probable violations. All violations were documented and routinely reviewed by Program Manager and Inspector to ensure compliance action was taken by operator personnel. No probable violations were issued but letters of compliance concerns issued.

f. Yes, Vermont Department of Public Service has issued a civil penalty in the amount \$15,000 again Haskins Gas Service on March 29, 2019.

- g. Satisfactory
- h. Satisfactory
- i. Satisfactory
- j. Satisfactory

All requirements for this question were found satisfied. No loss of points.

- 8 (Incident Investigations) Were all federally reportable incidents investigated, thoroughly documented, with conclusions and recommendations? Yes = 10 No = 0 Needs Improvement = 1-9Does state have adequate mechanism to receive and respond to operator reports a. of incidents, including after-hours reports? b. Did state keep adequate records of Incident/Accident notifications received? c. If onsite investigation was not made, did the state obtain sufficient information from the operator and/or by means to determine the facts to support the decision not to go on site? d. Were onsite observations documented? e. Were contributing factors documented? f. Were recommendations to prevent recurrences, where appropriate, documented? Did state initiate compliance action for any violations found during any g. incident/accident investigation? Did state assist Region Office or Accident Investigation Division (AID) by h. taking appropriate follow-up actions related to the operator incident reports to ensure accuracy and final report has been received by PHMSA? i. Does state share any lessons learned from incidents/accidents? **Evaluator Notes:**
 - One incident occurred on July 11, 2023, with Haskin Gas Service. The incident was investigated, and a report of findings will

10

10

10

All requirements for this question were found satisfied. No loss of points.

9 Did state respond to Chairman's letter on previous evaluation within 60 days and correct 1 1 1 or address any noted deficiencies? (If necessary) Chapter 8.1 Yes = 1 No = 0 Needs Improvement = .5

Evaluator Notes:

No response was required from previous letter.

10 Did State conduct or participate in pipeline safety training session or seminar in Past 3 Info Only Info Only Years? Chapter 8.5 Info Only = No Points

Evaluator Notes:

Yes, Vermont Department of Public Service participated in the NEPSR meeting held on October 24-25, 2023, in Westbourne, Mass. The number of participants at the meeting was 176 individuals.

All requirements for this question were found satisfied. No loss of points.

11	Has state confirmed transmission operators have submitted information into NPMS	Info Only Info Only
	database along with changes made after original submission?	
	Info Only = No Points	
Evaluator	Notes:	
Yes, Y	Vermont Gas Systems, Inc. submitted their report on March 10, 2023.	

All requirements for this question were found satisfied. No loss of points.

12	Does the state have a mechanism for communicating with stakeholders - other than state pipeline safety seminar? (This should include making enforcement cases available to public).	1	1
	Yes = 1 No = 0 Needs Improvement = .5		

Evaluator Notes:

Yes, this is accomplished via their website.

All requirements for this question were found satisfied. No loss of points.

13	Did state execute appropriate follow-up actions to Safety Related Condition (SRC)	1	1	
	Reports? Chapter 6.7			
	Yes = 1 No = 0 Needs Improvement = .5			
1 4	NI			

Evaluator Notes:

No safety related condition report issued in CY2023.

All requirements for this question were found satisfied. No loss of points.

 14
 Was the State responsive to: Yes = 1 No = 0 Needs Improvement = .5
 1
 1

 a.
 Surveys or information requests from NAPSR or PHMSA; and
 5
 1
 1

 b.
 PHMSA Work Management system tasks?
 5
 5
 5

 Evaluator Notes:
 a. Yes, Program Manager has responded to NAPSR surveys.
 5
 5
 5

 b. No WMS tasks were assigned in CY2023.
 5
 5
 5
 5
 5

All requirements for this question were found satisfied. No loss of points.

Vermont
VERMONT DEPARTMENT OF PUBLIC SERVICE, Page: 11

3 17 Discussion with State on accuracy of inspection day information submitted into State 3 Inspection Day Calculation Tool (SICT). Has the state updated SICT data? Yes = 3 No = 0 Needs Improvement = 1-2 **Evaluator Notes:** Program Manager is familiar and in the process of completing this year's SICT data. He has a good understanding of the requirements. All requirements for this question were found satisfied. No loss of points. 18 Discussion on State Program Performance Metrics found on Stakeholder Communication Info Only Info Only site.\ http://primis.phmsa.dot.gov/comm/states.htm?nocache=4805 Info Only = No Points question were found satisfied. No loss of points. 19 Did the state encourage and promote operator implementation of Pipeline Safety Info Only Info Only Management Systems (PSMS), or API RP 1173? This holistic approach to improving pipeline safety includes the identification, prevention and remediation of safety hazards. Info Only = No Points

Yes, reviewed file folders on their agency's drive and found all files well organized and accessible. No areas of concern.

Vermont Gas Systems Inc. has adopted the PSMS. All requirements for this question were found satisfied. No loss of points.

1

Info Only Info Only

15 If the State has issued any waivers/special permits for any operator, has the state verified conditions of those waivers/special permits are being met? This should include having the operator amend procedures where appropriate. Yes = 1 No = 0 Needs Improvement = .5

Evaluator Notes:

16

Evaluator Notes:

No waivers/special permits were issued in CY2023.

Info Only = No Points

Were pipeline program files well-organized and accessible?

Evaluator Notes: Yes, Program Manager is familiar with the state performance metrics and has reviewed the data. All requirements for this a. https://pipelinesms.org/ b. Reference AGA recommendation to members May 20, 2019 **Evaluator Notes:** 20 Info Only Info Only General Comments: Info Only = No Points Evaluator Notes: A loss of one point occurred in this section of the review. See question D.4. Total points scored for this section: 49 Total possible points for this section: 50

- 1 Operator, Inspector, Location, Date and PHMSA Representative (enter specifics into the Info Only Info Only comments box below)
 - Info Only = No Points
 - a. What type of inspection(s) did the state inspector conduct during the field
 - portion of the state evaluation? (i.e. Standard, Construction, IMP, etc)
 - b. When was the unit inspected last?
 - c. Was pipeline operator or representative present during inspection?
 - d. Effort should be made to observe newest state inspector with least experience

Evaluator Notes:

This was a construction inspection performed at 140 Federal Street in St. Albans, VT. The operator was Vermont Gas Company. Personnel in attendance was Chris Franley and Justin White with E. Pyle Construction Company. Matt Hecklinger was the Vermont Department of Public Service Inspector being observed. Glynn Blanton, PHMSA was in attendance.

2 Did the inspector use an appropriate inspection form/checklist and was the form/checklist 2 2 used as a guide for the inspection? (New regulations shall be incorporated) Yes = 2 No = 0 Needs Improvement = 1

Evaluator Notes:

Yes, inspector was using the Vermont Department of Public Service construction inspection form and completed the items observed into the form.

All requirements for this question were found satisfied. No loss of points.

3	 Did the inspector adequately review the following during the inspection Yes = 10 No = 0 Needs Improvement = 1-9 a. Procedures (were the inspector's questions of the operator adequate to determine compliance?) b. Records (did the inspector adequately review trends and ask in-depth questions?) c. Field Activities/Facilities (did inspector ensure that procedures were being followed, including ensuring that properly calibrated equipment was used and OQ's were acceptable?) d. Other (please comment) e. Was the inspection of adequate length to properly perform the inspection? 	10	10
Evaluato			
Allı	requirements for this question were found satisfied. No loss of points.		
4 Evaluato All 1	From your observation did the inspector have adequate knowledge of the pipeline safety program and regulations? (Evaluator will document reasons if unacceptable) Yes = 2 No = 0 Needs Improvement = 1 or Notes: requirements for this question were found satisfied. No loss of points.	2	2
5	Did the inspector conduct an exit interview, including identifying probable violations? (If inspection is not totally completed the interview should be based on areas covered during time of field evaluation) Yes = $1 \text{ No} = 0 \text{ Needs Improvement} = .5$	1	1
Evaluato			
Yes.	All requirements for this question were found satisfied. No loss of points.		
6	Was inspection performed in a safe, positive, and constructive manner ? Info Only = No Points a. No unsafe acts should be performed during inspection by the state inspector	Info Only Info	o Only

b. What did the inspector observe in the field? (Narrative description of field observations and how inspector performed)

c. Best Practices to Share with Other States - (Field - could be from operator

visited or state inspector practices)

d. Other

Evaluator Notes:

All requirements for this question were found satisfied. No loss of points.

7 General Comments:

Info Only = No Points

Evaluator Notes:

No loss of points occurred in this section of the review.

Info Only Info Only

Total points scored for this section: 15 Total possible points for this section: 15

1	Has the state reviewed Operator Annual reports, along with Incident/Accident reports, for accuracy and analyzed data for trends and operator issues. Yes = 2 No = 0 Needs Improvement = 1	2	2
Evaluato			
	Vermont Department of Public Service monitors Vermont Gas System damages in a spreadsh	eet entitle	d "Data of Hits
	alls". The annual reports are posted and compared to previous years.		
All r	requirements for this question were found satisfied. No loss of points.		
2	Has the state verified that the operators analyze excavation damages for the purpose of determining root causes and minimizing the possibility of a recurrence? (192.617) Has the state verified that the operators have appropriately identified excavators who have repeatedly violated one-call laws and damaged their facilities. Have the operators taken steps to mitigate that risks? (192.1007) $Yes = 2 No = 0$ Needs Improvement = 1	2	2
Evaluato			
	requirements for this question were found satisfied. No loss of points.		
3	Has the state reviewed the operator's annual report pertaining to Part D - Excavation Damage? Yes = $4 \text{ No} = 0 \text{ Needs Improvement} = 1-3$	4	4
Evaluato All 1	 a. Is the information complete and accurate with root cause numbers? b. Has the state evaluated the causes for the damages listed under "One-Call Notification Practices Not Sufficient" (Part D.1.a.)? c. Has the state evaluated the causes for the damages listed under "Locating Practices Not Sufficient" (Part D.1.b)? For each operator, does the state review the following? d. Is the operator or its locating contractor(s) qualified and following written procedures for locating and marking facilities? e. Is the operator appropriately requalifying locators to address performance deficiencies? f. What is the number of damages resulting from mismarks? g. What is the number of damages resulting from not locating within time requirements (no-shows)? h. Is the operator appropriately addressing discovered mapping errors resulting in excavation damages? i. Are mapping corrections timely and according to written procedures? j. Has the state evaluated the causes for the damages listed under "Excavation Practices Not Sufficient" (Part D.1.c.)? r Notes: 		
4	 Has the agency or another organization within the state collected data and evaluated trends on the number of pipeline damages per 1,000 locate requests? Yes = 2 No = 0 Needs Improvement = 1 a. What stakeholder group is causing the highest number of damages to the pipelines? Operator, contractor, locating company or public. b. Has the state verified the operator is appropriately focusing damage prevention education and training to stakeholders causing the most damages? c. Has the state evaluated which of the following best describes the reason for the excavation damages; i.e., operator or contractor not following written procedures, failure to maintain marks, failure to support exposed facilities, failure to use hand tools were required, failure to test-hole (pot hole), improper backfilling practices, failure to maintain clearance or insufficient excavation practices. d. Has the state verified the operator is appropriately focusing damage prevention education and training to address the causes of excavation damages? 	2	2

Evaluator Notes:

- a. Third party contractors are the group causing the highest number of damages.
- b. Yes, training is being provided by Vermont Gas Systems and VT DPS.
- c. Yes, insufficient excavation practices best describe the reason for the excavation damages.

d. Yes.

All requirements for this question were found satisfied. No loss of points.

5 General Comments:

Info Only = No Points

Evaluator Notes:

No loss of points occurred in this section of the review.

Total points scored for this section: 10

Info Only Info Only

Total possible points for this section: 10

