



Standards and Rulemaking Division  
Pipeline and Hazardous Materials Safety Administration  
Attn: PHH-10  
US Department of Transportation  
East Building  
1200 New Jersey Avenue, SE  
Washington, DC 20590-0001

18 September 2025

Timothy J. Nuoffer  
Field Services Manager  
Codes & Standards  
Tel.: (618) 444-7628  
Timothy\_Nuoffer@hsb.com

To whom it may concern:

**Requalification and Repair of Welded UN Pressure Receptacles**

I have a couple of questions regarding the requalification and repair of welded UN pressure receptacles. It appears 49CFR180.207 and 180.211 do not address welded UN pressure receptacles, like how 180.207 and 180.212 do for seamless UN pressure receptacles. In reviewing UN Model Regulations and CSA B341, it appears that ISO 10460:2018 would be the applicable ISO standard for periodic inspection and repair of welded UN pressure receptacles. ISO 10460:2018 is not listed in 49CFR171.7.

**The Hartford Steam Boiler  
Inspection and Insurance Co.**  
One State Street  
P.O. Box 5024  
Hartford, CT 06102-5024  
[www.munichre.com/HSB](http://www.munichre.com/HSB)

**Question #1:** Are welded UN pressure receptacles required to be requalified per 49CFR180.207?

**Answer #1:** Yes.

**Question #2:** Should ISO 10460:2018 be used for the requalification and if required repair of welded UN pressure receptacles?

**Answer #2:** Yes.

A reply as soon as possible would be appreciated. Should you have additional questions or need to discuss, please call 618-444-7628.

Sincerely,

The Hartford Steam Boiler Inspection and Insurance Co.