

1200 New Jersey Avenue, SE Washington, DC 20590

U.S. Department of Transportation **Pipeline and Hazardous Materials Safety Administration** 

## 2022 Annual Civil Penalty Report

The Pipeline and Hazardous Materials Safety Administration (PHMSA) Office of Hazardous Materials Safety (OHMS) collected payment for and closed 103 enforcement cases and 188 tickets in calendar year 2022, which is summarized in the table below. These enforcement actions resulted in the collection of \$1,306,711 in civil penalties. The information provided in the annual civil penalty report includes the company name, city, and state; ticket or case number; violation summary; regulatory citation(s); and total penalty amount collected.

OHMS Field Operations personnel verify compliance with the Hazardous Materials Regulations (HMR) through a risk-based inspection program. OHMS investigators inspect companies and individuals that offer or carry hazardous materials for transportation; or manufacture, maintain, repair, recondition, or test packages authorized for transporting hazardous materials. PHMSA's Field Operations have a direct impact on public safety by identifying and acting when compliance violations are found in the nation's transportation system.

Each time an HMR violation is noted by an investigator, the regulated entity is provided with an exit briefing describing the probable violation. Investigators also provide the regulated entity with guidance on how to comply with the HMR to correct the issues and ensure the safe transportation of hazardous materials. Civil penalties are determined in accordance with PHMSA's Guidelines for Civil Penalties, which are found in Appendix A to Subpart D of Part 107 in Title 49 of the Code of Federal Regulations. Additionally, the civil penalty assessments described in this report include penalty assessment considerations based on mitigating and aggravating factors of each specific situation.

Company Name	Violation Summary	Citations	Penalty Amount
6K Additives Washington, MO Ticket #: 22T-0258-SH-CE	Failed to register as an offeror of hazardous materials and pay registration fee. Offered a hazardous material in a UN standard marked and certified packaging that had not been closed in accordance with the manufacturer's closure instructions.	107.601(a)(6); 107.608(a) & (b); 173.22(a)(4); 173.24(f)(2)	\$1,480
A.N.S. Xtreme Performance, Inc. Simi Valley, CA Case #: 21-0360-SH-WE	Offered UN0507, Signals, Smoke, 1.4S without shipping papers, package markings, and labels. Failed to provide initial general awareness, function-specific, safety, and security awareness training. Offered UN0507, Signals, Smoke, 1.4S in an unauthorized non- UN standard or non-specification packaging.	172.200(a); 172.300(a); 172.301(a)(1); 172.400(a)(1); 172.411(c); 172.702(a), (b) & (d); 172.704(a)(1), (2), (3), (4), & (c)(1); 172.101(l)(2); 173.1(b); 173.22(a)(1) & (a)(2)(i); 173.24(c)(1)(i); 173.62(a), (b), & (c)	\$16,620
Ability Refrigerants Grand Prairie, TX Ticket #: 22T-0183-HM-SW	Failed to provide general awareness, function- specific, and security awareness training. Failed to register as an offeror of hazardous materials and pay registration fee.	172.702(b); 172.704(a)(1), (2), (3), & (4); 107.601(a); 107.608(b); 172.504(c)	\$1,920
Ability Refrigerants Phoenix, AZ Ticket #:	Failed to provide recurrent general awareness, function-specific, safety, and security awareness training.	172.702(a); 172.704(a)(1), (2), (3), (4), & (c)(2)	\$2,000
22T-0199-SH-SO ACE Welding Supply, Inc. Tampa, FL	Failed to provide recurrent general awareness, function-specific, safety, and security awareness training.	172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(2)	\$5,000
Case #: 22T-0025-SH-SO ACL, Inc. Chicago, IL Ticket #: 22T-0240-SH-EA	Offered hazardous materials in UN standard packaging when the packaging had not been closed in accordance with manufacturer's closure instructions. Offered a hazardous material without properly marking the packages with the proper sized identification number.	173.22(a)(4); 173.24(f)(2); 172.300(a); 172.301(a)	\$2,000
Advance Paving and Construction Co., Inc. Fisherville, KY Ticket #: 22T-0095-SH-CE	Failed to provide initial in-depth security training and failed to maintain records. Failed to retain shipping papers.	172.702(a) & (b); 172.704(a), (2), & (5); 172.201€	\$3,240

Company Name	Violation Summary	Citations	Penalty Amount
American Water Treatment, Inc. St Louis, MO Case #: 22-0045-SH-CE	Failed to register as an offeror of hazardous materials and pay registration fee. Failed to maintain training records. Offered a hazardous material, when the shipping paper failed to follow an approved format for listing hazardous materials on a shipping paper— namely, leaving off a secondary hazard class for both a PG II and a PG III. Offered a hazardous material that was misclassified on the shipping paper. Offered a hazardous material in an improper package, reused a package not authorized for reuse, and failed to conduct leakproofness test or properly mark the package as retested. Offered hazardous materials, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Failed to label a package or apply a label that represents a hazard other than the hazard	107.601(a)(6); 107.608(a) & (b); 172.704(d); 172.202(a)(3); 172.200(a); 172.201(a); 173.28(b)(2) & (4); 178.604; 173.22(a)(4); 173.24(f)(2); 172.400	\$10,350
AMP Services, LLC, d/b/a, IceCold.US Granite Falls, NC	presented by the hazardous material in the package. Failed to provide initial general awareness, function-specific, safety, and security awareness training.	172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(1)	\$4,400
Case #: 21-0285-SH-SO			
Aqua Ventures LTD, dba Scuba Emporium Orland Park, IL Case #: 20-0151-CR-CE	Represented, certified, and marked DOT specification cylinders as having been successfully retested in accordance with the HMR when the accuracy of the pressure indicating device within the test system could not be demonstrated at any point within 500 psi of the actual test pressure for test pressures at or above 3000 psi. Failed to keep complete accurate records of cylinder reinspection and retest. Failed to properly mark the cylinder. Failed to properly mark the	180.205(g)(3)(i); 180.215(b); 180.213(b) & (d)	\$6,226
Aero Metal Finishing, LLC Fenton, MO	RIN or retest date on a cylinder. Offered hazardous materials, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.22(a)(4); 173.24(f)(2)	\$720
Ticket #: 22T-0262-SH-CE			
Agrisel USA, Inc. Suwanee, GA Ticket #: 22T-0169-SH-SO	Failed to provide general awareness, function- specific, safety, and security awareness training.	172.702(a); 172.704(a)(1), (2), (3), (4), & (c)(1)	\$1,600

Company Name	Violation Summary	Citations	Penalty
			Amount
Airosol Company,	Failed to maintain training records. Offered a	172.704(d); 172.200(a);	\$800
nc.	hazardous material, while including an	172.202(a)	
Neodesha, KS	improper subsidiary hazard class in the proper shipping description on a shipping paper.		
Ticket #:			
22T-0224-SH-CE			
Aisin Manufacturing	Offered hazardous materials, while failing to	173.22(a)(4); 173.24(c)(1) &	\$3,240
llinois, LLC	close a UN standard packaging in accordance	(f)(2); 178.503(a)	
Marion, IL	with the manufacturer's closure instructions. Offered a hazardous material in UN certified		
Ficket #:			
22T-0114-SH-CE	1A1 drums when the manufacturers UN		
221-0114-3H-CE	performance standard markings were partially		
	covered by the product information label,		
	while failing to render the manufacturers		
Alan Environmental	marking as readily visible.	172 704(d)	\$540
	Failed to maintain training records.	172.704(d)	Ş54U
Products			
Maryland Heights,			
MO			
Ticket #:			
22T-0260-SH-CE			
All Seasons	Transported hazardous material when an	172.604(a); 172.704(a)(1),	\$4,350
Commercial Systems,	emergency response telephone number was	(2), (3), & (4); 172.202(b)	
nc.	not present on the hazardous material		
Westbury, NY	shipping paper. Failed to provide hazardous		
	material training. Failed to include a shipping		
Ticket #:	description on the shipping paper in required		
22T-0211-SH-EA	sequence.		44.425.22
American Packing &	Failed to provide general awareness, function-	172.702(a) & (b);	\$4,425.82
Crating of Virginia,	specific, safety, and security awareness	172.704(a)(1), (2), (3), (4) &	
LC	training.	(c)(1)	
Savannah, GA			
Ticket #:			
21T-0073-SH-SO			
American Scientific,	Offered a hazardous material, while failing to	173.1(b); 173.22(a) &	\$2,480
nc.	close a UN standard packaging in accordance	(a)(4)(i); 173.24(a) & (f);	. ,
Portland, OR	with the manufacturer's closure instructions.	107.601(a)(6), 107.608(b);	
,	Failed to register as an offeror of hazardous	107.612; 172.504;	
Ticket #:	materials and pay registration fee. Failed to	172.702(a) & (b);	
22T-0019-SH-WE	provide recurrent general awareness,	172.704(a)(2), (c)(2), & (d)	
	function-specific, safety, and security		
	awareness training. Failed to maintain training		
	records.		

Company Name	Violation Summary	Citations	Penalty Amount
Amerisan, LLC Souderton, PA Ticket #: 22T-0093-SH-EA	Failed to register as an offeror of hazardous materials and pay registration fee. Failed to provide initial general awareness, function- specific, safety, and security awareness training. Failed to follow an approved format for listing hazardous materials on a shipping paper.	107.601(a)(6); 107.608(a) & (b); 172.702(a); 172.201(a)(4); 172.202(a)(1); 172.204(d)	\$3,120
Armor Shield, Inc. Falmouth, KY Case #: 22-0008-SH-SO	Offered a hazardous material that released a portion of its contents with hazardous material residue evident on the outside of the package. Offered hazardous materials while failing to ensure the packages and overpack were marked and labeled with the prescribed information listed. Offered a hazardous material while failing to properly package the hazardous material in authorized UN performance-oriented packaging. Failed to provide hazardous material training.	173.24(b)(1), (2), (4), & (c); 172.301(a); 172.400(a)(1); 173.25(a)(2) & (4); 173.22(a)(2); 173.173(b); 173.203; 173.225; 172.702; 172.704(c)(1), (2), & (d)	\$1,000
Arrowstar, LLC Dalton, GA Ticket #: 22T-0037-SH-SO	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	172.702(a); 172.704(a)(1), (2), (3), (4) & (c)(1); 173.22(a)(4); 173.24(b) & (f)(2)	\$3,040
Austin Powder Company, Inc. McArthur, OH Case #: 21-0404-SH-EA	Filled and offered a hazardous material in UN standard packaging when the material exceeds the package's marked gross mass. Offered and transported an unapproved explosive that minimally deviates from an approved design in a manner that does not impact safety. Offered hazardous materials in UN standard packages when the packages had not been closed in accordance with the package qualification test closure method. Offered a hazardous material while failing to label the package with required labels of the specified color.	173.22(a)(2) & (4); 173.24a(b)(2) & (f)(2); 173.21(b); 173.54(a); 173.56(b); 172.400(a); 172.407(d)	\$11,175
Auto-Chlor Systems Atlanta, GA Ticket #: 22T-0198-SH-SO	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.22(a)(4)(i); 173.24(f)(2)	\$1,440
Auto-Chlor Systems Tyler, TX Ticket #: 22T-0235-SH-SW	Failed to provide function-specific and safety training.	172.702(b); 172.704(a) (2) & (3)	\$800

Company Name	Violation Summary	Citations	Penalty Amount
AutoZone, Inc. Distribution Center Terrell, TX Ticket #: 22T-0082-FF-SW	Failed to provide security awareness training. Failed to maintain training records. Offered and transported hazardous materials accompanied by shipping papers, while failing to list the type of packages.	172.702(b); 172.704(a)(4), (d)(4), & (5); 172.202(a)(7)	\$1,085
AutoZone, Inc. Store #5852 Terrell, TX	Failed to provide general awareness, function- specific, and security awareness training. Failed to retain shipping papers.	172.702(b); 172.704(a)(1), (2), & (4); 172.201(e)	\$2,730
Ticket #: 22T-0081-HM-SW			
Avery Dennison Mount Juliet, TN	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.22(a)(4)(i); 173.24(f)(2); 172.300(a); 172.301(a)(1); 172.315(a); 172.704(d)	\$2,320
Ticket #: 22T-0127-SH-CE	Offered a hazardous material, while failing to utilize the proper size mark on the package. Offered a hazardous material, while failing to mark the package with a limited quantity marking. Failed to maintain training records.		
Bastech, LLC Jacksonville, FL	Failed to register as an offeror of hazardous materials and pay registration fee.	107.601(a)(6); 107.608(a) & (b)	\$480
Ticket #: 22T-0200-SH-SO			
Beckat Oil & Fuel, LP Tyler, TX	Failed to provide recurrent general awareness, function-specific, safety, security, and in-depth security training.	172.702(b), 172.704(a)(1), (2), (3), (4), (5), & (c)(2)	\$2,000
Ticket #: 22T-0161-SH-SW			
Beckman Coulter, Inc. Hebron, KY	Offered a hazardous material in a UN certified 4G box without shipping papers, markings, and labels.	172.200; 172.300; 172.400	\$7,500
Case #: 22-0175-SH-CE			

Company Name	Violation Summary	Citations	Penalty
			Amount
Bellman Oil Co. Bremen, IN Case #: 22-0137-SH-EA	Failed to remove an intermediate bulk container (IBC) from a transport motor vehicle prior to discharging hazardous materials. Offered and transported hazardous materials for transportation in commerce in an IBC while failing to mark the UN identification number of the hazardous material on the motor vehicle. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Offered hazardous materials, while failing to include an authorized emergency response telephone number on a shipping paper. Offered hazardous materials, while failing to label the package with a primary hazard label of at least 100 millimeters in size. Offered a hazardous material, while failing to include the proper identification number in the proper shipping	177.801; 177.834(h); 172.302(a); 172.331(c); 172.332; 173.22(a)(4); 172.201(d); 172.604(a); 172.400(a); 172.407(c); 172.200(a); 172.202(a)(1)	\$8,160
Benjamin Moore	description on shipping papers. Offered a hazardous material, while failing to	173.22(a)(4)(i); 173.24(f)(2)	\$1,200
Paint Pell City, AL Ticket #:	close a UN standard packaging in accordance with the manufacturer's closure instructions.	1, 5.22(0)(+)(1), 1, 5.24(1)(2)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
22T-0017-SH-SO			4
Bisco Industries, Inc. Anaheim, CA Ticket #: 22T-0141-SH-WE	Failed to register as an offeror of hazardous materials and pay registration fee. Failed to create and maintain training records.	107.601(a)(6); 107.608(a) & (b); 107.612(a); 172.504; 172.702(a), (4), & (b); 172.704(d); 177.800(c)	\$975
Bison Cooperative Association Bison, OK Case #: 22-0047-SH-SW	Offered and transported a hazardous material in a UN standard IBC, without labeling the IBC with the required hazard class warning label on opposing sides. Offered and transported a hazardous material, without creating hazardous material shipping papers. Offered and transported a hazardous material contained in a UN standard IBC that was on a trailer and discharging the hazardous material from the IBC without removing the IBC from the trailer. Offered and transported a hazardous material in a UN standard IBC without a visible identification number marking, and without marking the identification number on the transport vehicle on each side and each end.	172.400(a)(2); 172.514(c)(4); 172.200(a); 177.817(a); 177.834(h); 172.331(c)	\$7,200

Company Name	Violation Summary	Citations	Penalty
			Amount
BKC Industries, Inc. Creedmoor, NC	Failed to provide general awareness, function- specific, and security awareness training.	172.702(a); 172.704(a)(1), (2), (4), & (c)(2)	\$1,200
Ticket #: 22T-0245-CR-SO			
Black Hills	Failed to put the security plan in writing to	172.800(b); 172.802(b) &	\$2,320
Ammunition, Inc.	develop a complete security plan. Failed to list	(c); 172.201(d); 172.604(a)	<i>42,32</i> 0
Rapid City, SD	an emergency response telephone number in the shipping paper that is monitored 24 hours	& (b); 107.601(a)(6); 107.608(a) & (b)	
Ticket #:	a day. Failed to register as an offeror of		
22T-0217-SH-CE	hazardous material and pay registration fee.		
BLT Tanks, LLC Kingfisher, OK Ticket #:	Failed to provide general awareness, function- specific, and security awareness training. Failed to create and maintain training records. Failed to mark, placard, or label a bulk	172.702(b); 172.704(a)(1), (2), (4), & (d); 172.302(a); 172.331; 172.332; 172.336(a) & (d); 172.400;	\$2,600
22T-0128-HM-SW	packaging.	172.500; 172.514(c)(3)	\$1,000
Blue Grass Chemical	Failed to provide function-specific training.	172.702(a); 172.704(a)(2) &	\$1,000
Specialties, LLC New Albany, IN	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	(d); 173.22(a)(4); 173.24(f)(2)	
Ticket #:			
22T-0113-SH-CE			
Blue Ribbon	Offered a hazardous material, while failing to	173.22(a)(4)(i); 173.24(f)(2);	\$2,360
Products, Inc.	close a UN standard packaging in accordance	107.601(a)(6); 107.608(a),	
Indianapolis, IN	with the manufacturer's closure instructions.	(b); 107.612(b) & (c)(1);	
	Failed to register as an offeror of hazardous	172.300(a); 172.301(a)(1);	
Ticket #:	materials and pay registration fee. Failed to	172.200(a), 172.202(a) & (b)	
22T-0069-SH-CE	mark the package with the correct size identification number. Offered hazardous materials accompanied by shipping papers, while failing to list the hazardous materials in proper sequence		
Bradley Industrial	proper sequence. Failed to register as an offeror of hazardous	107.601(a)(6); 107.608(a) &	\$4,275
Chemicals	materials and pay registration fee. Failed to	(b); 172.504(c)(1);	Ş <del>4</del> ,275
Madison, TN	provide general awareness, function-specific, safety, and security awareness training.	(1), 172.304(c)(1), 172.702(a); 172.704(a)(1), (2), (3), (4), & (d);	
Case #:	Offered a hazardous material, while failing to	173.22(a)(4); 173.24(f)(2)	
22-0142-SH-CE	close a UN standard packaging in accordance with the manufacturer's closure instructions.		
Bravo Wireline, LLC	Failed to provide recurrent general	172.702(b); 172.704(a) (1),	\$2,000
Midland, TX	awareness, function-specific, safety, security awareness, and in-depth security training.	(2), (3), (4), (5), & (c)(2)	
Ticket #:			
22T-0139-SH-SW			

Company Name	Violation Summary	Citations	Penalty
			Amount
Breakwater	Represented, marked, and certified DOT	180.209(a)(1); 180.205(c);	\$2,965
International Texas,	specification 3AL cylinders as having been	DOT-SP 10915;	
LLC	successfully requalified in accordance with the	180.215(b)(2)	
Houston, TX	HMR, while failing to perform hydro-static		
	testing at the minimum of 5/3 times the		
Ticket #:	service pressure. Failed to perform		
22T-0145-CR-SW	requalifications as prescribed by the		
	applicable DOT special permit. Failed to		
	maintain the prescribed information on a		
	record for each cylinder requalified or visually		
	inspected.		
Brenntag Mid-South,	Represented and offered a UN certified IBC	178.813€; 180.2(a);	\$4,000
Inc.	that had not been properly tested and	180.3(a); 180.352(a) &	
Indianapolis, IN	inspected. Offered a hazardous material,	(b)(1); 173.22(a)(4)(i);	
	while failing to close a UN standard packaging	173.24(f)(2)	
Ticket #:	in accordance with the manufacturer's closure		
22T-0071-SH-CE	instructions.		
Brenntag Southwest,	Failed to provide security awareness and in-	172.702(b); 172.704(a)(4) &	\$1,772.53
Inc.	depth security training. Offered and	(5); 172.800(b)(9);	
Elmendorf, TX	transported hazardous material requiring a	172.802(a) & (c)	
,	security plan which failed to include a written	(-) (-)	
Ticket #:	risk assessment.		
21T-0278-CA-SW			
Brenntag Mid-South,	Offered a hazardous material in UN certified	172.402(a)(1); 173.24(c)(1);	\$2,820
Inc.	containers without a subsidiary hazard class	178.703(a)(1); 172.704(d)(5)	+=)==0
Louisville, KY	label. Offered for transportation a hazardous	1,0,,00(0)(1), 1,2,,0 (0)(0)	
	material, in UN certified IBC when the		
Ticket #:	manufacturers UN performance standard		
22T-0119-SH-CE	markings were partially covered by the		
221-0113-311-CL	product information label, thereby failing to		
	render the manufacturers marking as "durable		
	and clearly visible". Failed to not contain the		
	required certification statement in training		
Broadway	records. Represented, manufactured, marked, and	178.2(a) & (b); 178.801(a),	\$10,040
Containers,	offered UN standard IBCs, while failing to	(b), & (e); 178.813(c);	Ş10,040
Hacienda Heights, CA	conduct periodic design qualification testing.		
nacienua Heights, CA		180.352; 178.2(a) & (b);	
Casa #:	Represented, marked, certified, and offered	178.703(a)1) & (b);	
Case #:	UN standard packaging, while failing to	180.352(b)(2)(i), (e) & (f);	
22-0099-PM-WE	properly test and inspect the packaging.	172.702(a) & (b);	
	Represented, manufactured, marked, and	172.704(a)(1), (2), (3), (4), &	
	offered UN standard IBCs, while failing to	(d)	
	ensure the packaging contained correct		
	specification and routine maintenance		
	markings. Failed to create and maintain		
	training records.		

Amount \$8,790 (3);
; (3);
3);
'(a) & \$950
02(a);
\$240
\$480
54(a); \$9,375
\$440
÷ · · •
)1(a) \$2,160
-(w) 92,200

Company Name	Violation Summary	Citations	Penalty
			Amount
Chemetall, US	Represented and offered a UN certified	173.22(a); 173.24(c);	\$2,440
lackson, MI	packaging, while the UN Standard marking	178.2(b); 178.3(a) & (b);	
	had been obliterated rendering it an	172.704(d); 172.101(b)(4);	
Ficket #:	unauthorized packaging. Failed to maintain	172.200(a); 172.203(k)	
22T-0215-SH-CE	training records. Failed to include the		
	technical name in parentheses for a listed		
	generic or "N.O.S." material.		
Chemex Paints	Failed to provide initial general awareness and	172.702(a); 172.704(a)(1),	\$1,200
Гатра, FL	security awareness training.	(2), (4), & (c)(1)	
Ticket #:			
22T-0016-SH-SO			
Chemical Marketing	Offered a hazardous material in an	173.22(a)(2); 173.24(c)(l);	\$6,975
Corporation of	unauthorized non-UN standard packaging	173.202; 172.704(d)	
America	when UN standard specification packaging is		
Blaine, MN	prescribed. Failed to create and maintain		
	training records.		
Case #:			
21-0116-SH-CE			
Chemisphere	Offered a hazardous material, while failing to	173.22(a)(4); 173.24(f)(2) &	\$2,080
Corporation	close a UN standard packaging in accordance	(c)(1); 178.703(a)(1);	
St Louis, MO	with the manufacturer's closure instructions.	172.203(c)	
	Failed to render the manufacturers marking as		
Ticket #:	"durable and clearly visible". Failed to include		
22T-0155-SH-CE	on a shipping paper, as required, "RQ" for a		
	hazardous substance.		
Chemtron Supply	Offered a hazardous material, while failing to	173.22(a)(4)(ii); 173.24(f)(2)	\$800
Corporation	close a UN standard packaging in accordance		
st. Charles, MO	with the manufacturer's closure instructions.		
, -			
Ficket #:			
22T-0123-SH-CE			
Cintas Corporation	Failed to provide hazardous materials shipping	172.200; 172.202; 172.604	\$1,480
No. 2	papers, including failing to provide an		
Rockford, TN	emergency response telephone number.		
Ticket #:			
22T-0201-SH-SO			
Clean Harbors	Offered a hazardous material, while failing to	173.22(a)(4); 173.24(b) &	\$1,440
Environmental	close a UN standard packaging in accordance	(f)(2)	
Services, Inc.	with the manufacturer's closure instructions.		
Reidsville, NC			
Ticket #:			
22T-0107-SH-SO			

Violation Summary	Citations	Penalty Amount
Failed to properly conduct testing for UN standard packaging.	178.601(b)	\$2,800
Failed to provide general awareness, function- specific, safety, security awareness, and in- depth security training.	172.702(b); 172.704(a)(1), (2), (3), (4), & (5)	\$2,000
Offered hazardous materials, without declaring the shipments as a hazardous material by providing proper shipping papers, package markings, package labels, and compliance with emergency response requirements.	172.200(a); 172.300(a); 172.400(a); 172.600(c); 173.1(b); 173.22(a)(1) & (2)	\$18,750
Represented and certified UN standard 55- gallon drum (1H1 & 1H2) as meeting the requirements of the Hazardous Materials Regulations, when the drums were not	173.28(a); 173.28(b)(4); 178.503(a)(9); 180.2; 180.352(g)	\$880
marked with the minimum thickness. Represented and certified UN standard IBCs as meeting the requirements of the HMR, when records of periodic retest and inspection failed to include the specific address of test and inspection facility, names or name of any person conducting test or inspections, and test or inspection results.		
Failed to provide general awareness, function- specific, safety, and security awareness training.	172.702(b); 172.704(a)(1), (2), (3) & (4)	\$1,600
Failed to register as an offeror of hazardous materials and pay registration fee. Failed to provide general awareness, function-specific, safety, and security awareness training.	107.601(a)(6); 107.608(a) & (b); 172.702(a); 172.704(a)(1), (2), (3), (4) & (c)(2)	\$2,080
Offered UN3480, lithium-ion batteries, 9, and UN3481, lithium-ion batteries contained in equipment, 9, in unauthorized packaging. Offered hazardous materials while failing to create shipping papers.	173.185(f); 172.201(d); 172.202(a)	\$16,200
	Failed to properly conduct testing for UN standard packaging.         Failed to provide general awareness, function-specific, safety, security awareness, and indepth security training.         Offered hazardous materials, without declaring the shipments as a hazardous material by providing proper shipping papers, package markings, package labels, and compliance with emergency response requirements.         Represented and certified UN standard 55-gallon drum (1H1 & 1H2) as meeting the requirements of the Hazardous Materials Regulations, when the drums were not marked with the minimum thickness.         Represented and certified UN standard IBCs as meeting the requirements of the HMR, when records of periodic retest and inspection failed to include the specific address of test and inspection facility, names or name of any person conducting test or inspections, and test or inspection results.         Failed to register as an offeror of hazardous materials and pay registration fee. Failed to provide general awareness, function-specific, safety, and security awareness training.         Offered UN3480, lithium-ion batteries, 9, and UN3481, lithium-ion batteries contained in equipment, 9, in unauthorized packaging.	Failed to properly conduct testing for UN standard packaging.178.601(b)Failed to provide general awareness, function- specific, safety, security awareness, and in- depth security training.172.702(b); 172.704(a)(1), (2), (3), (4), & (5)Offered hazardous materials, without declaring the shipments as a hazardous material by providing proper shipping papers, package markings, package labels, and compliance with emergency response requirements.172.200(a); 172.300(a); 172.400(a); 172.600(c); 173.1(b); 173.22(a)(1) & (2) 173.1(b); 173.22(a)(1) & (2) 173.1(b); 173.22(a)(1) & (2) 173.1(b); 173.22(a)(1) & (2) 178.503(a)(9); 180.2; 180.352(g)Represented and certified UN standard 55- gallon drum (1H1 & 1H2) as meeting the requirements of the Hazardous Materials Reguetations, when the drums were not marked with the minimum thickness. Represented and certified UN standard IBCs as meeting the requirements of the HMR, when records of periodic retest and inspection failed to include the specific address of test and inspection faulty, names or name of any person conducting test or inspections, and test or inspection results.172.702(b); 172.704(a)(1), (2), (3) & (4)Failed to register as an offeror of hazardous materials and pay registration fee. Failed to provide general awareness, function-specific, safety, and security awareness training.107.601(a)(6); 107.608(a) & (b); 172.704(a)(1), (2), (3), (4) & (c)(2)Offered UN3480, lithium-ion batteries, 9, and UN3481, lithium-ion batteries, 9, and Guipment, 9, in unauthorized packaging. Offered hazardous materials while failing to173.185(f); 172.201(d); 172.202(a)

Company Name	Violation Summary	Citations	Penalty
			Amount
CTI Industrial Supply,	Failed to provide recurrent general	172.702(a) & (b);	\$2,000
	awareness, function-specific, safety, and	172.704(a)(1), (2), (3), (4), &	
Las Vegas, NV	security awareness training.	(c)(2)	
Ticket #:			
22T-0129-SH-WE			
Cummings	Offered a hazardous material, while failing to	173.22(a)(4)(i); 173.24(f)(2)	\$1,000
Investment Bankers,	close a UN standard packaging in accordance		
Inc.	with the manufacturer's closure instructions.		
Houston, TX	Failed to maintain training records.		
Ticket #:			
22T-0084-SH-SW			
Custom Industrial	Failed to provide initial and recurrent general	172.702(b); 172.704(c)(1)(ii)	\$1,600
Coatings	awareness, function-specific, safety, and	& (2)	
McKinney, TX	security awareness training.		
Ticket #:			
22T-0050-CA-SW			
D & D Industrial	Failed to provide general awareness, function-	172.702(b); 172.704(a)(1),	\$1,600
Welding Supply, Inc.	specific, safety, and security awareness	(2), (3), (4), & (c)(2)	
Kilgore, TX	training.		
Ticket #:			
21T-0408-SH-SW			
Dart Advantage	Failed to provide initial hazardous materials	172.702(a); 172.704(a)(1),	\$1,600
Warehousing	general awareness, function-specific, safety,	(2), (3), (4) & (c)(1)	
Buford, GA	and security awareness training.		
Ticket #:			
22T-0244-SH-SO			
Deep South	Offered and transported a hazardous material	172.200; 172.300;	\$750
Fireworks	while failing to properly declare the hazardous	172.315(a); 172.400	
Hawkinsville, GA	material with shipping papers, package		
c "	marking, and package labeling.		
Case #:			
22-0131-HM-SO	Failed to register as an offerer of becord and	107 601/0/(6): 107 600/2)	¢ 9 9 0
Del Corona &	Failed to register as an offeror of hazardous	107.601(a)(6); 107.608(a);	\$880
Scardigli USA, Inc. Franklin Bark, II	materials and pay registration fee. Offered a	(b); $107.612(b) \& (c)(1);$ 172.400(c) & (b): 172.406(c)	
Franklin Park, IL	hazardous material, while placing labels on	172.400(a) & (b); 172.406(a)	
Tickot #:	the package that did not contrast with the background color.	& (d); 173.25(a)(2)	
Ticket #: 22T-0112-SH-CE			
221-0112-3U-CE			

Company Name	Violation Summary	Citations	Penalty Amount
Diken International, LLC Richland Hills, TX Ticket #: 22T-0192-SH-SW	Failed to register as an offeror of hazardous materials and pay registration fee. Failed to mark the proper shipping name on the package. Offered hazardous materials, while failing to label non-bulk packages with hazard class labels not meeting the minimum size requirements and containing unauthorized label modifications. Failed to list the correct packing group and contained additional information interspersed within the basic description on the shipping paper.	107.601(a); 107.608(b); 172.504(c); 172.301(a)(1); 172.407(c); 172.426; 172.442; 172.201(a)(4); 172.202(a)(4); 172.202(b)	\$2,120
Disco, Inc. McDonough, GA Ticket #: 22T-0170-SH-SO	description on the shipping paper.Offered a hazardous material in an unauthorized non-UN specification packaging when specification packaging is prescribed.Failed to register as an offeror of hazardous materials and pay registration fee. Failed to include the required shipper's certification on a shipping paper. Failed to follow an approved format for listing hazardous materials on a shipping paper. Offered a hazardous material, while listing an emergency response telephone number on a shipping paper that causes emergency responders delay in obtaining emergency response information.Failed to provide general awareness, function- specific, safety, and security awareness training.	173.22(a)(2); 173.24(c); 173.202(a); 173.211; 107.601(a)(6); 107.608(a) & (b); 172.204; 172.201(a)(1); 172.604(b)(2); 172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(1)	\$7,440
Dixie Products, Inc. Cartersville, GA Ticket #:	Failed to provide recurrent hazardous materials general awareness, safety, and security awareness training.	172.702(a); 172.704(a)(1), (3), (4), & (c)(2)	\$1,200
22T-0166-SH-SO DM Diving, Inc. Sand City, CA Case #: 21-0211-CR-WE	Represented, marked, and certified a DOT specification cylinder as having been successfully requalified while failing to comply with eddy current examination requirements for DOT 3AL cylinders manufactured of aluminum alloy 6351-T6. Represented, certified, marked, and offered DOT specification packages while failing to notify of any change in facility name, address, ownership, management, equipment, or testing personnel within 20 days of change. Represented, marked, and certified a DOT specification cylinder as having been successfully requalified while failing to keep complete and accurate records of cylinder reinspection and retest, specifically, failure to keep accurate test records.	180.2; 180.3(a); 180.205(f)(4) & (g); 180.209(m); Appendix C to Part 180; 180.215(b)(2)	\$5,250

Company Name	Violation Summary	Citations	Penalty Amount
DMJ Solutions Fire Protection Plus Little Ferry, NJ	Failed to keep complete accurate records of cylinder reinspection and retest. Failed to maintain current copies of HMR and Compressed Gas Association (CGA) pamphlets	180.215(a)(6) & (b); 107.805(g)	\$5,520
Case #: 21-0293-CR-EA	applicable to inspection, retesting, and marking activities. Failed to notify within 20 days of a change in personnel performing a requalifying function.		
Dora Industries, Inc., dba Gold Coast Chemical Products Medley, FL Case #:	Offered a hazardous material in non-UN certified poly pails. Offered and transported a hazardous material in a non-bulk package, while failing to mark the package with a correctly sized identification number.	173.22(a)(2); 173.202(a)(c); 173.203(a)(c); 173.213(a)(c); 172.301(a)	\$1,000
22-0022-PM-SO			
Dru-Chem, Inc. El Campo, TX Ticket #:	Offered and transported hazardous materials, accompanied by shipping papers with hazmat shipping descriptions that are incorrect, incomplete, out of order, or missing type of	172.200(a); 172.202(a)(1), (2), (7), & (b)	\$640
22T-0066-SH-SW Dyno Nobel, Inc.	package. Failed to include the required technical name	172.101(b)(4); 172.203(k);	\$640
Olin, NC Ticket #:	in parenthesis for a listed generic or "N.O.S." material on the shipping paper. Offered a hazardous material, "UN3099, oxidizing liquid,	172.202(a)(3) & (4)	\$640
22T-0009-SH-SO	toxic, N.O.S. (sodium nitrite, calcium nitrate) RQ, PG III" accompanied by a shipping paper which did not include a subsidiary risk and contained the wrong packing group.		
Eclectic Products, LLC Pineville, LA	Offered a hazardous material without properly labeling the package with a primary hazard label. Failed to mark the proper	172.400(a); 172.406(a); 172.419; 172.300(a); 172.301(a)	\$4,000
Ticket #: 22T-0204-SH-SO	shipping name and UN-identification number on the package.		
Elkay Greensboro, NC Ticket #:	Offered waste aerosol receptacles intended for recycling, which failed to remove the valve stem from the aerosol or secure the aerosol with a cap to protect the valve stem.	173.306(k)(ii)	\$1,000
22T-0246-PM-SO			
EKC Technology, Inc. Hayward, CA	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.1(b); 173.22(a)(1), (2), & (a)(4)(i); 173.24(a) & (f)(2)	\$400
Ticket #: 21T-0402-PM-WE			
Electronic Recyclers International, Inc. Fresno, CA	Offered "UN3480, lithium-ion batteries including lithium-ion polymer batteries, 9," while failing to prepare batteries to prevent damage in transit. Offered a hazardous	173.21(c); Special Permit 16532; 173.1(b); 173.22(a)(1), (2), & (4); 173.24(a), (b), (c), & (f);	\$9,000
Case #: 22-0054-HMI-WE	material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.185(b)(1), (2), & (3), (c), (d), & (f)	

Company Name	Violation Summary	Citations	Penalty Amount
Elementis Specialties, Inc. St. Louis, MO	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.22(a)(4); 173.24(f)(2)	\$500
Ticket #: 22T-0053-SH-CE			
Elite Crete Systems, Florida, Inc. Cape Coral, FL Case #: 21-0318-SH-SO	Offered hazardous materials packaged in non- UN Standard packaging when UN Standard packaging was required, and one UN Standard packaging that was an unauthorized design. Offered hazardous materials accompanied by shipping papers with an incorrect shipping description that changes the response information. Offered hazardous materials, some packaged in non-bulk UN Standard packaging without an identification number, others with incorrect size identification number markings, and with insufficient orientation markings for liquid hazardous materials in combination packaging. Failed to provide initial general awareness, function- specific, safety, and security awareness	173.22(a)(2); 173.24(c)(1); 173.1(b); 173.150; 173.154(b)(1); 173.202(b) & (c); 172.200(a); 172.202(a)(1), (2), (3), & (4); 172.300(a); 172.301(a)(1); 172.312(a)(2); 172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(1)	\$15,319
Encore Plastics PKG Purchase Greenville, SC Case #: 22-0021-PM-SO 22-0100-PM-SO	training. Manufactured, marked, certified, and sold Composite IBCs as meeting the "UN31HA1" standard, when packages were not capable of passing the vibration or hydrostatic pressure tests. Represented, marked, and certified composite IBCs, marked as "UN31HA1," and plastic drums, marked as "UN31HA1," and plastic drums, marked as "UN1H2W/Y200/S/21/USA/M6076," while failing to properly prepare and conduct periodic retesting. Failed to properly prepare and maintain records of performance- oriented packaging tests. Represented, marked, and certified plastic drums as "UN1H2W/Y200/S/21/USA/M6076," in compliance with Competent Authority Approval (CAA) requirements under an expired approval. Represented, marked, and certified plastic drums as "UN1H2W/Y200/S/21/USA/M6076," while failing to notify each person of consistent and repeatable means of closure. Represented, marked, certified, and sold solid composite IBCs, marked as "UN31HA1," while failing to restore original performance markings to composite IBCs subjected to routine maintenance.	178.2(b); 178.801(b) & (e); 178.814; 178.819; 178.3(b); 178.601(e); 178.602; 178.2(b)(1) & (2); 178.601(l); 178.801(l); 178.509(b); 178.601(h); CA2012050004; Sections 5.1 & 5.2; 178.2(c)(1)(i)(B); 178.703; 180.350(c); 180.352(b)(2)(i)	\$25,050

Company Name	Violation Summary	Citations	Penalty
			Amount
Environmental	Offered a hazardous material when the	173.21(c); 173.159;	\$38,250
Restoration, LLC	lithium batteries have not been protected	173.185(b)(2)(i), (ii), (iii),	
Mt. Horeb, WI	against short circuit, movement within the	(f)(1), (2), (3), & (4);	
	package, or accidental activation of	172.101; 172.400; 172.447;	
Case #:	equipment. Offered a hazardous material,	173.22(a)(4)(i) & (ii);	
20-0327-SH-CE	while failing to label the package. Offered for	173.24(f)(2); 172.702(a);	
	a hazardous material in a UN standard marked	172.704(a)(1), (2), (3), (4), &	
	and certified packaging that had not been	(d); 177.834(a)	
	closed in accordance with the manufacturer's		
	closure instructions and where a copy of the		
	manufacturer's notification, including closure		
	instructions was not retained. Failed to		
	provide initial function-specific, safety, and		
	security awareness training. Offered a		
	hazardous material, when the damaged		
	lithium batteries have not been placed in non-		
	metallic inner packagings that completely		
	enclose the cells or batteries or surrounded by		
	cushioning material that is non-combustible,		
	non-conductive, and absorbent, and were		
	transported in an unauthorized inner package.		
	Offered a hazardous material, while failing to		
	mark the package with "damaged/defective		
	lithium-ion battery" mark. Offered hazardous		
	material while failing to secure against		
	shifting, including relative motion between		
	packages, within the vehicle on which it is		
	being transported, under conditions normally		
	incident to transportation.	172,400(-)(2)	¢10.000
EnviroTech Chemical	•	172.400(a)(2);	\$10,800
Services, LLC	packaged in UN standard IBCs, without	172.402(a)(2);	
Helena, AR	labeling the IBCs with the required hazard	172.514(c)(4); 180.352(b)(1)	
Cana #.	class warning labels on opposing sides or	& (2); 173.22(a)(4)(i);	
Case #:	placarding the IBCs. Filled and offered	173.24(f)(2); SP 12412,	
22-0035-SH-SW	hazardous materials in out-of-test UN	Section 10; 172.202(a)(7)	
	standard IBCs. Offered a hazardous material,		
	while failing to close a UN standard packaging in accordance with the manufacturer's closure		
	instructions. Offered and transported		
	hazardous materials using DOT Special Permit, without carrying a current copy of the special		
	permit aboard the transport vehicle. Offered and transported hazardous materials		
	accompanied by shipping papers that did not		
	list the number and type of package.	172 22(2)(2), 172 405(4)	¢E 000
EPC Warehouse	Offered a damaged lithium battery packaged	173.22(a)(2); 173.185(f)	\$5,000
Wright City, MO	for recycling when the contents of the		
Fieldet #4	package require packaging for damaged,		
Ticket #:	defective, or recalled (DDR).		
22T-0272-SH-SO			<u> </u>

Company Name	Violation Summary	Citations	Penalty
			Amount
Epic Chemical	Failed to provide general awareness, function-	172.702(b); 172.704(a)(1),	\$2,440
Solutions, Inc.	specific, safety, and security awareness	(2), (3), & (4); 172.200;	
San Antonio, TX	training. Offered and transported a hazardous	172.202(a)(2), (3), & (b)	
	material accompanied by shipping papers that		
Ticket #:	failed to include the correct proper shipping		
21T-0405-SH-SW	name and shipping description sequence.		
ETTL Engineers &	Offered and transported UN3332, Radioactive	173.475(b); 172.403(g)(1) &	\$7,500
Consultants	Material, Type A Package, Special Form, 7, in a	(2); 172.201(d);	
Texarkana, AR	Type A package, while failing to ensure that	172.202(a)(2) & (7);	
	the packaging was in unimpaired physical	172.203(d)(3)	
Case #:	condition. Offered and transported a		
22-0043-SH-SW	hazardous material contained in a DOT		
	Specification 7A, Type A package that had		
	illegible radionuclide and activity listings on		
	the hazardous warning labels. Offered and		
	transported hazardous materials accompanied		
	by shipping papers that listed an unauthorized		
	emergency response telephone number,		
	wrong proper shipping name, failed to include		
	the number and type of package, and listed		
	the wrong activity for the radioactive material.		
Evans Distributing,	Offered and transported hazardous materials	172.200(a); 172.202(a)(1),	\$1,220
LLC	accompanied by shipping papers with hazmat	(2), (5), (7), & (b);	+
Fort Smith, AR	shipping descriptions missing type of package,	172.704(d)	
	out of sequence, and missing unit of measure.		
Ticket #:	Failed to create and maintain training records.		
22T-0068-SH-SW			
Falco Emotors, Inc.	Offered UN3480, lithium-ion batteries, 9, in	172.200(a); 172.300(a);	\$4,200
Dulles, VA	packaging without shipping papers, marking,	172.400(a); 172.704(c)(1)(i)	<i>φ</i> ¬,200
Bulles, VI	and labeling. Offered hazardous materials,	1, 2, 400 (0), 1, 2, , 04 (0)(1)(1)	
Case #:	while failing to provide supervision to a		
20-0034-SH-EA	temporary hazardous materials employee.		
Farmers Cooperative	Offered and transported a hazardous	173.33(a)(3); 173.315(m)	\$1,000
Elevator Co.	material, UN1005, Ammonia, Anhydrous, 2.2,		÷-,000
Bentley, KS	in non-DOT cargo tanks with missing or loose		
Denticy, NJ	mounting bolts.		
Ticket #:			
22T-0178-SH-SO			
221-01/0-30-30			

Company Name	Violation Summary	Citations	Penalty Amount
Farmers Grain	Offered and transported UN 1397, aluminum	172.200 & (a); 172.300;	\$39,420
Company, Inc.	phosphide mixture, 4.3, PGI, without shipping	172.400; 172.500; 172.101;	+
Pond Creek, OK	papers, package markings, and placards.	173.211; 172.201(e);	
Renfrow, OK	Offered a hazardous material in an	172.202(a); 177.801;	
Neimow, OK	unauthorized non-UN standard or non-	177.817(a) & (f);	
Case #:	specification packaging. Failed to create and	177.817(a) & (1), 180.417(d); 173.33(a)(3);	
22-0065-HM-SW			
	retain shipping papers. Offered UN1005,	180.407(a)(1) & (c);	
22-0057-HM-SW	Ammonia, anhydrous, 2.2, in a MC 331	173.33(a)(3); 180.407(a)(1)	
	specification cargo tank while failed to retain	& (c)	
	a copy of the manufacturer's Certificate of		
	Compliance for the cargo tank. Filled and		
	offered UN1005, Ammonia, anhydrous, 2.2, in		
	a MC331specification cargo tank that was		
	overdue the prescribed periodic test and		
	inspections. Offered and transported UN1005,		
	Ammonia, anhydrous, 2.2, in a ASME non-		
	specification nurse tank that was overdue the		
	prescribed periodic retest.		
Federal Fire	Failed to provide initial hazmat training. Failed	172.702(a); 172.704(a)(1),	\$8,100
Protection	to keep complete and accurate records of	(2), (3), & (4); 180.215(b);	
Berkeley Heights, NJ	cylinder reinspection and retest. Failed to	180.213(a) & (d)	
	properly mark a cylinder after subjecting it to		
Case #:	modified proof pressure procedures.		
21-0207-CR-EA			
Ferguson	Offered hazardous materials in unauthorized	173.22(a); 172.300(a);	\$7,440
Enterprises, LLC	non-UN standard packaging. Offered a	172.301(a)	
Columbus, OH	hazardous material while marking the		
	packages with improperly sized identification		
Case #:	number.		
21-0306-SH-EA			
Finishmaster, Inc.	Filled a limited quantity of a compressed gas	173.306(a)(3)(v)	\$2,000
Fort Worth, TX	in a DOT 2Q aerosol container intended to		
	expel a non-poisonous material, while failing		
Ticket #:	to subject the filled aerosol container to a hot		
22T-0196-SH-SW	water bath and ensuring container reaches an		
	internal temperature of 131 degrees		
	Fahrenheit.		
Fire Equipment	Failed to provide initial general awareness,	172.702(a) & (b);	\$1,215.83
Company of Florida,	function-specific, and security awareness	172.704(a)(1), (2), (4), &	
LLC	training.	(c)(1)	
Fort Myers, FL			
Ticket #:			
21T-0322-CR-SO			
Fire Force, Inc.	Failed to condemn a cylinder. Failed to	180.205(i); SP-10915;	\$6,705
Butler, PA	maintain requalification records of a		C,705
bullel, FA		180.215(b)	
Caco #1	hydrostatic pressure test performed on a DOT		
Case #:	special permit cylinder.		
21-0307-SI-EA			

Company Name	Violation Summary	Citations	Penalty Amount
Florence B Deyo, Inc. Crown Point, NY Ticket #: 21T-0406-CA-EA	Failed to provide the shipping paper to authorities upon request. Failed to create and retain training records. Failed to annually review the security plan.	177.817(e); 172.704(d); 172.802(c)	\$880
Florida Chemical Supply, Inc. Tampa, FL Ticket #: 22T-0115-SH-CE	Offered a hazardous material in UN certified IBCs when the manufacturers UN performance standard markings were partially covered by the product information label, thereby failing to render the manufacturer's marking as "durable and clearly visible". Offered a hazardous material in a UN standard marked and certified packaging when the UN ID number marking size was under the regulation height requirements. Offered a hazardous material, while failing to close a UN	173.24(c)(1); 178.703(a)(1); 172.301(a)(1); 173.22(a)(4); 173.24(f)(2)	\$3,640
Florigas, Inc. Miami, FL	standard packaging in accordance with the manufacturer's closure instructions. Failed to develop a security plan. Failed to provide general awareness, function-specific, safety, security awareness, and in-depth	172.800(b); 172.802; 172.704(a)(1), (2), (3), (4), (5), & (c)(2); 172.200(a);	\$9,900
Case #: 22-0023-SH-SO	security training. Offered and transported UN1075, Propane, 2.1, while failing to properly retain copies of shipping papers.	172.201(e); 177.817(f)	
Fort Worth Welders Supply, Inc. Fort Worth, TX Ticket #: 22T-0060-CA-SW	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Offered a hazardous material, while listing an emergency response telephone number on a shipping paper that causes emergency responders delay in	172.702(b); 172.704(c)(1)(i) & (ii); 172.604(b)(1) & (2)	\$2,880
Fullerton Hydrotest, Inc. Inola, OK Ticket #: 22T-0146-CA-SW	obtaining emergency response information. Represented, marked, and certified a DOT specification cylinders as having been successfully requalified in accordance with the HMR, while failing to increase test pressure by 10 percent or 100 psi, whichever is less, when a test is repeated due to equipment	180.205(g)(5); 180.417(a)	\$4,500
	malfunction. Transported hazardous materials in specification cargo tanks, while failing to retain the manufacturer's certificate of compliance which certifies the cargo tank was manufactured and tested.		
Gabel's Cosmetics, Inc. Los Angeles, CA Ticket #: 22T-0194-SH-WE	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Failed to provide function-specific, general awareness, safety, and security awareness training.	173.1(b), 173.22(a)(1), (2), & (4), 173.24(a) & (f)(2); 172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(2)	\$2,000

Company Name	Violation Summary	Citations	Penalty
			Amount
Gebhardt, Inc. Mineola, NY Ticket #:	Failure to provide recurrent general awareness, function-specific, safety and security awareness training.	172.702(a)	\$2,000
22T-0173-CR-EA			
General Steel Drum, LLC Charlotte, NC Ticket #: 22T-0177-PM-SO	Manufactured, represented, marked, and sold steel drums certified to UN Standard 1A1 and 1A2, as meeting the requirements of the HMR, when the periodic test records were incomplete or inaccurate.	178.600; 178.601(l)	\$1,000
Geo Cam San Antonio, TX Ticket #: 22T-0236-SH-SW	Offered and transported a hazardous material, UN0124, Jet perforating guns, charged, 1.1D, accompanied by shipping papers that failed to include the assigned identification number as listed in the hazardous materials table column 4 and failed to include the net explosive mass for a shipment of Class 1 explosive articles.	172.202(a)(1) & (5)(i)	\$960
Georgia Container Reconditioning, LLC Adel, GA Case #: 22-0086-PC-SO	Failed to provide general awareness, function- specific, and security awareness training. Represented, marked, and sold plastic drums certified to UN standard 1H1 and intended for reuse according to the requirements of the HMR, while failing to conduct leakproofness testing of those drums.	172.702(a) & (b); 172.704(a)(1), (2), (4), & (c)(1); 173.28(b)(2)(i); 178,604	\$4,425
Gillespie Coatings Operating, LLC Longview, TX Ticket #:	Failed to provide general awareness, function- specific, safety, and security awareness training.	172.702(b); 172.704(a)(1), (2), (3), & (4)	\$2,039.51
22T-0073-SH-SW Global Fire and Safety, Inc. Oakland, CA Ticket #: 22T-0002-CR-WE	Represented, marked, and certified DOT specification cylinders as having been successfully retested in accordance with the HMR, without the current RIN approval.	180.1; 180.2; 180.3; 180.205(b); RIN Approval C719; DOT SP-9421	\$400
GM Industrial, LLC, dba Chemsafe International, LLC Cleveland, OH Case #: 22-0014-SH-EA	Discharged a hazardous material from an IBC without removing the IBC from the motor vehicle. Offered hazardous materials in UN standard packages when the packages had not been closed in accordance with the packages closure instructions. Failed to create and maintain training records.	177.834(h); 173.22(a)(4); 173.24(f)(2); 172.704(d)	\$2,250

Company Name	Violation Summary	Citations	Penalty Amount
Graphic Solutions Group, Inc. Austin, TX	Failed to properly prepare shipping papers.	172.101(b)(4); 172.200(a); 172.202(a) & (b); 172.203(k)	\$1,280
Ticket #: 22T-0216-SH-CE			
Greif, Inc. Delaware, OH Case #: 19-0123-PM-EA 19-0162-PM-WE 20-0024-PM-SW	Failed to ensure a packaging certified as meeting the UN standard can pass the required performance testing (leakproofness test). Packing Group II. Failed to keep complete and uphold accurate test records. Failed to properly conduct a production leakproofness test on a new 1A1/Y1.8/300/YR/USA/GBC UN rated drum, when Alternative Leakproofness Test Method, Solution over partial seams test, used for production leakproofness test did not meet minimum testing requirement for the UN	178.601(a); 178.604(f); 178.601(l); 178.2(b) & (d); 178.604(a), (b)(1), (d), & (e); Appendix B to 178 option (4)	\$14,400
Greif, Inc. Lavonia, GA Case #: 21-0365-PM-SO	rating specification. Manufactured, marked, certified, and sold 55- gallon poly drums as meeting the UN1H1 standard, when packages were not capable of passing the drop, leakproofness, or hydrostatic pressure tests.	178.2(b); 178.601(b); 178.603(a); 178.605(a)	\$10,125
21-0366-PM-SO Greenmont Liquid Gas & Fertilizer Co., Inc. Montgomery, AL	Failed to provide recurrent general awareness, function-specific, safety, security awareness, and in-depth security training.	172.702(a); 172.704(a)(1), (2), (3), (4), (5), & (c)(2)	\$2,000
Ticket #: 22T-0026-SH-SO GSI Engineering Wichita, KS Ticket #: 22T-0222-SH-CE	Offered a hazardous material in a packaging that has been successfully tested to an applicable DOT Specification but is not marked with the required manufacturers name and address. Offered a hazardous material, when listing a shipping description that is not in the required sequence and failed to include "RQ" for a hazardous substance on a shipping paper. Failed to apply the "RQ" mark on a non-bulk package containing a hazardous substance.	178.3(a); 172.200(a); 172.202(a) & (b); 172.203(c)(2); 172.324(b)	\$2,280
Grill Gas Express Midsouth, LLC Olive Branch, MS Ticket #: 21T-0347-SH-SO	Offered and transported a hazardous material, while having failed to provide hazardous materials shipping papers. Failed to provide initial general awareness, function- specific, safety and security awareness training.	172.200; 172.201; 172.202; 172.702(a); 172.704(a)(1), (2), (3), (4), & (c)(2)	\$5,345.49

Company Name	Violation Summary	Citations	Penalty Amount
Hale Fireworks, LLC Buffalo, MO Case #:	Offered a forbidden explosive. Offered explosives with a false explosive approval number.	173.21(b); 173.Sl(a); 173.54(a); 173.56(b)(l); 171.2(a), (b), (e), & (m)	\$21,500
21-0115-SH-CE Hantover, Inc. Kansas City, MO Ticket #: 22T-0227-SH-CE	Failed to provide recurrent general awareness, function-specific, safety, and security awareness training. Failed to maintain training records. Offered a hazardous material with a label affixed to a package that did not meet the label design specifications. Failed to include the required technical name(s) in parentheses for a listed generic or "N.O.S." entry on the package marking.	172.702(a); 172.704(a)(1), (2), (3), (4), (c)(2), & (d); 172.407(b) & (c); 172.419; 172.301(b)	\$2,240
Harchem, LLC Rhome, TX Ticket #: 22T-0056-SH-SW	Failed to register as an offeror of hazardous materials and pay registration fee. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Offered a hazardous material, while listing an emergency response telephone number on shipping papers without authorization. Offered a hazardous material accompanied by shipping papers that failed to list the basic description in the order specified.	107.601(a); 107.608(b); 172.504(c); 173.22(a)(4)(i) & (ii); 173.24(f)(2); 172.201(d); 172.604(b)(1) & (2); 172.202(b)	\$3,300
Harper-Love Adhesives Corporation Charlotte, NC Ticket #: 22T-0167-SH-SO	Failed to register as an offeror of hazardous materials and pay registration fee. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Failed to provide general awareness and security awareness training.	107.601(a)(6); 107.608(a) & (b); 173.22(a)(4); 173.24(f)(2); 172.702(a); 172.704(a)(1), (2), (4), & (c)(1)	\$2,720
Hasa Inc. Longview, WA Case #: 22-0090-SH-WE	Filled an IBC (31H2) with a hazardous material to be offered for transportation in commerce, while failing to properly perform the required leak test. Filled an IBC (31H2) with hazardous material to be offered, while failing to keep test records of IBC retest and reinspection. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	180.351; 180.352(b); 178.801(l); 180.352(g); 173.1(b); 173.22(a)(1), (2), & (4); 173.24(a) & (f)(2); 177.800(a); 177.801	\$5,850

Company Name	Violation Summary	Citations	Penalty Amount
Hawkins, Inc. Superior, WI Ticket #: 22T-0230-SH-CE	Represented and offered a UN certified packaging, while the UN Standard marking had been obscured and obliterated rendering it an unauthorized packaging. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Offered a hazardous material, while failing to mark the package with an adequate size identification number and the correct proper shipping name. Offered a hazardous material, while placing a label on a different surface of the package than, or away from the proper shipping name.	173.24(c) & (f)(2); 178.2(b); 178.3(a) & (b); 173.22(a)(4); 172.301(a); 172.406(a)	\$4,040
Heil Trailer International, LLC Louisville, KY Ticket #: 22T-0048-ILA-SO	Offered and transported a hazardous material, while failing to retain shipping papers for two years after the date of shipment. Represented and certified an IBC marked UN 31A as being inspected and repaired without properly marking the IBCs with the country in which the tests and inspections were performed, the name or authorized symbol of the person performing the tests and inspections, and the date (month, year) of the tests and inspections. Represented and certified an IBC marked UN 31A as being inspected and repaired, without properly maintaining accurate records of those inspections.	172.201(e); 178.703; 178.813; 180.352(d), (f), & (g)	\$1,680
High Performance Product Engineering Columbus, GA Ticket #: 22T-0059-SH-SO	Offered hazardous materials accompanied by shipping papers which did not include an emergency response telephone number. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Failed to register as an offeror of hazardous materials and pay registration fee. Offered hazardous materials accompanied by shipping papers that contained incorrect shipping descriptions.	172.200(a); 172.201(d); 172.604(a); 173.22(a)(4)(i); 173.24(f)(2); 173.242(d); 178.2(c); 178.601(b); 107.601(a)(6); 107.608(a) & (b); 172.202(a)(1), (2), (3), (4), & (b)	\$4,300
Hingham Lumber Company Cohasset, MA Case #: 21-0050-SI-EA	Filled a DOT specification cylinder that is overdue for periodic requalification. Overfilled a DOT-specification cylinder with a hazardous material, so that the effectiveness of the cylinder was compromised, resulting in release of the contents (propane) to the environment. Failed to provide initial hazmat and in-depth security training. Failed to label a non-bulk package.	173.301(a)(6); 173.24(b)(2); 172.702(a); 172.704(a)(1), (2), (3), (4), & (5); 172.400(b)	\$20,800

Company Name	Violation Summary	Citations	Penalty Amount
Home Trade USA, LLC Middletown, NY	Failed to provide initial general awareness, function-specific, safety, and security awareness training.	172.702(a); 172.704(a)(1), (2), (3), & (4)	\$493
Case #: 21-0105-SH-EA			
Hub Chemical Wisconsin Dells, WI	Failed to properly conduct a leakproofness test on a reused, reconditioned, or remanufactured packaging, and offered a	173.28(a) & (b)(7)(iv)(B); 172.704(d); 173.22(a)(4)(i) & (a)(4)(ii); 173.24(f)(2)	\$4,273
Case #: 20-0202-SH-CE	hazardous material in an unauthorized non- UN standard or non-specification packaging. Failed to maintain training records. Offered a hazardous material in a UN standard marked certified packaging and failing to retain a copy of the manufacturer's notification, including closure instructions. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.		
Imperial Brown, Inc. Gresham, OR Ticket #:	Offered hazardous materials accompanied by shipping papers that were not properly prepared. Failed to register as an offeror of hazardous materials and pay registration fee.	172.200(a); 172.202(a)(1), (2), (3), (7) & (d); 172.203(a) & (k); 172.204; DOT- SP8995; 107.601(a)(6),	\$2,480
22T-0003-SH-WE	Failed to provide initial general awareness, function-specific, safety, and security awareness training.	107.608(b); 107.612; 172.504; 172.702(a) & (b); 172.704(a)(1), (2), (3), (4), (c)(1), & (d)	
Industrial Containers of Texas, LLC Houston, TX Case #: 21-0394-PM-SW	Represented, marked, certified, and sold UN standard 31HA1 IBCs as meeting the requirements of the HMR, without properly performing the leakproofness test. Represented, marked, certified, and sold UN standard 31HA1 IBCs, without marking the IBC with the minimum size requirements and without including stacking test load and gross mass in the marking.	178.813(c); 178.3(a); 178.703(a)(1)(vii) & (viii)	\$9,250
Innovative Water Care, LLC Alpharetta, GA	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.22(a)(4); 173.24(b) & (f)(2)	\$1,440
Ticket #: 22T-0108-SH-SO			
International Chemical Company Philadelphia, PA	Failed to register as an offeror of hazardous materials and pay registration fee.	107.601(a)(6); 107.608(a) & (b)	\$1,400
Ticket #: 22T-0091-SH-EA			

Company Name	Violation Summary	Citations	Penalty
			Amount
ron Mountain	Offered a hazardous material, while failing to	173.185(c)	\$480
Olathe, KS	mark the package with the lithium battery mark.		
Ticket #:	IIIdTK.		
22T-0220-SH-CE			
IBZ Dairy Advantage	Failure to provide initial general awareness,	172.704(a)(1), (2), (3), & (4);	\$4,080
Inc.	function-specific, safety, and security	107.201(e); 172.604(a)(b);	Ç4,000
Blue Ball, PA	awareness training. Failed to retain shipping	173.22(a)(4); 173.24(f)(2)	
,	paper(s). Provided incorrect Emergency		
Ticket #:	Response Information with or on a shipping		
22T-0075-SH-EA	paper for a PGII material with no significant		
	change in response. Offered a hazardous		
	material, while failing to close a UN standard		
	packaging in accordance with the		
	manufacturer's closure instructions.		
Jennings Oil Co.	Failed to include personnel security and en-	172.802(a)(1) & (3);	\$1,360
Gaylordsville, CT	route security elements in the security plan.	172.802(c)	
	Failed to review the security plan at least		
Ticket #:	annually.		
21T-0412-SH-EA	Failed to service and an end of the strength		\$2,480
JLB McAdams	Failed to provide general awareness, function-	172.702(b); 172.704(a)(1),	\$2,480
Enterprises, Inc. Carthage, TX	specific, safety, security awareness, and in- depth security training. Offered and	(2), (3), (4), & (5); 172.201(e)	
Cartilage, TA	transported a hazardous material, UN 1075,	1/2.201(8)	
Ticket #:	Liquified Petroleum Gas, 2.1, while failing to		
22T-0049-CR-SW	retain a record of each shipment made, to		
	include the identification number when using		
	a shipping paper without change for multiple		
	shipments of one or more hazardous		
	materials having the same shipping name and		
	identification number.		
John S Posen, Inc.	Failed to notify the cylinder owner in writing	180.205(i)(2)(ii)	\$600
Blue Bell, PA	when a cylinder has been condemned.		
Ticket #:			
22T-0158-CR-EA	Offered and transported a bezerdous material	172 202(2)(4): 172 202(4)	62.240
Jones Stephens Corp. Moody, AL	Offered and transported a hazardous material accompanied by a shipping paper while using	172.202(a)(4); 172.203(k)	\$2,240
WOUUY, AL	a shipping description with two or more		
Ticket #:	required elements incorrect or missing.		
22T-0029-SH-SO			
Keller Fire and	Offered and transported a hazardous material	172.200(a); 172.201;	\$3,300
Safety, Inc.	without shipping papers. Failed to maintain	172.704(d)	
Kansas City, KS	training records.		
Tieket #			
Ticket #: 22T-0225-CR-CE			
221-0223-CK-CE			

Company Name	Violation Summary	Citations	Penalty
			Amount
Kempen Paint Company East Carondelet, IL Ticket #: 22T-0125-SH-CE	Offered a hazardous material in a UN standard marked and certified packaging whose UN ID number marking height was not high enough. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Failed to maintain training records. Represented and offered a UN certified packaging, while failing to keep any records of IBC retest and reinspection most current	172.301(a)(1); 173.22(a)(4); 173.24(f)(2); 172.704(d); 180.352(g)	\$3,060
Ken-Mar Fire Extinguisher Co., Inc. East Northport, NY Case #: 21-0362-CR-EA	retest and/or inspection. Marked a "+" on a cylinder while failing to determine the elastic expansion and average or maximum wall stress by calculation. Failed to include an emergency response telephone number on a shipping paper. Failed to include the proper shipping name, hazard class, division, and number of packages on a shipping paper.	173.302a(b)(2) & (3); 172.604(a)(3); 172.202(a)(2), (3), & (7)	\$8,040
KFS Enterprises, LLC dba Lime City Propane Huntington, IN Case #: 20-0134-SH-CE	Failed to develop a security plan. Failed to provide initial general awareness, function- specific, safety, and security awareness training. Failed to register as an offeror of hazardous materials and pay registration fee. Offered a hazardous material accompanied by a shipping paper which failed to include an emergency response telephone number.	172.800(b)(3); 172.702(a); 172.704(a)(1), (2), (3), (4), & (d); 107.601(a)(6); 107.608(a) & (b); 172.201(d); 172.604(a)(1), (3), & (b)	\$10,980
Kimbro Oil Company Nashville, TN Case #: 22-0132-SH-CE	Offered a hazardous material in unauthorized non-UN standard or non-specification packaging without shipping papers. Offered a hazardous material without shipping papers. Failed to provide recurrent general awareness, function-specific, safety, and security awareness training. Offered a hazardous material, while failing to apply the limited quantity mark on a non-bulk package containing a hazardous substance.	172.101; 172.200; 172.201; 172.204; 173.24(c); 173.150(f); 173.203; 174.702(a) & (b); 172.704(a)(1), (2), (3), (4), (c), & (d); 172.315	\$17,110
Klebe Fuel Company, Inc. Winsted, CT Case #: 22-0036-SH-EA	Failing to develop and implement a security plan.	172.800(b)(3)	\$4,200

Company Name	Violation Summary	Citations	Penalty Amount
Kosan Crisplant Missouri, Inc. York, PA	Offered hazardous materials in packaging that was damaged and not suitable for shipment, resulting in DOT-4 cylinders leaking during highway transport. Offered a hazardous	173.24(b)(1); 172.201(a)(4); 172.202(a)(2) & (4); 172.204(a); 107.601(a)(6)	\$14,320
Case #: 21-0158-HMI-EA	material with shipping papers containing incorrect description and incorrect additional information, and failing to correctly account for cylinders. Failed to register as an offeror of hazardous materials and pay registration fee.		
Kysor Warren Columbus, GA	Failed to provide general awareness, function- specific, safety, and security awareness.	172.702(a) & (b); 172.704(a)(1), (2), (3), (4), (c)(1), & (2)	\$1,600
Ticket #: 22T-0031-SH-SO			
L.A. Chemicals, LTD Broadview, IL Ticket #:	Represented and offered a UN certified packaging, while the UN Standard marking had been obliterated, rendering it an unauthorized packaging.	173.24(c); 173.35(a); 178.2(b); 178.3(a) & (b)	1,800
22T-0226-SH-CE			
Landrum Chemical Louisville, KY	Failed to register as an offeror of hazardous materials and pay registration fee. Offered and transported a hazardous material	107.601(a)(6); 107.608(a) & (b); 172.202(a)(4); 172.203(k)	\$800
Ticket #: 22T-0038-SH-SO	accompanied by a shipping paper while using a shipping description with two or more required elements incorrect or missing.		
Landstar Ranger, Inc. Jacksonville, FL	Failed to include all required information on the Hazardous Materials incident Report and update the report within one year.	171.16(c)(2)	\$400
Ticket #: 22T-0210-CA-EA			
Lanning Chemical Company, Inc. Louisville, KY	Failed to register as an offeror of hazardous materials and pay registration fee. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the	107.601(a)(6); 107.608(a) & (b); 173.22(a)(4); 173.24(f)(2)	\$2,552.67
Ticket #: 22T-0039-SH-SO	manufacturer's closure instructions.		
Lanxness Corporation c/o Brook Warehouse Bridgewater, NJ	Offered hazardous materials that require a security plan, while failing to include security duties for each position in the plan. Failed to provide in-depth security training.	172.800(b)(5); 172.802(b)(2); 172.702(a) & (b); 172.704(a)(5) & (c)	\$3,052
Case #: 21-0398-SH-EA			
LAX Gadgets, Inc.	Failed to provide a foreign shipper of	171.22(f)(1)	\$4,127
Woodside, NY Case #:	hazardous materials with written requirements applicable to the specific shipment.		
22-0006-SH-EA			

Company Name	Violation Summary	Citations	Penalty
			Amount
Layne Christensen	Offered a hazardous material accompanied by	172.201(d); 172.604(a) &	\$640
Company	a shipping paper containing an unauthorized	(b)	
Fenton, MO	emergency response telephone number.		
Ticket #:			
22T-0104-SH-CE			
Lebro Distributing	Failed to provide hazardous materials shipping	172.200; 172.202; 172.604;	\$3,840
Tucker, GA	papers. Failed to provide an emergency response telephone number. Failed to provide	172.702(a); 172.704(a)(1), (2), (3), (4) & (c)(1)	
Ticket #:	initial general awareness, function-specific,		
22T-0085-SH-SO	safety, and security awareness training.		
Light Metals Coloring	Offered a hazardous material, while failing to	173.22(a)(4)(i)	\$1,600
Company, Inc.	close a UN standard packaging in accordance		
Southington, CT	with the manufacturer's closure instructions.		
Ticket #:			
22T-0077-SH-EA			
Lighting Resources,	Offered damaged and defective lithium	173.185(f)(2) & (3);	\$14,250
LLC	batteries packaged in unauthorized UN	172.702(a); 172.704(a)(1),	
Fort Worth, TX	standard packages rated for PGII and PGIII	(2), (3), (4), (c)(1), (2), & (d);	
	hazardous materials. Failed to provide general	173.22(a)(4)(i); 173.24(f)(2)	
Case #:	awareness/familiarization, function-specific,		
22-0188-SH-SW	safety, and security awareness training.		
	Offered a hazardous material, while failing to		
	close a UN standard packaging in accordance		
	with the manufacturer's closure instructions.		
Linde Gas North	Represented, certified, and marked DOT	107.805(a) & (g); RIN G302	\$280
America, LLC	specification packages while failing to report		
Phoenix, AZ	in writing a change in name, address,		
	ownership, management, or testing personnel		
Ticket #:	within 20 days of the change.		
21T-0190-CR-WE			
Long Island Propane,	Failed to register as an offeror of hazardous	107.601(a)(6); 107.608(b);	\$3,300
Inc.	materials and pay registration fee. Failed to	172.604(a); 172.802(b)(1) &	
Hicksville, NY	include an emergency response telephone	(2); 172.802(c); 172.704(d)	
	number on the shipping paper. Failed to		
Ticket #:	include in the security plan the identification		
22T-0172-SH-EA	of the management official who is responsible		
	for the development and implementation of		
	the security plan by title, and the description		
	of duties for such a position. Failed to review		
	the security plan at least annually. Failed to		
	create and maintain training records.		

Company Name	Violation Summary	Citations	Penalty Amount
Lonoke County Coop, Inc. Lonoke, AR Case #: 22-0160-HM-SW	Failed to create and retain shipping papers. Filled, offered, and transported UN2922, Corrosive liquid, Toxic, N.O.S., (paraquat dichloride), 8 (6.1), PGIII, in a UN standard packaging, IBC, that was past due for prescribed periodic retesting. Offered and transported UN2922, Corrosive liquid, Toxic, N.O.S., (paraquat dichloride), 8 (6.1), PGIII, contained in UN standard IBCs while failing to remove the IBCs from the motor vehicle before discharging the contents of the container. Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	172.200(a); 172.201(d), & (e); 172.202(a); 173.35(a); 180.352(a) & (b); 177.834(h); 173.22(a)(4)(i); 173.24(f)(2)	\$5,625
Lyon LP Gas, Inc. Alto, TX Ticket #: 22T-0163-PC-SW	Represented, marked, and certified DOT specification cylinders as having been successfully requalified in accordance with the HMR, while failing to report a change in address in writing to the Associate Administrator. Failed to develop a complete security plan. Failed to provide general awareness, function-specific, safety, security awareness, and in-depth security training.	107.805(g); 172.800(b)(3); 172.802(a) & (c); 172.702(b); 172.704(a)(1), (2), (3), (4), & (5)	\$2,800
Magruder Propane, Inc. Odessa, MO Ticket #: 22T-0055-SH-CE	Transported an ASME tank with greater than 5 percent capacity without conducting a visual inspection, completing an inspection record, and maintaining that record for a minimum of two year. Failed to maintain training records.	173.315(j)(2); 172.704(d) & (5)	\$3,240
Marken LLP Inglewood, CA Ticket #: 21T-0339-SH-SO	Offered UN2814, Infectious Substance Affecting Humans (Nipah Virus), 6.2, misclassified as a UN3373, Biological Substance, Category B, 6.2, by replacing the "Overpack" without placing the correct markings and labels, or providing the correct shipping paper for continued transportation.	172.200(a); 172.300(a); 172.303(a); 172.400(a) & (b)	\$4,822.67
Mary Kay, Inc. Lewisville, TX Ticket #: 22T-0046-SH-SW	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions.	173.22(a)(4)(i) & (ii); 173.24(f)(2)	\$1,000
Materion Advanced Materials Technologies Albuquerque, NM Ticket #: 21T-0242-SH-SW	Failed to provide general awareness, function- specific, safety, and security awareness training. Offered hazardous materials accompanied by shipping papers that failed to include the identification number, proper shipping name, hazard class, and packing group, and listed an un-authorized emergency response telephone number.	172.702(b); 172.704(a)(1), (2), (3), & (4); 172.200(a), 172.201(d)(e); 172.202(a)(1), (2), (3), & (4); 172.204(a); 172.604(a)	\$3,888.48

Company Name	Violation Summary	Citations	Penalty Amount
Mauser Packaging Solutions Homerville, GA	Manufactured, marked, certified, and sold steel drums as meeting the UN1A1 standard, when packages were not capable of passing the drop or hydrostatic pressure tests.	178.603(a); 178.605(a); 178.2(b); 178.601(b)	\$20,250
Case #: 21-0369-PM-SO 21-0370-PM-SO	Manufactured, marked, certified, and sold steel drums as meeting the UN1A2 standard, when packages were not capable of passing the drop or hydrostatic pressure tests.		
Mauser Packaging Solutions Mason, OH Ticket #: 21T-0381-PM-EA	Represented, marked, certified, offered, and sold UN standard steel drums as meeting the requirements of the Hazardous Materials Regulations, when the production leakproofness test was not properly conducted. Represented, marked, and offered steel drums marked as being UN standard steel drums meeting the requirements of the HMR when the package qualification test reports were not complete and accurate.	178.604(b)(1); Appendix B to Part 178; 178.2(a) & (b); 178.601(l)	\$3,120.70
Mauser USA, LLC dba Mauser Packaging Solutions East Brunswick, NJ Case #: 21-0335-PM-EA	Manufactured, marked, certified, and sold resin drums as meeting the UN1H1 standard, when packages were not capable of passing the drop or hydrostatic pressure tests.	178.603(a); 178.605(a); 178.2(b); 178.601(b)	\$10,125
Mauser USA, LLC dba Mauser Packaging Solutions Oak Brook, IL Case #: 21-0354-PM-SW 21-0356-PM-SW 22-0020-PM-SO	Manufactured, marked, certified, and sold steel drums as meeting the UN1A1 standard, when packages were not capable of passing the drop, leakproofness, and hydrostatic pressure tests. Represented, marked, certified, and sold UN standard 1A2 steel drums as meeting the requirements of the HMR, when the packaging were not capable of passing the drop and hydrostatic pressure tests. Represented, marked, certified, and sold UN standard 1A1 design type drums as meeting the requirements of the HMR, when the solution over partial seams test was not being performed on each drum, nor performed correctly when it was performed.	178.603(a) & (f); 178.604(a), (b), & (d); 178.605(a) & (e); 178.601(a) & (b); 178.2(a) & (b); 178 Appendix B, paragraph (4)	\$25,425
Mauser USA, LLC Charlotte, NC Case #: 21-0380-PM-SO	Manufactured, marked, certified, and offered poly drums as meeting the UN1H1 standard, when packages were not capable of passing the hydrostatic pressure tests.	178.605(a); 178.2(b); 178.601(b)	\$13,500

Company Name	Violation Summary	Citations	Penalty Amount
Mays Chemical Company, Inc. Greenwood, IN Ticket #: 22T-0042-SH-CE	Offered a hazardous material, while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Offered a hazardous material in a non-bulk package, while failing to mark the package with the correct size identification number.	173.22(a)(4)(i); 173.24(f)(2); 172.300(a); 172.301(a)(1)	\$1,400
Medline Industries, Inc. Grayslake, IL Ticket #:	Offered a hazardous material when the shipping paper failed to include complete proper shipping description.	172.200(a); 172.202(a)(3), (4), & (d); 172.203(k)	\$600
22T-0070-SH-CE Mesa Equipment Company, Inc. San Antonio, TX Ticket #: 21T-0395-SH-SW	Failed to provide initial general awareness, function-specific, and security awareness training. Offered and transported hazardous materials accompanied by shipping papers that failed to include the packing group in roman numerals and proper shipping description and name.	172.702(b); 172.704(a)(2); 172.202(a)(2) & (4)	\$2,390
Miami Screen Print Supply, Inc. Miami Gardens, FL Case #: 21T-0345-SH-SO	Offered and transported a hazardous material packaged in UN standard jerricans marked "UN 3H1," while failing to ensure the jerricans displayed a hazard warning label. Failed to provide initial general awareness, function- specific, safety, and security awareness training. Offered and transported a hazardous material, while failing to declare the hazardous material on a shipping paper. no basic shipping description, emergency response telephone number, shipper's certification, and signature were communicated. Offered and transported a hazardous material packaged in UN Standard jerricans marked "UN 3H1," while failing to ensure the proper shipping name and identification number were marked on the jerricans.	172.400(a)(1) & (b); 172.406(a); 172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(1); 177.816(d); 172.200(a); 172.201(a); 172.202(a) & (b); 177.817(a); 172.300(a); 172.301(a)(1)	\$6,000
Microporous, LLC Piney Flats, TN Ticket #: 22T-0243-SH-SO	Failed to register as an offeror of hazardous materials and pay registration fee.	107.601(a)(6); 107.608(a) & (b)	\$960

Company Name	Violation Summary	Citations	Penalty Amount
Midwest Engineering & Testing Corporation (METCO) Oklahoma City, OK Ticket #: 21T-0407-SH-SW	Offered and transported a DOT specification 7A packaging containing RQ, UN3332, Radioactive material, Type A package, Special form, 7, with labels listing the incorrect transport index and missing the contents and activity. Offered and transported hazardous materials accompanied by a shipping paper that listed shipping descriptions not in the required sequence by listing the letter "RQ" interspersed within the basic shipping description, to identify a material that is a hazardous substance.	172.403(b), (f), & (g); 172.203(c)(2)	\$1,640
Milford Barrel Company, Inc. New Haven, CT Ticket #: 22T-0078-PM-EA	Failed to provide the closure instructions to a person to whom the packaging is transferred.	178.2(c)(1)(i)[B]	\$1,240
Miller Paint Co., Inc.	Failed to register as an offeror of hazardous	107.601(a)(6); 107.608(b);	\$480
Portland, OR Ticket #: 22T-0001-SH-WE	materials and pay registration fee.	107.612; 172.504	
MOOG Louisville Warehouse Louisville, KY	Offered a hazardous material while failing to apply the "limited quantity" mark. Failed to provide initial general awareness, function- specific, and security awareness training.	172.315(a); 172.702(a); 172.704(a)(1), (2), (4), & (d)	\$1,440
Ticket #: 22T-0098-SH-CE			
Mr. W Fireworks, Inc. Somerset, TX Case #: 21-0319-CA-SW	Transported UN0336 Fireworks, 1.4G, without providing a hazardous material shipping paper to accompany the shipment, and without placarding the freight container, thereby creating an undeclared shipment of hazardous materials. Listed an unauthorized emergency response telephone number on shipping papers. Failed to provide recurrent general awareness, function-specific, safety and security awareness training.	172.200(a); 172.500(a); 172.504(a); 172.604(b)(1) & (2); 172.702(b); 172.704(c)(2)	\$22,040
Mulvane Coop Union Mulvane, KS Case #: 22-0040-SH-SO	Offered and transported UN 1005, Ammonia, anhydrous, 2.2, in an unauthorized packaging.	173.22(a)(2); 173.24(c); 173.33(a)(1); 173.315(a) & (m); 180.413(a)(1)	\$3,750

Company Name	Violation Summary	Citations	Penalty Amount
N. Glantz & Son, LLC Louisville, KY Ticket #: 22T-0256-SH-CE	Failed to provide recurrent general awareness, function-specific, safety and security awareness training. Offered a hazardous material, while failing to mark an overpack as required. Offered a hazardous material, when the shipping paper failed to include the proper shipping name in the shipping description. Failed to include the proper identification number on a shipping paper.	172.702(a); 172.704(a)(1), (2), (3), (4), (c)(2), & (d); 173.25(a)(4); 172.202(a) & (a)(2); 172.200(a)	\$3,600
Nalco Company, LLC Bedford Park, IL Ticket #: 22T-0041-SH-CE	Transported packages of hazardous materials that have not been secured against movement. Offered a hazardous material, while a marked package as containing a hazardous material when it did not contain any hazardous materials.	173.30; 177.834(a); 172.303(a); 172.401(a)	\$2,280
National Container Group, LLC North Wales, PA Case #: 18-0574-PM-EA	Failed to ensure a packaging certified as meeting the UN standard can pass the required performance testing (leakproofness and hydrostatic pressure test) at the Packing Group II level. Failed to mark the correct maximum permissible gross mass (MPGM) mark on the IBC and failed to restore IBC markings to the original condition after testing (incorrect manufacture number and IBC tare weight). Failed to keep complete records of IBC testing and inspections.	178.813; 178.814(e)(3); 178.703(b); 180.352(b)(2)(I), (g)(1) & (2)	\$7,425
Next Tech Inc. Arlington Heights, IL Ticket #:	Offered a hazardous material, while failing to mark the package with the lithium battery mark.	173.185(c)	\$1,600
22T-0213-SH-CE Norton Packaging, Inc. Hamlet, IN Ticket #: 22T-0157-PM-EA	Failed to provide recurrent hazardous materials training. Represented and certified plastic drums identified as being UN standard plastic drums meeting the requirements of the HMR when the qualification test reports were not complete and accurate.	172.702(a); 172.704(c); 178.2(a); 178.2(b); 178.601(l);	\$3,080
OBCO Chemical Corporation North Charleston, SC Case #:	Offered and transported a hazardous material while failing to properly declare the hazardous material with shipping papers, package marking, and package labeling.	172.200; 172.300; 172.315(a); 172.400	\$15,000
22-0072-SH-SO Orlando Drum Co. Orlando, FL Ticket #: 22T-0242-PM-SO	Failed to reproduce or restore missing or damaged UN design type marking to their original condition on an UN31HA1 IBC. Failed to provide the minimum required information on a manufacturer's test report.	180.352(b)(2)(i), (e)(1), & (2); 178.601(l)(2)	\$1,600

Company Name	Violation Summary	Citations	Penalty
			Amount
Ozark Automotive Distributors, Inc. Springfield, MO	Offered a hazardous material without shipping papers.	172.201; 172.200(a); 177.817(a)	\$2,240
Ticket #: 22T-0121-SH-CE			
PDQ Manufacturing Ellijay, GA Case #:	Offered a hazardous material in an unauthorized, non-UN specification packaging.	173.22(a)(2); 173.24(c); 173.202(a); 173.211	\$6,525
22-0171-SH-SO			
PFS Sales Company Raleigh, NC	Failed to provide hazardous materials shipping papers, including failing to provide an emergency response telephone number.	172.200; 172.202; 172.604; 172.702(a); 172.704(a)(1), (2), (3), (4), & (c)(1)	\$3,840
Ticket #: 22T-0106-SH-SO	Failed to provide initial general awareness, function-specific, safety, and security awareness training.		
Phoenix Container Corporation Turlock, CA	Represented, certified, and marked DOT specification packages without authorization after the approval Manufacturers M number letter had expired. Failed to provide initial	107.805(c); 173.28(b)(2)(ii); 178.2(a)(2); 178.503(c)(1); 172.702(a); 172.704(a)(1), (2), (4), & (c)(1)	\$1,440
Ticket #:	general awareness, function-specific, and		
22T-0151-PM-WE	security awareness training.		40.000
Pinnacle Propane, LLC Kilgore, TX	Failed to develop a complete security plan. Failed to provide general awareness, safety, security awareness, and in-depth security training.	172.800(b)(3); 172.802(a) & (c); 172.702(b); 172.704(a)(1), (3), (4), & (5)	\$2,920
Ticket #: 22T-0187-CR-SW			
Plant Protector, LLC Loleta, CA	Failed to register as an offeror of hazardous materials and pay registration fee.	107.601(a)(6); 107.608(a) & (b); 107.612(a)	\$480
Ticket #: 22T-0088-SH-WE			
PPG Architectural Finishes, Inc. Oklahoma City, OK Ticket #:	Offered a hazardous material while failing to close a UN standard packaging in accordance with the manufacturer's closure instructions. Offered a hazardous material without the proper sized UN identification number	173.22(a)(4)(i); 173.24(f)(2); 172.300(a); 172.301(a)(1)	\$1,600
22T-0250-SH-SW	marking.		
Pratt & Whitney Engine Services Midland, GA	Offered hazardous materials accompanied by shipping papers which included an emergency response telephone number that could cause	172.201(d); 172.604(a)(1) & (2)	\$2,100
Ticket #: 22T-0051-SH-SO	a delay in obtaining or incapable of providing required information.		

Company Name	Violation Summary	Citations	Penalty
			Amount
Preferred Foam Products, Inc. Clinton, CT Case #:	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Offered a hazardous material, while failing to retain written records of all required inspections and tests.	172.702; 172.704(a)(1), (2), (3), & (4); 180.215; 180.605(l)	\$3,900
19-0531-SH-CE			
Priority Plastics Mesa, AZ	Manufactured, marked, certified, and sold UN packaging, marked UN4G/Y33/S/20/USA/M5858, as meeting	178.2(a) & (b); 178.601(a) & (b); 178.603	\$10,800
Case #: 21-0341-PM-WE	HMR requirements, while failing to ensure a packaging certified as meeting the UN standard can pass the required performance testing as the packaging was not capable of passing the drop.		
Profrac Services, LLC Odessa, TX	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Offered and transported a	172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (d); 172.202(a)(2), (3), & (k);	\$3,498
Ticket #: 22T-0102-CA-SW	hazardous material accompanied by shipping papers that failed to list the correct proper shipping name, technical name, and primary hazard class. Failed to create and maintain hazardous materials training records.		
Pye Barker Fire & Safety Tualatin, OR	Failed to report in writing a change in name, address, ownership, test equipment, management, or test personnel. Represented, certified, and marked cylinders as having been	107.805(g); 180.2; RIN N202; 180.215(b)(1) & (2)	\$760
Ticket #: 22T-0004-CR-WE	successfully retested, while failing to keep complete and accurate records of cylinder reinspection and retest, did not list owner, no DOT specification, and no service pressure was listed.		
Quality Energy Services, Inc. Broussard, LA	Offered and transported hazardous materials accompanied by shipping papers that failed to list the type of packages and net explosive mass for the total quantity of material	172.202(a)(5)(i), (7), & (c)(1); 172.702(b); 172.704(a)(1), (2), (3) & (4)	\$2,094.77
Ticket #: 21T-0342-SH-SW	covered by one description. Failed to provide general awareness, function-specific, safety and security awareness training.		
Quinoco Energy, LLC Bristol, CT	Failed to create and maintain hazardous materials training records. Failed to identify by job title the management official	172.704(d); 172.802(b)(1)	\$1,000
Ticket #: 22T-0076-SH-EA	responsible for the overall development and implementation of the security plan.		

Company Name	Violation Summary	Citations	Penalty Amount
Rahway Steel Drum	Marked a UN packaging as being	173.28(b)(2); 178.503(c);	\$19,900
Co., Inc.	reconditioned when not performing a	180.350(a);	
Cranbury, NJ	leakproofness test on the packaging. Marked a reconditioned UN packaging with an	180.352(d)(1)(ii); 172.702(a); 172.704(a)	
Case #:	improper marking. Failed to conduct design		
21-0279-PC-EA	qualification testing. Offered packaging as UN		
	certified, while failing to conduct		
	leakproofness test on the packaging. Failed to		
	provide initial hazmat training.		
Raptor Wireline	Offered and transported hazardous materials	172.101; 172.200(a);	\$670
Placentia, CA	accompanied by shipping papers that were	172.202(a)(4); 172.320(a) &	
	not properly prepared. Failed to remove all	(d); 177.801; 177.817(a)	
Ticket #:	packing groups from explosive entries and		
22T-0133-SH-WE	listed the incorrect approval number. Failed to		
	mark the package with the EX-number for		
	each substance contained in the package.		
Red Ball Oxygen Co.,	Failed to provide recurrent general	172.702(b); 172.704(a)(1),	\$1,600
Inc.	awareness, function-specific, safety and	(2), (3), (4), & (c)(2)	
Longview, TX	security training.		
Ticket #:			
22T-0193-SH-SW			

Company Name	Violation Summary	Citations	Penalty
			Amount
Red Rock Oil Co.	Offered and transported a large bulk quantity	172.800(b)(6); 172.802;	\$12,000
Clovis, NM	of a Class 3 material meeting the criteria for	180.417(a)(1) & (b)(3);	
	PG II, without developing a security plan.	172.702(b); 172.704(a)(1),	
Case #:	Filled, offered, and transported a DOT	(2), (3), (4), & (5);	
21-0389-SH-SW	specification cargo tank without retaining the	172.602(a), (b), & (c);	
	manufacturer's certificate and a copy of the	172.604(a)(3); 172.201(e);	
	test and inspection reports for a test or	172.202(a)(2), (3), (4), & (7)	
	inspection of the cargo tank. Failed to provide		
	general awareness, function-specific, safety,		
	security awareness, and in-depth security		
	training. Offered and transported a hazardous		
	material without listing an emergency		
	response telephone number on the shipping		
	paper, without emergency response		
	information accompanying the shipment on or		
	with the shipping paper while in		
	transportation, and without maintaining		
	emergency response information at the		
	facility. Offered for transportation and		
	transporting in commerce a hazardous		
	material accompanied by a shipping paper		
	that did not include the correct proper		
	shipping name, the hazard class, the packing		
	group, or the number and type of package,		
	Failed to retain a record of each shipment		
	made that included the proper shipping name,		
	identification number, and quantity		
	transported for each material while using a		
	shipping paper without change for multiple		
	shipments of one or more hazardous		
	materials having the same shipping name and		
	identification number.		
Research Solutions	Failed to provide recurrent general	172.702(a) & (b);	\$1,600
Group, Inc.	awareness, function-specific, safety, and	172.704(c)(2)	÷ 1,000
La Vergne, TN	security awareness training.		
	security awareness training.		
Ticket #:			
22T-0011-SH-SO			

Company Name	Violation Summary	Citations	Penalty
			Amount
Ridge Wireline, LLC Lindale, TX Case #: 21-0409-SH-SW	Offered and transported a hazardous material without preparing and retaining a shipping paper. Failed to provide general awareness, function-specific, safety, and security awareness training. Offered and transported a hazardous material with an unauthorized emergency response telephone number listed on the shipping papers. Assembled, offered, and transported UN0494, Jet perforating guns, 1.4D, charged, to the designs outlined in the IME guide, that had not been approved or assigned an EX-number by the Associate Administrator.	172.200(a); 172.202(a); 172.201(e); 177.801; 177.817(a) & (f); 172.702(b); 172.704(a)(1), (2), (3) & (4); 172.604(b); 173.51(a); 173.56(b)	\$9,000
Roche	Failed to ensure that a hazardous materials	178.601(b); 178.603;	\$12,760
Manufacturing, Inc. Lowell, MA	specification package can meet the required tests. Failed to keep complete testing records.	178.601(l)(2)(iii)	\$12,700
Case #: 21-0186-PM-EA			
Rodda Paint Co. Portland, OR	Failed to close a UN specification packaging in accordance with the manufacturer's closure instructions.	173.1(b); 173.22(a)(1), (2), & (4); 173.24(a) & (f)(2)	\$400
Ticket #: 22T-0195-SH-WE			
Rogue Aquatics, Inc. Central Point, OR Case #: 21-0260-CR-WE	Represented, marked, and certified a DOT specification cylinder as having been successfully requalified while failing to comply with eddy current examination requirements for DOT 3AL cylinders manufactured of aluminum alloy 6351-T6.	180.2(a); 180.3(a); 180.205(f)(4); Appendix C to Part 180	\$2,250
Rohm and Haas Chemicals, LLC Knoxville, TN	Failed to close a UN specification packaging in accordance with the manufacturer's closure instructions.	173.22(a)(4); 173.24(b) & (f)(2)	\$1,440
Ticket #: 22T-0206-SH-SO			
Rotech Healthcare, Inc. Duluth, MN	Failed to provide initial hazmat training and maintain training records.	172.704(d)	\$240
Ticket #: 22T-0223-SH-CE			

Company Name	Violation Summary	Citations	Penalty
			Amount
Company Name RTX Wireline, LLC Odessa, TX Case #: 21-0358-SH-SW	Violation Summary Offered and transported radioactive sources with an activity level requiring a Radioactive Yellow III label, without placarding the vehicle containing the hazardous material. Offered and transported a material poisonous by inhalation (PIH) and an amount of a Division 1.4D hazardous material that required placarding, while using a security plan that did not address en-route security, did not identify by job title the senior management official responsible for overall development and implementation of the plan, did not include security duties for each position or department responsible for implementing the plan, did not include a training plan for hazmat employees, and was not reviewed annually. Offered and transported a Class 7 (radioactive) hazardous material contained in DOT Specification 7A, Type A packages with the following package marking and labeling issues: the packages were not marked with the proper shipping name, identification number of "RQ," name and address of package; a package was not labeled or label was illegible, where labels were present and legible; the correct category and quantity of radioactive label was not applied to the package, and where labels were present and legible; and the labels were missing contents, activity, and transport index. Failed to provide initial/recurrent DOT general awareness, function-specific, safety, security awareness and in-depth security training. Offered and transported jet perforating guns that were not marked with the hazmat identification number and proper shipping name. Offered and transported jet perforating us that were not marked with the hazmat identification number and proper shipping name. Offered and transported hazardous materials accompanied by shipping papers that failed to list the basic hazmat	Citations 172.500(a); 172.504(a); 172.800(b)(2) & (5); 172.802(a) & (a)(3); 172.802(b)(1), (2) & (3); 172.802(c); 172.301(a)(1); 172.310(a); 172.324(b); 172.403(g)(1), (2) & (3); 178.3(a)(1) & (2); 172.702(b); 172.704(a)(1), (2), (3), (4), (5), (c)(1) & (2); 172.301(a)(1); 172.202(a)(7) & (b); 172.203(a) & (d)(3), (4) & (5); 172.604(b)(2); 173.51(a); 173.56(b)	-

Company Name	Violation Summary	Citations	Penalty Amount
Rush Order, Inc. Gilroy, CA	Failed to register as an offeror of hazardous materials and pay registration fee.	107.601(a)(6); 107.608(a)	\$1,400
Ticket #:			
22T-0080-SH-EA			4
Rush Order, Inc. Wappingers Falls, NY	Failed to register as an offeror of hazardous materials and pay registration fee.	107.601(a)(6); 107.608(a)	\$1,400
Ticket #: 22T-0092-SH-EA			
Santa Rosa Fire Equipment Service, Inc. Cotati, CA Case #: 21-0209-CR-WE	Failed to condemn a cylinder when required when permanent expansion exceeds 10 percent of total expansion. Performed, represented, certified, and marked DOT cylinders as having been successfully retested without confirming the accuracy of the test equipment. Failed to keep complete and accurate records of cylinder re-inspection and retest. Failed to notify the cylinder owner in writing when a cylinder has been condemned. Represented, certified, marked, and offered DOT specification packages while failing to notify of any change in facility name, address, ownership, management, equipment, or testing personnel within 20 days of change. Represented, certified, marked, and offered DOT specification packages while failing to properly mark the designation for the proof	180.205(a), (b), (c), (g)(3)(i), (g)(5), & (i)(1)(iv); 180.2(a) & (b); 180.3(a); 180.215(b); 107.805(g); RIN Approval B567; 180.213(a), (d), & (f)(4)	\$12,825
Scarborough Oil Co., nc. Snow Hill, MD	pressure "S". Requalified DOT specification cylinders via visual inspection without keeping daily records of visual inspections.	180.215(b)	\$4,750
Case #: 21-0378-SH-EA			
Scuba Steve's Dive Service, LLC Summerland Key, FL Ticket #: 22T-0032-CR-SO	Represented, marked, and certified DOT specification cylinders as having been successfully retested, when the cylinders tested were not within 500 PSIG of the actual test pressure for test pressures above 3000 PSIG. Failed to maintain complete and	180.205(g)(3)(i); 180.215(b)(1) & (2)	\$2,800
Security Fire Equipment Company, Inc. Valdosta, GA	accurate daily records of re-qualification. Failed to declare the hazardous materials on shipping papers and that no basic shipping description and emergency response telephone number were communicated. Failed to ensure the proper shipping names	172.200(a); 172.201(a) & (d); 172.202(a) & (b); 177.817(a); 172.300(a); 172.301(a)(1); 172.400(a); 172.406(a)	\$6,840
Ticket #: 22T-0182-CR-SO	and identification numbers were marked on the cylinders. Failed to ensure the cylinders displayed a hazard warning label.		

Company Name	Violation Summary	Citations	Penalty Amount
Sherwin Williams Company Fresno, CA	Failed to close a UN standard packaging in accordance with the closure instructions.	173.1(b); 173.22(a)(1), (2), & (4); 173.24(f)(2)	\$400
Ticket #: 22T-0007-SH-WE			
Silgan Plastics Canada, Inc. dba Cousins-Currie Woodbridge, Ontario, Canada Case #: 21-0221-PM-EA	Manufactured, marked, certified, and sold UN specifications packagings, when the design- type was incapable of passing the drop test, the hydrostatic pressure test, and the stacking test. Manufactured, marked, certified, and sold UN specification packagings while failing to provide accurate and complete assembly and closure instructions to customer.	178.2(b) & (c)(1)(i)(B); 178.601(b); 178.603(a); 178.605(a); 178.606(a)	\$10,200
Silvertip Completion Services Operating, LLC Midland, TX Ticket #: 22T-0150-SH-SW	Offered and transported hazardous materials accompanied by shipping papers, while failing to list the number and type of packages. Offered and transported a quantity of a division 1.4 material requiring placarding, while failing to develop a complete security plan.	172.202(a)(7); 172.800(b)(2); 172.802	\$800
SOFIX, LLC Chattanooga, TN Ticket #: 22T-0179-SH-SO	Offered for transportation a hazardous material accompanied by a shipping paper while using a shipping description with two or more required elements incorrect or missing.	172.202(a)(4); 172.203(k)	\$480
Southern Polyurethanes, Inc. Blairsville, GA Ticket #:	Failed to provide recurrent hazardous materials general awareness, function- specific, safety, and security awareness training.	172.702(a); 172.704(a)(1), (2), (3), (4) & (c)(1)	\$1,600
22T-0012-SH-SO			
St Croix Gas Christiansted, VI Case #: 21-0239-CA-SO	Failed to develop a security plan. Failed to provide initial/recurrent general awareness, function-specific, safety, security awareness, and in-depth security training. Offered a hazardous material while failing to provide properly completed hazardous materials shipping papers, and which included additional unauthorized information. Failed to retain hazardous materials shipping papers.	172.800(b); 172.802; 172.702(a) & (b); 172.704(a)(1), (2), (3), (4), (5), & (c)(2); 172.200; 172.201(a)(4) & (e); 172.202(a)(1), (2), & (7)	\$10,975
Stockman Oil, Inc. Elberton, GA Case #: 22-0044-CA-SO	Offered UN1203, Gasoline 3, PG II, while failing to provide hazardous materials shipping papers with the required shipping description and emergency response information. Failed to develop a security plan. Failed to provide general awareness, function- specific, safety, and security awareness training.	172.200; 172.201(d) & (e); 172.202; 172.800(b); 172.802; 172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(2)	\$12,300

Company Name	Violation Summary	Citations	Penalty Amount
Strategy Oilfield Services, Inc.	Offered and transported hazardous materials contained in a packaging other than a cargo	177.834(h); 172.200(a); 172.202(a)(7)	\$2,700
Muenster, TX	tank or IM portable tank, without removing the container from the motor vehicle when		
Case #:	discharging the contents of the container.		
21-0257-SH-SW	Offered and transported in commerce		
	hazardous materials accompanied by a		
	shipping paper that did not include the		
	number and type of packages for each		
	shipping description.		¢0.250
Stuart L. White Fire	Represented, marked, or certified a cylinder	180.205(c); 172.702(a);	\$9,350
Protection	as meeting the requirements of a special	172.704(a)(2); 180.215(b)	
Milford, CT	permit when the cylinder was not maintained or retested pursuant to the terms of the		
Casa #:			
Case #: 21-0287-CR-EA	special permit. Failed to provide initial training. Failed to keep complete and accurate		
21-0207-CR-EA	records of cylinder reinspection and retest.		
Suburban Propane	Offered and transported a class 2.1 hazardous	172.800(b)(3);	\$765.15
Montgomery, AL	material in a large bulk quantity while having	172.802(b)(1)	\$705.15
Wongomery, AL	failed to update a security plan to reflect	172.802(0)(1)	
Ticket #:	changing circumstances.		
22T-0027-SH-SO			
Sun Coatings, Inc.	Offered for transportation a hazardous	172.200; 172.201; 172.202;	\$4,040
Tampa, FL	material, while having failed to provide	172.702(a); 172.704(a)(1),	<i>ç</i> 1,010
	hazardous materials shipping paper. Failed to	(2), (4) & (c)(1)	
Ticket #:	provide initial hazardous materials general		
22T-0015-SH-SO	awareness and security awareness training.		
Super Show	Offered and transported a hazardous	172.201(a)(4) & (d),	\$907.69
Fireworks, LLC	material, accompanied by a shipping paper	172.604(a)(1) & (2);	
Birmingham, AL	which listed an emergency response number	172.604(b); 172.202(a) &	
-	in a manner that it is not readily identifiable	(b)	
Ticket #:	while failing to include the name, contract		
22T-0028-SH-SO	number, or other unique identifier of the		
	person registered with the emergency		
	response provider. Offered and transported a		
	hazardous material, accompanied by a		
	shipping paper that failed to show the basic		
	description in the specified sequence.		
Superior Plus	Offered and transported UN1075, Propane,	180.407(c); 180.416(d)(5)	\$8,400
Propane, Inc.	2.1, in a cargo tank for which periodic testing		
Waterbury, CT	has become due. Offered and transported a		
o "	hazardous material contained in a CTMV,		
Case #:	while failing to perform monthly delivery hose		
21-0350-SH-EA	and discharge system inspections.	190 215(2)(6) 9 (5)(2)	¢2.220
Superior Products	Requalified DOT-specification cylinders while	180.215(a)(6) & (b)(2)	\$2,230
Distributors, Inc.	failing to maintain copies of CGA Pamphlets		
Milldale, CT	applicable to inspection, retesting, and		
Tickot #·	marking activities. Failed to record on the		
Ticket #:	requalification record the cylinders' serial		
22T-0174-CR-EA	numbers and the results of visual inspections.		

Company Name	Violation Summary	Citations	Penalty
			Amount
TCI Products Co. St. Louis, MO	Failed to maintain training records.	172.704(d)	\$540
Ticket #: 22T-0261-SH-CE			
Technick Products,	Failed to close a UN standard packaging in	173.22(a)(4); 173.24(b) &	\$1,200
nc.	accordance with the closure instructions.	(f)(2); 178.2(c); 178.601(b)	
South Plainsfield, NJ			
Ticket #:			
22T-0138-HM-EA	Offered and transported "UN2222	172 200, 172 201, 172 202,	¢2 202 25
Terracon	Offered and transported "UN3332, Radioactive material, Type A package, special	172.200; 172.201; 172.202; 172,203; 177.800; 177.801;	\$2,292.25
Consultants, Inc. Sacramento, CA	form, 7", without shipping papers.	177.817(a); 172.400(a) &	
Jaciamento, CA	Transported "UN3332, Radioactive material,	(b), 172.403(a) & (g)	
Ticket #:	Type A package, Special form, 7, while	(b), 1/2.703(a) & (B)	
21T-0391-SH-WE	marking the incorrect transportation index		
	and activity on the label.		
Terracon	Offered and transported "RQ, UN3332,	172.400(a) & (b); 172.403(a)	\$1,600
Consultants, Inc.	Radioactive Material, Type A Package, Special	& (g); 177.800; 177.801;	
Midvale, UT	Form, 7" while not marked with the	172.200; 172.201;	
	radionuclide, activity, and transport index on	172.202(a); 172.203(d);	
Ticket #:	the label. Offered "UN3322, Radioactive	172.401(b); 172.406(d)	
22T-0101-SH-WE	Material, Type A Package, Special Form, 7",		
	while using an incorrect identification number		
	and proper shipping name. Offered DOT Type		
	A packages as meeting the requirements of		
	the HMR, while bearing a marking or label		
	which by its color, design, or shape could be confused with or conflict with a label.		
Tetraco, LLC	Failed to provide initial hazmat training to	172.702(a); 172.704(a)(1),	\$3,080
Midland, TX	include general awareness, function-specific,	(2), (3), (4), & (d);	
	safety, and security awareness training. Failed	172.200(a); 172.202(a);	
Ticket #:	to list the proper shipping description in the	173.22(a)(4); 173.24(f)(2)	
22T-0103-SH-SW	required sequence and include the required		
	technical name in the shipping description on		
	shipping papers. Failed to close a UN standard		
	packaging in accordance with the closure instructions.		
Texas Finishing	Failed to register as an offeror of hazardous	107.601(a)(6); 107.608(a) &	\$720
Company, Inc.	materials and pay registration fee.	(b)	
Carrollton, TX		(-)	
Ticket #:			
22T-0033-SH-SW			

Company Name	Violation Summary	Citations	Penalty Amount
Texas Oncology- Mesquite Mesquite, TX	Failed to provide general awareness/familiarization, function-specific, and security awareness training.	172.702(b); 172.704(a)(1), (2), & (4)	\$1,200
Ticket #: 22T-0266-SH-SW			
Texas Star Chemical, LLC Longview, TX Ticket #: 22T-0058-SH-SW	Failed to register as an offeror of hazardous materials and pay registration fee. Failed to provide general awareness, function-specific, safety, and security awareness training. Failed to close a UN standard packaging in accordance with the closure instructions.	107.608(b); 172.702(b); 172.704(a)(1), (2), (3) & (4); 173.22(a)(4)(i); 173.24(f)(2)	\$2,980
The Lebermuth Company Inc. South Bend, IN Ticket #: 22T-0116-PM-SW	Failed to register as an offeror of hazardous materials and pay registration fee. Failed to provide initial general awareness/familiarization, function-specific, safety, and security awareness training. Failed to close a UN standard packaging in accordance with the closure instructions. Offered a hazardous materials accompanied by shipping papers that failed to include the correct hazard class/division number.	107.601(a); 107.608(b); 172.504(e); 172.702(b); 172.704(a); 173.22(a)(4)(i); 173.24(f)(2); 172.202(a)(3)	\$3,480
The PolyCube Company, LLC Levittown, PA Ticket #: 21T-0399-PM-EA	Represented, marked, certified, offered, and sold UN standard jerricans as meeting the requirements of the HMR when the production leakproofness test was not properly conducted.	178.604(b)(1); Appendix B to Part 178	\$1,250
The Propane Guys, Inc. Holbrook, NY Ticket #: 21T-0303-SH-EA	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Failed to include in the shipping description on the shipping paper the package type.	172.702(a); 172.704(a)(1), (2), (3), & (4); 172.202(a)(7)	\$1,380
The Rental Center of Monticello, Inc. Monticello, NY Case #: 21-0149-SH-EA	Filled a DOT specification cylinder with hazardous material, when the cylinder displayed evidence of rusting and corrosion. Failed to provide initial general awareness, function-specific, safety, and security awareness training.	173.301(a)(2); 173.301(a)(6); 172.702(a)(1), (2), (3) & (4)	\$5,000
The Sherwin- Williams Company Garland, TX Ticket #: 22T-0024-HM-SW	Failed to create and provide the motor carrier with hazardous material shipping papers. Failed to provide the motor carrier with the required placards prior to or at the same time the material was offered for transportation. Offered hazardous materials packaged in non- bulk packages that had an incorrect character size for identification number marking.	172.200(a); 172.506(a); 172.301(a)(1)	\$6,360

Company Name	Violation Summary	Citations	Penalty Amount
Thermo Fluids, Inc. Nampa, ID Case #:	Transported UN1203, Gasoline, 3, PGII, while failing to conduct a leakproof test and external visual inspection.	178.703; 178.801; 178.813; 180.352(a), (b)(1), & (2)	\$5,625
21-0286-SH-WE			
Tilden's Scuba Center	Condemned cylinders that failed the visual	180.215(b)(2)	\$1,875
Marathon, FL	inspection phase of re-qualification, while having failed to create and maintain records.		
Case #:			
22-0030-CR-SO			
TOK America, Inc. Hillsboro, OR	Offered a hazardous material while failing to properly test and inspect a portable tank.	173.22(a); 173.24(a); 173.32(a)(1) & (2); 180.605	\$1,725
Case #: 21-0392-PM-WE			
Total Safety U.S., Inc.	Offered a hazardous material while failing to	172.400(a)(1); 172.201(e);	\$3,520
Dickinson, ND	label a package. Failed to retain shipping papers. Failed to maintain training records.	172.704(d)	
Ticket #:			
22T-0219-SH-CE			
Tower Energy, LLC	Offered and transported UN1075, Liquefied	172.800(b)(3)	\$4,200
Plainville, CT	petroleum gas, 2.1, without developing and adhering to a transportation security plan.		
Case #: 21-0379-SH-EA			
TR Drum, LLC	Represented, marked, certified, and sold UN	173.1(a)(3); 173.28(a)(4)(i)	\$8,269
Plant City, FL	Standard drums as reconditioned UN Standard packaging meeting the requirements of the	& (c)(1)(i); 178.503(c)(1)(ii); Approval R1897	
Case #:	HMR, when the drums were not eligible to be		
21-0383-PM-SO	reconditioned, and others were not properly		
	prepared for reconditioning. Represented,		
	marked, certified, and sold UN Standard drums as reconditioned UN Standard		
	packaging meeting the requirements of the		
	HMR, while performing a marking function		
	covered by an approval in relation to the HMR		
	after that approval had been terminated.		
Tradebe Industrial	Offered hazardous materials in an	173.22(a)(2); 172.200(a);	\$17,595
Services, LLC	unauthorized non-UN DOT packaging. Offered	172.201(a)	
East Chicago, IN	a hazardous material that was misclassified on		
o "	the shipping paper.		
Case #: 20-0164-HMI-CE			
Transaction Packing,	Failed to close a UN standard packaging in	173.1(b); 173.22(a)(4)(i);	\$1,000
LLC	accordance with the closure instructions.	173.24(f)(2)	
Houston, TX			
Ticket #:			
22T-0191-SH-SW			

Company Name	Violation Summary	Citations	Penalty Amount
Transchemical, Inc. St. Louis, MO Ticket #: 22T-0259-SH-CE	Failed to close a UN standard packaging in accordance with the closure instructions. Offered a hazardous material when the shipping paper failed to include the correct proper shipping name in the shipping description.	173.22(a)(4); 173.24(f)(2); 172.202(a)(2)	\$1,600
Traxxas, L.P. McKinney, TX Ticket #: 22T-0034-SH-SW	Failed to provide general awareness, safety, and security awareness training. Offered hazardous materials accompanied by shipping papers, while failing to constantly monitor the emergency response telephone number while hazmat was in transportation, and the phone number was answered by someone not knowledgeable of the hazardous materials being shipped.	172.702(b); 172.704(a)(1), (3), (4), & (d); 172.604(a)(1) & (2)	\$3,480
Tubelite FL, LLC Apopka, FL Ticket #: 21T-0346-SH-SO	Failed to provide initial general awareness, function-specific, safety, and security awareness training.	172.702(a) & (b); 172.704(a)(1), (2), (3), & (4)	\$2,039.33
Tubelite NC, LLC Charlotte, NC Ticket #: 21T-0348-SH-SO	Failed to provide initial general awareness, function-specific, safety, and security awareness training.	172.702(a) & (b); 172.704(a)(1), (2), (3), & (4)	\$2,026.33
Turner Specialty Services, LLC Baton Rouge, LA Ticket #: 22T-0089-SH-SW	Offered and transported a hazardous material that listed an unauthorized emergency response telephone number on shipping papers. Offered and transported a known radionuclide listed by the International Atomic Energy Agency Code of Conduct (IBR, see § 171.7) Category 1 and 2 materials, Nuclear Regulatory Commission, Category 1 and Category 2 radioactive materials as listed in Table 1, Appendix A to 10 CFR part 37, while failing to develop a complete security plan that included an assessment of transportation security risks for shipments of the hazardous materials, including site-specific or location- specific risks. Offered and transported RQ, UN 2916, Radioactive Material, Type B(U) package, 7, while failing to list the physical and chemical form of the radioactive material contained in the package on the shipping paper.	172.604(b); 172.800(b)(15); 172.802(a); 172.203(d)(2)	\$2,000

Company Name	Violation Summary	Citations	Penalty
			Amount
Jnited Parts & Equipment, LLC Viami, FL	Offered a hazardous material without declaring the shipment as a hazardous material by providing proper shipping papers, package markings, package labels, and	172.200(a); 172.300(a); 172.400(a); 172.600(c); 173.1(b); 173.22(a)(1) & (2); 172.702(a) & (b);	\$30,000
Case #:	compliance with emergency response	172.704(a)(1), (2), (3), (4), &	
20-0175-SH-SO	requirements. Offered a hazardous material	(c)(1)	
20-0176-SH-SO	without declaring the shipment as a hazardous material by providing proper shipping papers, package markings, package labels, and compliance with emergency response requirements. Failed to provide initial general awareness, function-specific, safety, and security awareness training.		
Jltimate Pest	Offered and transported a hazardous material	SP 11220 sostion 82	\$2,200
Control Savannah, GA	while failing to comply with a provision of special permit. Offered a hazardous material, when the shipping paper failed to follow an	SP-11329, section 8a; 172.201(a)(1)	<i>Ş</i> 2,200
Ficket #: 22T-0241-SH-SO	approved format for listing hazardous		
Jniversal	materials on a shipping paper.	172 401(a): 172 415(a):	ćr 100
	Offered and transported radioactive	173.401(a); 173.415(a);	\$5,100
Ingineering Science,	hazardous materials in DOT Type A packages,	173.401(a); 173.476(a);	
Tampa, FL	while failing to maintain Type A Package documentation of tests and engineering evaluation. Offered and transported a	172.702(a) & (b); 172.704(a)(1), (2), (3), (4), & (c)(2)	
Ficket #:	hazardous material that was a radioactive		
22T-0013-SH-SO	material containing special form isotopes, while failing to maintain special form documentation for the isotopes. Failed to provide general awareness, function-specific, safety, and security awareness training.		
JS Container Depot,	Transported a hazardous material	172.201(d); 172.604(a) &	\$1,680
LC Riviera Beach, FL Ficket #: 22T-0087-CA-SO	accompanied by a shipping paper that failed to include an emergency response telephone number. Accepted and transported a hazardous material accompanied by a shipper paper that did not include the shipper's certification.	(b); 177.817(a) & (b)	
/axxen Labs, Inc. dba	Offered hazardous materials in unauthorized	173.22(a); 172.202(a)(2) &	\$7,745
Vedlab	non-UN standard packaging. Offered a	(3)	
nternational, Inc.	hazardous material with incorrect shipping		
Cortland, OH	name and missing hazard class division.		
Case #: 21-0297-SH-EA			
/entureTech, Inc.	Failed to close a UN standard packaging in	173.22(a)(4); 173.24(b) &	\$1,440
Knoxville, TN	accordance with the closure instructions.	(f)(2)	
Ficket #:			
2T-0205-SH-SO			

Company Name	Violation Summary	Citations	Penalty Amount
Victor Welding Supply Company Tulsa, OK	Offered and transported UN1075, Propane, 2.1, contained in cargo tank motor vehicles, while failing to conduct monthly hose assembly and piping system inspections.	180.416(d)	\$1,000
Ticket #: 22T-0186-SH-SW			
Water Well	Manufactured and offered an explosive after	173.22(a)(1); 173.51(a);	\$7 <i>,</i> 035
Developers Caldwell, ID	the explosive's approval has been terminated.	173.54(a)	
Case #: 22-0149-SH-WE			
Wesley Medical Center, LLC Wichita, KS Ticket #: 22T-0221-SI-CE	Failed to provide initial general awareness, function-specific, safety, and security awareness training. Offered and transported a hazardous material, while failing to close inner packaging to prevent leakage.	172.702(a), (b), & (d); 172.704(a), (c), & (d); 173.22(a)(4); 173.24(f); 173.134(c)(2)	\$3,840
Western Explosives Systems Company Moab, UT Ticket #: 22T-0018-SH-WE	Offered and transported a hazardous material in a package that was improperly marked. Transported a detonator on the same vehicle as incompatible materials using the approved method listed in 177.835(g)(3) without meeting the requirements of IME Standard 22. Specifically, the container was not properly marked.	173.22(a)(2); 177.800(a) & (b); 177.801; 178.3(a) & (c); 178.503(a); 178.521; SP- 11156; 173.63; 177.835(g)(3); 177.848(f), (g), & IME SLP-22	\$640
Winkle Oil Company, LLC Winnsboro, TX	Failed to provide recurrent general awareness, function-specific, safety, security, and in-depth security training.	172.702(b); 172.704(a) (1), (2), (3), (4), (5), & (c)(2)	\$2,000
Ticket #: 22T-0162-SH-SW			
WTG Fuels, Inc. Odessa, TX	Offered and transported UN1075, Liquefied petroleum gas, 2.1 contained in cargo tank motor vehicles (CTMV) in which the company	180.416(d)(5)	\$1,000
Ticket #: 22T-0289-CA-SW	failed to create and maintain a monthly hose assembly and piping system report for each CTMV.		
Wurth Wood Group, Inc. Raleigh, NC	Failed to close a UN standard packaging in accordance with the closure instructions. Failed to provide general awareness, function- specific, safety, and security awareness	173.22(a)(4); 173.24(b) & (f)(2); 172.702(a); 172.704(a)(1), (2), (3), (4) & (d)	\$1,680
Ticket #: 22T-0109-SH-SO	training. Failed to maintain training records.		

Company Name	Violation Summary	Citations	Penalty
			Amount
Zinc Point	Offered hazardous materials packaged in	173.60(a); EX Approval	\$9,200
Manufacturing	unauthorized non-bulk packages and	EX2015090803;	
Cleburne, TX	unauthorized limited quantity packages.	173.63(b)(2); 172.702(b);	
	Failed to provide general awareness, function-	172.704(a)(1), (2), (3), & (4);	
Case #:	specific, safety, and security awareness	172.202(a)(5)(i)	
21-0159-SH-SW	training. Offered hazardous materials listed on		
	shipping papers that failed to list the net		
	explosive mass for Division 1 materials.		
ZSR Patlayıcı Sanayi	Offered a hazardous material without a valid	173.21(b); 173.51(a);	\$2,400
A.Ş. c/o DRZ	Competent Authority Approval.	173.54(a)	
Ammunition			
Manufacturing			
Company, LLC			
Las Vegas, NV			
Case #:			
22-0134-SH-EA			