



U.S. Department of Transportation  
Pipeline and Hazardous Materials  
Safety Administration

1200 New Jersey Ave, S.E.  
Washington, D.C. 20590

JUN 17 2014

Mr. Brian C. Sheppard  
Vice President, Pipeline Operations  
Dominion Transmission, Inc.  
445 West Main Street  
Clarksburg, WV 26302-2450

**PHMSA-2007-28458**

Dear Mr. Sheppard:

The Pipeline and Hazardous Materials Safety Administration (PHMSA) reviewed the documentation that you made available to the PHMSA Central Region staff during a pipeline inspection on April 8, 2014. This inspection was in response to Dominion Transmission, Inc., (DTI) request of January 22, 2014, to withdraw Special Permit number PHMSA-2007-28458.

According to DTI's records, the replaced pipe segments included in the TL-400 system of Special Permit No. PHMSA-2007-28458 was put into service on July 17, 2013. Based on PHMSA's inspection of the records, Special Permit No. PHMSA-2007-28458 was terminated on April 8, 2014.

My staff would be pleased to discuss any other Special Permit or regulatory matter pertaining to pipelines operated by Dominion Transmission, Inc. Ms. Linda Daugherty, Central Region Director, may be contacted at 816-329-3800 for questions regarding the oversight of this pipeline. Mr. John Gale, Director of Standards and Rulemaking, may be contacted at 202-366-4046 for regulatory matters. Mr. Kenneth Lee, Director of Engineering and Research, may be contacted at 202-366-0568 for technical matters.

Sincerely,

Jeffrey D. Wiese  
Associate Administrator for Pipeline Safety